



Ministry of Environment  
**Inspection Record**

**Environmental  
Protection  
Division**

EP System: <u>AMS</u>	Inspection Status: <u>FINAL</u>
System Number: <u>105179</u>	Inspection No: <u>1991</u>
EP System Status: <u>Active</u>	Inspection Date: <u>2012-05-11</u>
Region: <u>Skeena</u>	Office: <u>Smithers</u>
Trigger: <u>Incident</u>	<b>Incidents of Non-Compliance Observed: <u>No</u></b>
Non-Compliance Decision Matrix Level: <u>Level 1 - No impact likely</u>	Non-Compliance Decision Matrix Category: <u>Category A - No previous NCs, good awareness/attitude</u>
Inspector Name(s): <u>Lisa Torunski</u>	Risk Ranking: <u>0 to 1 = Low</u>
Audit: <input type="text"/>	Total Non-Compliance(s): <u>0</u>
Regulated Party: <u>CHEIFTAIN METALS INC</u>	
Regulated Party Contact(s): <u>Joanne Thompson, Sustainability Manager (205)651-7662</u>	
Mailing Address: <u>2200-1055 West Hastings St. Vancouver BC V6E 2E9</u>	
Phone No: <u>(250)651-7662</u>	Fax No: <input type="text"/>
Contact Email: <u>Joanne.Thompson@cheiftainmetals.com</u>	
Location Description: <u>The Tulsequah Project is located in northwestern British Columbia on the Tulsequah River near its junction with the Taku River, approximately 100 kilometres south of the town of Atlin, British Columbia and 65 kilometres northeast of Juneau, Alaska. Incident site - Tulsequah River.</u>	
Latitude: <u>58.73444</u> N	Longitude: <u>133.6016</u> W
Receiving Environment(s): <u>Surfacewater</u>	

# Summary

## MONITORING AND REPORTING REQUIREMENTS

Inspection Period:

**From:** 2012-05-11

**To:** 2012-05-11

Requirement Source:

Permit

Activity: Office Review

Waste Type: Effluent

### Inspection Summary :

Approximately 300 gallons of untreated mine water was released into the Tulsequah River from the Tulsequah Chief Interim Water Treatment Plant Acid Water Storage Pond at 5:27PM on 8 May 2012. This release lasted for three minutes and was monitored for the duration by the Tulsequah Chief Site Manager. The affected environment was "surface water". The cause of the spill was - complications due to equipment failure.

The release occurred as a result of a number of factors. These were:  
Several failures in the IWTP lime dosage system (solenoids, ports, valves, impeller) requiring maintenance downtime to repair;  
Problems with hydrated lime product consistency;  
The polymer system remaining offline after the plant was re-started following maintenance activities; and  
Spring freshet flows augmented by rainfall at site increasing the volume of pond inflows.

The incident was reported by the permittee May 9th 2012, via e-mail to Jeanien Carmody-Fallows, MOE EPO with an attached incident bulletin.

### Response:

Advisory

Compliance Summary	In	Out	N/A	N/D
Reporting	2	0	0	1

## Inspection Details

Requirement Type: Reporting

### Requirement Description:

Discharge Permit 105719 Section 2.1. Bypass

### Findings:

This incident represents non-compliance with discharge permit 105719, Section 2.1 Bypasses; under the provisions of the Environmental Management Act.

Compliance: In

**Requirement Type: Reporting****Requirement Description:**

Discharge Permit 105719 Section 5.6. Spill Reporting

**Findings:**

As per Section 5.6, Spill Reporting, of discharge permit 105719, the permittee is required to report spills to the Provincial Emergency Program. (<http://www.env.gov.bc.ca/eemp/>).

The permittee was reminded of this requirement is an e-mail response in the advisory letter issued.

**Compliance:** Not Determined

**Requirement Type: Reporting****Requirement Description:**

Discharge Permit 105719 Section 5.2 Non-Compliance Reporting & Section 5.3 Non-Compliance Follow - Up

**Findings:**

The attached incident bulletin provides a detailed event timeline of the plant failures, maintenance and restarts leading up to the decision to pump water, overflowing the pump house to the river, followed by monitoring and cessation of the bypass. It also provides planned activities to prevent any discharge to the Tulseqhah River in the future.

**Compliance:** In

**ACTIONS REQUIRED BY REGULATED PARTY & ADDITIONAL COMMENTS:**

MOE concurs that the following activities should be carried out to prevent any discharge to the Tulseqhah River in the future:

- Maintaining the IWTP Acid Water Storage Pond at the lowest possible level;
- Installing a pipeline from the IWTP Acid Water Storage Pond to the Exfiltration Pond as a secondary storage option in the event of a pond overflow.
- Increasing water storage capacity within the 5200 level of the Tulsequah Chief Mine.
- Implementing an IWTP Start-Up checklist, which includes checking of all valves and pumps in the water treatment system to ensure full plant start-up.
- Investigating automation options for IWTP start-up which will prevent the plant from starting unless all pumps are online.

An advisory letter was sent to the permittee acknowledging the non-compliance. With no further reporting on the incident required by MOE.

**INSPECTION CONDUCTED BY:**

*Signature*

Lisa Torunski

*Date Signed :*

2012-05-16

**ENCLOSURE(S) TO REGULATED PARTY & DESCRIPTION:**

120509 Tulsequah Chief IWTP Pond Release Incident Bulletin.pdf

[file:///P:/WANSHARE/FPD/FPD\\_SHARED/!Compliance/!CVIS](file:///P:/WANSHARE/FPD/FPD_SHARED/!Compliance/!CVIS)

**REGULATORY CONSIDERATIONS:**

--

Ministry of Environment	Skeena Region Environmental Protection Division	Mailing Address: Bag 5000, 3726 Alfred St Smithers, BC V0J 2N0	Phone: (250) 847-7260 Fax: (250) 847-7591 Website: <a href="http://www.gov.bc.ca/env">http://www.gov.bc.ca/env</a>
-------------------------	---	--	---