

From: SPOMO1701@outlook.com
Sent: Tuesday, July 3, 2018 7:05 AM
To: Environmental Compliance ENV:EX; marty@chholdings.ca
Subject: SPO MO1701-Status Update June 30, 2018
Attachments: June 30, 2018 CHH Progress Report.pdf

- ***The sending date of this submittal complies with item 4b of the Oct 11, 2017 Ministry of Environment Letter entitled Re: Spill Prevention Order for Cobble Hill Holdings Landfill – Reporting Requirements File MO1701***
- ***Please find information regarding the Leachate reporting requirements for the June 30, 2018 reporting period as per SPILL PREVENTION ORDER : MO1701 Section 1d***

Total Leachate Collected= 5.39 m³

Total Leachate Stored= 37.60 m³

Total Leachate Transported= 0 m³

- ***Sampling was conducted on June 26, 2018 as per Section 6biii of File 311372 August 11, 2017 letter. Laboratory results are pending.***

Sampling Summary:

1. SHA-SW1
2. SHA-SW2 (No Flow)
3. MW6
4. MW3
5. MW2
6. SHA-LE-1
7. SHA-LD-1 (Dry)
8. SB-1
9. SB-2
10. SB-3 (Dry)

- ***Attached is the QP Progress Report for June 30, 2018 as per File 311372 August 11, 2017 letter.***

Thank you



ISLANDER

ENGINEERING

FIELD REVIEW REPORT		DATE: June 30 2018	ISLANDER PROJECT No.: 2087
REPORT No: 23	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Cloud cover, Sunny, 22 deg	1 of 3 PAGE:
PROJECT: Cobble Hill Landfill 2017 Minor Construction Works			
TO: CHH	ATTENTION: Marty Block		
CC:			

The field review included the inspection of the following items included in the detailed summary of works section of the *Cobble Hill Landfill — 2017 Minor Construction Works, Detailed Construction Plan (Sperling Hansen Associates, September 13, 2017)*

- **PEA**
 - Liner appears to be in good condition, and no noticeable changes since the date of our last inspection
- **Leachate and Leak Detention facility**
 - Total leachate collected: = **5.39 m³**
 - Total leachate stored = **37.60 m³**
 - Total leachate transported = **0 m³**
- **Soil Management Area (SMA)**
 - All works are in good condition and no noticeable changes since the date of our last inspection
- **Contact Water Containment Pond**
 - All works are in good condition and no noticeable changes since the date of our last inspection
- **cut-off ditch upland of PEA**
 - All works are in good condition, ditch still performing well.

ISLANDER ENGINEERING LTD.



Mike Achtem, P.Eng


29 JUNE 2018

FIELD REVIEW REPORT	DATE: June 30 2018	ISLANDER PROJECT No.: 2087
----------------------------	---------------------------	--------------------------------------



ISLANDER ENGINEERING

REPORT No: 23	STAGE OF CONSTRUCTION: Landfill Closure	Cloud cover, Sunny, 22 deg	PAGE: 2 of 3
------------------	--	----------------------------------	--------------



SMA - looking south



SMA – looking north



Contact water containment Pond



Pipe trenching and Leachate and Leak Detention facility

FIELD REVIEW REPORT

DATE: June 30 2018

ISLANDER
PROJECT No.: 2087



ISLANDER

ENGINEERING

REPORT No: 23	STAGE OF CONSTRUCTION: Landfill Closure	Cloud cover, Sunny, 22 deg	PAGE: 3 of 3
------------------	---	----------------------------------	--------------




PEA – liner near NE corner



PEA– NW corner



PEA ditch



PEA north face