



GPS RECEIVER:

- 2006/12/04 22:00UT Leica GRX1200 PRO GG s/n 351093  
- 2006/04/07 03:00UT Leica SR530 s/n# 82195

---

FIRMWARE:

- 2015/06/18 14:34 UT Firmware 9.20 / ME 3.823  
- 2013/11/06 15:30UT Firmware 8.71 / ME 3.822  
- 2012/05/02 17:26UT Firmware 8.15 / ME 3.019  
- 2011/09/12 15:55UT Firmware 8.20 / ME 3.019  
- 2011/02/22 15:40UT Firmware 8.10 / ME 3.019  
- 2010/09/08 14:45UT Firmware 8.0  
- 2010/05/05 18:30UT Firmware 7.80  
- 2009/05/05 14:00UT Firmware 7.50  
- 2008/10/31 15:00UT Firmware 6.00  
- 2008/02/26 16:30UT Firmware 5.62  
- 2007/03/06 16:09UT Firmware 5.10  
- 2006/04/07 03:00UT Firmware ver. 5.00

---

ANTENNA (diagram below):

- 2006/12/04 22:00UT Leica Choke Ring - GLONASS with LEIS Dome  
sn 200012 (LEIAT504GG LEIS)  
- 2006/04/07 03:00UT Leica Choke Ring with LEIS Dome sn# 103106

---

ANTENNA CABLE:

- 2006/04/07 03:00UT

---

CLOCK:

- 2006/04/07 03:00UT GPS Receiver Internal Clock

---

COMPUTER HARDWARE:

- 2006/04/07 03:00UT N/A

---

MODEMS:

- 2006/12/04 N/A  
- 2006/04/07 Lantronix MSS100

---

UNINTERRUPTABLE POWER SUPPLY:

- 2006/04/07 03:00UT

---

STATUS:

---

AGENCY: GeoBC  
Prince of British Columbia

CONTACT: Vern Vogt P. Eng.  
Province of British Columbia  
GeoBC  
3400 Davidson Ave.  
Victoria, BC, Canada V8Z 3P8  
Tel: (250) 952-6571  
Fax: (250) 952-4188  
email: vern.vogt@gov.bc.ca

---

ANTENNA DIAGRAM:

2006/12/04 DM T Style Leica Choke Ring with Leica dome (LEIAT504GG LEIS)



