

From: SPOMO1701@outlook.com
To: Environmental.Compliance ENV:EX; marty@chholdings.ca
Subject: SPO MO1701-Status Update March 15, 2019
Date: March 15, 2019 21:36:30
Attachments: [CHH Status Report Mar 15, 2019.pdf](#)

- ***Please find information regarding the Leachate reporting requirements for the MARCH 15, 2019 reporting period as per SPILL PREVENTION ORDER : MO1701 Section 1d***

Total Leachate Collected= 5.49 m³
Total Leachate Stored= 17.27 m³
Total Leachate Transported= 0.00 m³

- ***Sampling was conducted on February 25 , 2019 as per Section 6biii of File 311372 August 11, 2017 letter. Laboratory results are pending.***

Sampling Summary:

1. *SHA-SW1*
2. *SHA-SW2 (no flow)*
3. *MW6*
4. *MW3*
5. *MW2*
6. *SHA-LE-1*
7. *SHA-LD-1 (Dry)*
8. *SB-1*
9. *SB-2*
10. *SB-3 (Insufficient volume)*

- ***Attached is the QP Progress Report for March 15, 2019 as per File 311372 August 11, 2017 letter.***

Thank you



FIELD REVIEW REPORT		DATE: March 15, 2019	ISLANDER PROJECT No.: 2087
REPORT No: 40	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Sun 2°C	PAGE: 1 of 3
PROJECT: Cobble Hill Landfill 2017 Minor Construction Works			
TO: CHH	ATTENTION: Marty Block		
CC:			

The field review included the inspection of the following items included in the detailed summary of works section of the *Cobble Hill Landfill — 2017 Minor Construction Works, Detailed Construction Plan (Sperling Hansen Associates, September 13, 2017)*:

- **PEA**
 - Liner appears to be in good condition, with no noticeable changes since the date of our last inspection
- **Leachate and Leak Detention facility**
 - Total leachate collected: = 5.49 m³
 - Total leachate stored = 17.27 m³
 - Total leachate transported = 0 m³
- **Soil Management Area (SMA)**
 - All works are in good condition and no noticeable changes since the date of our last inspection
- **Contact Water Containment Pond**
 - All works are in good condition and no noticeable changes since the date of our last inspection
- **cut-off ditch upland of PEA**
 - All works are in good condition, ditch still performing well.

ISLANDER ENGINEERING LTD.

Mike Achtem, P.Eng



FIELD REVIEW REPORT		DATE: March 15, 2019	ISLANDER PROJECT No.: 2087
REPORT No: 40	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Sun 2°C	PAGE: 2 of 3



SMA - looking south



SMA - looking north



Contact water containment Pond



Leak and leachate detection works



FIELD REVIEW REPORT		DATE: March 15, 2019	ISLANDER PROJECT No.: 2087
REPORT No: 40	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Sun 2°C	PAGE: 3 of 3



PEA – liner near NE corner



PEA– NW corner



PEA north face