

From: SPOMO1701@outlook.com
To: [Environmental Compliance ENV:EX](#); marty@chholdings.ca
Subject: 105809 Status Update
Date: June 17, 2019 19:18:23
Attachments: [June 15, 2019 CHH Progress Report.pdf](#)

- ***The sending date of this submittal complies with item 4b of the Oct 11, 2017 Ministry of Environment Letter entitled Re: Spill Prevention Order for Cobble Hill Holdings Landfill – Reporting Requirements File MO1701***
- ***Please find information regarding the Leachate reporting requirements for the June 15, 2019 reporting period as per SPILL PREVENTION ORDER: MO1701 Section 1d***

Total Leachate Collected= 2.24 m³
Total Leachate Stored= 35.16 m³
Total Leachate Transported= 0.00 m³

- ***Sampling was conducted on May 30 , 2019 as per Section 6biii of File 311372 August 11, 2017 letter. Laboratory results are pending.***

Sampling Summary May 30, 2019:

1. *SHA-SW1*
2. *SHA-SW2 (no flow)*
3. *MW6*
4. *MW3*
5. *MW2*
6. *SHA-LE-1*
7. *SHA-LD-1 (Dry)*
8. *SB-1*
9. *SB-2*
10. *SB-3 (Dry)*

- ***Attached is the QP Progress Report for June 15, 2019 as per File 311372 August 11, 2017 letter.***

Thank you



FIELD REVIEW REPORT		DATE: JUNE 15, 2019	ISLANDER PROJECT No.: 2087
REPORT No: 46	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Sun 22°C	PAGE: 1 of 3
PROJECT: Cobble Hill Landfill 2017 Minor Construction Works			
TO: CHH	ATTENTION: Marty Block		
CC:			

The field review included the inspection of the following items included in the detailed summary of works section of the *Cobble Hill Landfill — 2017 Minor Construction Works, Detailed Construction Plan (Sperling Hansen Associates, September 13, 2017)*:

- **PEA**
 - Liner appears to be in good condition, with no noticeable changes since the date of our last inspection
- **Leachate and Leak Detention facility**
 - Total leachate collected: = 2.24 m³
 - Total leachate stored = 35.16 m³
 - Total leachate transported = 0 m³
- **Soil Management Area (SMA)**
 - All works are in good condition and no noticeable changes since the date of our last inspection
- **Contact Water Containment Pond**
 - All works are in good condition and no noticeable changes since the date of our last inspection
- **cut-off ditch upland of PEA**
 - All works are in good condition, ditch still performing well.

ISLANDER ENGINEERING LTD.

Mike Achtem, P.Eng



FIELD REVIEW REPORT		DATE: JUNE 15, 2019	ISLANDER PROJECT No.: 2087
REPORT No: 46	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Sun 22°C	PAGE: 2 of 3



SMA - looking south



SMA - looking north



Contact water containment Pond



Leak and leachate detection works



FIELD REVIEW REPORT		DATE: JUNE 15, 2019	ISLANDER PROJECT No.: 2087
REPORT No: 46	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Sun 22°C	PAGE: 3 of 3



PEA – liner near NE corner



PEA– NW corner



PEA north face



PEA ditch