



<b>FIELD REVIEW REPORT</b>		DATE: <b>March 27, 2018</b>	ISLANDER PROJECT No.: <b>2087</b>
REPORT No: <b>17</b>	STAGE OF CONSTRUCTION: <b>Landfill Closure</b>	WEATHER: <b>Rain &amp; cloudy</b>	PAGE: <b>1 of 3</b>
PROJECT: <b>Cobble Hill Landfill 2017 Minor Construction Works</b>			
TO:	<b>CHH</b>	ATTENTION:	<b>Marty Block</b>
CC:			

The field review included the inspection of the following items included in the detailed summary of works section of the *Cobble Hill Landfill — 2017 Minor Construction Works, Detailed Construction Plan (Sperling Hansen Associates, September 13, 2017)*:

- **PEA**
  - Liner appears to be in good condition, with no noticeable changes since the date of our last inspection
- **Leachate and Leak Detention facility**
  - Total leachate collected: = 5.59 m<sup>3</sup>
  - Total leachate stored = 52.53 m<sup>3</sup>
  - Total leachate transported = 0 m<sup>3</sup>
- **Soil Management Area (SMA)**
  - All works are in good condition and no noticeable changes since the date of our last inspection
- **Contact Water Containment Pond**
  - All works are in good condition and no noticeable changes since the date of our last inspection
- **cut-off ditch upland of PEA**
  - All works are in good condition, ditch still performing well.

ISLANDER ENGINEERING LTD.



Mike Achtem, P.Eng



<b>FIELD REVIEW REPORT</b>		DATE: <b>March 27, 2018</b>	ISLANDER PROJECT No.: <b>2087</b>
REPORT No: <b>17</b>	STAGE OF CONSTRUCTION: <b>Landfill Closure</b>	WEATHER: <b>Cloudy &amp; Rain</b>	PAGE: <b>2 of 3</b>



**SMA - looking south**



**SMA – looking north**



**Contact water containment Pond**



**Leak and leachate detection works**



<b>FIELD REVIEW REPORT</b>		DATE: <b>March 27 2018</b>	ISLANDER PROJECT No.: <b>2087</b>
REPORT No: <b>17</b>	STAGE OF CONSTRUCTION: <b>Landfill Closure</b>	WEATHER: <b>Cloudy &amp; Rain</b>	PAGE: <b>3 of 3</b>



**PEA – liner near NE corner**



**PEA– NW corner**



**Cut-off ditch upland of PEA**



**PEA north face**



ISLANDER  
ENGINEERING