

From: SPOMO1701@outlook.com
Sent: Thursday, May 31, 2018 8:39 PM
To: Environmental Compliance ENV:EX; marty@chholdings.ca
Subject: SPO MO1701-Status Update May 30, 2018
Attachments: May 30, 2018 CHH Progress Report.pdf

- ***Please find information regarding the Leachate reporting requirements for the May 30, 2018 reporting period as per SPILL PREVENTION ORDER : MO1701 Section 1d***

Total Leachate Collected= 4.36 m³

Total Leachate Stored= 26.01 m³

Total Leachate Transported= 0 m³

- ***Sampling was conducted on May 30, 2018 as per Section 6biii of File 311372 August 11, 2017 letter. Laboratory results are pending.***

Sampling Summary:

1. *SHA-SW1*
2. *SHA-SW2 (No Flow)*
3. *MW6*
4. *MW3*
5. *MW2*
6. *SHA-LE-1*
7. *SHA-LD-1 (Dry Conditions)*
8. *SB-1*
9. *SB-2*
10. *SB-3 (Dry Conditions)*

- ***Attached is the QP Progress Report for May 30, 2018 as per File 311372 August 11, 2017 letter.***

Thank you



FIELD REVIEW REPORT		DATE: May 30 2018	ISLANDER PROJECT No.: 2087
REPORT No: 21	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Cloud/Sunny	1 of 3 PAGE:
PROJECT: Cobble Hill Landfill 2017 Minor Construction Works			
TO: CHH	ATTENTION: Marty Block		
CC:			

The field review included the inspection of the following items included in the detailed summary of works section of the *Cobble Hill Landfill — 2017 Minor Construction Works, Detailed Construction Plan (Sperling Hansen Associates, September 13, 2017)*

- **PEA**
 - Liner appears to be in good condition, and no noticeable changes since the date of our last inspection
- **Leachate and Leak Detention facility**
 - Total leachate collected: = **4.36 m³**
 - Total leachate stored = **26.01 m³**
 - Total leachate transported = **0 m³**
- **Soil Management Area (SMA)**
 - All works are in good condition and no noticeable changes since the date of our last inspection
- **Contact Water Containment Pond**
 - All works are in good condition and no noticeable changes since the date of our last inspection
- **cut-off ditch upland of PEA**
 - All works are in good condition, ditch still performing well.

ISLANDER ENGINEERING LTD.



Mike Achtem, P.Eng



FIELD REVIEW REPORT		DATE: May 30 2018	ISLANDER PROJECT No.: 2087
REPORT No: 21	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Cloudy/Sun	PAGE: 2 of 3



SMA - looking south



SMA – looking north



Contact water containment Pond



Pipe trenching and Leachate and Leak Detention facility



ISLANDER
ENGINEERING

FIELD REVIEW REPORT		DATE: May 30 2018	ISLANDER PROJECT No.: 2087
REPORT No: 21	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Cloudy/Sun	PAGE: 3 of 3



PEA – liner near NE corner



PEA– NW corner



PEA ditch



PEA north face