

From: spomo1701@outlook.com
To: [Environmental Compliance ENV:EX; marty@chholdings.ca](#)
Subject: SPO MO1701 20180228 Status Update
Date: Wednesday, February 28, 2018 11:13:54 PM
Attachments: [Feb 28, 2018 CHH Progress Report.pdf](#)

- ***Please find information regarding the Leachate reporting requirements for the Feb 28, 2018 reporting period as per SPILL PREVENTION ORDER : MO1701 Section 1d***

Total Leachate Collected= 8.03 m³

Total Leachate Stored= 37.50 m³

Total Leachate Transported= 0 m³

- ***Sampling was conducted on Feb 27, 2018 as per Section 6biii of File 311372 August 11, 2017 letter. Laboratory Results are pending.***

Sampling Summary:

1. *SHA-SW1*
2. *SHA-SW2 (No Flow)*
3. *MW6*
4. *MW3*
5. *MW2*
6. *SHA-LE-1*
7. *SHA-LD-1 (Dry Conditions)*
8. *SB-1*
9. *SB-2*
10. *SB-3*

- ***Attached is the QP Progress Report for Feb 28, 2018 as per File 311372 August 11, 2017 letter.***

Thank you



FIELD REVIEW REPORT		DATE: February 28 2018	ISLANDER PROJECT No.: 2087
REPORT No: 15	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Cloudy 1 deg	PAGE: 1 of 3
PROJECT: Cobble Hill Landfill 2017 Minor Construction Works			
TO: CHH	ATTENTION: Marty Block		
CC:			

The field review included the inspection of the following items included in the detailed summary of works section of the *Cobble Hill Landfill — 2017 Minor Construction Works, Detailed Construction Plan (Sperling Hansen Associates, September 13, 2017)*:

- **PEA**
 - Liner appears to be in good condition, with no noticeable changes since the date of our last inspection
- **Leachate and Leak Detention facility**
 - Total leachate collected: = **8.03 m³**
 - Total leachate stored = **37.5 m³**
 - Total leachate transported = **0 m³**
- **Soil Management Area (SMA)**
 - All works are in good condition and no noticeable changes since the date of our last inspection
- **Contact Water Containment Pond**
 - All works are in good condition and no noticeable changes since the date of our last inspection
- **cut-off ditch upland of PEA**
 - All works are in good condition, ditch still performing well.

ISLANDER ENGINEERING LTD.



Mike Achtem, P.Eng



ISLANDER
ENGINEERING

FIELD REVIEW REPORT		DATE: Feb 28 2018	ISLANDER PROJECT No.: 2087
REPORT No: 15	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Cloudy 1 deg	PAGE: 2 of 3



SMA - looking south



SMA – looking north



Contact water containment Pond



Leak and leachate detection works



FIELD REVIEW REPORT		DATE: Feb 28 2018	ISLANDER PROJECT No.: 2087
REPORT No: 15	STAGE OF CONSTRUCTION: Landfill Closure	WEATHER: Cloudy 1 deg	PAGE: 3 of 3



PEA – liner near NE corner



PEA– NW corner



Cut-off ditch upland of PEA



PEA north face