

Weekly Summary of Reportable Incidents

Sharing safety with the mining industry



- 1. Surface Blasting: Unauthorized entrance onto loaded blast pattern.
- 2. Surface Slope Failure/Unstable Face: A bench-scale slough of a high wall slope occurred.
- 3. Underground Falling Objects: A wireline pulley on a diamond drill fell and contacted a worker.
- 4. Surface Mobile Equipment Unexpected Movement: Dozer tracks were delivered on a truck and trailer. A forklift lifted the dozer tracks off the trailer and the truck began rolling forward. The truck operator was able to secure the vehicle.
- 5. Surface Mobile Equipment Collision: After being loaded by the shovel, a haul truck turned right and contacted a rubber-tired dozer in its blind spot.
- 6. Surface Maintenance: A worker was using a torque wrench to free bolts when the bolt shifted and cut through their glove and cut their wrist.
- Surface Mobile Equipment Rollover: A water truck tipped over mine rescue was called to remove the operator.
- **8.** Surface Mobile Equipment Collision: A haul truck pulled into a stockpile area and made a right-hand turn to park when it contacted another haul truck on its blind side.

Comments: Ensure blast areas are blocked to prevent inadvertent access. This includes posting signs to make people aware of blasting activities, and ensuring they stay a safe distance from any related hazards.