



# Weekly Summary of Reportable Incidents

*Sharing safety with the mining industry*



Mine Incident Reporting Line

**1-888-348-0299**

Email: [MineIncidents@gov.bc.ca](mailto:MineIncidents@gov.bc.ca)

**Reportable Incidents**

**11**

## Incidents Reported October 6<sup>th</sup> to October 12<sup>th</sup>, 2025

1. **Surface Blasting:** A dozer breached a miss hole barricade. The breach was discovered the next morning, and the barricade was re-established.
2. **Surface Mobile Equipment Out of Control:** A loaded haul truck travelling at 10 to 12 km/hr drifted across the road and contacted a pile of material.
3. **Surface Mobile Equipment Rollover:** A dozer rolled twice while side-cutting on a steep slope. The operator who was wearing their seatbelt, exited the cab independently and sustained a minor cut to their hand and a contusion to their lower leg.
4. **Surface Operations:** While cutting a rock sample, an operator's hand was pulled into a rotating saw blade, cutting through two pairs of gloves and injuring a finger.
5. **Surface Mobile Equipment Autonomous:** An empty autonomous haul truck slipped into the loaded lane. Steering calibration was performed, and the area was graded.
6. **Surface Mobile Equipment Autonomous Fire:** A tire fire occurred on an autonomous haul truck enroute to the dump. Mine Rescue responded and extinguished the fire.
7. **Surface Mobile Equipment Fire:** Smoke and the smell of burning material were observed from a parked service truck. A small fire under the hood was extinguished with a 20 lb extinguisher.
8. **Surface Mobile Equipment:** A 25 cm rock penetrated an excavator cab through the lower window, striking the operator's knee and causing bruising.
9. **Surface Mobile Equipment Collision:** Two light vehicles made contact after one lost traction and slid backward. The rear passenger door and taillight were damaged.
10. **Surface Explosives:** After completing loading of a blast hole, a mobile mixing unit (MMU) operator and helper repositioned a carry box containing boosters and detonators two rows over. While manoeuvring the MMU toward the box, a tire contacted and damaged the carry box.
11. **Surface Operations:** During hoist rope replacement on a shovel, one worker attempted to free a bottle with a pry bar while another prepared to use a sledgehammer. As the sledgehammer was being swung, the pry bar slipped and struck the worker in the face, resulting in a 2.5 cm laceration to their cheek requiring stitches.

**Comments: Control fall hazards. Plan ahead and use proper fall protection.**