



Weekly Summary of Reportable Incidents

Sharing safety with the mining industry



Mine Incident Reporting Line

1-888-348-0299

Email: MineIncidents@gov.bc.ca

Reportable Incidents

14

Incidents Reported October 27th to November 2nd, 2025

- 1. Surface Geotechnical Fall of Ground:** Personnel in a parked truck heard rockfall and attempted to exit the area. A rock struck the passenger-side rear door of the vehicle, causing damage to the vehicle.
- 2. Surface Mobile Equipment Unexpected Movement:** A transport truck rolled approximately 30 metres and contacted stationary tires, resulting in damage to the truck's front bumper.
- 3. Underground Mobile Equipment Collision:** Tow equipment failed while a scoop was pulling a drill, resulting in a collision with a light vehicle.
- 4. Surface Mobile Equipment Collision:** A loader reversed into a guy wire, causing a power pole to shake and damage an insulator, resulting in power loss across multiple sites.
- 5. Surface Environmental Other:** A mine reported a drill sump overflow. The site was contained and sediment removed.
- 6. Surface Mobile Equipment Collision:** An articulated truck reversed into an unattended excavator, pushing it approximately 2.5 metres.
- 7. Surface Electrical Arc Flash:** An arc flash occurred during welding machine setup. The welder experienced eye symptoms and was transported for medical aid.
- 8. Surface Mobile Equipment Out of Control:** An empty autonomous haul truck travelling at approximately 45 KM/H spun approximately 100 degrees and came to a stop in the oncoming lane.
- 9. Surface Mobile Equipment Out of Control:** An empty autonomous haul truck travelling at approximately 21 KM/H spun approximately 110 degrees and came to a stop in its own lane.
- 10. Surface Mobile Equipment Fire:** An autonomous haul truck's grid box caught fire. Mine rescue responded and extinguished the fire.
- 11. Surface Geotechnical Slope Failure:** A light vehicle with four occupants became stuck when part of the road collapsed near a dig face. Mine rescue responded and rescued the individuals.
- 12. Surface Mobile Equipment Unexpected Movement:** A loaded haul truck's tire blew after leaving a shovel, causing it to tip back and lift the front approximately 3 metres. Mine rescue responded and rescued the operator.
- 13. Surface Mobile Equipment Other:** A dozer operator fell while climbing onto the cab. Mine rescue attended, and the operator was assessed for hand and wrist injuries.
- 14. Surface Mobile Equipment Other:** A haul truck contacted a power cable under an arch, causing power loss to a drill.

Comments: The transition to winter, and winter driving conditions is underway. Ensure vehicles are prepared, and operators are aware of changing conditions. Review the [CCOHS page](#) on Winter Driving for more information.