



# Weekly Summary of Reportable Incidents

*Sharing safety with the mining industry*



Mine Incident Reporting Line

**1-888-348-0299**

Email: [MineIncidents@gov.bc.ca](mailto:MineIncidents@gov.bc.ca)

**Reportable Incidents**

**19**

## Incidents Reported February 16<sup>th</sup> to 22<sup>nd</sup>, 2026

1. **Surface Blasting Explosives:** A dozer pushing materials came within one metre of a loaded blast hole.
2. **Surface Mobile Equipment:** An autonomous haul truck spun out on the ramp and slid backwards.
3. **Underground Ventilation:** The generator unexpectedly shutoff causing a loss of underground ventilation. Workers were brought to the surface.
4. **Surface Maintenance:** A pipe clamp fell 24 feet, landing near workers working below. No injuries were reported.
5. **Surface Electrical:** A long-reach excavator was clearing a settling pond when it contacted the ground cable of the overhead powerlines. No injuries were reported.
6. **Surface Mobile Equipment Fire:** A fire started in the cab of a sewage truck. The fire was immediately extinguished.
7. **Surface Maintenance Lockout/tag out:** While working, contractors discovered that an improper lockout location was used.
8. **Surface Maintenance Fire:** A spark caused the flashback arrestor on an acetylene tank to activate. The fire was extinguished, and the tank valve was closed.
9. **Surface Autonomous Mobile Equipment:** An autonomous haul truck experienced a lane departure; no damage or injuries reported.
10. **Surface Slip and Fall:** A worker tripped on a wheel chock and injured their arm, resulting in a possible fracture.
11. **Surface Fire:** Carbon monoxide levels increased due to a smouldering grease fire near a conveyor. The fire was extinguished by mine rescue.
12. **Surface Mobile Equipment Collision:** While attempting to pass another haul truck, the haul truck's right side of the box contacted the left rear of the other, causing minor damage, but no injuries.
13. **Surface Mobile Equipment:** A haul truck lost traction and spun in its lane, contacting the berm before stopping.

- 14. Surface Mobile Equipment Fire:** A haul truck lost its retarder, requiring the use of service brakes. The heat from the service brakes caused the wheel covers to catch fire, which were extinguished with a handheld extinguisher.
- 15. Surface Maintenance:** A welder burned their left wrist while using a torch, resulting in 2<sup>nd</sup> degree burns.
- 16. Surface Mobile Equipment Fire:** The hoist line on a haul truck ruptured, spraying hydraulic oil on the exhaust blanket, causing a fire. The fire was extinguished:
- 17. Surface Mobile Equipment Electrical:** While turning around, a loader contacted and sheared off a power pole. The power pole was deenergized due to an unrelated shutdown. No injuries were reported.
- 18. Surface Mobile Equipment:** While loading, a rock from the shovel fell and hit the side mirror of a haul truck, resulting in the rock hitting the side window, entering the cab and striking and cracking the windshield from the inside. No injuries were reported.
- 19. Surface Autonomous Mobile Equipment:** While being escorted, a contractor did not have the appropriate levels of control while driving in an autonomous haulage zone.

**Comments: Ensure contractors are trained and familiar with applicable lockout and tagout procedures. Always verify that the equipment is de-energized before starting work. Review the latest [Health and Safety Notice](#) regarding lockout and captive key systems.**