

SC-8314
SC-8314

TEXADA ISLAND 0.55km

2025 Inspection

CBR iPad Offline Ver 0.36B



CBR Data

Latitude 49°38'37.6" Longitude -124°26'17"

Site Status Active

Insp. Status Inspect

Crossing Name Mouat Creek

FSR # 5829 Branch # 1

Road Name TEXADA ISLAND

User km 0.55

Previous Load Rating (tonnes) 136

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Composite

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 16.5

Deck Width (m) 4.88

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5526320.1 Accuracy (m)

Inspection

Date of Inspection 2025-07-29 9:50:40 AM

Inspector Name Richard Mills

Inspector Comments Serial/ID Plate

Recommended Next Inspection 2028

Inspection Company MoF

P.Eng Comments

Ministry of Forests Reviewing Engineer: Richard Mills P.Eng.
Review Date: Feb 6, 2026
Load Rating: L150 or 136 tonnes
Recommended Next Inspection: 2028

PERMIT TO
PRACTICE: 1003022

SC-8314
SC-8314

TEXADA ISLAND 0.55km

2025 Inspection

CBR iPad Offline Ver 0.36B



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Good**

Posted Load Rating

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete **Good**

Caps or Sills **Good**

Piles or Posts **Good**

Ballast Wall **Good**

Wing Wall

Bracing **Good**

Hardware **Good**

Fill **Good**

Riprap **Good**

Bearings **Good**

Corrosion Protection **Good**

SC-8314
SC-8314

TEXADA ISLAND 0.55km

2025 Inspection

CBR iPad Offline Ver 0.36B



Deck

Running Surface **Good**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck **Good**

Grout Pockets **Good**

Deck Joints **Good**

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts **Good**

Hand Rails/Walkouts

Hardware **Good**

Overall Deck Condition **Good**

Gravel Depth (mm)

Pier Deck

SC-8314
SC-8314

TEXADA ISLAND 0.55km

2025 Inspection

CBR iPad Offline Ver 0.36B



Steel/Concrete

Girders Fair

Rust scale at deck joints. Mainly confined to upper flange.

Diaphragms Good

Bracing N/A

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8314
SC-8314

TEXADA ISLAND 0.55km

2025 Inspection

CBR iPad Offline Ver 0.36B



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0.5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	2.5	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
1	Monitor girder corrosion	Routine Inspection

2

3



Approach from Left Bank when facing downstream



Deck



Approach from Right Bank when facing downstream



Downstream Profile



Upstream Profile



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream