

SC-8626
SC-8626

SECHELT ROBERTS 0.42km

2025 Inspection

CBR iPad Offline Ver 0.36B



CBR Data

Latitude 49°26'49.3" Longitude -123°34'41.1"

Site Status Active

Insp. Status Inspect

Crossing Name Unnamed

FSR # 7575 Branch # 27

Road Name SECHELT ROBERTS

User km 0.42

Previous Load Rating (tonnes) 0

Structure Class Temporary Bridge

Portable N

Superstructure Log Stringers

Deck Type Gravel

Abutment Left Crib, Log or Untreated Timber

Abutment Right Crib, Log or Untreated Timber

Spans 1

Total Length (m) 7.9

Deck Width (m) 5.1

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5504418.0 Accuracy (m)

Inspection

Date of Inspection 2025-07-22 9:44:46 AM

Inspector Name Richard Mills

Inspector Comments
Inaccessible

Serial/ID Plate

Recommended Next Inspection 2026

Inspection Company MoF

P.Eng Comments

Ministry of Forests Reviewing Engineer: Richard Mills P.Eng.
Review Date: Jan 26, 2026
Load Rating: 0 tonnes
Recommended Next Inspection: 2026
Comments: Ensure access is blocked and remove bridge.

PERMIT TO
PRACTICE: 1003022

SC-8626
SC-8626

SECHELT ROBERTS 0.42km

2025 Inspection

CBR iPad Offline Ver 0.36B



Approach

Alignment

Bridge Ahead Signs
Missing ☐ 0 ☐ 1 ☐ 2

Brushing Required

Delineator Missing
Left ☐ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☐ 2

Fender Condition

Posted Load Rating

Road Surface

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill

Riprap

Bearings

Corrosion Protection

SC-8626
SC-8626

SECHELT ROBERTS 0.42km

2025 Inspection

CBR iPad Offline Ver 0.36B



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Overall Deck Condition

Gravel Depth (mm)

Pier Deck

SC-8626
SC-8626

SECHELT ROBERTS 0.42km

2025 Inspection

CBR iPad Offline Ver 0.36B



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8626
SC-8626

SECHELT ROBERTS 0.42km

2025 Inspection

CBR iPad Offline Ver 0.36B



Hazards

Estimated Present Water Level Depth (m)

High Water ☐

Debris ☐

Estimated Present Water Level Width (m)

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance

Ic ☐

Comments

Repairs and Monitoring

Repair Item

Repair Description

1

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3



2025 Inspection

CBR iPad Offline Ver 0.36B

SECHELT ROBERTS 0.42km

SC-8626
SC-8626



Approach from Right Bank when facing downstream