

SC-8638
SC-8638

SECHELT ROBERTS 0.85km

2025 Inspection

CBR iPad Offline Ver 0.36B



CBR Data

Latitude 49°26'3.5"
Longitude -123°32'15.5"

Site Status Active

Insp. Status Inspect

Crossing Name Unnamed

FSR # 7575 Branch # 23

Road Name SECHELT ROBERTS

User km 0.85

Previous Load
Rating (tonnes) 5

Structure Class Temporary Bridge

Portable N

Superstructure Log Stringers

Deck Type Gravel

Abutment Left Crib, Log or Untreated Timber

Abutment Right Crib, Log or Untreated Timber

Spans 1

Total Length (m) 8

Deck Width (m) 7.5

Updated Data

Latitude °0'0"
Longitude °0'0"

HD Diff. (m) 5503001.8 Accuracy (m)

Inspection

Date of Inspection 2025-07-22 9:18:07 AM

Inspector Name Richard Mills

Recommended Next Inspection 2026

Inspection Company MoF

Inspector Comments
Serial/ID Plate

Conk in stringers 3,7,10. Tight lashing at centre. 40mm sap rot average. 5 tonnes posted. Estimated closure 3 years.

P.Eng Comments

Ministry of Forests Reviewing Engineer: Richard Mills P.Eng.
Review Date: Jan 26, 2026
Load Rating: 5 tonnes
Recommended Next Inspection: 2026

PERMIT TO
PRACTICE: 1003022

SC-8638
SC-8638

SECHELT ROBERTS 0.85km

2025 Inspection

CBR iPad Offline Ver 0.36B



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Good**

Posted Load Rating **5** **5 tonnes**

Road Surface **Good**

Abutment

Log/Timber Crib **N/A**

Tie Backs

Bin Wall

Pier

Concrete

Caps or Sills **Poor** **Sap rot**

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware

Fill **Good**

Riprap **Fair**

Bearings

Corrosion Protection

SC-8638
SC-8638

SECHELT ROBERTS 0.85km

2025 Inspection

CBR iPad Offline Ver 0.36B



Deck

Running Surface **Fair**

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface **Fair** 600mm

Curb Rail/Blocks/Posts

Hand Rails/Walkouts

Hardware

Overall Deck Condition **Fair**

Gravel Depth (mm)

Pier Deck

SC-8638
SC-8638

SECHELT ROBERTS 0.85km

2025 Inspection

CBR iPad Offline Ver 0.36B



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8638
SC-8638

SECHELT ROBERTS 0.85km

2025 Inspection

CBR iPad Offline Ver 0.36B



Hazards

Estimated Present Water Level Depth (m)	0	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	0	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	1.8	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3



2025 Inspection

CBR iPad Offline Ver 0.36B

SECHELT ROBERTS 0.85km

SC-8638
SC-8638



Approach from Right Bank when facing downstream



Bearing