

SC-8639
SC-8639

SECHELT ROBERTS 1.06km

2025 Inspection

CBR iPad Offline Ver 0.36B



CBR Data

Latitude

49°26'6"

Longitude

-123°32'6.7"

Site Status Active

Insp. Status Inspect

Crossing Name Unnamed

FSR # 7575

Branch # 23

Road Name SECHELT ROBERTS

User km 1.06

Previous Load
Rating (tonnes) 5

Structure Class Temporary Bridge

Portable N

Superstructure Log Stringers

Deck Type Gravel

Abutment Left Crib, Log or Untreated Timber

Abutment Right Crib, Log or Untreated Timber

Spans 1

Total Length (m) 7.6

Deck Width (m) 6.5

Updated Data

Latitude

°0'0"

Longitude

°0'0"

HD Diff. (m)

5503079.0

Accuracy (m)

Inspection

Date of Inspection 2025-07-22 9:09:36 AM

Inspector Name Richard Mills

Recommended Next Inspection 2026

Inspection Company MoF

Inspector Comments Serial/ID Plate

No apparently change since past inspection. Stringers 3,5,8,9 have konk, est 100mm sap rot. Lashing tight. Established closure date 3 years.

P.Eng Comments

Ministry of Forests Reviewing Engineer: Richard Mills P.Eng.
Review Date: Jan 26, 2026
Load Rating: 5 tonnes
Recommended Next Inspection: 2026

PERMIT TO
PRACTICE: 1003022

SC-8639
SC-8639

SECHELT ROBERTS 1.06km

2025 Inspection

CBR iPad Offline Ver 0.36B



Approach

Alignment Fair

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required Y

Delineator Missing
Left ☐ 0 ☐ 1 ☒ 2

Delineator Missing
Right ☐ 0 ☐ 1 ☒ 2

Fender Condition Fair

Posted Load Rating

Road Surface Fair

Abutment

Log/Timber Cribs Poor Conk

Tie Backs Poor Conk

Bin Wall

Pier

Concrete

Caps or Sills

Piles or Posts

Ballast Wall

Wing Wall

Bracing

Hardware Good Lashing tight

Fill Good

Riprap Fair Steep

Bearings

Corrosion Protection

SC-8639
SC-8639

SECHELT ROBERTS 1.06km

2025 Inspection

CBR iPad Offline Ver 0.36B



Deck

Running Surface

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck

Grout Pockets

Deck Joints

Steel Deck Plate

Gravel Surface **Fair**

Curb Rail/Blocks/Posts **Fair**

Hand Rails/Walkouts

Hardware **Fair**

Overall Deck Condition **Fair**

Gravel Depth (mm)

Pier Deck

SC-8639
SC-8639

SECHELT ROBERTS 1.06km

2025 Inspection

CBR iPad Offline Ver 0.36B



Steel/Concrete

Girders

Diaphragms

Bracing

Under Trussing

Hardware

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)

Needle Diameter (mm)

Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment
--------------------	---------	--------	------------------	-------------------	-----------	---------

SC-8639
SC-8639

SECHELT ROBERTS 1.06km

2025 Inspection

CBR iPad Offline Ver 0.36B



Hazards

Estimated Present Water Level Depth (m)	0.1	High Water	☐	Debris	☐
Estimated Present Water Level Width (m)	1.5	Aggradation	☐	Scour	☐
Estimated High Water Level Clearance	1.8	Ice	☐		

Comments

Repairs and Monitoring

Repair Item	Repair Description
-------------	--------------------

1

2

3

4

5

6

7

Item	Monitor Description	Frequency
------	---------------------	-----------

1

2

3



Approach from Right Bank when facing downstream



Stringers



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream