

SC-8662
SC-8662

RAINY RIVER 0.66km

2025 Inspection

CBR iPad Offline Ver 0.36B



CBR Data

Latitude 49°35'8.7" Longitude -123°30'47.5"

Site Status Active

Insp. Status Inspect

Crossing Name Unnamed

FSR # 7590 Branch # 2

Road Name RAINY RIVER

User km 0.66

Previous Load Rating (tonnes) 150

Structure Class Permanent Bridge

Portable N

Superstructure Steel I-beam

Deck Type Concrete Composite

Abutment Left Steel Pipe and Precast Pad

Abutment Right Steel Pipe and Precast Pad

Spans 1

Total Length (m) 30.5

Deck Width (m) 4.88

Updated Data

Latitude °0'0" Longitude °0'0"

HD Diff. (m) 5519860.4 Accuracy (m)

Inspection

Date of Inspection 2025-07-21 1:46:42 PM

Inspector Name Richard Mills

Inspector Comments Serial/ID Plate

Recommended Next Inspection 2028

Inspection Company MoF

P.Eng Comments

Ministry of Forests Reviewing Engineer: Richard Mills P.Eng.
Review Date: Jan 26, 2026
Load Rating: L165 or 150 tonnes
Recommended Next Inspection: 2028
Comments: Remove rubber matting from deck.

PERMIT TO
PRACTICE: 1003022

SC-8662
SC-8662

RAINY RIVER 0.66km

2025 Inspection

CBR iPad Offline Ver 0.36B



Approach

Alignment **Good**

Bridge Ahead Signs
Missing ☒ 0 ☐ 1 ☐ 2

Brushing Required **N**

Delineator Missing
Left ☒ 0 ☐ 1 ☐ 2

Delineator Missing
Right ☒ 0 ☐ 1 ☐ 2

Fender Condition **Good**

Posted Load Rating

Road Surface **Good**

Abutment

Log/Timber Cribs

Tie Backs

Bin Wall

Pier

Concrete **Good**

Caps or Sills **Good**

Piles or Posts **Good**

Ballast Wall **Good**

Wing Wall

Bracing **Good**

Hardware **Good**

Fill **Good**

Riprap **Good**

Bearings **Good**

Corrosion Protection **Good**

SC-8662
SC-8662

RAINY RIVER 0.66km

2025 Inspection

CBR iPad Offline Ver 0.36B



Deck

Running Surface Fair

Running Planks

Sub Deck

Ties

Nails

Deck to Girder Bolts

Concrete Deck Good

Grout Pockets Good

Deck Joints Good

Steel Deck Plate

Gravel Surface

Curb Rail/Blocks/Posts Good

Hand Rails/Walkouts

Hardware Good

Overall Deck Condition Good

Gravel Depth (mm)

Pier Deck

SC-8662
SC-8662

RAINY RIVER 0.66km

2025 Inspection

CBR iPad Offline Ver 0.36B



Steel/Concrete

Girders Good

Diaphragms Good

Bracing Good

Under Trussing

Hardware Good Splice ok

Welded/grouted
shear connectors

Log

Log Curbs

Needle Beam

Needle Lashing/
Shimming

Needle Beam to Crib (m)			Needle Diameter (mm)			
Stringer Number	Species	Peeled	Diameter (mm)	Rot Depth (mm)	Condition	Comment

SC-8662
SC-8662

RAINY RIVER 0.66km

2025 Inspection

CBR iPad Offline Ver 0.36B



Hazards

Estimated Present Water Level Depth (m) 0.4

High Water ☐

Debris ☐

Estimated Present Water Level Width (m) 5

Aggradation ☐

Scour ☐

Estimated High Water Level Clearance 5

Ic ☐

Comments

Repairs and Monitoring

Repair Item

Repair Description

1 Structure. Clean Deck. # of Rubber matting should be removed from deck
delineators. Priority:Low

2

3

4

5

6

7

Item

Monitor Description

Frequency

1

2

3



Approach from Right Bank when facing downstream



Deck



Approach from Left Bank when facing downstream



Upstream Profile



Left Bank Abutment when facing downstream



Right Bank Abutment when facing downstream