# Pro D·I·G·I·T·A·L

This is a reference guide for operating the ProDIGITAL line of handhelds. Refer to the User Manual for more information.

Micro USB port

Battery indicator

Press the **Probe** key to setup sensors and select displayed units

Press the **Cal** key to calibrate attached sensors

Press the **System** key to setup the handheld and adjust logging settings

Press the **File** key to access logged data

System   Probe   Calibration   File

Esc

Press the **Esc** key to return to the Run screen or to exit an alpha/numeric entry screen

Toggle **Backlight**

ENTER

Press the **Enter** key to activate the selection

Use the **left arrow** key to go back one screen

Use the **right arrow** key to toggle graph view on the Run screen

Activate **Help** Menu

Press the **Power** key to turn on the instrument. Press and hold for 1.5 seconds to turn the instrument off

Use the **up** and **down arrow** keys to highlight a desired menu option

Military spec, twist-lock **cable connector**

YSI.com

Setting Up

Charge the battery by connecting the handheld to an AC power supply or USB connector using the micro USB cable. Ensure all components are dry when charging. A full charge takes approximately 9 hours.

Make sure the **date/time** is correct and set the **logging mode** (Single or Continuous).

Setup sensor parameters and select **units displayed** on the Run and Data View screens.

Calibrate sensors prior to taking measurements; sensor-specific calibration instructions can be found in the User Manual.

Taking Measurements

Insert the probe into the sample and briefly move it up and down to release any air bubbles. Allow measurements to stabilize and press the Enter key to **log data**. To stop Continuous logging, simply press the Enter key again.

Data Management

Press the File key to **view**, **delete**, or **backup** logged data. Data can be filtered by date/time and by the user-created Site and/or Data ID.

Transfer data to your PC using **KorDSS Software**. Make sure the instrument driver and software are installed from the included USB flash drive or from **YSI.com**.

1. Open KorDSS Software.

2. Use the micro USB cable to connect the handheld to the PC.

3. Power on the handheld; there may be a short delay before it shows up in the software.

4. Select the handheld under the **Instrument Connection Panel** and click Connect.

5. Click **Start Download from Device**.

6. After data download, click **View Logged Data** to view, print, and export data files from KorDSS.

YSI

a **xylem** brand

1725 Brannum Lane
Yellow Springs, OH 45387
(800) 765-4974, (937) 767-7241
info@ysi.com