

Overall Rating - High



This notification is intended as an informational bulletin for technical audiences.

Summary

The Vulnerability and Risk Management (VRM) Team is aware HPE published a security advisory to address a vulnerability in the following products:

- HPE Integrated Lights-Out 5 (iLO 5) for HPE Gen10 Servers – firmware version 2.63 to versions prior to 3.0
- HPE Integrated Lights-Out 6 (iLO 6) – firmware version 1.05 to versions prior to 1.55

Technical Details

A potential security vulnerability has been identified in HPE Integrated Lights-Out 5 (iLO 5) and Integrated Lights-Out 6 (iLO 6). The vulnerability could be remotely exploited to allow authentication bypass.

These vulnerabilities are rated as an overall **High** Severity.

Recommended Action

- Investigate how your area of responsibility is affected.
- Notify business owner(s) as required.
- *Ensure mitigation is performed at your next change window.*

Please notify [VRM](#) with any questions or concerns you may have.

References

- CVE-2023-50272, CVE-2023-41914, CVE-2023-49933, CVE-2023-49934, CVE-2023-49935, CVE-2023-49936, CVE-2023-49937, CVE-2023-49938
- [HPE Security Bulletin - hpesbnw04584en_us](#)
- [HPE Security Bulletins](#)