

Ministry of Energy, Mines and Low Carbon Innovation

Weekly Summary of Dangerous Occurrences

Sharing safety with the mining industry



Dangerous Occurrences Reported for the Week of May 23 to 29, 2022

#1: Surface Mobile Equipment: A rubber tire dozer got too close to a shovel during cleanup. While swinging, the counterweight of the shovel contacted and damaged the fender of the rubber tire dozer.

#2: Surface Mobile Equipment: After an excavator completed stripping organic material off a bluff, it began to descend. While descending, the operator started to slide on sheer rock. The machine's track caught soft material and tipped over. No injuries were reported.

#3: Surface Drilling: A drill head assembly guide-roller fell from partway up the mast and fell to the deck during operation. The operator was in the cab, and no injuries were reported.

#4: Underground Geotechnical: A fall of ground occurred in an access drift – approximately 10 to 15 tons of material fell. A remote scoop was in the area; however, the operator was not near the failure.

Comments:

Ensure equipment operators are trained on the machines required to complete assigned tasks.; this includes the machine's capabilities and limits.