

## **Weekly Summary of Dangerous Occurrences**

Sharing safety with the mining industry



Mine Incident Reporting Line 1-888-348-0299

Email: MineIncidents@gov.bc.ca

Dangerous Occurrences
5

## Dangerous Occurrences Reported for the Week of September 5<sup>th</sup> to 11<sup>th</sup>.

- 1. Surface Mobile Equipment: The operator of an explosives truck was travelling loaded. The operator missed a gear, and the brakes were unresponsive. The machine left the road and rolled. Mine rescue completed the extraction. Injuries were noted.
- **2. Underground Ventilation:** An unplanned power outage caused a stoppage of ventilation. No injuries were reported.
- **3. Surface Mobile Equipment:** The operator had parked the machine when they noticed flames from the haul truck's rear tires. Mine rescue was dispatched to extinguish the fire. No injuries were reported.
- **4. Surface Mobile Equipment**: A loaded haul truck was travelling down switchbacks when the machine rolled. The operator was extracted by mine rescue and was transported to the hospital.
- **5. Underground Ventilation:** The power system was overloaded causing loss of power to the site and shutting down the main ventilation fan. No injuries were reported.

**Comments:** Ensure pre-operation vehicle inspections are completed, with results noted in the dedicated log book for that vehicle.