

Ministry of Energy, Mines and Low Carbon Innovation

Weekly Summary of Reportable Incidents

Sharing safety with the mining industry



- 1. Undergorund Operations: During a tube retrieval the quick coupler failed on the water line of a diamond drill striking the driller helper in the forehead. The worker was sent to medical aid for a concussion assessment.
- 2. Surface Operations: A grader operator was observed to be in distress and was sent to medical aid.
- 3. Surface Falling Objects: Process slurry material fell 20 feet to the mill floor from a broken SAG mill discharge line.
- 4. Surface Mobile Equipment Roll Over: A dozer was removing snow from a construction panel when it rolled onto its side.

Comments:

On November 30, 2022, changes to Code requirements for Notification of Reportable Incidents came into effect:

- 1.7.2 (1)(c) within 60 days of a reportable incident, or within any longer time that may be specified by the chief inspector, submit the investigation report required under section 1.7.4 (2) to the chief inspector.
- 1.7.2(2) The manager must engage with First Nations that may be affected by reportable incidents to determine which reportable incidents must be reported to the First Nations.

Health, Safety and Reclamation Code for Mines in British Columbia - Province of British Columbia (gov.bc.ca)