

Ministry of Energy, Mines and Low Carbon Innovation

## Weekly Summary of Reportable Incidents

Sharing safety with the mining industry



- 1. Surface Electrical An arc flash/blast event occurred in a panel when an operator attempted to start a piece of equipment from the field.
- 2. Surface Mobile Equipment A shovel operator noted a grid box fire on an unloaded autonomous haul truck driving towards their shovel's location. Mine rescue responded and extinguished the fire.
- 3. Surface Mobile Equipment While making a pass onto a pile of fine rock, the front tire of the scraper climbed the fine rock pile too high resulting in the scraper rolling slowly onto its side.
- 4. Surface Mobile Equipment An autonomous haul truck veered off course into an oncoming lane. One other autonomous haul truck was in the area but was not at risk of collision.
- Surface Fire A mill employee saw smoke coming from the Mill Dry Building and activated the mine's emergency notification procedure. Mine rescue responded and extinguished a fire found in the electrical room.
- 6. Surface Mobile Equipment While travelling onto a section of haul road that had been recently excavated approximately 2.5m lower, a loaded haul truck tipped over and came to rest on its side.

**Comments:** Reportable Incidnets related to surface mobile equipment remain high. Workers are reminded to be cognizant of changing conditions as the season transitions from winter to spring.