

Weekly Summary of Reported Incidents

Sharing safety with the mining industry



1. Surface Mobile Equipment Out of Control: A maintenance van travelling down a road, lost traction and slid into a snowbank. The vehicle was travelling approximately 10 km/hr upon impact.

- 2. Surface Mobile Equipment Collision: An articulating haul truck lost traction and slid out of control. The haul truck contacted a parked, empty pick-up truck and continued to slide before contacting the rear of a parked, occupied garbage truck.
- 3. Surface Explosives: While pushing material, a dozer exposed a live booster and primer.
- **4. Surface Operations:** A worker completed repairs on a tracked screener unit. While stepping down, the worker cut the inside of their knee on an exposed metal edge, resulting in a 4 cm laceration. First-aid was administered on site before the worker was brought to hospital for further assessment.
- 5. Surface Electrical: A machine operator contacted an overhead powerline, resulting in the line falling onto the machine. An electrician attended to de-energize the line before the operator and machine were moved away.
- **6.** Surface Mobile Equipment Rollover: A dozer was moving material for a shovel. While backing up, the dozer contacted a wall of material and rolled onto its side.
- **7. Surface Mobile Equipment Unexpected Movement:** The boom of a scoop started to lift unintentionally. The operator shut the machine down immediately.
- **8.** Surface Mobile Equipment Fire: A haul truck operator smelled smoke and discovered a fire behind the seat. The operator put on a glove and used a rag to smother the flame.
- 9. Surface Explosives: A booster was exposed by an excavator.

Comments: Machinery contact with overhead powerlines presents a significant risk to workers. Review the Hazard Alert on <u>"Contact with Overhead Powerlines</u>" for more information.