

Weekly Summary of Reportable Incidents

Sharing safety with the mining industry



Reportable Incidents

10

Incidents Reported July 28th to August 3rd, 2025

1. **Surface Operations:** An electrician noticed a pump operating without required ground fault protection, creating a risk of electric shock.
2. **Surface Mobile Equipment Collision:** While reversing during loading, an articulating dump truck contacted an excavator, resulting in damage to the excavator cage.
3. **Surface Environmental Wild Animal:** A worker encountered a grizzly bear with a cub – approximately 15 metres. After a bluff charge, the bears moved away from the area.
4. **Surface Mobile Equipment Unexpected Movement:** A rock truck box tipped over on the road while travelling to the crusher.
5. **Surface Mobile Equipment Unexpected Movement:** A tow-haul truck was towing another truck when it came loose, causing damaged to both units.
6. **Surface Working at Height Falling Object:** While performing drill services in the field, a helicopter dropped an empty fuel tank after it became disconnected.
7. **Surface Mobile Equipment Other:** While reversing with a spotter, a steam truck contacted the spotter.
8. **Surface Geotechnical Slope Failure:** A rockfall event in an open pit was reported.
9. **Surface Mobile Equipment:** A loaded haul truck tire blew, and two nearby workers received first aid for headache and ear ringing due to the loud noise.
10. **Surface Mobile Equipment Out of Control:** An autonomous haul truck travelling at 57 KM/H skidded approximately 55 metres and stopped in the oncoming lane.

Comment: Reversing equipment can pose significant risks to personnel working nearby. These risks can be managed by following safe reversing and spotting practices.

For more information on backing up safely visit [Canadian Centre for Occupational Health and Safety \(CCOHS\)](#).