



Ministry of
Mining and
Critical Minerals

Weekly Summary of Reportable Incidents

Sharing safety with the mining industry



Mine Incident Reporting Line

1-888-348-0299

Email: MineIncidents@gov.bc.ca

Reportable Incidents

14

Incidents Reported September 15th to 21st, 2025

1. **Surface Mobile Equipment Other:** A haul truck blew a #6 tire while departing a shovel; a nearby dozer was operating within 6- 7 metres.
2. **Surface Mobile Equipment Fire:** A haul truck's grid box caught fire while descending a ramp. The fire was extinguished by shutting off the master switch
3. **Surface Mobile Equipment Fire:** A loaded haul truck's #5 tire caught fire while in transit. Mine rescue responded and extinguished the fire
4. **Surface Mobile Equipment Autonomous:** An empty autonomous haul truck veered off course on a wet road and stopped in the opposite lane.
5. **Surface Chemical Exposure:** A worker was sprayed in the face, chest, and hands with gear oil while sampling, resulting in burns. The worker was taken to medical aid.
6. **Surface Mobile Equipment Collision Near Miss:** While escorting another vehicle, a light duty vehicle tried to pass a stopped haul truck which began turning left but braked upon seeing the light duty vehicle.
7. **Surface Mobile Equipment Fire:** An autonomous haul truck's #5 tire caught fire. Mine rescue extinguished the fire and established a fire watch perimeter.
8. **Surface Mobile Equipment Collision Near Miss:** A haul truck entered an intersection and crossed into the path of a light duty vehicle. The haul truck stopped, and the light duty vehicle maneuvered around it.
9. **Surface Electrical:** Workers cutting an I-beam with a torch contacted a 600V Teck cable causing it to melt.
10. **Surface Mobile Equipment Rollover:** A loaded haul truck tipped over while dumping material.
11. **Surface Mobile Equipment Rollover:** A tractor end dump trailer rolled over while unloading, causing the truck to rollover. The operator was extricated through the windshield with a broken collar bone.
12. **Surface Mobile Equipment Rollover:** An excavator tipped over a bench edge during a swing, rolling 90 degrees before the boom stopped a full rollover. The operator reported soreness and back pain.
13. **Surface Mobile Equipment Out of Control:** An empty haul truck lost traction downhill, slid into a windrow and spun sideways before stopping.
14. **Surface Mobile Equipment Collision Near Miss:** An empty haul truck slid into the loaded lane stopping near a loaded haul truck.

Comments: Safe mining operations are no accident. Collision risk is shaped by how work is planned, organized, and controlled.