



# Weekly Summary of Reportable Incidents

*Sharing safety with the mining industry*



Mine Incident Reporting Line

**1-888-348-0299**

Email: [MineIncidents@gov.bc.ca](mailto:MineIncidents@gov.bc.ca)

**Reportable Incidents**

**11**

## Incidents Reported September 22<sup>nd</sup> to 28<sup>th</sup>, 2025

1. **Surface Mobile Equipment Other:** While removing a tire bead with a hydraulic ram, the equipment slipped, projecting the anchor attachment, which struck a worker's face and caused a laceration above the right eye.
2. **Surface Geotechnical Unstable Face:** A haul truck tire dislodged from a pit wall and contacted a service truck during nearby drill maintenance.
3. **Surface Mobile Equipment Collision:** A loader reversed into a grader while both were operating on the same road.
4. **Surface Explosives:** Two boosters were discovered during in a shovel bucket during loading of haul trucks.
5. **Surface Mobile Equipment Autonomous:** An autonomous haul truck slowed down and then slid due to a proximity alert triggered by a water truck entering a narrow section of road.
6. **Surface Mobile Equipment Rollover:** A dozer reversed over a 1.5-meter drop. While attempting to maneuver out of the situation the dozer tipped on its side.
7. **Surface Other:** A drill pad shifted approximately three inches during rod removal. Operations were paused for assessment.
8. **Surface Mobile Equipment Collision:** A haul truck rolled forward unexpectedly during a jump-start attempt, contacting a light duty vehicle.
9. **Surface Mobile Equipment Other:** An excavator helping to move a drill was climbing up a bank when it slid backwards into a mud filled sump. A front-end loader and bulldozer were brought in to stabilize the ground by backfilling the sump which allowed the excavator to reverse out.
10. **Surface Mobile Equipment Other:** While positioning a haul truck's aftercooler using a come-along, a worker's fingers were pinched between the aftercooler and frame resulting in multiple breaks on two fingers.
11. **Surface Mobile Equipment Collision Near Miss:** A haul truck reversed, nearly contacting a light duty vehicle that was following it.

**Comments: Ensure an emergency response plan is in place for all hazardous work to support timely and effective incident management. All work involving unusual hazards must be personally supervised and follow approved safe work plans.**