

Service Area: Lakes



	Service Area Boundary Crossing		Longitude	Latitude	Description at Crossing
İ	111	0016	125° 21' 1.71" W	54° 7' 21.22" N	Highway 16 EB 0.5km South of Priestly Hill Road
	307	0016	126° 50' 47.24" W	54° 36' 30.98" N	Intersection at Highway 16 EB and Larch Road
	489	0131	126° 50' 47.50" W	54° 36' 31.47" N	Intersection at Wakefield Road and Highway 16 EB








Crossing: 111 MoTI Road/Hwy: 24-A-@-00016 Service Area: Lakes

Crossing Description:


Highway 16 EB 0.5km South of Priestly Hill Road





Latitude: 54° 7' 21.22" N

Longitude: 125° 21' 1.71" W








Crossing: 489 MoTI Road/Hwy: 24-B-@-00131 Service Area: Lakes

Crossing Description:


Intersection at Wakefield Road and Highway 16 EB






Latitude: 54° 36' 31.47" N

Longitude: 126° 50' 47.50" W









Crossing: Service Area: Lakes 307 MoTI Road/Hwy: 24-B-@-00016

Crossing Description:

Intersection at Highway 16 EB and Larch Road





Latitude: 54° 36' 30.98" N

Longitude: 126° 50' 47.24" W

