

Table 2: Jubilee Parkway, Summary of Asphalt Core Thickness

HRP	Offset	Location Description	Asphalt Core Thickness	Comments
0.00	-	Hwy 19 SB, shoulder	-	Reference point
0.50	+1.5	Lane 1, center of travel lane	81	-
0.50	+5.3	Lane 1, shoulder	85	-
1.45	-2.4	Lane 2, center of travel lane	68	-
1.45	-6.3	Lane 2, shoulder	72	-
3.00	+1.7	Center of left turn lane	68	Recent widening on both
3.00	+6.4	Lane 1, outside wheel path	103	sides of highway to
3.00	+8.6	Lane 1, shoulder	60	accommodate Willow
3.20	-1.7	Lane 2, inside wheel path	80	Creek Road left turning
3.20	-7.6	Lane 2, shoulder	60	lane
4.00	+1.5	Lane 1, center of travel lane	55	-
4.00	+4.9	Lane 1, shoulder	60	-
4.00	-2.0	Lane 2, center of travel lane	53	-
4.00	-5.5	Lane 2, shoulder	67	-
4.64	-	Highway 19 A	-	Reference point

As requested by MoTI, approximate locations of the asphalt cores are included in .kmz files, sent separately from this letter.