

Ministry of Energy, Mines and Low Carbon Innovation

## Weekly Summary of Dangerous Occurrences

Sharing safety with the mining industry



## Dangerous Occurrences Reported for the Week of October 31st to November 6th

- 1. Underground Ventilation: A phase to phase fault resulted in an underground ventilation stoppage.
- 2. Surface Mobile Equipment: During operation a haul truck was moving erratically, contacted a berm and drove on a crush pile. The truck came to a stop and the operator was taken to medical aid.
- **3.** Surface Mobile Equipment: Brake drag on a wiggle wagon caused a grease fire. The operator shutdown and secured the equipment. The fire was put out with fire extinguishers.
- 4. Surface Mobile Equipment: A haul truck drove up a bank which caused it to fall over on its side.
- **5. Surface Blasting:** A drill operator discovered that they had drilled into a bootleg from the previous drill pattern.

## **Comments:**

- Before using portable fire extinguishers ensure that you know:
  - what material is burning,
  - $\circ$   $\;$  what type of fire extinguisher to use and how to use it, and
  - $\circ$   $\;$  that the fire has not spread from its starting point.
- When using fire extinguishers remember PASS: Pull, Aim, Squeeze, Sweep.
- For more information visit the Canadian Centre for Occupational Health and Safety (CCOHS),

https://www.ccohs.ca/oshanswers/safety\_haz/fire\_extinguishers.html.