

Weekly Summary of Reportable Incidents

Sharing safety with the mining industry



Reportable Incidents

7

Incidents Reported August 4th to 10th, 2025

- 1. Surface Working at Height Falling Objects:** During a lifting operation using a telescopic handler, the load shifted and struck the worker holding the tagline in the leg, causing them to fall to the ground. The worker was transported for medical aid and assessed for hip pain.
- 2. Surface Mobile Equipment Unexpected Movement:** While pushing materials along the pit ramp, the right track of a dozer sank approximately one metre, causing the dozer to tilt to one side.
- 3. Surface Mobile Equipment Autonomous:** An empty autonomous mining truck slipped and turned 90 degrees within its lane before coming to a stop.
- 4. Surface Fire:** During hotwork in the mill, a fire was observed in the basement beneath a ball mill. Fire was extinguished using a fire hose.
- 5. Surface Mobile Equipment Fire:** A haul truck's grid box caught fire. Mine rescue responded and extinguished the fire.
- 6. Surface Mobile Equipment Out of Control:** An autonomous haul truck slid approximately 38 metres, contacted the berm, and came to a stop.
- 7. Surface Mobile Equipment Out of Control:** While travelling approximately 35 KM/H, an empty haul truck lost control while turning at an intersection, spun 90 degrees, and contacted the berm, resulting in damage to the front of the vehicle.

Comment: Mine operators should be aware of active wildfires and the potential impact to site access/egress. To report a wildfire, call 1 800 663-5555 (or *5555 from a cell phone). All calls are answered by BC Wildfire Service Staff at the Provincial Wildfire Reporting Centre. For more information related to wildfires, including prevention and an interactive map of active wildfires, visit [Wildfire Service - Province of British Columbia](#).