



Ministry of
Mining and
Critical Minerals

Weekly Summary of Reportable Incidents

Sharing safety with the mining industry



Mine Incident Reporting Line

1-888-348-0299

Email: MineIncidents@gov.bc.ca

Reportable Incidents

8

Incidents Reported November 10th to 16th, 2025

1. **Surface Mobile Equipment Fire:** A haul truck's exhaust caught fire. The operator stopped the vehicle and activated the fire suppression system. Mine rescue responded and extinguished the fire.
2. **Surface Mobile Equipment Unexpected Movement/Out of Control:** A haul truck rolled forward and contacted another haul truck.
3. **Surface Mobile Equipment Other:** A haul truck operator experienced neck pain after being jarred in the cab while receiving material from a loader. Mine rescue responded, and the operator was transported for medical assessment.
4. **Surface Mobile Equipment Other:** A boom crane struck a worker in the wash bay, pinning them against the wall. The worker was assessed for shoulder pain and transported for medical aid.
5. **Surface Working at Height Falling Worker:** A worker fell approximately 2.1 metres from the front of a haul truck while cleaning the windshield.
6. **Surface Working at Height Falling Worker:** A worker fell approximately 1.5 metres from a deck of a cement truck. First aid assessed head lacerations and chest pain, and transported the worker for medical aid.
7. **Surface Mobile Equipment Unexpected Movement/Out of Control:** While ascending a slope, a truck slid and veered into a drainage ditch along a road.
8. **Surface Equipment Contact with Drilling or Other Rotational Equipment:** During a swivel head change, the drill head pinned a helper's foot against the slide. The worker was assessed and transported to the hospital for further evaluation.

Comments: Stay alert while working around mobile equipment and on their elevated work areas. Inspect equipment regularly, reinforce hazard awareness, and always use fall protection when working at height.