

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
33	Chilliwack	A D RUNDLE MIDDLE	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
33	Chilliwack	A D RUNDLE MIDDLE	2	Classrooms	Medium	Non Structural Upgrade Required	
33	Chilliwack	A D RUNDLE MIDDLE	3	Shops	Medium	Non Structural Upgrade Required	
33	Chilliwack	A D RUNDLE MIDDLE	4	Classrooms	Medium	Non Structural Upgrade Required	
33	Chilliwack	A D RUNDLE MIDDLE	5	1999 Addition	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	BERNARD ELEMENTARY	1	Post 1990 Addition	Low	Meets Structural Life Safety Requirements	Medium
33	Chilliwack	BERNARD ELEMENTARY	2	Classroom Block	Medium	Non Structural Upgrade Required	
33	Chilliwack	BERNARD ELEMENTARY	3	Gymnasium	Medium	Non Structural Upgrade Required	
33	Chilliwack	CHANCE ALTERNATE	1	Classrooms and Administration	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	CHEAM ELEMENTARY	1	Classrooms/Admin.	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	CHEAM ELEMENTARY	2	Classrooms/Library	Medium	Non Structural Upgrade Required	
33	Chilliwack	CHEAM ELEMENTARY	3	Gymnasium	Medium	Non Structural Upgrade Required	
33	Chilliwack	CHILLIWACK CENTRAL COMMUNITY EL	1	Gymnasium	N/A	Completed	N/A
33	Chilliwack	CHILLIWACK CENTRAL COMMUNITY EL	2	Classrooms	N/A	Completed	
33	Chilliwack	CHILLIWACK MIDDLE	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
33	Chilliwack	CHILLIWACK MIDDLE	2	Shop	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	CHILLIWACK MIDDLE	3	Classrooms-Renovated 1995	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	CHILLIWACK MIDDLE	4	Classrooms-New 1995	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	CHILLIWACK SECONDARY	1	2-Storey Classroom	N/A	Completed	N/A
33	Chilliwack	CHILLIWACK SECONDARY	2	Vocational and Shops Buildings	N/A	Completed	
33	Chilliwack	CHILLIWACK SECONDARY	3	Library and Music Buildings	N/A	Completed	
33	Chilliwack	CHILLIWACK SECONDARY	4	Gymnasium/Washrooms	N/A	Completed	
33	Chilliwack	CHILLIWACK SECONDARY	5	2003 Maintenance Building	N/A	Completed	
33	Chilliwack	CHILLIWACK SECONDARY	6	2004 Lobby Exercise addition	N/A	Completed	
33	Chilliwack	CULTUS LAKE COMMUNITY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
33	Chilliwack	CULTUS LAKE COMMUNITY	2	Classrooms (West)	Medium	Non Structural Upgrade Required	
33	Chilliwack	CULTUS LAKE COMMUNITY	3	Classrooms (North)	Medium	Non Structural Upgrade Required	
33	Chilliwack	CULTUS LAKE COMMUNITY	4	Classrooms (East)	Medium	Non Structural Upgrade Required	
33	Chilliwack	EAST CHILLIWACK ELEMENTARY	1	Gymnasium (Post 1993)	Low	Meets Structural Life Safety Requirements	Medium
33	Chilliwack	EAST CHILLIWACK ELEMENTARY	2	Classrooms/Admin.	Medium	Non Structural Upgrade Required	
33	Chilliwack	EAST CHILLIWACK ELEMENTARY	3	Classrooms (1993)	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	F G LEARY ELEMENTARY	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	F G LEARY ELEMENTARY	2	Classrooms (1974)	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	F G LEARY ELEMENTARY	3	Gymnasium/Classrooms (2001)	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	KIPP CENTRE	1	Classrooms/Admin.	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	KIPP CENTRE	2	Classrooms (East)	Medium	Non Structural Upgrade Required	
33	Chilliwack	LITTLE MOUNTAIN ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	LITTLE MOUNTAIN ELEMENTARY	2	Classrooms (Central)	Medium	Non Structural Upgrade Required	
33	Chilliwack	LITTLE MOUNTAIN ELEMENTARY	3	Classrooms (East)	Medium	Non Structural Upgrade Required	
33	Chilliwack	LITTLE MOUNTAIN ELEMENTARY	4	Classrooms (West)	Medium	Non Structural Upgrade Required	
33	Chilliwack	LITTLE MOUNTAIN ELEMENTARY	5	Classrooms (North) 1999	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	MCCAMMON ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	MCCAMMON ELEMENTARY	2	1957 Classroom	Medium	Non Structural Upgrade Required	
33	Chilliwack	MCCAMMON ELEMENTARY	3	1990 Classrooms	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	MCCAMMON ELEMENTARY	4	1999 Classroom	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	REGIONAL CORRESPONDENCE CENTR	1	1962 Office Building	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	REGIONAL CORRESPONDENCE CENTR	2	2003 Office Building	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	REGIONAL CORRESPONDENCE CENTR	3	Portable Buildings	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	ROBERTSON ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
33	Chilliwack	ROBERTSON ELEMENTARY	2	1961/1970 Classrooms	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	ROBERTSON ELEMENTARY	3	2001 Classrooms	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	ROBERTSON on Elm	1	Classroom/Administration	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	ROSEDALE ELEMENTARY	1	Gymnasium	N/A	Completed	
33	Chilliwack	ROSEDALE ELEMENTARY	2	1 Storey Classroom/Admin.	N/A	Completed	N/A
33	Chilliwack	ROSEDALE ELEMENTARY	3	3 Storey Classroom	N/A	Completed	
33	Chilliwack	ROSEDALE MIDDLE	1	Gymnasium	N/A	Completed	
33	Chilliwack	ROSEDALE MIDDLE	2	2 Storey Classroom/Admin.	N/A	Completed	N/A
33	Chilliwack	ROSEDALE MIDDLE	3	1 Storey Classroom	N/A	Completed	
33	Chilliwack	ROSEDALE MIDDLE	4	Music Room	N/A	Completed	
33	Chilliwack	SARDIS ELEMENTARY	1	1950 Gymnasium	Medium	Non Structural Upgrade Required	
33	Chilliwack	SARDIS ELEMENTARY	2	1955/1974 Classrooms	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	SARDIS ELEMENTARY	3	1992 Classrooms	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	STRATHCONA ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
33	Chilliwack	STRATHCONA ELEMENTARY	2	1970/71/74 Classrooms	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	STRATHCONA ELEMENTARY	3	1961 Classrooms	Medium	Non Structural Upgrade Required	
33	Chilliwack	STRATHCONA ELEMENTARY	4	1996 Classrooms	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	TYSON ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
33	Chilliwack	TYSON ELEMENTARY	2	Classrooms (Centre)	Low	Meets Structural Life Safety Requirements	Medium
33	Chilliwack	TYSON ELEMENTARY	3	Classrooms (East Wing)	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	VEDDER MIDDLE	1	Classrooms & Administration	Medium	Non Structural Upgrade Required	
33	Chilliwack	VEDDER MIDDLE	2	Gym and Classrooms - 1993	Low	Meets Structural Life Safety Requirements	Medium
33	Chilliwack	VEDDER MIDDLE	3	Gym - upgraded in 2004	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	WATSON ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	WATSON ELEMENTARY	2	Classrooms (Centre)	Medium	Non Structural Upgrade Required	
33	Chilliwack	WATSON ELEMENTARY	3	Multi-Purpose	Medium	Non Structural Upgrade Required	Medium
33	Chilliwack	WATSON ELEMENTARY	4	Classrooms (south & east)	Medium	Non Structural Upgrade Required	
33	Chilliwack	WATSON ELEMENTARY	5	Classroom (North) 1999	Low	Meets Structural Life Safety Requirements	
33	Chilliwack	YARROW COMMUNITY	1	Gymnasium	N/A	Completed	N/A
33	Chilliwack	YARROW COMMUNITY	2	Classroom	N/A	Completed	
34	Abbotsford	YARROW COMMUNITY	1	West Classroom Building (1954/1959)	Medium	Non Structural Upgrade Required	
34	Abbotsford	YARROW COMMUNITY	2	Administration & Misc	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	YARROW COMMUNITY	3	Gym / Lunchroom & Misc	Medium	Non Structural Upgrade Required	
34	Abbotsford	YARROW COMMUNITY	4	Classroom Annex (1966)	Medium	Non Structural Upgrade Required	
34	Abbotsford	ABBOTSFORD SENIOR SECONDARY	1	Gymnasium/Music	N/A	Completed	
34	Abbotsford	ABBOTSFORD SENIOR SECONDARY	2	Entry Canopy and Cafeteria	N/A	Completed	
34	Abbotsford	ABBOTSFORD SENIOR SECONDARY	3	North Classroom Wing	N/A	Completed	
34	Abbotsford	ABBOTSFORD SENIOR SECONDARY	4	West Classroom Wing	N/A	Completed	
34	Abbotsford	ABBOTSFORD SENIOR SECONDARY	7	Administration Area	N/A	Completed	N/A
34	Abbotsford	ABBOTSFORD SENIOR SECONDARY	8	Library (2001)	N/A	Completed	
34	Abbotsford	ABBOTSFORD SENIOR SECONDARY	9	New Gymnasium/Classroom Wing (2001)	N/A	Completed	
34	Abbotsford	ABBOTSFORD SENIOR SECONDARY	5	South 2 Storey Classroom Block	N/A	Completed	
34	Abbotsford	ABBOTSFORD SENIOR SECONDARY	6	Industrial Education Wing	N/A	Completed	
34	Abbotsford	ABBOTSFORD TRADITIONAL SECONDA	1	1959 2-Storey Center Classroom Wing	High 1	Supported 2013	
34	Abbotsford	ABBOTSFORD TRADITIONAL SECONDA	2	1959 1-Storey West Workshop Wing	High 3	Supported 2013	
34	Abbotsford	ABBOTSFORD TRADITIONAL SECONDA	3	1959 1-Storey Admin. Wing	High 3	Supported 2013	
34	Abbotsford	ABBOTSFORD TRADITIONAL SECONDA	4	1959 Gymnasium	Medium	Supported 2013	High 1
34	Abbotsford	ABBOTSFORD TRADITIONAL SECONDA	5	1974 Cafeteria	Medium	Supported 2013	
34	Abbotsford	ABBOTSFORD TRADITIONAL SECONDA	6	1968 2-Storey North Wing	High 2	Supported 2013	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
34	Abbotsford	ABBOTSFORD TRADITIONAL SECONDA	7	1997 DND Addition	Low	Supported 2013	
34	Abbotsford	ABERDEEN ELEMENTARY	1	1955 1-Storey Centre East Block	N/A	Completed	N/A
34	Abbotsford	ABERDEEN ELEMENTARY	2	1955 2-Storey West Wing	N/A	Completed	
34	Abbotsford	ABERDEEN ELEMENTARY	3	1981 1-Storey North Wing	N/A	Completed	
34	Abbotsford	ABERDEEN ELEMENTARY	4	1981 Gymnasium	N/A	Completed	
34	Abbotsford	ABERDEEN ELEMENTARY	5	1992 Multi-Purpose Room	N/A	Completed	
34	Abbotsford	ABERDEEN ELEMENTARY	6	1992 South Wing	N/A	Completed	
34	Abbotsford	ALEXANDER ELEMENTARY	1	North Classroom Wing	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	ALEXANDER ELEMENTARY	2	Gym	Medium	Non Structural Upgrade Required	
34	Abbotsford	ALEXANDER ELEMENTARY	3	South Classroom Wing	Medium	Non Structural Upgrade Required	
34	Abbotsford	ALEXANDER ELEMENTARY	4	Entrance and administration (1993)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	ALEXANDER ELEMENTARY	5	East Classroom Wing (1993)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	BAKerview ELEMENTARY	1	1972 Gymnasium	High 3	Inactive	High 2
34	Abbotsford	BAKerview ELEMENTARY	2	1972 1-Storey Classrooms	Medium	Inactive	
34	Abbotsford	BAKerview ELEMENTARY	3	1974 2-Storey Classrooms	High 2	Inactive	
34	Abbotsford	BARROWTOWN ELEMENTARY	1	Gym (1952)	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	BARROWTOWN ELEMENTARY	2	Main Building (1952)	Medium	Non Structural Upgrade Required	
34	Abbotsford	BLUE JAY ELEMENTARY	1	Main Original Bldg (1989)	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	BLUE JAY ELEMENTARY	2	West Addition (2001)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	BRADNER ELEMENTARY	1	East Classrooms (1974)	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	BRADNER ELEMENTARY	2	Mid Classrooms (1968)	Medium	Non Structural Upgrade Required	
34	Abbotsford	BRADNER ELEMENTARY	3	Staff Room and Offices (1972)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	BRADNER ELEMENTARY	4	South Classrooms (1961)	Medium	Non Structural Upgrade Required	
34	Abbotsford	BRADNER ELEMENTARY	5	Two Story Storage and Classrooms (1925)	Medium	Non Structural Upgrade Required	
34	Abbotsford	BRADNER ELEMENTARY	6	Gymnasium (1999)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	CENTENNIAL PARK ELEMENTARY	1	Original Classroom East (1968)	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	CENTENNIAL PARK ELEMENTARY	2	Gymnasium and Misc. Rooms (1974)	Medium	Non Structural Upgrade Required	
34	Abbotsford	CENTENNIAL PARK ELEMENTARY	3	Two Storey Classrooms West (1974)	Medium	Non Structural Upgrade Required	
34	Abbotsford	CENTENNIAL PARK ELEMENTARY	4	Changerooms & Storage N-W (1976)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	CENTENNIAL PARK ELEMENTARY	5	1990 Additions at North S-W (1990)	Medium	Non Structural Upgrade Required	
34	Abbotsford	CHIEF DAN GEORGE MIDDLE	1	East Block Single Storey Classrooms	Low	Meets Structural Life Safety Requirements	Low
34	Abbotsford	CHIEF DAN GEORGE MIDDLE	2	Multi-Purpose Room	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	CHIEF DAN GEORGE MIDDLE	3	West Block Single Story Classroom	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	CHIEF DAN GEORGE MIDDLE	4	Art and Shop Rooms	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	CHIEF DAN GEORGE MIDDLE	5	Gymnasium	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	CLEARBROOK ELEMENTARY	1	East Multi-Purpose Room Addition (1989)	Medium	Non Structural Upgrade Required	Low
34	Abbotsford	CLEARBROOK ELEMENTARY	2	West Classrooms Addition (1990)	Medium	Non Structural Upgrade Required	
34	Abbotsford	CLEARBROOK ELEMENTARY	3	Staff and Special Ed Rooms (1976)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	CLEARBROOK ELEMENTARY	4	East Classrooms Addition (1981)	Medium	Non Structural Upgrade Required	
34	Abbotsford	CLEARBROOK ELEMENTARY	5	Gymnasium (1981)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	CLEARBROOK ELEMENTARY	6	North West Classrooms Addition (1981)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	CLEARBROOK ELEMENTARY	7	Original Classrooms and Library (1951)	Medium	Non Structural Upgrade Required	
34	Abbotsford	DORMICK PARK ELEMENTARY	1	N/E Classroom/Library Wing	Low	Meets Structural Life Safety Requirements	Low
34	Abbotsford	DORMICK PARK ELEMENTARY	2	Gymnasium (Upgraded 1998)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	DORMICK PARK ELEMENTARY	3	West Classroom Wing (1998)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	DR THOMAS A SWIFT ELEMENTARY	1	Gymnasium (1979)	Low	Meets Structural Life Safety Requirements	Low
34	Abbotsford	DR THOMAS A SWIFT ELEMENTARY	2	Classrooms / Admin (1979 & 1982)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	DR THOMAS A SWIFT ELEMENTARY	3	Classrooms (1993)	Low	Meets Structural Life Safety Requirements	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
34	Abbotsford	DUNACH ELEMENTARY	1	Original West Wing (1925)	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	DUNACH ELEMENTARY	2	Gym and Offices (1975)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	DUNACH ELEMENTARY	3	Classrooms East End (1982)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	GODSON ELEMENTARY	1	Small Gym	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	GODSON ELEMENTARY	2	Original School	Medium	Non Structural Upgrade Required	
34	Abbotsford	GODSON ELEMENTARY	3	East Classroom Addition	Medium	Non Structural Upgrade Required	
34	Abbotsford	GODSON ELEMENTARY	4	West Classroom Addition	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	GODSON ELEMENTARY	5	Gym & Library Wing	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	JACKSON ELEMENTARY	1	South Wing	N/A	Completed	N/A
34	Abbotsford	JACKSON ELEMENTARY	2	East Side	N/A	Completed	
34	Abbotsford	JACKSON ELEMENTARY	3	North Wing	N/A	Completed	
34	Abbotsford	JACKSON ELEMENTARY	4	Gymnasium	N/A	Completed	
34	Abbotsford	JOHN MACLURE COMMUNITY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
34	Abbotsford	JOHN MACLURE COMMUNITY	2	Administration	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	JOHN MACLURE COMMUNITY	3	Two Storey Classroom Wing	Medium	Non Structural Upgrade Required	
34	Abbotsford	KING TRADITIONAL ELEMENTARY	2	Gymnasium (2000)	Low	Meets Structural Life Safety Requirements	High 3
34	Abbotsford	KING TRADITIONAL ELEMENTARY	3	East Classrooms (2000)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	KING TRADITIONAL ELEMENTARY	1	Central Classrooms (1951)	High 3	Structural Upgrade Required	
34	Abbotsford	MARGARET STENERSEN ELEMENTARY	1	Classrooms / Admin (64, 67, 69, 71, 72)	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	MARGARET STENERSEN ELEMENTARY	2	Gymnasium (1967, 1975)	Medium	Non Structural Upgrade Required	
34	Abbotsford	MARGARET STENERSEN ELEMENTARY	3	Library (1975)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	MARGARET STENERSEN ELEMENTARY	4	Storage / Change (1975)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	MARGARET STENERSEN ELEMENTARY	5	Classrooms South (1981)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	MARGARET STENERSEN ELEMENTARY	6	Classrooms East (1997)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	MCMILLAN ELEMENTARY	1	Original Classrooms	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	MCMILLAN ELEMENTARY	2	North Classroom Addition	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	MCMILLAN ELEMENTARY	3	Gymnasium	Medium	Non Structural Upgrade Required	
34	Abbotsford	MCMILLAN ELEMENTARY	4	South Classroom Addition (1993)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	MT LEHMAN ELEMENTARY	1	Original Two Storey (1910)	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	MT LEHMAN ELEMENTARY	2	Centre Classrooms (1968)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	MT LEHMAN ELEMENTARY	3	Gymnasium (1975)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	MT LEHMAN ELEMENTARY	4	West Wing (1994)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	NORTH POPLAR FINE ARTS	1	East Wing (1968)	Low	Meets Structural Life Safety Requirements	Low
34	Abbotsford	NORTH POPLAR FINE ARTS	2	West Wing & Gym (1990)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	PHILIP SHEFFIELD ELEMENTARY	1	classroom wing	Medium	Inactive	High 3
34	Abbotsford	PHILIP SHEFFIELD ELEMENTARY	2	gymnasium (seismic upgrade 2001)	Low	Inactive	
34	Abbotsford	PHILIP SHEFFIELD ELEMENTARY	3	Library wing	High 3	Inactive	
34	Abbotsford	PRINCE CHARLES ELEMENTARY	1	Gym (1983)	Low	Meets Structural Life Safety Requirements	Low
34	Abbotsford	PRINCE CHARLES ELEMENTARY	2	Main building (1983)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	PRINCE CHARLES ELEMENTARY	3	N/W corner and S/W corner (1992)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	RESOURCE CENTRE	1	West wing (1959, 1966)	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	RESOURCE CENTRE	2	East addition (1983)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	ROSS ELEMENTARY	1	Center Classrooms (1969/1972)	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	ROSS ELEMENTARY	2	Gymnasium & Staff Room (1974)	Medium	Non Structural Upgrade Required	
34	Abbotsford	ROSS ELEMENTARY	3	Multi-Purpose & Offices (1994)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	ROSS ELEMENTARY	4	West Area Classrooms (1994)	Low	Meets Structural Life Safety Requirements	
34	Abbotsford	SANDY HILL ELEMENTARY	1	Gymnasium (1990)	Medium	Non Structural Upgrade Required	Medium
34	Abbotsford	SANDY HILL ELEMENTARY	2	Kindergarten and change rooms (1990)	Medium	Non Structural Upgrade Required	
34	Abbotsford	SANDY HILL ELEMENTARY	3	Classrooms and library (1990)	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk	
34	Abbotsford	SANDY HILL ELEMENTARY	4	Classrooms addition (1990)	Medium	Non Structural Upgrade Required		
34	Abbotsford	SIMPSON TRADITIONAL MIDDLE	1	S/E Library-Corridor (1951)	Medium	Partially Complete		
34	Abbotsford	SIMPSON TRADITIONAL MIDDLE	2	Main Core Area (1951/1969)	Medium	Partially Complete		
34	Abbotsford	SIMPSON TRADITIONAL MIDDLE	3	N/E Classroom (1969)	Medium	Partially Complete	Medium	
34	Abbotsford	SIMPSON TRADITIONAL MIDDLE	4	N/W Drama Room (1981)	Low	Partially Complete		
34	Abbotsford	SIMPSON TRADITIONAL MIDDLE	5	S/W Gym and Misc. (1981)	Low	Partially Complete		
34	Abbotsford	SOUTH POPLAR ELEMENTARY	1	Original Main Bldg (1933)	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	SOUTH POPLAR ELEMENTARY	2	West Wing (1971)	Medium	Non Structural Upgrade Required		Medium
34	Abbotsford	SOUTH POPLAR ELEMENTARY	3	Gym (1994)	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	TEN BROECK ELEMENTARY	1	Original Building - Classrooms (1966)	Medium	Non Structural Upgrade Required		
34	Abbotsford	TEN BROECK ELEMENTARY	2	Enclosed Covered Play Area (1966, 1975)	Medium	Non Structural Upgrade Required		
34	Abbotsford	TEN BROECK ELEMENTARY	3	Classrooms West (1971)	Medium	Non Structural Upgrade Required		
34	Abbotsford	TEN BROECK ELEMENTARY	4	Classrooms / Admin (1969, 1977)	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	TEN BROECK ELEMENTARY	5	Gymnasium (1969, 1977)	Medium	Non Structural Upgrade Required		
34	Abbotsford	TEN BROECK ELEMENTARY	6	Classrooms North (1993)	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	TEN BROECK ELEMENTARY	7	Entry Renovation (1993)	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	TERRY FOX ELEMENTARY	1	Original classroom wing (1981)	Medium	Non Structural Upgrade Required		
34	Abbotsford	TERRY FOX ELEMENTARY	2	Gymnasium (1981)	Medium	Non Structural Upgrade Required	Medium	
34	Abbotsford	TERRY FOX ELEMENTARY	3	West classroom addition (1991)	Low	Meets Structural Life Safety Requirements		
34	Abbotsford	UPPER SUMAS ELEMENTARY	1	Classrooms	Medium	Non Structural Upgrade Required		
34	Abbotsford	UPPER SUMAS ELEMENTARY	2	Connector and washrooms	Low	Meets Structural Life Safety Requirements	Medium	
34	Abbotsford	UPPER SUMAS ELEMENTARY	3	Gym	Medium	Non Structural Upgrade Required		
34	Abbotsford	W J MOUAT SECONDARY	1	North - West Wing (2001)	N/A	Completed		
34	Abbotsford	W J MOUAT SECONDARY	2	South - East Wing (1987)	N/A	Completed		
34	Abbotsford	W J MOUAT SECONDARY	3	Music Room (1981)	N/A	Completed	N/A	
34	Abbotsford	W J MOUAT SECONDARY	4	Original Single Storey (1974)	N/A	Completed		
34	Abbotsford	W J MOUAT SECONDARY	5	Original Two Storey (1974)	N/A	Completed		
34	Abbotsford	WILLIAM A. FRASER ELEMENTARY	1	1980 Addition NW	N/A	Completed		
34	Abbotsford	WILLIAM A. FRASER ELEMENTARY	2	1974 Addition SW	N/A	Completed		
34	Abbotsford	WILLIAM A. FRASER ELEMENTARY	3	Gymnasium	N/A	Completed	N/A	
34	Abbotsford	WILLIAM A. FRASER ELEMENTARY	4	1992 Addition NE	N/A	Completed		
34	Abbotsford	WILLIAM A. FRASER ELEMENTARY	5	(1992) Multipurpose Room	N/A	Completed		
34	Abbotsford	YALE SECONDARY	1	1971 1-Storey Admin/Drams/Music	N/A	Under Construction		
34	Abbotsford	YALE SECONDARY	2	1971 2-Storey Original Classrooms	N/A	Under Construction		
34	Abbotsford	YALE SECONDARY	3	1971 Original Shop	N/A	Under Construction		
34	Abbotsford	YALE SECONDARY	4	2000 Large Gymnasium	N/A	Under Construction		
34	Abbotsford	YALE SECONDARY	5	1985 2-Storey Classroom Addn	N/A	Under Construction	N/A	
34	Abbotsford	YALE SECONDARY	6	1988 Cafeteria	N/A	Under Construction		
34	Abbotsford	YALE SECONDARY	7	1985 Small Gymnasium	N/A	Under Construction		
34	Abbotsford	YALE SECONDARY	8	1985 Shop Addition	N/A	Under Construction		
34	Abbotsford	YALE SECONDARY	9	1988 1-Storey Classroom Addn	N/A	Under Construction		
34	Abbotsford	YALE SECONDARY	10	2000 2-Storey N. Classroom/Theatre	N/A	Under Construction		
35	Langley	ALDERGROVE COMMUNITY SECONDAF	1	Gymnasium (West)	Medium	Non Structural Upgrade Required		
35	Langley	ALDERGROVE COMMUNITY SECONDAF	2	Classrooms (West)	Medium	Non Structural Upgrade Required		
35	Langley	ALDERGROVE COMMUNITY SECONDAF	3	Classrooms (North)	Medium	Non Structural Upgrade Required		
35	Langley	ALDERGROVE COMMUNITY SECONDAF	4	Small Gymnasium	Medium	Non Structural Upgrade Required	Medium	
35	Langley	ALDERGROVE COMMUNITY SECONDAF	5	Shops	Medium	Non Structural Upgrade Required		
35	Langley	ALDERGROVE COMMUNITY SECONDAF	6	Gymnasium/Theatre	Medium	Non Structural Upgrade Required		
35	Langley	ALDERGROVE COMMUNITY SECONDAF	7	Classrooms/Shops	Medium	Non Structural Upgrade Required		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk	
35	Langley	ALDERGROVE COMMUNITY SECONDARY	8	Library	Low	Meets Structural Life Safety Requirements		
35	Langley	ALDERGROVE ELEMENTARY	1	Gymnasium	Low	Inactive		
35	Langley	ALDERGROVE ELEMENTARY	2	Library	Medium	Inactive		
35	Langley	ALDERGROVE ELEMENTARY	3	2-Storey Classrooms	Medium	Inactive	Medium	
35	Langley	ALDERGROVE ELEMENTARY	4	Classrooms - North/West	Medium	Inactive		
35	Langley	ALDERGROVE ELEMENTARY	5	Classrooms - West	Medium	Inactive		
35	Langley	ALDERGROVE ELEMENTARY	6	Classrooms - South/West	Medium	Inactive		
35	Langley	ALEX HOPE ELEMENTARY	1	1988 Block 1	Low	Meets Structural Life Safety Requirements		
35	Langley	ALEX HOPE ELEMENTARY	2	1988 Block 2	Low	Meets Structural Life Safety Requirements		
35	Langley	ALEX HOPE ELEMENTARY	3	1988 Block 3	Low	Meets Structural Life Safety Requirements	Low	
35	Langley	ALEX HOPE ELEMENTARY	4	1998 Block 4	Low	Meets Structural Life Safety Requirements		
35	Langley	ALEX HOPE ELEMENTARY	5	1988 Block 5	Low	Meets Structural Life Safety Requirements		
35	Langley	ALICE BROWN ELEMENTARY	1	1976 Block 1	Low	Meets Structural Life Safety Requirements		
35	Langley	ALICE BROWN ELEMENTARY	2	1976 Block 2	Low	Meets Structural Life Safety Requirements	Medium	
35	Langley	ALICE BROWN ELEMENTARY	3	1976 Block 3	Medium	Non Structural Upgrade Required		
35	Langley	APEX SECONDARY (was OTTER ELEMENTARY)	1	1976 Block 1	Low	Meets Structural Life Safety Requirements		
35	Langley	APEX SECONDARY (was OTTER ELEMENTARY)	2	1976 Block 2	Low	Meets Structural Life Safety Requirements	High 3	
35	Langley	APEX SECONDARY (was OTTER ELEMENTARY)	3	1913 Block 3 (2 Classroom structure)	High 3	Structural Upgrade Required		
35	Langley	BELMONT ELEMENTARY	1	1971 Block 1	N/A	Completed		
35	Langley	BELMONT ELEMENTARY	2	2001 Block 2	N/A	Completed		
35	Langley	BELMONT ELEMENTARY	3	1972 Block 3	N/A	Completed	N/A	
35	Langley	BELMONT ELEMENTARY	4	1955/1972 Block 4	N/A	Completed		
35	Langley	BELMONT ELEMENTARY	5	2001 Block 5	N/A	Completed		
35	Langley	BELMONT ELEMENTARY	6	1972 Block 6	N/A	Completed		
35	Langley	BLACKLOCK ELEMENTARY	1	1971 Block 1	Medium	Non Structural Upgrade Required		
35	Langley	BLACKLOCK ELEMENTARY	2	1974 Block 2	Low	Meets Structural Life Safety Requirements	Medium	
35	Langley	BLACKLOCK ELEMENTARY	3	1974 Block 3	Low	Meets Structural Life Safety Requirements		
35	Langley	BLACKLOCK ELEMENTARY	4	1974 Block 4	Low	Meets Structural Life Safety Requirements		
35	Langley	BRADSHAW ELEMENTARY	1	Classroom / Admin	Low	Inactive		
35	Langley	BRADSHAW ELEMENTARY	2	Classrooms (West)	Medium	Inactive	Medium	
35	Langley	BRADSHAW ELEMENTARY	3	Classrooms (East)	Low	Inactive		
35	Langley	BRADSHAW ELEMENTARY	4	Gymnasium (upgraded 2002)	Low	Inactive		
35	Langley	BROOKSWOOD SECONDARY	1	1974 Block 1	High 3	Structural Upgrade Required		
35	Langley	BROOKSWOOD SECONDARY	2	1982 Block 2	Medium	Non Structural Upgrade Required		
35	Langley	BROOKSWOOD SECONDARY	3	1982/1986 Block 3	Medium	Non Structural Upgrade Required	High 3	
35	Langley	BROOKSWOOD SECONDARY	4	1982/1986 Block 4	Medium	Non Structural Upgrade Required		
35	Langley	BROOKSWOOD SECONDARY	5	Block 5 1990+/-	Low	Meets Structural Life Safety Requirements		
35	Langley	BROOKSWOOD SECONDARY	6	Block 6 1990 +/-	Low	Meets Structural Life Safety Requirements		
35	Langley	COGHLAN ELEMENTARY	1	1958 1-storey classroom	Medium	Non Structural Upgrade Required		
35	Langley	COGHLAN ELEMENTARY	2	1973 Gymnasium	Medium	Non Structural Upgrade Required	Medium	
35	Langley	COGHLAN ELEMENTARY	3	1994 1-storey classroom	Low	Meets Structural Life Safety Requirements		
35	Langley	COUNTY LINE ELEMENTARY	1	1947 1-storey classroom	Medium	Inactive		
35	Langley	COUNTY LINE ELEMENTARY	2	1976 gymnasium	Low	Inactive	Medium	
35	Langley	COUNTY LINE ELEMENTARY	3	1986 1-storey classroom	Low	Inactive		
35	Langley	D W POPPY SECONDARY	1	1972 2-storey classroom	High 3	Structural Upgrade Required		
35	Langley	D W POPPY SECONDARY	2	1979 2-storey classroom	Low	Meets Structural Life Safety Requirements		
35	Langley	D W POPPY SECONDARY	3	1972 1-storey classroom	High 3	Structural Upgrade Required	High 3	
35	Langley	D W POPPY SECONDARY	4	1972 gymnasium	Low	Meets Structural Life Safety Requirements		
35	Langley	D W POPPY SECONDARY	5	1988 Fine Arts	Low	Meets Structural Life Safety Requirements		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
35	Langley	DOUGLAS PARK COMMUNITY	1	1981 Block 1	Low	Meets Structural Life Safety Requirements	Medium
35	Langley	DOUGLAS PARK COMMUNITY	2	1981 Block 2	Low	Meets Structural Life Safety Requirements	
35	Langley	DOUGLAS PARK COMMUNITY	3	1991 Block 3	Medium	Non Structural Upgrade Required	
35	Langley	DOUGLAS PARK COMMUNITY	4	1992 Block 4	Low	Meets Structural Life Safety Requirements	
35	Langley	FORT LANGLEY ELEMENTARY	1	Original Structure	N/A	Completed	N/A
35	Langley	FORT LANGLEY ELEMENTARY	2	Classroom Addition (1969, 71,76)	N/A	Completed	
35	Langley	FORT LANGLEY ELEMENTARY	3	Covered play areas	N/A	Completed	
35	Langley	FORT LANGLEY ELEMENTARY	4	Gymnasium (Seismic upgrade 2002)	N/A	Completed	
35	Langley	GLENWOOD ELEMENTARY	1	1950 1-storey classroom	Medium	Non Structural Upgrade Required	Medium
35	Langley	GLENWOOD ELEMENTARY	2	1963 gymnasium	Medium	Non Structural Upgrade Required	
35	Langley	GLENWOOD ELEMENTARY	3	1916 2-storey classroom	High 2	Inactive	
35	Langley	H D STAFFORD MIDDLE (was Secondary)	1	1969 Block 1	High 3	Structural Upgrade Required	High 3
35	Langley	H D STAFFORD MIDDLE (was Secondary)	2	1969 Block 2	High 3	Structural Upgrade Required	
35	Langley	H D STAFFORD MIDDLE (was Secondary)	3	1969 Block 3	High 3	Structural Upgrade Required	
35	Langley	H D STAFFORD MIDDLE (was Secondary)	4	1971 Block 4	High 3	Structural Upgrade Required	
35	Langley	H D STAFFORD MIDDLE (was Secondary)	5	1991 Block 5	Low	Meets Structural Life Safety Requirements	
35	Langley	H D STAFFORD MIDDLE (was Secondary)	6	1991 Block 6	Low	Meets Structural Life Safety Requirements	
35	Langley	H D STAFFORD MIDDLE (was Secondary)	7	1991 Block 7	High 3	Structural Upgrade Required	
35	Langley	JAMES KENNEDY ELEMENTARY	1	1986 1-storey classroom	Low	Meets Structural Life Safety Requirements	Low
35	Langley	JAMES KENNEDY ELEMENTARY	2	1986 Gymnasium	Low	Meets Structural Life Safety Requirements	
35	Langley	JAMES KENNEDY ELEMENTARY	3	2000 1-storey classroom	Low	Meets Structural Life Safety Requirements	
35	Langley	LANGLEY FINE ARTS	1	Original structure	N/A	Completed	N/A
35	Langley	LANGLEY FINE ARTS	2	Original gym	N/A	Completed	
35	Langley	LANGLEY FINE ARTS	3	1995 addition	N/A	Completed	
35	Langley	LANGLEY FINE ARTS	4	1998 addition	N/A	Completed	
35	Langley	LANGLEY FUNDAMENTAL ELEMENTARY	1	1981 Gymnasium	High 2	Structural Upgrade Required	High 2
35	Langley	LANGLEY FUNDAMENTAL ELEMENTARY	2	Classrooms, 1981 original construction, wood and sorr	Medium	Non Structural Upgrade Required	
35	Langley	LANGLEY FUNDAMENTAL ELEMENTARY	3	SW Classrooms, 1984 addition, wood and masonry	Medium	Non Structural Upgrade Required	
35	Langley	LANGLEY FUNDAMENTAL ELEMENTARY	4	NW Classrooms, 1991 addition, wood construction suk	Medium	Non Structural Upgrade Required	
35	Langley	LANGLEY FUNDAMENTAL MIDDLE HIGH	1	1992 Block 1	Low	Meets Structural Life Safety Requirements	Low
35	Langley	LANGLEY FUNDAMENTAL MIDDLE HIGH	2	1992 Block 2	Low	Meets Structural Life Safety Requirements	
35	Langley	LANGLEY FUNDAMENTAL MIDDLE HIGH	3	2000 Block 3	Low	Meets Structural Life Safety Requirements	
35	Langley	JAMES ANDERSON LEARNING CENTRE	1	1956/1961/1965/1969 Block 1	Medium	Non Structural Upgrade Required	Medium
35	Langley	JAMES ANDERSON LEARNING CENTRE	2	1971 Block 2	Medium	Non Structural Upgrade Required	
35	Langley	JAMES ANDERSON LEARNING CENTRE	3	1973 Block 3	Medium	Non Structural Upgrade Required	
35	Langley	LANGLEY MEADOWS ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
35	Langley	LANGLEY MEADOWS ELEMENTARY	2	Classrooms (West)	Medium	Non Structural Upgrade Required	
35	Langley	LANGLEY MEADOWS ELEMENTARY	3	Classroom (Central)	Low	Meets Structural Life Safety Requirements	
35	Langley	LANGLEY MEADOWS ELEMENTARY	4	Classroom (East)	Low	Meets Structural Life Safety Requirements	
35	Langley	LANGLEY SECONDARY	1	1947 1-Storey Science Block	High 1	Supported 2013	High 1
35	Langley	LANGLEY SECONDARY	2	1948 2-Storey Classrooms	High 1	Supported 2013	
35	Langley	LANGLEY SECONDARY	3	1987 2-Storey Block	Medium	Supported 2013	
35	Langley	LANGLEY SECONDARY	4	1965 1-Storey Classrooms	High 2	Supported 2013	
35	Langley	LANGLEY SECONDARY	5	1989 2-Storey Block	Low	Supported 2013	
35	Langley	LANGLEY SECONDARY	6	1978 1-Storey Block	Medium	Supported 2013	
35	Langley	LANGLEY SECONDARY	7	1974 1-Storey Block	Medium	Supported 2013	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
35	Langley	LANGLEY SECONDARY	8	1987 1-Storey Renovation	Low	Supported 2013	
35	Langley	LANGLEY SECONDARY	9	1948 1-Storey Block	High 3	Supported 2013	
35	Langley	LANGLEY SECONDARY	10	1951 1-Storey Vocational Training Block	High 1	Supported 2013	
35	Langley	LANGLEY SECONDARY	11	1975 2-Storey Block	Medium	Supported 2013	
35	Langley	LANGLEY SECONDARY	12	1965 1-Storey Block	Medium	Supported 2013	
35	Langley	LANGLEY SECONDARY	13	1965 1-Storey Small Block	Medium	Supported 2013	
35	Langley	LOCHIEL U-CONNECT CENTRE	1	1974 1-Storey classroom	Medium	Non Structural Upgrade Required	
35	Langley	LOCHIEL U-CONNECT CENTRE	2	1974 Gymnasium	Medium	Non Structural Upgrade Required	Medium
35	Langley	MOUNTAIN SECONDARY	1	1975 2-Storey Classrooms	High 3	Structural Upgrade Required	
35	Langley	MOUNTAIN SECONDARY	2	1975 1-Storey Classrooms	High 3	Structural Upgrade Required	
35	Langley	MOUNTAIN SECONDARY	3	1975 Gymnasium	High 2	Structural Upgrade Required	High 2
35	Langley	MOUNTAIN SECONDARY	4	1985 shops add'n	Medium	Non Structural Upgrade Required	
35	Langley	MOUNTAIN SECONDARY	5	1989 2-storey classroom	Low	Meets Structural Life Safety Requirements	
35	Langley	MURRAYVILLE ELEMENTARY	1	Gymnasium	Medium	Inactive	
35	Langley	MURRAYVILLE ELEMENTARY	2	Classroom - East	Medium	Inactive	
35	Langley	MURRAYVILLE ELEMENTARY	3	Classroom / Admin	Low	Inactive	High 3
35	Langley	MURRAYVILLE ELEMENTARY	4	Classroom - West	High 3	Inactive	
35	Langley	NICOMEKL ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
35	Langley	NICOMEKL ELEMENTARY	2	Classroom and Admin (Central)	Low	Meets Structural Life Safety Requirements	Low
35	Langley	NICOMEKL ELEMENTARY	3	Classrooms (East)	Low	Meets Structural Life Safety Requirements	
35	Langley	NICOMEKL ELEMENTARY	4	Classroom / Multi purpose (2001)	Low	Meets Structural Life Safety Requirements	
35	Langley	NOEL BOOTH ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
35	Langley	NOEL BOOTH ELEMENTARY	2	Classrooms and Administration	Medium	Non Structural Upgrade Required	Medium
35	Langley	NOEL BOOTH ELEMENTARY	3	Classrooms	Low	Meets Structural Life Safety Requirements	
35	Langley	NORTH OTTER ELEMENTARY	1	1971/1973 Block 1	Low	Meets Structural Life Safety Requirements	
35	Langley	NORTH OTTER ELEMENTARY	2	1964 Block 2	Medium	Non Structural Upgrade Required	
35	Langley	NORTH OTTER ELEMENTARY	3	1990 Block 3	Low	Meets Structural Life Safety Requirements	
35	Langley	NORTH OTTER ELEMENTARY	4	1971 Block 4	Low	Meets Structural Life Safety Requirements	Medium
35	Langley	NORTH OTTER ELEMENTARY	5	1990 Block 5	Low	Meets Structural Life Safety Requirements	
35	Langley	NORTH OTTER ELEMENTARY	6	1973/1981 Block 6	Medium	Non Structural Upgrade Required	
35	Langley	NORTH OTTER ELEMENTARY	7	1990 Block 7	Low	Meets Structural Life Safety Requirements	
35	Langley	PARKSIDE CENTENNIAL ELEMENTARY	1	1971 2-storey classroom block	Low	Meets Structural Life Safety Requirements	
35	Langley	PARKSIDE CENTENNIAL ELEMENTARY	2	1974 1-storey classroom	Low	Meets Structural Life Safety Requirements	Low
35	Langley	PARKSIDE CENTENNIAL ELEMENTARY	3	1995 1-storey classroom	Low	Meets Structural Life Safety Requirements	
35	Langley	PETERSON ROAD ELEMENTARY	1	1971 Block 1	N/A	Completed	
35	Langley	PETERSON ROAD ELEMENTARY	2	1974 Block 2	N/A	Completed	
35	Langley	PETERSON ROAD ELEMENTARY	3	1962/1965 Block 3	N/A	Completed	N/A
35	Langley	PETERSON ROAD ELEMENTARY	4	1974 Block 4	N/A	Completed	
35	Langley	PETERSON ROAD ELEMENTARY	5	1974 Block 5	N/A	Completed	
35	Langley	SHORTREED COMMUNITY	1	1978 1-storey classroom	High 3	Structural Upgrade Required	
35	Langley	SHORTREED COMMUNITY	2	1978 Gymnasium	Medium	Non Structural Upgrade Required	
35	Langley	SHORTREED COMMUNITY	3	1981 1-storey classroom	Low	Meets Structural Life Safety Requirements	High 3
35	Langley	SHORTREED COMMUNITY	4	1999 1-storey classroom	Low	Meets Structural Life Safety Requirements	
35	Langley	SIMONDS ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
35	Langley	SIMONDS ELEMENTARY	2	Classrooms (Central)	Medium	Non Structural Upgrade Required	
35	Langley	SIMONDS ELEMENTARY	3	Classroom (West)	Low	Meets Structural Life Safety Requirements	High 3
35	Langley	SIMONDS ELEMENTARY	4	1959 1-Storey Office & Admin.	High 3	Structural Upgrade Required	
35	Langley	SOUTH CARVOLTH ELEMENTARY	1	Gymnasium	Medium	Inactive	
35	Langley	SOUTH CARVOLTH ELEMENTARY	2	Classrooms - West	Medium	Inactive	Medium

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
35	Langley	SOUTH CARVOLTH ELEMENTARY	3	Classrooms - East	Medium	Inactive	
35	Langley	UPLANDS ELEMENTARY	1	1974/1975 Block 1	Medium	Non Structural Upgrade Required	Medium
35	Langley	UPLANDS ELEMENTARY	2	1974/1977 Block 2	Medium	Non Structural Upgrade Required	
35	Langley	UPLANDS ELEMENTARY	3	1975 Block 3	Medium	Non Structural Upgrade Required	
35	Langley	WEST LANGLEY ELEMENTARY	1	1980 1-story classroom	Low	Meets Structural Life Safety Requirements	Medium
35	Langley	WEST LANGLEY ELEMENTARY	2	1980 gymnasium	Medium	Non Structural Upgrade Required	
35	Langley	WILLOUGHBY ELEMENTARY	1	1971 1-storey classroom	Medium	Non Structural Upgrade Required	Medium
35	Langley	WILLOUGHBY ELEMENTARY	2	1971 gymnasium	Low	Meets Structural Life Safety Requirements	
35	Langley	WILLOUGHBY ELEMENTARY	3	1982 1-storey classroom	Low	Meets Structural Life Safety Requirements	
35	Langley	WILLOUGHBY ELEMENTARY	4	1994 1-storey classroom	Low	Meets Structural Life Safety Requirements	
35	Langley	WILLOUGHBY ELEMENTARY	5	2000 1-storey classroom	Low	Meets Structural Life Safety Requirements	
35	Langley	WIX-BROWN ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
35	Langley	WIX-BROWN ELEMENTARY	2	Classrooms - North	Medium	Non Structural Upgrade Required	Medium
35	Langley	WIX-BROWN ELEMENTARY	3	Administration	Medium	Non Structural Upgrade Required	
35	Langley	WIX-BROWN ELEMENTARY	4	2-Storey Classrooms 2003	Low	Meets Structural Life Safety Requirements	
36	Surrey	A H P MATTHEW ELEMENTARY	1	1957 2-storey classroom	N/A	Completed	N/A
36	Surrey	A H P MATTHEW ELEMENTARY	2	1960 gymnasium	N/A	Completed	
36	Surrey	ANNIE DALE TRADITIONAL	1	1966 Gymnasium	Medium	Inactive	High 3
36	Surrey	ANNIE DALE TRADITIONAL	2	1954 Classroom Block	High 3	Inactive	
36	Surrey	ANNIE DALE TRADITIONAL	3	1890 Heritage and Portable	Medium	Inactive	
36	Surrey	BAYRIDGE ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36	Surrey	BAYRIDGE ELEMENTARY	2	1990 Classrooms	Low	Meets Structural Life Safety Requirements	
36	Surrey	BAYRIDGE ELEMENTARY	3	1999 Classrooms	Low	Meets Structural Life Safety Requirements	High 1
36	Surrey	BEAR CREEK ELEMENTARY	1	1964 1-Storey Classrooms	High 3	Structural Upgrade Required	
36	Surrey	BEAR CREEK ELEMENTARY	2	1964 Gymnasium	High 1	Structural Upgrade Required	
36	Surrey	BEAR CREEK ELEMENTARY	3	1972 1-Storey Classrooms	Medium	Non Structural Upgrade Required	
36	Surrey	BEAR CREEK ELEMENTARY	4	1991 1-Storey Classrooms	Low	Meets Structural Life Safety Requirements	
36	Surrey	BEAR CREEK ELEMENTARY	5	2000 1-Storey Classrooms	Low	Meets Structural Life Safety Requirements	
36	Surrey	BERKSHIRE PARK ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36	Surrey	BERKSHIRE PARK ELEMENTARY	2	1987 Classrooms	Low	Meets Structural Life Safety Requirements	
36	Surrey	BERKSHIRE PARK ELEMENTARY	3	1999 Classrooms	Low	Meets Structural Life Safety Requirements	Medium
36	Surrey	BETTY HUFF ELEMENTARY	1	1976 1-storey classroom	Medium	Non Structural Upgrade Required	
36	Surrey	BETTY HUFF ELEMENTARY	2	1976 Gymnasium	Medium	Non Structural Upgrade Required	
36	Surrey	BETTY HUFF ELEMENTARY	3	1980 1-storey classroom addition	Medium	Non Structural Upgrade Required	
36	Surrey	BETTY HUFF ELEMENTARY	4	2000 1-storey classroom	Low	Meets Structural Life Safety Requirements	Medium
36	Surrey	BONACCORD ELEMENTARY	1	Old Classrooms	Medium	Non Structural Upgrade Required	
36	Surrey	BONACCORD ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
36	Surrey	BONACCORD ELEMENTARY	3	2000 Classrooms	Low	Meets Structural Life Safety Requirements	
36	Surrey	BROOKSIDE ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36	Surrey	BROOKSIDE ELEMENTARY	2	1990 Classrooms	Low	Meets Structural Life Safety Requirements	
36	Surrey	BROOKSIDE ELEMENTARY	3	1993 and 1999 Classrooms	Low	Meets Structural Life Safety Requirements	
36	Surrey	CEDAR HILLS ELEMENTARY	1	1964 1-storey classroom	Medium	Non Structural Upgrade Required	Medium
36	Surrey	CEDAR HILLS ELEMENTARY	2	1964 gymnasium	Medium	Non Structural Upgrade Required	
36	Surrey	CEDAR HILLS ELEMENTARY	3	1999 1-storey classroom	Low	Meets Structural Life Safety Requirements	
36	Surrey	CLAYTON ELEMENTARY	1	1955 classroom block	N/A	Completed	N/A
36	Surrey	CLAYTON ELEMENTARY	2	1964 gymnasium	N/A	Completed	
36	Surrey	CLAYTON ELEMENTARY	3	1920 2-storey classroom block	N/A	Completed	
36	Surrey	CLOVERDALE TRADITIONAL	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
36	Surrey	CLOVERDALE TRADITIONAL	2	Gymnasium	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
36 Surrey		CLOVERDALE TRADITIONAL	3	Washrooms	Medium	Non Structural Upgrade Required	
36 Surrey		COLEBROOK ELEMENTARY	1	1940, 1965, 1967 Classroom Blocks	N/A	Completed	N/A
36 Surrey		COLEBROOK ELEMENTARY	2	1967, 1987 Gymnasium	N/A	Completed	
36 Surrey		COLEBROOK ELEMENTARY	3	1921, 1987, 2000 Classroom Blocks	N/A	Completed	
36 Surrey		CRESCENT PARK ANNEX (36031)	1	Classroom Block	Medium	Non Structural Upgrade Required	Medium
36 Surrey		CRESCENT PARK ELEMENTARY	1	1947 2-storey	Medium	Non Structural Upgrade Required	
36 Surrey		CRESCENT PARK ELEMENTARY	2	1963 gymnasium	Medium	Non Structural Upgrade Required	
36 Surrey		CRESCENT PARK ELEMENTARY	3	1967 1-storey classroom	Medium	Non Structural Upgrade Required	
36 Surrey		CRESCENT PARK ELEMENTARY	4	1980 1-storey classroom	Low	Meets Structural Life Safety Requirements	
36 Surrey		CRESCENT PARK ELEMENTARY	5	1974 2-storey classroom	Medium	Non Structural Upgrade Required	
36 Surrey		DAVID BRANKIN ELEMENTARY	1	3 Storey Classroom	High 3	Structural Upgrade Required	High 3
36 Surrey		DAVID BRANKIN ELEMENTARY	2	1 Storey Classrooms	Low	Meets Structural Life Safety Requirements	
36 Surrey		DAVID BRANKIN ELEMENTARY	3	Gymnasium Washrooms	Low	Meets Structural Life Safety Requirements	
36 Surrey		DAVID BRANKIN ELEMENTARY	4	Gymnasium	High 3	Structural Upgrade Required	
36 Surrey		DISCOVERY ELEMENTARY	1	1966 Classroom/Admin	N/A	Completed	N/A
36 Surrey		DISCOVERY ELEMENTARY	2	1966 Gymnasium	N/A	Completed	
36 Surrey		DISCOVERY ELEMENTARY	3	1970 Classrooms	N/A	Completed	
36 Surrey		DON CHRISTIAN ELEMENTARY	1	1981 1-storey classroom	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		DON CHRISTIAN ELEMENTARY	2	1981 Gymnasium	Low	Meets Structural Life Safety Requirements	
36 Surrey		DR F D SINCLAIR ELEMENTARY	1	1955 2-storey classroom	N/A	Completed	N/A
36 Surrey		DR F D SINCLAIR ELEMENTARY	2	1958 2-storey classroom	N/A	Completed	
36 Surrey		DR F D SINCLAIR ELEMENTARY	3	1958 gymnasium	N/A	Completed	
36 Surrey		DR F D SINCLAIR ELEMENTARY	4	2000 2-storey classroom	N/A	Completed	
36 Surrey		EARL MARRIOTT SECONDARY	1	3-storey classroom & gymnasium	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		EAST CLAYTON ELEMENTARY	1	1970 1-storey classroom	Medium	Inactive	Medium
36 Surrey		EAST CLAYTON ELEMENTARY	2	1971 gymnasium	Medium	Inactive	
36 Surrey		EAST KENSINGTON ELEMENTARY	1	2 Storey Classroom	N/A	Completed	N/A
36 Surrey		EAST KENSINGTON ELEMENTARY	2	1 Storey Classroom/Library	N/A	Completed	
36 Surrey		EAST KENSINGTON ELEMENTARY	3	Gymnasium/Administration	N/A	Completed	
36 Surrey		ELLENDALE ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
36 Surrey		ELLENDALE ELEMENTARY	2	1968 Classrooms	N/A	Completed	
36 Surrey		ELLENDALE ELEMENTARY	3	1993 Classrooms	N/A	Completed	
36 Surrey		ELLENDALE ELEMENTARY	4	Portable Unit	N/A	Completed	
36 Surrey		ERMA STEPHENSON ELEMENTARY	1	1963 1-storey classroom	Medium	Non Structural Upgrade Required	Medium
36 Surrey		ERMA STEPHENSON ELEMENTARY	2	1963 classroom & Gymnasium	Low	Meets Structural Life Safety Requirements	
36 Surrey		FLEETWOOD ELEMENTARY	1	East Classrooms	Medium	Inactive	Medium
36 Surrey		FLEETWOOD ELEMENTARY	2	Central Classrooms/Admin.	Medium	Inactive	
36 Surrey		FLEETWOOD ELEMENTARY	3	Gymnasium	Medium	Inactive	
36 Surrey		FLEETWOOD ELEMENTARY	4	2 Storey West Classrooms	Medium	Inactive	
36 Surrey		FRANK HURT SECONDARY	1	Gymnasium	N/A	Completed	N/A
36 Surrey		FRANK HURT SECONDARY	2	3-storey Classroom	N/A	Completed	
36 Surrey		FRANK HURT SECONDARY	3	Cafeteria and Shops	N/A	Completed	
36 Surrey		FRANK HURT SECONDARY	4	Leased Gymnasium	N/A	Completed	
36 Surrey		FRANK HURT SECONDARY	5	Art Building	N/A	Completed	
36 Surrey		FRASER WOOD ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		FRASER WOOD ELEMENTARY	2	1989 Classrooms	Low	Meets Structural Life Safety Requirements	
36 Surrey		FRASER WOOD ELEMENTARY	3	New Classrooms	Low	Meets Structural Life Safety Requirements	
36 Surrey		GEORGE GREENAWAY ELEMENTARY	1	Gymnasium	High 3	Structural Upgrade Required	High 3
36 Surrey		GEORGE GREENAWAY ELEMENTARY	2	1975 Classrooms	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
36	Surrey	GEORGE GREENAWAY ELEMENTARY	3	1992 Classrooms	Low	Meets Structural Life Safety Requirements	
36	Surrey	GEORGES VANIER ELEMENTARY	1	1967 Classroom/Admin	Medium	Non Structural Upgrade Required	
36	Surrey	GEORGES VANIER ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
36	Surrey	GEORGES VANIER ELEMENTARY	3	1989 Classrooms	Low	Meets Structural Life Safety Requirements	
36	Surrey	GEORGES VANIER ELEMENTARY	4	1999 Classrooms	Low	Meets Structural Life Safety Requirements	
36	Surrey	GRANDVIEW HEIGHTS ELEMENTARY	1	1922 Annex	Medium	Inactive	
36	Surrey	GRANDVIEW HEIGHTS ELEMENTARY	2	Gymnasium	Medium	Inactive	
36	Surrey	GRANDVIEW HEIGHTS ELEMENTARY	3	Classrooms	Medium	Inactive	Medium
36	Surrey	GREEN TIMBERS ELEMENTARY	1	1955 2-storey classroom	N/A	Completed	
36	Surrey	GREEN TIMBERS ELEMENTARY	2	1958 2-storey classroom	N/A	Completed	
36	Surrey	GREEN TIMBERS ELEMENTARY	3	1958 gymnasium	N/A	Completed	N/A
36	Surrey	GREEN TIMBERS ELEMENTARY	4	1980 2-storey classroom	N/A	Completed	
36	Surrey	GREEN TIMBERS ELEMENTARY	5	1990 2-storey classroom	N/A	Completed	
36	Surrey	GUILDFORD PARK SECONDARY	1	1&2-storey classroom & Gymnasium	N/A	Completed	N/A
36	Surrey	GUILDFORD PARK SECONDARY	2	1-storey Main Hall	N/A	Completed	
36	Surrey	H T THRIFT ELEMENTARY	1	East Wing Classroom (1958)	Medium	Non Structural Upgrade Required	
36	Surrey	H T THRIFT ELEMENTARY	2	West Wing Classroom (1967)	Medium	Non Structural Upgrade Required	Medium
36	Surrey	H T THRIFT ELEMENTARY	3	Gymnasium/Library	Low	Meets Structural Life Safety Requirements	
36	Surrey	HALLS PRAIRIE ELEMENTARY	1	1956 single-storey classroom	N/A	Completed	
36	Surrey	HALLS PRAIRIE ELEMENTARY	2	1964 gymnasium	N/A	Completed	
36	Surrey	HALLS PRAIRIE ELEMENTARY	3	1975 classroom block	N/A	Completed	N/A
36	Surrey	HALLS PRAIRIE ELEMENTARY	4	1930 2-storey classroom block	N/A	Completed	
36	Surrey	HAROLD BISHOP ELEMENTARY	1	1963 & 1991 Classroom & Gym	Low	Meets Structural Life Safety Requirements	
36	Surrey	HAROLD BISHOP ELEMENTARY	2	1999 1-storey classroom	Low	Meets Structural Life Safety Requirements	Low
36	Surrey	HENRY BOSE ELEMENTARY	1	1964 1-storey classroom	Medium	Non Structural Upgrade Required	
36	Surrey	HENRY BOSE ELEMENTARY	2	1964 gymnasium	Medium	Non Structural Upgrade Required	Medium
36	Surrey	HENRY BOSE ELEMENTARY	3	1979 single-storey classroom	Low	Meets Structural Life Safety Requirements	
36	Surrey	HJORTH ROAD ELEMENTARY	1	1954 2-storey Classroom block	Medium	Non Structural Upgrade Required	
36	Surrey	HJORTH ROAD ELEMENTARY	2	1964 gymnasium	Medium	Non Structural Upgrade Required	Medium
36	Surrey	HJORTH ROAD ELEMENTARY	3	1964 2-storey classroom block	Medium	Non Structural Upgrade Required	
36	Surrey	HJORTH ROAD ELEMENTARY	4	1909 2-storey classroom block	Medium	Non Structural Upgrade Required	
36	Surrey	HOLLY ELEMENTARY	1	1967 1-storey classroom	High 3	Structural Upgrade Required	
36	Surrey	HOLLY ELEMENTARY	2	1967 gymnasium	Medium	Non Structural Upgrade Required	High 3
36	Surrey	HOLLY ELEMENTARY	3	2000 1-storey classroom	Low	Meets Structural Life Safety Requirements	
36	Surrey	J T BROWN ELEMENTARY	1	1955 2-Storey Classrooms	N/A	Completed	
36	Surrey	J T BROWN ELEMENTARY	2	1958 Gymnasium	N/A	Completed	N/A
36	Surrey	J T BROWN ELEMENTARY	3	1958 Classrooms	N/A	Completed	
36	Surrey	JAMES ARDIEL ELEMENTARY	1	Classrooms - Old	Medium	Non Structural Upgrade Required	
36	Surrey	JAMES ARDIEL ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	
36	Surrey	JAMES ARDIEL ELEMENTARY	3	Library/Washrooms/Mechanical	Medium	Non Structural Upgrade Required	Medium
36	Surrey	JAMES ARDIEL ELEMENTARY	4	Classrooms - New	Low	Meets Structural Life Safety Requirements	
36	Surrey	JESSIE LEE ELEMENTARY	1	1973 single-storey classroom	Medium	Non Structural Upgrade Required	
36	Surrey	JESSIE LEE ELEMENTARY	2	1973 gymnasium	Medium	Non Structural Upgrade Required	Medium
36	Surrey	JESSIE LEE ELEMENTARY	3	1980 2-storey classroom	Medium	Non Structural Upgrade Required	
36	Surrey	JESSIE LEE ELEMENTARY	4	2000 2-storey classroom	Low	Meets Structural Life Safety Requirements	
36	Surrey	JOHNSTON HEIGHTS SECONDARY	1	2-storey classrooms & Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36	Surrey	K B WOODWARD ELEMENTARY	1	Gymnasium	N/A	Completed	
36	Surrey	K B WOODWARD ELEMENTARY	2	2 Storey Classroom	N/A	Completed	
36	Surrey	K B WOODWARD ELEMENTARY	3	1 Storey Classroom	N/A	Completed	N/A

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
36 Surrey		K B WOODWARD ELEMENTARY	4	Portable Units	N/A	Completed	
36 Surrey		KENNEDY TRAIL ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
36 Surrey		KENNEDY TRAIL ELEMENTARY	2	1987 Classrooms	N/A	Completed	
36 Surrey		KENNEDY TRAIL ELEMENTARY	3	1992 Classrooms	N/A	Completed	
36 Surrey		KENSINGTON PRAIRIE ELEMENTARY	1	2 Storey Classroom	Medium	Inactive	Medium
36 Surrey		KENSINGTON PRAIRIE ELEMENTARY	2	Gymnasium	Medium	Inactive	
36 Surrey		KENSINGTON PRAIRIE ELEMENTARY	3	1 Storey Classrooms	Medium	Inactive	
36 Surrey		KENSINGTON PRAIRIE ELEMENTARY	4	Portable Units	Low	Inactive	
36 Surrey		L A MATHESON SECONDARY	1	Block1	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		LARONDE ELEMENTARY	1	1-storey classroom & gymnasium	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		LENA SHAW ELEMENTARY	1	single storey classroom & gymnasium	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		LORD TWEEDSMUIR SECONDARY	1	Classroom Block & Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		M B SANFORD ELEMENTARY	1	1985 Classroom & Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		M B SANFORD ELEMENTARY	2	2001 Classroom	Low	Meets Structural Life Safety Requirements	
36 Surrey		MAPLE GREEN ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		MAPLE GREEN ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	
36 Surrey		MARTHA CURRIE ELEMENTARY	1	1962 1-storey classroom	Medium	Non Structural Upgrade Required	Medium
36 Surrey		MARTHA CURRIE ELEMENTARY	2	1962 gymnasium	Medium	Non Structural Upgrade Required	
36 Surrey		MARTHA JANE NORRIS ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		MARTHA JANE NORRIS ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	
36 Surrey		MARY JANE SHANNON ELEMENTARY	1	1958 Gymnasium	High 1	Structural Upgrade Required	High 1
36 Surrey		MARY JANE SHANNON ELEMENTARY	2	1958 2-Storey Classrooms	High 2	Structural Upgrade Required	
36 Surrey		MARY JANE SHANNON ELEMENTARY	3	1965 Lunch Room	Medium	Non Structural Upgrade Required	
36 Surrey		MARY JANE SHANNON ELEMENTARY	4	Change Room	Low	Meets Structural Life Safety Requirements	
36 Surrey		MARY JANE SHANNON ELEMENTARY	5	1958 1-Storey Classroom/Covered Walkway	Medium	Non Structural Upgrade Required	
36 Surrey		MCLEOD ROAD ELEMENTARY	1	1962 1-storey classroom	N/A	Completed	N/A
36 Surrey		MCLEOD ROAD ELEMENTARY	2	1962 gymnasium	N/A	Completed	
36 Surrey		MCLEOD ROAD ELEMENTARY	3	1967 1-storey classroom	N/A	Completed	
36 Surrey		MCLEOD ROAD ELEMENTARY	4	1980 1-storey classroom	N/A	Completed	
36 Surrey		MOUNTAINVIEW MONTESSORI	1	1965 Gymnasium	N/A	Completed	N/A
36 Surrey		MOUNTAINVIEW MONTESSORI	2	Modular Buildings	N/A	Completed	
36 Surrey		NEWTON ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
36 Surrey		NEWTON ELEMENTARY	2	Old Classrooms	Medium	Non Structural Upgrade Required	
36 Surrey		NEWTON ELEMENTARY	3	New Classrooms	Low	Meets Structural Life Safety Requirements	
36 Surrey		NEWTON ELEMENTARY	4	1999 1-storey classroom	Low	Meets Structural Life Safety Requirements	
36 Surrey		NORTH RIDGE ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		NORTH RIDGE ELEMENTARY	2	1990 Classrooms	Low	Meets Structural Life Safety Requirements	
36 Surrey		NORTH RIDGE ELEMENTARY	3	1999 Classrooms	Low	Meets Structural Life Safety Requirements	
36 Surrey		OCEAN CLIFF ELEMENTARY	1	Classrooms/Admin.	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		OCEAN CLIFF ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
36 Surrey		OLD YALE ROAD ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
36 Surrey		OLD YALE ROAD ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
36 Surrey		OLD YALE ROAD ELEMENTARY	3	Portable Unit	Low	Meets Structural Life Safety Requirements	
36 Surrey		PANORAMA PARK ELEMENTARY	1	1987 Classroom & Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36 Surrey		PANORAMA PARK ELEMENTARY	2	2000 Classroom	Low	Meets Structural Life Safety Requirements	
36 Surrey		PEACE ARCH ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
36 Surrey		PEACE ARCH ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
36 Surrey		PEACE ARCH ELEMENTARY	3	1993 Library Addition	Low	Meets Structural Life Safety Requirements	
36 Surrey		PORT KELLS ELEMENTARY	1	2 Storey Classrooms	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
36	Surrey	PORT KELLS ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	Medium
36	Surrey	PORT KELLS ELEMENTARY	3	1 Storey Classrooms	Medium	Non Structural Upgrade Required	
36	Surrey	PRINCE CHARLES ELEMENTARY	1	1957 Gymnasium	Medium	Non Structural Upgrade Required	
36	Surrey	PRINCE CHARLES ELEMENTARY	2	1954 2-Storey Classrooms	High 3	Structural Upgrade Required	High 3
36	Surrey	PRINCE CHARLES ELEMENTARY	3	1957 2-Storey Classrooms	Medium	Non Structural Upgrade Required	
36	Surrey	QUEEN ELIZABETH SECONDARY	1	1967 Shops	High 3	Structural Upgrade Required	
36	Surrey	QUEEN ELIZABETH SECONDARY	2	1967 3-Storey Classrooms	High 3	Structural Upgrade Required	High 3
36	Surrey	QUEEN ELIZABETH SECONDARY	3	1997 Classrooms and Gymnasium	Low	Meets Structural Life Safety Requirements	
36	Surrey	RAY SHEPHERD ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
36	Surrey	RAY SHEPHERD ELEMENTARY	2	2 Storey Classroom	Medium	Non Structural Upgrade Required	
36	Surrey	RAY SHEPHERD ELEMENTARY	3	1 Storey Classroom	Medium	Non Structural Upgrade Required	Medium
36	Surrey	RAY SHEPHERD ELEMENTARY	4	Covered Play Area	Medium	Non Structural Upgrade Required	
36	Surrey	RAY SHEPHERD ELEMENTARY	5	1 Storey Classroom (2001)	Low	Meets Structural Life Safety Requirements	
36	Surrey	RIVERDALE ELEMENTARY	1	Gymnasium / Stage	Medium	Non Structural Upgrade Required	
36	Surrey	RIVERDALE ELEMENTARY	2	Classroom / Administration Areas	Medium	Non Structural Upgrade Required	Medium
36	Surrey	RIVERDALE ELEMENTARY	3	Classroom / Covered Play Areas	Medium	Non Structural Upgrade Required	
36	Surrey	RIVERDALE ELEMENTARY	4	Classroom Areas	Medium	Non Structural Upgrade Required	
36	Surrey	ROYAL HEIGHTS ELEMENTARY	1	Classroom & Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36	Surrey	SEMAIHMOO SECONDARY	1	1989 Classroom & Gymnasium	Low	Meets Structural Life Safety Requirements	
36	Surrey	SEMAIHMOO SECONDARY	2	1966 2-storey classroom	Medium	Non Structural Upgrade Required	Medium
36	Surrey	SEMAIHMOO SECONDARY	3	1978 2-storey classroom	Low	Meets Structural Life Safety Requirements	
36	Surrey	SENATOR REID ELEMENTARY	1	Gymnasium	N/A	Completed	
36	Surrey	SENATOR REID ELEMENTARY	2	Classrooms (1961, 1966)	N/A	Completed	N/A
36	Surrey	SENATOR REID ELEMENTARY	3	1999 Classrooms	N/A	Completed	
36	Surrey	SERPENTINE HEIGHTS ELEMENTARY	1	Classroom & Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36	Surrey	SOUTH MERIDIAN ELEMENTARY	1	Classrooms/Admin.	Low	Meets Structural Life Safety Requirements	Low
36	Surrey	SOUTH MERIDIAN ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
36	Surrey	STRAWBERRY HILL ELEMENTARY	1	Classroom & Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36	Surrey	STUDENT SUPPORT CENTRE	1	1949 2-storey classroom	Medium	Non Structural Upgrade Required	
36	Surrey	STUDENT SUPPORT CENTRE	2	1962 gymnasium	Medium	Non Structural Upgrade Required	Medium
36	Surrey	STUDENT SUPPORT CENTRE	3	1944 2-storey classroom	Medium	Non Structural Upgrade Required	
36	Surrey	SULLIVAN ELEMENTARY	1	1949 2-storey classroom	N/A	Completed	
36	Surrey	SULLIVAN ELEMENTARY	2	1965 gymnasium	N/A	Completed	N/A
36	Surrey	SULLIVAN ELEMENTARY	3	1982 2-storey classroom	N/A	Completed	
36	Surrey	SULLIVAN ELEMENTARY	4	2000 1-storey modular	N/A	Completed	
36	Surrey	SUNNYSIDE ELEMENTARY	1	1 Storey Classrooms	N/A	Completed	
36	Surrey	SUNNYSIDE ELEMENTARY	2	Gymnasium	N/A	Completed	N/A
36	Surrey	SUNNYSIDE ELEMENTARY	3	2 Storey Classrooms	N/A	Completed	
36	Surrey	SURREY TRADITIONAL	1	Gymnasium / Stage	N/A	Completed	
36	Surrey	SURREY TRADITIONAL	2	Classroom / Administration Areas	N/A	Completed	N/A
36	Surrey	SURREY TRADITIONAL	3	Classroom Areas	N/A	Completed	
36	Surrey	SURREY TRADITIONAL	4	Classroom Areas	N/A	Completed	
36	Surrey	T E SCOTT ELEMENTARY	1	1957 2-storey classroom	N/A	Completed	N/A
36	Surrey	T E SCOTT ELEMENTARY	2	1965 gymnasium	N/A	Completed	
36	Surrey	W E KINVIG ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
36	Surrey	W E KINVIG ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	
36	Surrey	WILLIAM WATSON ELEMENTARY	1	1958 single-storey classroom	Low	Meets Structural Life Safety Requirements	
36	Surrey	WILLIAM WATSON ELEMENTARY	2	1973 Multi-purpose	Low	Meets Structural Life Safety Requirements	Low
36	Surrey	WILLIAM WATSON ELEMENTARY	3	1989 classroom & gymnasium	Low	Meets Structural Life Safety Requirements	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
36	Surrey	WILLIAM WATSON ELEMENTARY	4	1999 classroom	Low	Meets Structural Life Safety Requirements	
36	Surrey	WOODLAND PARK ELEMENTARY	1	Classroom & Gymnasium	Low	Meets Structural Life Safety Requirements	Low
37	Delta	ANNIEVILLE ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
37	Delta	ANNIEVILLE ELEMENTARY	2	Classroom	Low	Meets Structural Life Safety Requirements	
37	Delta	BEACH GROVE ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
37	Delta	BEACH GROVE ELEMENTARY	2	Classroom/Administration	Medium	Non Structural Upgrade Required	Medium
37	Delta	BEACH GROVE ELEMENTARY	3	Classroom 2000	Low	Meets Structural Life Safety Requirements	
37	Delta	BROOKE ELEMENTARY	1	Classroom Block	Medium	Non Structural Upgrade Required	Medium
37	Delta	BROOKE ELEMENTARY	2	Gymnasium/Admin.	Medium	Non Structural Upgrade Required	
37	Delta	BURNSVIEW JR SECONDARY	1	Classroom Block	N/A	Completed	
37	Delta	BURNSVIEW JR SECONDARY	2	Central (Science)	N/A	Completed	N/A
37	Delta	BURNSVIEW JR SECONDARY	3	Shop Wing	N/A	Completed	
37	Delta	BURNSVIEW JR SECONDARY	4	Gymnasium and Cafeteria	N/A	Completed	
37	Delta	CHALMERS ELEMENTARY	1	Gymnasium, Change Room, Admin.	Low	Meets Structural Life Safety Requirements	
37	Delta	CHALMERS ELEMENTARY	2	Classroom, Library (Centre)	Medium	Non Structural Upgrade Required	Medium
37	Delta	CHALMERS ELEMENTARY	3	Classrooms (South-West)	Medium	Non Structural Upgrade Required	
37	Delta	CHALMERS ELEMENTARY	4	Classrooms (North)	Low	Meets Structural Life Safety Requirements	
37	Delta	CLIFF DRIVE ELEMENTARY	1	Classrooms	Low	Meets Structural Life Safety Requirements	Low
37	Delta	CLIFF DRIVE ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
37	Delta	COUGAR CANYON ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
37	Delta	COUGAR CANYON ELEMENTARY	2	Classrooms (East)	Low	Meets Structural Life Safety Requirements	Low
37	Delta	COUGAR CANYON ELEMENTARY	3	Classrooms (West)	Low	Meets Structural Life Safety Requirements	
37	Delta	DELTA MANOR ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
37	Delta	DELTA MANOR ELEMENTARY	2	2-Storey Classroom	Low	Meets Structural Life Safety Requirements	Low
37	Delta	DELTA MANOR ELEMENTARY	3	1-Storey Classroom/Administration	Low	Meets Structural Life Safety Requirements	
37	Delta	DELTA SECONDARY	1	1974 Gymnasium	N/A	Under Construction	
37	Delta	DELTA SECONDARY	2	1988 Theatre	N/A	Under Construction	
37	Delta	DELTA SECONDARY	3	1992 2-Storey Admin.	N/A	Under Construction	
37	Delta	DELTA SECONDARY	4	1983 Art Wing/Music Room	N/A	Under Construction	
37	Delta	DELTA SECONDARY	5	1965 Mechanical and Wood Shops	N/A	Under Construction	
37	Delta	DELTA SECONDARY	6	1960 2-Storey Library	N/A	Under Construction	
37	Delta	DELTA SECONDARY	7	Shops (1997 Upgrade)	N/A	Under Construction	N/A
37	Delta	DELTA SECONDARY	8	New Gymnasium (2001)	N/A	Under Construction	
37	Delta	DELTA SECONDARY	9	Classroom (1993, 2000)	N/A	Under Construction	
37	Delta	DELTA SECONDARY	10	Science Wing (1992, 1994)	N/A	Under Construction	
37	Delta	DELTA SECONDARY	11	1994 Carrier Centre	N/A	Under Construction	
37	Delta	DELTA SECONDARY	12	1983 2-Storey Learning Assistance	N/A	Under Construction	
37	Delta	DELTA SECONDARY	13	1983 Music Room	N/A	Under Construction	
37	Delta	DELVIEW JR SECONDARY	1	Gymnasium	N/A	Completed	
37	Delta	DELVIEW JR SECONDARY	2	Science Rooms	N/A	Completed	
37	Delta	DELVIEW JR SECONDARY	3	Library	N/A	Completed	N/A
37	Delta	DELVIEW JR SECONDARY	4	Aux. Gym and Cafeteria	N/A	Completed	
37	Delta	DELVIEW JR SECONDARY	5	Classrooms	N/A	Completed	
37	Delta	DEVON GARDENS ELEMENTARY	1	Classroom Block	N/A	Completed	N/A
37	Delta	DEVON GARDENS ELEMENTARY	2	Gymnasium	N/A	Completed	
37	Delta	ENGLISH BLUFF ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
37	Delta	ENGLISH BLUFF ELEMENTARY	2	2-Storey Classroom	Medium	Non Structural Upgrade Required	Medium
37	Delta	ENGLISH BLUFF ELEMENTARY	3	Single Storey Classroom/Administration	Medium	Non Structural Upgrade Required	
37	Delta	GIBSON ELEMENTARY	1	1969 1-Storey Classroom Block	High 3	Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
37 Delta		GIBSON ELEMENTARY	2	1969 Gymnasium	High 3	Structural Upgrade Required	High 3
37 Delta		GIBSON ELEMENTARY	3	2000 Classroom Block Addition	Low	Meets Structural Life Safety Requirements	
37 Delta		GRAY ELEMENTARY	1	Classroom, Library (North)	Medium	Non Structural Upgrade Required	Medium
37 Delta		GRAY ELEMENTARY	2	Gymnasium, Administration	Medium	Non Structural Upgrade Required	
37 Delta		GRAY ELEMENTARY	3	Classrooms (South-West)	Medium	Non Structural Upgrade Required	
37 Delta		HAWTHORNE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
37 Delta		HAWTHORNE ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
37 Delta		HAWTHORNE ELEMENTARY	3	Classrooms - Portable	Low	Meets Structural Life Safety Requirements	
37 Delta		HEATH ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
37 Delta		HEATH ELEMENTARY	2	Single Storey Classroom	Medium	Non Structural Upgrade Required	
37 Delta		HEATH ELEMENTARY	3	2-Storey Classroom	Medium	Non Structural Upgrade Required	
37 Delta		HELLINGS ELEMENTARY	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
37 Delta		HELLINGS ELEMENTARY	2	Gymnasium/Change Room Addition	Medium	Non Structural Upgrade Required	
37 Delta		HELLINGS ELEMENTARY	3	Multi-Purpose, Office Addition - 1999	Low	Meets Structural Life Safety Requirements	
37 Delta		HOLLY ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
37 Delta		HOLLY ELEMENTARY	2	Classrooms (East)	Medium	Non Structural Upgrade Required	
37 Delta		HOLLY ELEMENTARY	3	Classrooms/Multipurpose room	Low	Meets Structural Life Safety Requirements	
37 Delta		HOLLY ELEMENTARY	4	1999 Classroom (West)	Low	Meets Structural Life Safety Requirements	
37 Delta		JARVIS ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
37 Delta		JARVIS ELEMENTARY	2	Classroom, Multi Purpose	Medium	Non Structural Upgrade Required	
37 Delta		JARVIS ELEMENTARY	3	Classroom, Library	Medium	Non Structural Upgrade Required	
37 Delta		JARVIS ELEMENTARY	4	Classrooms - North	Medium	Non Structural Upgrade Required	
37 Delta		LADNER ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
37 Delta		LADNER ELEMENTARY	2	2-Storey Classroom	Low	Meets Structural Life Safety Requirements	
37 Delta		LADNER ELEMENTARY	3	1-Storey Classroom	Medium	Non Structural Upgrade Required	
37 Delta		MCCLOSKEY ELEMENTARY	1	Classroom/Administration	Medium	Non Structural Upgrade Required	Medium
37 Delta		MCCLOSKEY ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
37 Delta		MCCLOSKEY ELEMENTARY	3	Classroom - 2000	Low	Meets Structural Life Safety Requirements	
37 Delta		NORTH DELTA SENIOR SECONDARY	1	Shops	Medium	Non Structural Upgrade Required	Medium
37 Delta		NORTH DELTA SENIOR SECONDARY	2	Classrooms	Medium	Non Structural Upgrade Required	
37 Delta		NORTH DELTA SENIOR SECONDARY	3	Drama/Cafeteria	Medium	Non Structural Upgrade Required	
37 Delta		NORTH DELTA SENIOR SECONDARY	4	Music room	Medium	Non Structural Upgrade Required	
37 Delta		NORTH DELTA SENIOR SECONDARY	5	Library	Medium	Non Structural Upgrade Required	
37 Delta		NORTH DELTA SENIOR SECONDARY	6	Automotive Shop	Medium	Non Structural Upgrade Required	
37 Delta		NORTH DELTA SENIOR SECONDARY	7	Gymnasium/Classrooms/Canopy - 2001	Low	Meets Structural Life Safety Requirements	
37 Delta		PEBBLE HILL ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
37 Delta		PEBBLE HILL ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
37 Delta		PINEWOOD ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
37 Delta		PINEWOOD ELEMENTARY	2	Classrooms	N/A	Completed	
37 Delta		PINEWOOD ELEMENTARY	3	Library/Multipurpose	N/A	Completed	
37 Delta		PINEWOOD ELEMENTARY	4	Classrooms (2000)	N/A	Completed	
37 Delta		PORT GUICHON ELEMENTARY	1	Classrooms	N/A	Completed	N/A
37 Delta		PORT GUICHON ELEMENTARY	2	Gymnasium	N/A	Completed	
37 Delta		RICHARDSON ELEMENTARY	1	Classrooms	Low	Meets Structural Life Safety Requirements	Low
37 Delta		RICHARDSON ELEMENTARY	2	Gym/Classrooms/Admin. Area - 1998	Low	Meets Structural Life Safety Requirements	
37 Delta		SANDS JR SECONDARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
37 Delta		SANDS JR SECONDARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	
37 Delta		SANDS JR SECONDARY	3	Shops	Low	Meets Structural Life Safety Requirements	
37 Delta		SEAQUAM SECONDARY	1	Gymnasium	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
37 Delta		SEAQUAM SECONDARY	2	Small Gymnasium	Medium	Non Structural Upgrade Required	Medium
37 Delta		SEAQUAM SECONDARY	3	North Wing	Medium	Non Structural Upgrade Required	
37 Delta		SEAQUAM SECONDARY	4	Theatre/Music	Medium	Non Structural Upgrade Required	
37 Delta		SEAQUAM SECONDARY	5	Classrooms (Central Wing)	Medium	Non Structural Upgrade Required	
37 Delta		SEAQUAM SECONDARY	6	Shops	Medium	Non Structural Upgrade Required	
37 Delta		SOUTH DELTA SECONDARY	1	Gymnasium	N/A	Completed	N/A
37 Delta		SOUTH DELTA SECONDARY	2	Auditorium	N/A	Completed	
37 Delta		SOUTH DELTA SECONDARY	3	Cafeteria	N/A	Completed	
37 Delta		SOUTH DELTA SECONDARY	4	1973 2-Storey Classrooms	N/A	Completed	
37 Delta		SOUTH DELTA SECONDARY	5	1973 1-Storey Classrooms	N/A	Completed	
37 Delta		SOUTH DELTA SECONDARY	6	1973 Shops	N/A	Completed	
37 Delta		SOUTH DELTA SECONDARY	7	Classrooms/Small Gymnasium (2003)	N/A	Completed	Medium
37 Delta		SOUTH PARK ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
37 Delta		SOUTH PARK ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	
37 Delta		SUNSHINE HILLS ELEMENTARY	1	2 storey classrooms (West)	N/A	Completed	N/A
37 Delta		SUNSHINE HILLS ELEMENTARY	2	Classrooms (East)	N/A	Completed	
37 Delta		SUNSHINE HILLS ELEMENTARY	3	Gymnasium	N/A	Completed	
37 Delta		SUNSHINE HILLS ELEMENTARY	4	Classrooms (South)	N/A	Completed	
37 Delta		SUNSHINE HILLS ELEMENTARY	5	Covered play area	N/A	Completed	
38 Richmond		ALFRED B DIXON ELEMENTARY	1	West Wing	Medium	Non Structural Upgrade Required	High 2
38 Richmond		ALFRED B DIXON ELEMENTARY	2	South Wing	Medium	Non Structural Upgrade Required	
38 Richmond		ALFRED B DIXON ELEMENTARY	3	1958 1-Storey North Wing	High 2	Structural Upgrade Required	
38 Richmond		ALFRED B DIXON ELEMENTARY	4	Covered Play Area	Medium	Non Structural Upgrade Required	
38 Richmond		ALFRED B DIXON ELEMENTARY	5	Activity Room	Low	Meets Structural Life Safety Requirements	High 1
38 Richmond		BLUNDELL ELEMENTARY	1	1954 1-Storey North Classroom Wing	High 1	Structural Upgrade Required	
38 Richmond		BLUNDELL ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
38 Richmond		BLUNDELL ELEMENTARY	3	1957 1-Storey South & East Classroom Wings	High 1	Structural Upgrade Required	Low
38 Richmond		CHARLES E LONDON SECONDARY	1	Classrooms, Gymnasium and Administration	Low	Meets Structural Life Safety Requirements	
38 Richmond		CHARLES E LONDON SECONDARY	2	Multipurpose and Classrooms	Low	Meets Structural Life Safety Requirements	High 1
38 Richmond		CHARLES E LONDON SECONDARY	3	Gymnasium	Low	Meets Structural Life Safety Requirements	
38 Richmond		DANIEL WOODWARD ELEMENTARY	1	1960 1-Storey Original Classrooms	High 2	Structural Upgrade Required	
38 Richmond		DANIEL WOODWARD ELEMENTARY	2	1966 2-Storey Classroom Additions	High 1	Structural Upgrade Required	High 2
38 Richmond		DANIEL WOODWARD ELEMENTARY	3	1966 Gymnasium	Medium	Non Structural Upgrade Required	
38 Richmond		DONALD E MCKAY ELEMENTARY	1	1961/65/75 1-Storey West Classroom Wing	High 2	Structural Upgrade Required	High 2
38 Richmond		DONALD E MCKAY ELEMENTARY	2	1971 1-Storey East Classroom Wing	High 3	Structural Upgrade Required	
38 Richmond		DONALD E MCKAY ELEMENTARY	3	1971 Gymnasium	Low	Meets Structural Life Safety Requirements	
38 Richmond		DONALD E MCKAY ELEMENTARY	4	2001 North Addition	Low	Meets Structural Life Safety Requirements	High 2
38 Richmond		ecole des Navigateurs (ALEXANDER KILG	1	1963 1-Storey North Classrooms	High 2	Structural Upgrade Required	
38 Richmond		ecole des Navigateurs (ALEXANDER KILG	2	1975 Classroom Wing Addition	Low	Meets Structural Life Safety Requirements	
38 Richmond		ecole des Navigateurs (ALEXANDER KILG	3	Storage, Changing Rooms and Kitchen Addition	Low	Meets Structural Life Safety Requirements	
38 Richmond		ecole des Navigateurs (ALEXANDER KILG	4	Gymnasium	Medium	Non Structural Upgrade Required	N/A
38 Richmond		GARDEN CITY ELEMENTARY	1	original classroom block	N/A	Completed	
38 Richmond		GARDEN CITY ELEMENTARY	2	gymnasium	N/A	Completed	
38 Richmond		GARDEN CITY ELEMENTARY	3	Classroom additions	N/A	Completed	Low
38 Richmond		HOWARD DE BECK ELEMENTARY	1	1990 original school	Low	Meets Structural Life Safety Requirements	
38 Richmond		HOWARD DE BECK ELEMENTARY	2	1990 gymnasium	Low	Meets Structural Life Safety Requirements	High 1
38 Richmond		HOWARD DE BECK ELEMENTARY	3	1999 addition	Low	Meets Structural Life Safety Requirements	
38 Richmond		HUGH BOYD SECONDARY	1	1994 2-Storey Admin., Classrooms & Gymnasium	Low	Meets Structural Life Safety Requirements	
38 Richmond		HUGH BOYD SECONDARY	2	1960 2-Storey Classroom Block	Low	Meets Structural Life Safety Requirements	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
38	Richmond	HUGH BOYD SECONDARY	3	1960 Gymnasium	Low	Meets Structural Life Safety Requirements	High 1
38	Richmond	HUGH BOYD SECONDARY	4	1960 Workshops	High 1	Structural Upgrade Required	
38	Richmond	HUGH MCROBERTS SECONDARY	1	SMALL GYMNASIUM	Low	Meets Structural Life Safety Requirements	
38	Richmond	HUGH MCROBERTS SECONDARY	2	MUSIC ROOM	Low	Meets Structural Life Safety Requirements	
38	Richmond	HUGH MCROBERTS SECONDARY	3	GYMNASIUM	Low	Meets Structural Life Safety Requirements	
38	Richmond	HUGH MCROBERTS SECONDARY	4	CENTRAL TEACHING	Low	Meets Structural Life Safety Requirements	Low
38	Richmond	HUGH MCROBERTS SECONDARY	5	SW CLASSROOMS	Low	Meets Structural Life Safety Requirements	
38	Richmond	HUGH MCROBERTS SECONDARY	6	SOUTH SHOPS	Low	Meets Structural Life Safety Requirements	
38	Richmond	HUGH MCROBERTS SECONDARY	7	EAST CLASSROOMS	Low	Meets Structural Life Safety Requirements	
38	Richmond	JAMES GILMORE ELEMENTARY	1	1959 North Wing, 1-Storey	High 1	Supported 2013	
38	Richmond	JAMES GILMORE ELEMENTARY	2	1963 Classroom East Wing, 2-Storey	High 1	Supported 2013	High 1
38	Richmond	JAMES GILMORE ELEMENTARY	3	Activity Room, Changing Rooms and Storages	Medium	Supported 2013	
38	Richmond	JAMES GILMORE ELEMENTARY	4	1962 South Wing, 1-Storey	High 1	Supported 2013	
38	Richmond	JAMES MCKINNEY ELEMENTARY	1	West block	Low	Meets Structural Life Safety Requirements	
38	Richmond	JAMES MCKINNEY ELEMENTARY	2	1974 1-Storey Central Block	High 3	Structural Upgrade Required	High 3
38	Richmond	JAMES MCKINNEY ELEMENTARY	3	East block	Low	Meets Structural Life Safety Requirements	
38	Richmond	JAMES THOMPSON ELEMENTARY	1	1955 1-Storey North East Classroom Wing	High 1	Structural Upgrade Required	
38	Richmond	JAMES THOMPSON ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
38	Richmond	JAMES THOMPSON ELEMENTARY	3	1973 1-Storey SouthWest Classroom Wing	High 2	Structural Upgrade Required	
38	Richmond	JAMES THOMPSON ELEMENTARY	4	North West Classroom Wing	Low	Meets Structural Life Safety Requirements	
38	Richmond	JAMES THOMPSON ELEMENTARY	5	Administration Wing	Low	Meets Structural Life Safety Requirements	High 1
38	Richmond	JAMES THOMPSON ELEMENTARY	6	1962 1-Storey Central Block	High 2	Structural Upgrade Required	
38	Richmond	JAMES THOMPSON ELEMENTARY	7	1966 1-Storey East Central Classroom Wing	High 2	Structural Upgrade Required	
38	Richmond	JAMES THOMPSON ELEMENTARY	8	South East Classroom Wing	Medium	Non Structural Upgrade Required	
38	Richmond	JAMES THOMPSON ELEMENTARY	9	Covered Play Area	Medium	Non Structural Upgrade Required	
38	Richmond	JAMES WHITESIDE ELEMENTARY	1	1958 1-Storey Original Classrooms	High 1	Structural Upgrade Required	
38	Richmond	JAMES WHITESIDE ELEMENTARY	2	1960 Gym Addition	Medium	Non Structural Upgrade Required	High 1
38	Richmond	JAMES WHITESIDE ELEMENTARY	3	1969 1-Storey Classroom Addition	High 3	Structural Upgrade Required	
38	Richmond	JOHN G DIEFENBAKER ELEMENTARY	1	1980 1-Storey South East Classroom Wing	High 3	Structural Upgrade Required	
38	Richmond	JOHN G DIEFENBAKER ELEMENTARY	2	Relocatable Classroom Blocks	Low	Meets Structural Life Safety Requirements	High 3
38	Richmond	JOHN G DIEFENBAKER ELEMENTARY	3	West Classroom Wing	Low	Meets Structural Life Safety Requirements	
38	Richmond	JOHN T ERRINGTON ELEMENTARY	1	1957 1-Storey Main Building	High 2	Structural Upgrade Required	
38	Richmond	JOHN T ERRINGTON ELEMENTARY	2	1960 Gymnasium Addition	High 3	Structural Upgrade Required	High 2
38	Richmond	JOHN T ERRINGTON ELEMENTARY	3	1975 Gymnasium Addition	Medium	Non Structural Upgrade Required	
38	Richmond	KINGSWOOD ELEMENTARY	1	original classroom block	Medium	Non Structural Upgrade Required	
38	Richmond	KINGSWOOD ELEMENTARY	2	gymnasium	Low	Meets Structural Life Safety Requirements	Medium
38	Richmond	KINGSWOOD ELEMENTARY	3	classroom additions	Low	Meets Structural Life Safety Requirements	
38	Richmond	MANOAH STEVES ELEMENTARY	1	1963 1-Storey Administration Wing	High 1	Structural Upgrade Required	
38	Richmond	MANOAH STEVES ELEMENTARY	2	1971 1-Storey South & West Classrooms	High 2	Structural Upgrade Required	High 1
38	Richmond	MANOAH STEVES ELEMENTARY	3	1965 1-Storey North Classroom Wing	High 1	Structural Upgrade Required	
38	Richmond	MANOAH STEVES ELEMENTARY	4	Gymnasium	Low	Meets Structural Life Safety Requirements	
38	Richmond	MAPLE LANE ELEMENTARY	1	1-Storey Classroom & Administration	High 1	Structural Upgrade Required	
38	Richmond	MAPLE LANE ELEMENTARY	2	North Classroom Addition	Low	Meets Structural Life Safety Requirements	High 1
38	Richmond	MAPLE LANE ELEMENTARY	3	Gymnasium	Medium	Non Structural Upgrade Required	
38	Richmond	MATTHEW MCNAIR SECONDARY	1	Original Classrooms	Medium	Non Structural Upgrade Required	
38	Richmond	MATTHEW MCNAIR SECONDARY	2	Original Gymnasium	Medium	Non Structural Upgrade Required	Medium
38	Richmond	MATTHEW MCNAIR SECONDARY	3	Classroom Addition	Medium	Non Structural Upgrade Required	
38	Richmond	MATTHEW MCNAIR SECONDARY	4	1993 & 1995 Additions	Low	Meets Structural Life Safety Requirements	
38	Richmond	MITCHELL ELEMENTARY	1	1928 2-Storey Original School	NA	Demolished	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
38	Richmond	MITCHELL ELEMENTARY	2	1960 1-Storey Annex	High 2	Structural Upgrade Required	High 2
38	Richmond	MITCHELL ELEMENTARY	3	1975 Gym Addition	Medium	Non Structural Upgrade Required	
38	Richmond	MITCHELL ELEMENTARY	4	1991 Addition	Low	Meets Structural Life Safety Requirements	
38	Richmond	MITCHELL ELEMENTARY	5	1999 Addition	Low	Meets Structural Life Safety Requirements	High 1
38	Richmond	QUILCHENA ELEMENTARY	1	1961 1-Storey West Classroom Wing	High 1	Structural Upgrade Required	
38	Richmond	QUILCHENA ELEMENTARY	2	1988 West Classroom Addition	Low	Meets Structural Life Safety Requirements	
38	Richmond	QUILCHENA ELEMENTARY	3	1974 Gymnasium	High 3	Structural Upgrade Required	
38	Richmond	R C PALMER SECONDARY	1	Original Gymnasium	Medium	Non Structural Upgrade Required	
38	Richmond	R C PALMER SECONDARY	2	1965 Shops Addition	Medium	Non Structural Upgrade Required	Medium
38	Richmond	R C PALMER SECONDARY	3	1976 Classroom Addition	Medium	Non Structural Upgrade Required	
38	Richmond	R C PALMER SECONDARY	4	1998 addition	Low	Meets Structural Life Safety Requirements	
38	Richmond	R M GRAUER ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	High 1
38	Richmond	R M GRAUER ELEMENTARY	2	1947 2-Storey Classroom Wing	High 1	Structural Upgrade Required	
38	Richmond	R M GRAUER ELEMENTARY	3	1-Storey Classroom Wing	Medium	Non Structural Upgrade Required	
38	Richmond	RIDEAU PARK ELEMENTARY	1	Classroom Wing	Low	Meets Structural Life Safety Requirements	Low
38	Richmond	RIDEAU PARK ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
38	Richmond	ROBERT J TAIT ELEMENTARY	1	1955 1-Storey Original Classrooms	High 3	Structural Upgrade Required	High 3
38	Richmond	ROBERT J TAIT ELEMENTARY	2	Gymnasium Addition	Medium	Non Structural Upgrade Required	
38	Richmond	ROBERT J TAIT ELEMENTARY	3	Phase I, II, III Additions	Low	Meets Structural Life Safety Requirements	
38	Richmond	SAMUEL BRIGHOUSE ELEMENTARY	1	West Classroom Wing	N/A	Completed	N/A
38	Richmond	SAMUEL BRIGHOUSE ELEMENTARY	2	East Classroom Wing	N/A	Completed	
38	Richmond	SAMUEL BRIGHOUSE ELEMENTARY	3	Gymnasium	N/A	Completed	
38	Richmond	SAMUEL BRIGHOUSE ELEMENTARY	4	Multipurpose / Library Wing	N/A	Completed	
38	Richmond	SAMUEL BRIGHOUSE ELEMENTARY	5	North Classroom Wing	N/A	Completed	
38	Richmond	SAMUEL BRIGHOUSE ELEMENTARY	6	Covered Play Area	N/A	Completed	
38	Richmond	SEA ISLAND ELEMENTARY	1	1946 2-Storey Original School	High 1	Structural Upgrade Required	High 1
38	Richmond	SEA ISLAND ELEMENTARY	2	Gymnasium Addition	Low	Meets Structural Life Safety Requirements	
38	Richmond	SIDAWAY ELEMENTARY	1	original classrooms	Medium	Inactive	Medium
38	Richmond	SIDAWAY ELEMENTARY	2	classroom addition	Medium	Inactive	
38	Richmond	SIDAWAY ELEMENTARY	3	gymnasium	Medium	Inactive	
38	Richmond	STEVESTON SECONDARY	1	Original School	N/A	Completed	N/A
38	Richmond	STEVESTON SECONDARY	2	Gymnasium	N/A	Completed	
38	Richmond	STEVESTON SECONDARY	3	1977 Plus Additions	N/A	Completed	
38	Richmond	THOMAS KIDD ELEMENTARY	1	Original Classrooms	Medium	Non Structural Upgrade Required	Medium
38	Richmond	THOMAS KIDD ELEMENTARY	2	Gymnasium Addition	Low	Meets Structural Life Safety Requirements	
38	Richmond	TOMEKICHI HOMMA ELEMENTARY	1	1989 Original School	Low	Meets Structural Life Safety Requirements	Low
38	Richmond	TOMEKICHI HOMMA ELEMENTARY	2	2000 East Classroom Wing Addition	Low	Meets Structural Life Safety Requirements	
38	Richmond	TOMSETT ELEMENTARY	1	1959 1-Storey Classrooms	High 2	Structural Upgrade Required	High 2
38	Richmond	TOMSETT ELEMENTARY	2	1988 gymnasium addition	Low	Meets Structural Life Safety Requirements	
38	Richmond	TOMSETT ELEMENTARY	3	1999 addition	Low	Meets Structural Life Safety Requirements	
38	Richmond	W D FERRIS ELEMENTARY	1	1960 1-Storey Original Classrooms	High 2	Structural Upgrade Required	High 2
38	Richmond	W D FERRIS ELEMENTARY	2	Gym Addition	Low	Meets Structural Life Safety Requirements	
38	Richmond	W D FERRIS ELEMENTARY	3	Classrooms Addition	Medium	Non Structural Upgrade Required	
38	Richmond	W D FERRIS ELEMENTARY	4	1990 Addition	Medium	Non Structural Upgrade Required	
38	Richmond	WALTER LEE ELEMENTARY	1	Original Classrooms	Medium	Non Structural Upgrade Required	
38	Richmond	WALTER LEE ELEMENTARY	2	Gymnasium Addition	Low	Meets Structural Life Safety Requirements	High 1
38	Richmond	WALTER LEE ELEMENTARY	3	1969 2-Storey Classroom Addition	High 1	Structural Upgrade Required	
38	Richmond	WALTER LEE ELEMENTARY	4	1999 Addition	Low	Meets Structural Life Safety Requirements	
38	Richmond	WESTWIND ELEMENTARY	1	1994 1-Storey West Classroom Wing	High 3	Structural Upgrade Required	High 3
38	Richmond	WESTWIND ELEMENTARY	2	1978 1-Storey East Classroom Wing	High 3	Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
38	Richmond	WESTWIND ELEMENTARY	3	1983 1-Storey North East Classroom Wing	High 3	Structural Upgrade Required	High 3
38	Richmond	WESTWIND ELEMENTARY	4	Gymnasium Block	Medium	Non Structural Upgrade Required	
38	Richmond	WESTWIND ELEMENTARY	5	Multipurpose Wing	Medium	Non Structural Upgrade Required	
38	Richmond	WILLIAM BRIDGE ELEMENTARY	1	1969 2-Storey Original Classrooms	High 1	Structural Upgrade Required	High 1
38	Richmond	WILLIAM BRIDGE ELEMENTARY	2	1969 Gymnasium & Change Rooms	High 1	Structural Upgrade Required	
38	Richmond	WILLIAM COOK ELEMENTARY	1	1954 1-Storey Original Classroom Building	High 1	Structural Upgrade Required	High 1
38	Richmond	WILLIAM COOK ELEMENTARY	2	1957 1-Storey Classrooms	High 2	Structural Upgrade Required	
38	Richmond	WILLIAM COOK ELEMENTARY	3	1957 Gymnasium	High 2	Structural Upgrade Required	
38	Richmond	WILLIAM COOK ELEMENTARY	4	1999 Addition	High 2	Structural Upgrade Required	
39	Vancouver	ADMIRAL SEYMOUR ELEMENTARY	1	1902 3-Storey Classrooms	High 1	Structural Upgrade Required	High 1
39	Vancouver	ADMIRAL SEYMOUR ELEMENTARY	2	1907 3-Storey Classrooms	High 2	Structural Upgrade Required	
39	Vancouver	ADMIRAL SEYMOUR ELEMENTARY	3	1963 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	BAYVIEW COMMUNITY ELEMENTARY	1	1913/29 Classrooms	High 1	Supported 2013	High 1
39	Vancouver	BAYVIEW COMMUNITY ELEMENTARY	2	1929 Gymnasium	High 1	Supported 2013	
39	Vancouver	BAYVIEW COMMUNITY ELEMENTARY	3	1962 Multipurpose	High 1	Supported 2013	N/A
39	Vancouver	BRITANNIA COMMUNITY ELEMENTARY	1	Classroom	N/A	Completed	
39	Vancouver	BRITANNIA COMMUNITY SECONDARY	1	1911 Classrooms	Low	Meets Structural Life Safety Requirements	High 1
39	Vancouver	BRITANNIA COMMUNITY SECONDARY	2	1965 Extension	Low	Meets Structural Life Safety Requirements	
39	Vancouver	BRITANNIA COMMUNITY SECONDARY	3	1967 Shops and Science Classrooms	High 1	Structural Upgrade Required	N/A
39	Vancouver	BRITANNIA COMMUNITY SECONDARY	4	1954 Gymnasium	Medium	Non Structural Upgrade Required	
39	Vancouver	CAPTAIN JAMES COOK ELEMENTARY	1	North Classrooms	N/A	Completed	N/A
39	Vancouver	CAPTAIN JAMES COOK ELEMENTARY	2	Gymnasium	N/A	Completed	
39	Vancouver	CAPTAIN JAMES COOK ELEMENTARY	3	Library	N/A	Completed	
39	Vancouver	CAPTAIN JAMES COOK ELEMENTARY	4	Interior Classrooms	N/A	Completed	
39	Vancouver	CAPTAIN JAMES COOK ELEMENTARY	5	South Classrooms	N/A	Completed	High 3
39	Vancouver	CARNARVON COMMUNITY ELEMENTAR	1	1966 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	CARNARVON COMMUNITY ELEMENTAR	2	1966 1-Storey Central Classrooms & Library	High 3	Structural Upgrade Required	
39	Vancouver	CARNARVON COMMUNITY ELEMENTAR	3	1954 1-Storey South Classrooms	High 3	Structural Upgrade Required	Medium
39	Vancouver	CHAMPLAIN HEIGHTS ANNEX	1	1984 Gymnasium	Medium	Non Structural Upgrade Required	
39	Vancouver	CHAMPLAIN HEIGHTS ANNEX	2	1984 1-Storey Classrooms	Medium	Non Structural Upgrade Required	High 3
39	Vancouver	CHAMPLAIN HEIGHTS COMMUNITY ELE	1	1973 1-Storey Classrooms	High 3	Structural Upgrade Required	
39	Vancouver	CHAMPLAIN HEIGHTS COMMUNITY ELE	2	1973 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	CHAMPLAIN HEIGHTS COMMUNITY ELE	3	1977 Community Facilities Addition	High 3	Structural Upgrade Required	Medium
39	Vancouver	CHAMPLAIN HEIGHTS COMMUNITY ELE	4	West Addition	Low	Meets Structural Life Safety Requirements	
39	Vancouver	CHARLES DICKENS ANNEX	1	Gym	Medium	Non Structural Upgrade Required	Medium
39	Vancouver	CHARLES DICKENS ANNEX	2	Classroom	Medium	Non Structural Upgrade Required	
39	Vancouver	CHARLES DICKENS ELEMENTARY	1	Classroom Wing	N/A	Completed	N/A
39	Vancouver	CHARLES DICKENS ELEMENTARY	2	Gymnasium Wing	N/A	Completed	
39	Vancouver	CHIEF MAQUINNA ANNEX	1	Classroom	Medium	Non Structural Upgrade Required	Medium
39	Vancouver	CHIEF MAQUINNA ANNEX	2	Gymnasium	Medium	Non Structural Upgrade Required	
39	Vancouver	CHIEF MAQUINNA ELEMENTARY	1	1959 2-Storey West Classroom	High 3	Structural Upgrade Required	High 3
39	Vancouver	CHIEF MAQUINNA ELEMENTARY	2	1959 2-Storey Central Classrooms	Medium	Structural Upgrade Required	
39	Vancouver	CHIEF MAQUINNA ELEMENTARY	3	1952 1-Storey East Classrooms	High 3	Non Structural Upgrade Required	
39	Vancouver	CHIEF MAQUINNA ELEMENTARY	4	1959 Gymnasium	Medium	Structural Upgrade Required	
39	Vancouver	DAVID LIVINGSTONE ELEMENTARY	1	1913 3-Storey Classrooms (Main Building)	High 1	Structural Upgrade Required	High 1
39	Vancouver	DAVID LIVINGSTONE ELEMENTARY	2	1955 3-Storey Classroom Block + Covered Play Area	High 2	Structural Upgrade Required	
39	Vancouver	DAVID LIVINGSTONE ELEMENTARY	3	1955 Gymnasium	Medium	Non Structural Upgrade Required	High 1
39	Vancouver	DAVID LLOYD GEORGE ELEMENTARY	1	1922 3-Storey Classrooms (Original Classrooms)	High 1	Supported 2013	
39	Vancouver	DAVID LLOYD GEORGE ELEMENTARY	2	1954 Gymnasium + 2-Storey Classrooms	High 1	Supported 2013	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
39	Vancouver	DAVID OPPENHEIMER ELEMENTARY	1	East Classroom	Medium	Non Structural Upgrade Required	Medium
39	Vancouver	DAVID OPPENHEIMER ELEMENTARY	2	West Classroom	Medium	Non Structural Upgrade Required	
39	Vancouver	DAVID OPPENHEIMER ELEMENTARY	3	Gymnasium	Medium	Non Structural Upgrade Required	
39	Vancouver	DAVID THOMPSON SECONDARY	1	1957 2-Storey Auditorium/Classrooms	High 2	Supported 2013	High 1
39	Vancouver	DAVID THOMPSON SECONDARY	2	1957 3-Storey South Wing Classrooms	High 1	Supported 2013	
39	Vancouver	DAVID THOMPSON SECONDARY	3	1957 3-Storey West Wing Classrooms	High 1	Supported 2013	
39	Vancouver	DAVID THOMPSON SECONDARY	4	1957 Gymnasium and Change Rooms	High 1	Supported 2013	
39	Vancouver	DAVID THOMPSON SECONDARY	5	1957 1-Storey Classrooms (Shops, Cafeteria)	High 1	Supported 2013	
39	Vancouver	DAVID THOMPSON SECONDARY	6	1978 Workshops	High 2	Supported 2013	
39	Vancouver	DAVID THOMPSON SECONDARY	7	1961 3-Storey SouthWest Wing Classrooms	High 1	Supported 2013	
39	Vancouver	DAVID THOMPSON SECONDARY	8	NorthEast Shops	Medium	Supported 2013	
39	Vancouver	DR. ANNIE B. JAMIESON ELEMENTARY	1	1959 2-Storey Classrooms	High 1	Supported 2013	High 1
39	Vancouver	DR. ANNIE B. JAMIESON ELEMENTARY	2	1959 Administration/Covered Play Area	High 1	Supported 2013	
39	Vancouver	DR. ANNIE B. JAMIESON ELEMENTARY	3	1959 Gymnasium/Multipurpose Room/Boiler Room	High 1	Supported 2013	
39	Vancouver	DR. ANNIE B. JAMIESON ELEMENTARY	4	Second South Addition	Low	Supported 2013	
39	Vancouver	DR. A R LORD ELEMENTARY	1	1964 2-Storey Classroom	High 3	Structural Upgrade Required	High 3
39	Vancouver	DR. A R LORD ELEMENTARY	2	1964 2-Storey Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	DR. A R LORD ELEMENTARY	3	Annex Building	Medium	Non Structural Upgrade Required	
39	Vancouver	DR. GEORGE M WEIR ELEMENTARY	1	1960 2-Storey Classrooms	High 1	Supported 2012	High 1
39	Vancouver	DR. GEORGE M WEIR ELEMENTARY	2	1960 Library	High 2	Supported 2012	
39	Vancouver	DR. GEORGE M WEIR ELEMENTARY	3	1960 Gymnasium	High 1	Supported 2012	
39	Vancouver	DR. GEORGE M WEIR ELEMENTARY	4	1999 2-Storey Classroom Wing	Low	Supported 2012	
39	Vancouver	DR. H N MACCORKINDALE ELEM	1	1966 Library	High 2	Structural Upgrade Required	High 2
39	Vancouver	DR. H N MACCORKINDALE ELEM	2	1966 Classroom Wing	High 2	Structural Upgrade Required	
39	Vancouver	DR. H N MACCORKINDALE ELEM	3	1966 Gymnasium	High 2	Structural Upgrade Required	
39	Vancouver	DR. R E MCKECHNIE ELEMENTARY	1	Original Building - Gym	Medium	Non Structural Upgrade Required	Medium
39	Vancouver	DR. R E MCKECHNIE ELEMENTARY	2	Original Building - Classroom - Office	Medium	Non Structural Upgrade Required	
39	Vancouver	DR. R E MCKECHNIE ELEMENTARY	3	South Addition - Classroom	Medium	Non Structural Upgrade Required	
39	Vancouver	DR. R E MCKECHNIE ELEMENTARY	4	South Addition - Lunchroom	Medium	Non Structural Upgrade Required	
39	Vancouver	ECOLE JULES QUESNEL ELEMENTARY	1	Main Classrooms	N/A	Completed	N/A
39	Vancouver	ECOLE JULES QUESNEL ELEMENTARY	2	South Classrooms	N/A	Completed	
39	Vancouver	ECOLE JULES QUESNEL ELEMENTARY	3	Gymnasium	N/A	Completed	
39	Vancouver	EDITH CAVELL ELEMENTARY	1	1919 3-Storey Classrooms	High 1	Supported 2013	High 1
39	Vancouver	EDITH CAVELL ELEMENTARY	2	1956 Gymnasium	High 1	Supported 2013	
39	Vancouver	EDITH CAVELL ELEMENTARY	3	1920 1-Storey Classrooms	High 2	Supported 2013	
39	Vancouver	EMILY CARR ELEMENTARY	1	1910 3-Storey Classroom (84A)	High 3	Structural Upgrade Required	High 1
39	Vancouver	EMILY CARR ELEMENTARY	2	1910 2-Storey Classroom (84D)	Medium	Non Structural Upgrade Required	
39	Vancouver	EMILY CARR ELEMENTARY	3	1954 1-Storey Classrooms	Medium	Non Structural Upgrade Required	
39	Vancouver	EMILY CARR ELEMENTARY	4	1964 Gymnasium	High 1	Structural Upgrade Required	
39	Vancouver	ERIC HAMBER SECONDARY	1	1961 3-Storey Classroom	High 1	Supported 2013	High 1
39	Vancouver	ERIC HAMBER SECONDARY	2	1961 Theatre	High 3	Supported 2013	
39	Vancouver	ERIC HAMBER SECONDARY	3	1961 Large Gymnasium	High 1	Supported 2013	
39	Vancouver	ERIC HAMBER SECONDARY	4	1961 Cafeteria/Offices	High 1	Supported 2013	
39	Vancouver	ERIC HAMBER SECONDARY	5	1961 Large Shops	High 1	Supported 2013	
39	Vancouver	ERIC HAMBER SECONDARY	6	1966 2-Storey Small Shops	High 1	Supported 2013	
39	Vancouver	ERIC HAMBER SECONDARY	7	1966 3-Storey Counseling Block	High 1	Supported 2013	
39	Vancouver	ERIC HAMBER SECONDARY	8	1966 Lecture Hall/Small Gymnasium	High 1	Supported 2013	
39	Vancouver	ERIC HAMBER SECONDARY	9	1966 3-Storey Library	High 1	Supported 2013	
39	Vancouver	ERIC HAMBER SECONDARY	10	1961 1-Storey Music Block	High 1	Supported 2013	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
39	Vancouver	ERIC HAMBER SECONDARY	11	1961 1-Storey Art Classrooms	High 1	Supported 2013	
39	Vancouver	ERIC HAMBER SECONDARY	12	1961 1-Storey Classrooms	High 1	Supported 2013	
39	Vancouver	FALSE CREEK ELEMENTARY	1	1977 2-Storey Classrooms	High 2	Structural Upgrade Required	High 1
39	Vancouver	FALSE CREEK ELEMENTARY	2	1977 Gymnasium	High 1	Structural Upgrade Required	
39	Vancouver	FLORENCE NIGHTINGALE ELEMENTAR'	1	1911 3-Storey Main Building	High 1	Structural Upgrade Required	High 1
39	Vancouver	FLORENCE NIGHTINGALE ELEMENTAR'	2	1953 Gymnasium	High 1	Structural Upgrade Required	
39	Vancouver	G T CUNNINGHAM ELEMENTARY	1	1959 1-Storey East Classrooms	Medium	Non Structural Upgrade Required	
39	Vancouver	G T CUNNINGHAM ELEMENTARY	2	1965 1-Storey North Classrooms	High 3	Structural Upgrade Required	High 1
39	Vancouver	G T CUNNINGHAM ELEMENTARY	3	1966 Gymnasium	High 1	Structural Upgrade Required	
39	Vancouver	G T CUNNINGHAM ELEMENTARY	4	2002 Addition	Low	Meets Structural Life Safety Requirements	
39	Vancouver	GARIBALDI ANNEX	1	Classroom	Medium	Non Structural Upgrade Required	
39	Vancouver	GARIBALDI ANNEX	2	Activity/Office	Medium	Non Structural Upgrade Required	Medium
39	Vancouver	GARIBALDI ANNEX	3	Washrooms	Medium	Non Structural Upgrade Required	
39	Vancouver	GENERAL BROCK ANNEX (Total Educatio	1	Main Building	N/A	Completed	N/A
39	Vancouver	GENERAL BROCK ELEMENTARY	1	1908 3-Storey Classrooms	High 3	Structural Upgrade Required	
39	Vancouver	GENERAL BROCK ELEMENTARY	2	1923 1-Storey Classrooms	High 3	Structural Upgrade Required	High 2
39	Vancouver	GENERAL BROCK ELEMENTARY	3	1955 2-Storey Classroom Block	High 2	Structural Upgrade Required	
39	Vancouver	GENERAL BROCK ELEMENTARY	4	1955 Gymnasium & Admin incl. Covered Play Area	Medium	Non Structural Upgrade Required	
39	Vancouver	GENERAL GORDON ELEMENTARY	1	Classroom	N/A	Under Construction	
39	Vancouver	GENERAL GORDON ELEMENTARY	2	Gymnasium/Auditorium	N/A	Under Construction	N/A
39	Vancouver	GENERAL GORDON ELEMENTARY	3	Multipurpose/Lunchroom	N/A	Under Construction	
39	Vancouver	GENERAL WOLFE ELEMENTARY	1	1910 3-Storey Classrooms (Main Building)	High 1	Supported 2013	
39	Vancouver	GENERAL WOLFE ELEMENTARY	2	1950 Gym & Change Rooms	Medium	Supported 2013	High 1
39	Vancouver	GENERAL WOLFE ELEMENTARY	3	1924 1-Storey Annex	High 3	Supported 2013	
39	Vancouver	GLADSTONE SECONDARY	1	1947 3-Storey East Wing Classrooms	High 1	Structural Upgrade Required	
39	Vancouver	GLADSTONE SECONDARY	2	1948 2-Storey Middle Wing Classrooms	High 1	Structural Upgrade Required	
39	Vancouver	GLADSTONE SECONDARY	3	1948 Shops	Medium	Non Structural Upgrade Required	
39	Vancouver	GLADSTONE SECONDARY	4	1948 Cafeteria	Medium	Non Structural Upgrade Required	
39	Vancouver	GLADSTONE SECONDARY	5	1951 3-Storey North Wing Classrooms & Auditorium	High 3	Structural Upgrade Required	High 1
39	Vancouver	GLADSTONE SECONDARY	6	1948 2-Storey Gym & Classrooms	High 2	Structural Upgrade Required	
39	Vancouver	GLADSTONE SECONDARY	7	1977 Workshops	Low	Meets Structural Life Safety Requirements	
39	Vancouver	GLADSTONE SECONDARY	8	1951 Small Gymnasium	Medium	Non Structural Upgrade Required	
39	Vancouver	GLADSTONE SECONDARY	9	1964 Drama & Art Rooms	Low	Meets Structural Life Safety Requirements	
39	Vancouver	GRAHAM BRUCE COMMUNITY ELEMEN	1	1963 2-Storey Classrooms (Original)	High 3	Structural Upgrade Required	High 1
39	Vancouver	GRAHAM BRUCE COMMUNITY ELEMEN	2	1968 2-Storey Gym/Classrooms (Addition)	High 1	Structural Upgrade Required	
39	Vancouver	GRANDVIEW ELEMENTARY	1	1926 3-Storey Classrooms	High 1	Structural Upgrade Required	
39	Vancouver	GRANDVIEW ELEMENTARY	2	1952 Cafeteria/Auditorium	Medium	Non Structural Upgrade Required	High 1
39	Vancouver	GRANDVIEW ELEMENTARY	3	1973 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	GRANDVIEW ELEMENTARY	4	1973 Library	High 3	Structural Upgrade Required	
39	Vancouver	HASTINGS COMMUNITY ELEMENTARY	1	Classroom Block	Low	Meets Structural Life Safety Requirements	
39	Vancouver	HASTINGS COMMUNITY ELEMENTARY	2	1996 Link	Low	Meets Structural Life Safety Requirements	Low
39	Vancouver	HASTINGS COMMUNITY ELEMENTARY	3	Gym	Low	Meets Structural Life Safety Requirements	
39	Vancouver	HASTINGS COMMUNITY ELEMENTARY	4	2003 addition	Low	Meets Structural Life Safety Requirements	
39	Vancouver	HENRY HUDSON ELEMENTARY	1	1911 3-Storey Classrooms	High 1	Structural Upgrade Required	
39	Vancouver	HENRY HUDSON ELEMENTARY	2	1949 Gymnasium	High 3	Structural Upgrade Required	High 1
39	Vancouver	HENRY HUDSON ELEMENTARY	3	1-Storey Out-of-School Care Building	High 1	Structural Upgrade Required	
39	Vancouver	J. W. SEXSMITH COMMUNITY ELEMENT	1	North addition-Gym	N/A	Completed	
39	Vancouver	J. W. SEXSMITH COMMUNITY ELEMENT	2	South addition-Classrooms	N/A	Completed	N/A
39	Vancouver	J. W. SEXSMITH COMMUNITY ELEMENT	3	old building-office-classroom-library	N/A	Completed	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
39	Vancouver	J. W. SEXSMITH COMMUNITY ELEMENT	4	Wood frame building	N/A	Completed	
39	Vancouver	JOHN HENDERSON ANNEX	1	Classroom Wing	Medium	Non Structural Upgrade Required	Medium
39	Vancouver	JOHN HENDERSON ANNEX	2	Administrative Wing	Medium	Non Structural Upgrade Required	
39	Vancouver	JOHN HENDERSON ANNEX	3	Gymnasium Wing	Medium	Non Structural Upgrade Required	
39	Vancouver	JOHN HENDERSON ELEMENTARY	1	1954 1-Story Classrooms (Original)	Medium	Non Structural Upgrade Required	High 3
39	Vancouver	JOHN HENDERSON ELEMENTARY	2	1962 1-Storey Extension	High 3	Structural Upgrade Required	
39	Vancouver	JOHN HENDERSON ELEMENTARY	3	(Post 1990) 2nd Extension	Low	Meets Structural Life Safety Requirements	
39	Vancouver	JOHN NORQUAY ELEMENTARY	1	Main Building	N/A	Completed	N/A
39	Vancouver	JOHN NORQUAY ELEMENTARY	2	1994 Addition	N/A	Completed	
39	Vancouver	JOHN NORQUAY ELEMENTARY	3	Gymnasium	N/A	Completed	
39	Vancouver	JOHN NORQUAY ELEMENTARY	4	1999 Addition	N/A	Completed	
39	Vancouver	JOHN OLIVER SECONDARY	1	1953 3-Storey East Wing Classrooms	High 2	Supported 2004	High 1
39	Vancouver	JOHN OLIVER SECONDARY	2	1953 Auditorium	High 3	Supported 2004	
39	Vancouver	JOHN OLIVER SECONDARY	3	1953 1-Storey Shops/Cafeteria	High 1	Supported 2004	
39	Vancouver	JOHN OLIVER SECONDARY	4	1948 3-Storey North & West Wing Classrooms	High 1	Supported 2004	
39	Vancouver	JOHN OLIVER SECONDARY	5	1948 Gymnasium & 1969 Library	High 1	Supported 2004	
39	Vancouver	JOHN OLIVER SECONDARY	6	1938 Small Gymnasium	High 3	Supported 2004	
39	Vancouver	JOHN OLIVER SECONDARY	7	1965 Workshops	High 1	Supported 2004	
39	Vancouver	JOHN OLIVER SECONDARY	8	1925 1-Storey Drama Building	High 2	Supported 2004	
39	Vancouver	JOHN OLIVER SECONDARY	9	1926 3-Storey School Building	High 1	Supported 2004	
39	Vancouver	JOHN OLIVER SECONDARY	10	1918 3-Storey South Classroom Wing	Medium	Supported 2004	
39	Vancouver	JOHN OLIVER SECONDARY	11	1918 1-Storey North Wing	Medium	Supported 2004	
39	Vancouver	KERRISDALE ANNEX	1	Activity Room	Medium	Non Structural Upgrade Required	Medium
39	Vancouver	KERRISDALE ANNEX	2	Central Classroom	Medium	Non Structural Upgrade Required	
39	Vancouver	KERRISDALE ANNEX	3	East Classrooms	Medium	Non Structural Upgrade Required	
39	Vancouver	KERRISDALE ELEMENTARY	1	Original (1921)	N/A	Completed	N/A
39	Vancouver	KERRISDALE ELEMENTARY	2	Extension (1924)	N/A	Completed	
39	Vancouver	KERRISDALE ELEMENTARY	3	Addition (1956)	N/A	Completed	
39	Vancouver	KILLARNEY SECONDARY	1	1956 3-Storey Classrooms	High 1	Supported 2013	High 1
39	Vancouver	KILLARNEY SECONDARY	2	1956 Workshops	High 1	Supported 2013	
39	Vancouver	KILLARNEY SECONDARY	3	1956 Cafeteria and Gymnasium	High 3	Supported 2013	
39	Vancouver	KILLARNEY SECONDARY	4	1961 Classrooms and Auditorium	High 1	Supported 2013	
39	Vancouver	KILLARNEY SECONDARY	5	1961 Gymnasium and Workshops	High 3	Supported 2013	
39	Vancouver	KILLARNEY SECONDARY	6	1967 Science/Shops	High 1	Supported 2013	
39	Vancouver	KILLARNEY SECONDARY	7	New Classrooms	Medium	Supported 2013	
39	Vancouver	KING GEORGE SECONDARY	1	1962 3-Storey Classroom Block	High 1	Structural Upgrade Required	High 1
39	Vancouver	KING GEORGE SECONDARY	2	1962 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	KITSILANO SECONDARY	1	Shops	N/A	Under Construction	N/A
39	Vancouver	KITSILANO SECONDARY	2	South Gymnasium	N/A	Under Construction	
39	Vancouver	KITSILANO SECONDARY	3	Metalworks & Drama	N/A	Under Construction	
39	Vancouver	KITSILANO SECONDARY	4	Change Rooms	N/A	Under Construction	
39	Vancouver	KITSILANO SECONDARY	5	Auditorium/North Gym	N/A	Under Construction	
39	Vancouver	KITSILANO SECONDARY	6	East Classrooms	N/A	Under Construction	
39	Vancouver	KITSILANO SECONDARY	7	West Classrooms	N/A	Under Construction	
39	Vancouver	KITSILANO SECONDARY	8	S.W. Classrooms	N/A	Under Construction	
39	Vancouver	LAURA SECORD ELEMENTARY	1	Main Building	N/A	Completed	N/A
39	Vancouver	LAURA SECORD ELEMENTARY	2	Auditorium	N/A	Completed	
39	Vancouver	LAURA SECORD ELEMENTARY	3	Change Rooms	N/A	Completed	
39	Vancouver	LAURA SECORD ELEMENTARY	4	Gymnasium	N/A	Completed	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
39	Vancouver	LAURA SECORD ELEMENTARY	5	Recent Addition	N/A	Completed	
39	Vancouver	L'ECOLE BILINGUE ELEMENTARY	1	Main Building	N/A	Under Construction	N/A
39	Vancouver	L'ECOLE BILINGUE ELEMENTARY	2	Gymnasium	N/A	Under Construction	
39	Vancouver	LORD BEACONSFIELD ELEMENTARY	1	1914 3-Storey Classrooms	High 1	Structural Upgrade Required	High 1
39	Vancouver	LORD BEACONSFIELD ELEMENTARY	2	1949 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	LORD BYNG SECONDARY	1	1936 3-Storey East Classrooms	Low	Meets Structural Life Safety Requirements	High 3
39	Vancouver	LORD BYNG SECONDARY	2	1926 3-Storey Centre Classrooms	Low	Meets Structural Life Safety Requirements	
39	Vancouver	LORD BYNG SECONDARY	3	1950 3-Storey West Classrooms	Low	Meets Structural Life Safety Requirements	
39	Vancouver	LORD BYNG SECONDARY	4	1950 Workshops	Medium	Non Structural Upgrade Required	
39	Vancouver	LORD BYNG SECONDARY	5	1950 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	LORD BYNG SECONDARY	6	1950 Cafeteria	Medium	Non Structural Upgrade Required	
39	Vancouver	LORD BYNG SECONDARY	7	1950 Auditorium	High 3	Structural Upgrade Required	
39	Vancouver	LORD BYNG SECONDARY	8	Library	Low	Meets Structural Life Safety Requirements	
39	Vancouver	LORD BYNG SECONDARY	9	North-East Gymnasium	Low	Meets Structural Life Safety Requirements	
39	Vancouver	LORD KITCHENER ELEMENTARY	1	Classroom Block	N/A	Completed	N/A
39	Vancouver	LORD KITCHENER ELEMENTARY	2	Gymnasium	N/A	Completed	
39	Vancouver	LORD KITCHENER ELEMENTARY	3	North Classroom Addition	N/A	Completed	
39	Vancouver	LORD KITCHENER ELEMENTARY	4	1914 2-Storey Classroom (Wood Frame Bldg)	N/A	Completed	
39	Vancouver	LORD NELSON ELEMENTARY	1	1910 3-Storey Original Building	High 1	Proceeding to Construction	High 1
39	Vancouver	LORD NELSON ELEMENTARY	2	1963 3-Storey Classroom (South Addition)	High 1	Proceeding to Construction	
39	Vancouver	LORD NELSON ELEMENTARY	3	1951 Gymnasium	Medium	Proceeding to Construction	
39	Vancouver	LORD ROBERTS ANNEX	1	Classrooms/Gym	Medium	Non Structural Upgrade Required	Medium
39	Vancouver	LORD ROBERTS ELEMENTARY	1	Classrooms	Low	Meets Structural Life Safety Requirements	Medium
39	Vancouver	LORD ROBERTS ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
39	Vancouver	LORD ROBERTS ELEMENTARY	3	Classroom Addition	Medium	Non Structural Upgrade Required	
39	Vancouver	LORD SELKIRK ANNEX	1	1965 1-Storey Classroom	High 3	Structural Upgrade Required	High 3
39	Vancouver	LORD SELKIRK ANNEX	2	1965 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	LORD SELKIRK ELEMENTARY	1	1910 Classrooms (Upgraded in 1996)	Low	Meets Structural Life Safety Requirements	High 3
39	Vancouver	LORD SELKIRK ELEMENTARY	2	Gym (Upgraded in 1996)	Low	Meets Structural Life Safety Requirements	
39	Vancouver	LORD SELKIRK ELEMENTARY	3	1922 3-Storey Classrooms (Wood Frame)	High 3	Structural Upgrade Required	
39	Vancouver	LORD SELKIRK ELEMENTARY	4	1950 1-Storey Wood Frame (Portable)	Medium	Non Structural Upgrade Required	
39	Vancouver	LORD SELKIRK ELEMENTARY	5	2000 2-Storey South Wing	Low	Meets Structural Life Safety Requirements	
39	Vancouver	LORD STRATHCONA COMMUNITY ELEM	1	1891 3-Storey Classrooms (Junior Building)	N/A	Under Construction	N/A
39	Vancouver	LORD STRATHCONA COMMUNITY ELEM	2	1915 3-Storey Classrooms (Senior Building)	N/A	Under Construction	
39	Vancouver	LORD STRATHCONA COMMUNITY ELEM	3	1930 2-Storey Auditorium Building	N/A	Under Construction	
39	Vancouver	LORD STRATHCONA COMMUNITY ELEM	4	1921 2-Storey Primary Building	N/A	Under Construction	
39	Vancouver	LORD STRATHCONA COMMUNITY ELEM	5	Administration Building	N/A	Under Construction	
39	Vancouver	LORD TENNYSON ELEMENTARY	1	1910 3-Storey Classrooms	High 1	Supported 2013	High 1
39	Vancouver	LORD TENNYSON ELEMENTARY	2	1912 Gymnasium	High 1	Supported 2013	
39	Vancouver	LORD TENNYSON ELEMENTARY	3	1957 Change Rooms	High 1	Supported 2013	
39	Vancouver	MAPLE GROVE ELEMENTARY	1	1924 3-Storey Classrooms	High 1	Supported 2013	High 1
39	Vancouver	MAPLE GROVE ELEMENTARY	2	1952 3-Storey Classrooms & Gymnasium	High 1	Supported 2013	
39	Vancouver	MOUNT PLEASANT ELEMENTARY	1	1971 2-Storey Classrooms	High 3	Structural Upgrade Required	High 3
39	Vancouver	MOUNT PLEASANT ELEMENTARY	2	1971 Gymnasium	Medium	Non Structural Upgrade Required	
39	Vancouver	NOOTKA COMMUNITY ELEMENTARY	1	1959 South East Classrooms	Medium	Non Structural Upgrade Required	High 3
39	Vancouver	NOOTKA COMMUNITY ELEMENTARY	2	1959 Administration Wing	Medium	Non Structural Upgrade Required	
39	Vancouver	NOOTKA COMMUNITY ELEMENTARY	3	1959 Activity Room	Medium	Non Structural Upgrade Required	
39	Vancouver	NOOTKA COMMUNITY ELEMENTARY	4	1963 1-Storey North Classrooms	High 3	Structural Upgrade Required	
39	Vancouver	NOOTKA COMMUNITY ELEMENTARY	5	1963 Gymnasium	High 3	Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
39	Vancouver	NOOKA COMMUNITY ELEMENTARY	6	South West Classrooms	Low	Meets Structural Life Safety Requirements	
39	Vancouver	POINT GREY SECONDARY	1	1928 3-Storey Classrooms	High 1	Supported 2013	High 1
39	Vancouver	POINT GREY SECONDARY	2	1928 3-Storey Small Gym & Library	High 1	Supported 2013	
39	Vancouver	POINT GREY SECONDARY	3	1964 Large Gymnasium	High 1	Supported 2013	
39	Vancouver	POINT GREY SECONDARY	4	1964 Shops & Covered Work Area	High 1	Supported 2013	
39	Vancouver	POINT GREY SECONDARY	5	1964 1-Storey Sciences Block	High 1	Supported 2013	
39	Vancouver	PRINCE OF WALES SECONDARY	1	1959 2-Storey Offices & Science Classrooms	High 1	Supported 2013	High 1
39	Vancouver	PRINCE OF WALES SECONDARY	2	1959 2-Storey Auditorium, Library & Music	High 2	Supported 2013	
39	Vancouver	PRINCE OF WALES SECONDARY	3	1959 Cafeteria & Lab	High 1	Supported 2013	
39	Vancouver	PRINCE OF WALES SECONDARY	4	1959 2-Storey East Wing Classrooms & Shops	High 1	Supported 2013	
39	Vancouver	PRINCE OF WALES SECONDARY	5	1959 Gymnasium	High 2	Supported 2013	
39	Vancouver	PRINCE OF WALES SECONDARY	6	1959 Mini School Annex	High 1	Supported 2013	High 1
39	Vancouver	QUEEN ALEXANDRA ELEMENTARY	1	1908 3-Storey Classrooms	High 2	Structural Upgrade Required	
39	Vancouver	QUEEN ALEXANDRA ELEMENTARY	2	1947 Gymnasium	High 1	Structural Upgrade Required	
39	Vancouver	QUEEN ALEXANDRA ELEMENTARY	3	1961 Lunchroom	Medium	Non Structural Upgrade Required	
39	Vancouver	QUEEN ELIZABETH ANNEX	1	1963 1-Storey Classroom Annex	High 3	Structural Upgrade Required	
39	Vancouver	QUEEN ELIZABETH ELEMENTARY	1	1940 1-Storey Daycare Block	Medium	Non Structural Upgrade Required	High 3
39	Vancouver	QUEEN ELIZABETH ELEMENTARY	2	1940 West Gym/Auditorium	High 3	Structural Upgrade Required	
39	Vancouver	QUEEN ELIZABETH ELEMENTARY	3	1940 1-Storey Centre Block	High 3	Structural Upgrade Required	
39	Vancouver	QUEEN ELIZABETH ELEMENTARY	4	1940 East Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	QUEEN ELIZABETH ELEMENTARY	5	1940 1-Storey West Classrooms	High 3	Structural Upgrade Required	
39	Vancouver	QUEEN ELIZABETH ELEMENTARY	6	1940 1-Storey East Classrooms	High 3	Structural Upgrade Required	High 3
39	Vancouver	QUEEN ELIZABETH ELEMENTARY	7	1957 1-Storey North Classrooms	Medium	Non Structural Upgrade Required	
39	Vancouver	QUEEN ELIZABETH ELEMENTARY	8	1957 1-Storey South Classrooms	Low	Meets Structural Life Safety Requirements	
39	Vancouver	QUEEN MARY ELEMENTARY	1	1909 3-Storey (Original Classrooms)	N/A	Under Construction	
39	Vancouver	QUEEN MARY ELEMENTARY	2	East Classroom Bldg.	N/A	Under Construction	
39	Vancouver	QUEEN MARY ELEMENTARY	3	Classroom Addition	N/A	Under Construction	N/A
39	Vancouver	QUEEN MARY ELEMENTARY	4	Gymnasium	N/A	Under Construction	
39	Vancouver	QUEEN VICTORIA ANNEX	1	1963 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	QUEEN VICTORIA ANNEX	2	1963 1-Storey Classrooms (Ground)	High 3	Structural Upgrade Required	
39	Vancouver	QUEEN VICTORIA ANNEX	3	1969 1-Storey Classrooms (Elevated)	Medium	Non Structural Upgrade Required	
39	Vancouver	QUILCHENA ELEMENTARY	1	1926 3-Storey Central Classrooms	Medium	Non Structural Upgrade Required	High 1
39	Vancouver	QUILCHENA ELEMENTARY	2	1954 3-Storey North Wing Addition	High 1	Structural Upgrade Required	
39	Vancouver	QUILCHENA ELEMENTARY	3	1954 Gymnasium	High 1	Structural Upgrade Required	
39	Vancouver	RENFREW COMMUNITY ELEMENTARY	1	1928 3-Storey Center Classrooms	High 1	Supported 2013	
39	Vancouver	RENFREW COMMUNITY ELEMENTARY	2	1928 Gymnasium	High 1	Supported 2013	
39	Vancouver	RENFREW COMMUNITY ELEMENTARY	3	1928 3-Storey East Classrooms	High 1	Supported 2013	High 1
39	Vancouver	RENFREW COMMUNITY ELEMENTARY	4	Classroom Wing	Low	Supported 2013	
39	Vancouver	RENFREW COMMUNITY ELEMENTARY	5	Classroom Annex	Low	Supported 2013	
39	Vancouver	SHANNON PARK ANNEX	1	Classroom	Medium	Inactive	
39	Vancouver	SHAUGHNESSY ELEMENTARY	1	Classrooms	Low	Meets Structural Life Safety Requirements	
39	Vancouver	SHAUGHNESSY ELEMENTARY	2	Multi-Purpose	Low	Meets Structural Life Safety Requirements	Low
39	Vancouver	SHAUGHNESSY ELEMENTARY	3	Gymnasium	Low	Meets Structural Life Safety Requirements	
39	Vancouver	SIMON FRASER ELEMENTARY	1	Gymnasium	N/A	Completed	
39	Vancouver	SIMON FRASER ELEMENTARY	2	Classrooms	N/A	Completed	N/A
39	Vancouver	SIR ALEXANDER MACKENZIE ELEM	1	1929 3-Storey Classrooms (Wing 104A)	High 1	Supported 2013	
39	Vancouver	SIR ALEXANDER MACKENZIE ELEM	2	1958 Gymnasium Wing	High 1	Supported 2013	
39	Vancouver	SIR ALEXANDER MACKENZIE ELEM	3	Classroom Wing	Low	Supported 2013	High 1
39	Vancouver	SIR CHARLES KINGSFORD-SMITH	1	1954 2-Storey Classroom Wing	High 1	Proceeding to Construction	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
39	Vancouver	SIR CHARLES KINGSFORD-SMITH	2	1954 Administrative Wing	Medium	Proceeding to Construction	High 1
39	Vancouver	SIR CHARLES KINGSFORD-SMITH	3	1954 Gymnasium	High 1	Proceeding to Construction	
39	Vancouver	SIR CHARLES TUPPER SECONDARY	1	1957 2-Storey Auditorium & Classrooms	Low	Meets Structural Life Safety Requirements	
39	Vancouver	SIR CHARLES TUPPER SECONDARY	2	1957 4-Storey Classrooms & Cafeteria	Low	Meets Structural Life Safety Requirements	Medium
39	Vancouver	SIR CHARLES TUPPER SECONDARY	3	1957 4-Storey Shops - Labs - Gymnasium	Low	Meets Structural Life Safety Requirements	
39	Vancouver	SIR CHARLES TUPPER SECONDARY	4	1965 Workshops-Gymnasium	Medium	Non Structural Upgrade Required	
39	Vancouver	SIR GUY CARLETON COMMUNITY ELEM	1	1911 3-Storey Original Building	High 1	Supported 2005	
39	Vancouver	SIR GUY CARLETON COMMUNITY ELEM	2	1909 3-Storey Classrooms (Wood Frame)	High 1	Supported 2005	
39	Vancouver	SIR GUY CARLETON COMMUNITY ELEM	3	1896 1-Storey Classroom Building	High 1	Supported 2005	High 1
39	Vancouver	SIR GUY CARLETON COMMUNITY ELEM	4	1896 1-Storey Classroom Building (Smallest)	Medium	Supported 2005	
39	Vancouver	SIR GUY CARLETON COMMUNITY ELEM	5	1949 Gymnasium	High 2	Supported 2005	
39	Vancouver	SIR JAMES DOUGLAS ANNEX	1	Building 131	N/A	Completed	N/A
39	Vancouver	SIR JAMES DOUGLAS ELEMENTARY	1	Main Building	N/A	Completed	
39	Vancouver	SIR JAMES DOUGLAS ELEMENTARY	2	North Addition - Classroom	N/A	Completed	N/A
39	Vancouver	SIR JAMES DOUGLAS ELEMENTARY	3	Gym	N/A	Completed	
39	Vancouver	SIR JOHN FRANKLIN COMMUNITY	1	1926 3-Storey Classrooms	High 1	Structural Upgrade Required	
39	Vancouver	SIR JOHN FRANKLIN COMMUNITY	2	1926 Gymnasium	Medium	Non Structural Upgrade Required	High 1
39	Vancouver	SIR JOHN FRANKLIN COMMUNITY	3	1954 Lunchroom Block	High 3	Structural Upgrade Required	
39	Vancouver	SIR MATTHEW BEGBIE ELEMENTARY	1	1929 3-Storey Original Building	High 1	Supported 2005	High 1
39	Vancouver	SIR MATTHEW BEGBIE ELEMENTARY	2	1947 3-Storey South Addition	High 1	Supported 2005	
39	Vancouver	SIR RICHARD MCBRIDE ANNEX	1	1963 1-Storey Classrooms	High 3	Structural Upgrade Required	High 3
39	Vancouver	SIR RICHARD MCBRIDE ANNEX	2	1963 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	SIR RICHARD MCBRIDE ELEMENTARY	1	Brick Building	N/A	Completed	
39	Vancouver	SIR RICHARD MCBRIDE ELEMENTARY	2	Gymnasium	N/A	Completed	N/A
39	Vancouver	SIR RICHARD MCBRIDE ELEMENTARY	3	South Woodframe Building	N/A	Completed	
39	Vancouver	SIR SANDFORD FLEMING ELEMENTARY	1	1958 3-Storey Classroom Addition	High 1	Proceeding to Construction	
39	Vancouver	SIR SANDFORD FLEMING ELEMENTARY	2	1912 3-Storey Original Building	High 1	Proceeding to Construction	High 1
39	Vancouver	SIR SANDFORD FLEMING ELEMENTARY	3	1958 Gymnasium	High 2	Proceeding to Construction	
39	Vancouver	SIR SANDFORD FLEMING ELEMENTARY	4	1914 1-Storey Wood Frame Classrooms	Medium	Proceeding to Construction	
39	Vancouver	SIR SANDFORD FLEMING ELEMENTARY	5	Recent Addition	Low	Proceeding to Construction	
39	Vancouver	SIR WILFRED GRENFELL ELEMENTARY	1	1954 2-Storey Classrooms	High 1	Supported 2012	
39	Vancouver	SIR WILFRED GRENFELL ELEMENTARY	2	1954 1-Storey Administration Block	Medium	Supported 2012	High 1
39	Vancouver	SIR WILFRED GRENFELL ELEMENTARY	3	1954 Gymnasium	High 1	Supported 2012	
39	Vancouver	SIR WILFRED GRENFELL ELEMENTARY	4	1910 1-Storey Timber Classroom Building	High 1	Supported 2012	
39	Vancouver	SIR WILFRED GRENFELL ELEMENTARY	5	Classroom Wing	Low	Supported 2012	
39	Vancouver	SIR WILFRID LAURIER ANNEX (Ideal Min	1	Main Building	N/A	Completed	N/A
39	Vancouver	SIR WILFRID LAURIER ANNEX (Ideal Min	2	Gymnasium	N/A	Completed	
39	Vancouver	SIR WILFRID LAURIER ELEMENTARY	1	Main Classrooms	N/A	Completed	
39	Vancouver	SIR WILFRID LAURIER ELEMENTARY	2	Gymnasium	N/A	Completed	N/A
39	Vancouver	SIR WILFRID LAURIER ELEMENTARY	3	1999 Addition	N/A	Completed	
39	Vancouver	SIR WILFRID LAURIER ELEMENTARY	4	Laurier Mini School	N/A	Completed	
39	Vancouver	SIR WILLIAM MACDONALD ELEM	1	1908 3-Storey Original School	High 1	Structural Upgrade Required	High 1
39	Vancouver	SIR WILLIAM MACDONALD ELEM	2	1929 Gymnasium	High 1	Structural Upgrade Required	
39	Vancouver	SIR WILLIAM OSLER ELEMENTARY	1	1953 2-Storey Classrooms	High 1	Structural Upgrade Required	
39	Vancouver	SIR WILLIAM OSLER ELEMENTARY	2	1953 1-Storey Classrooms	High 1	Structural Upgrade Required	High 1
39	Vancouver	SIR WILLIAM OSLER ELEMENTARY	3	1973 Gymnasium	Medium	Non Structural Upgrade Required	
39	Vancouver	SIR WILLIAM OSLER ELEMENTARY	4	1950 1-Storey Main Building	High 3	Structural Upgrade Required	
39	Vancouver	SIR WINSTON CHURCHILL SEC	1	1958 2-Storey Auditorium	High 3	Structural Upgrade Required	
39	Vancouver	SIR WINSTON CHURCHILL SEC	2	1955 3-Storey Classrooms	High 3	Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
39	Vancouver	SIR WINSTON CHURCHILL SEC	3	1955 Shops	High 1	Structural Upgrade Required	High 1
39	Vancouver	SIR WINSTON CHURCHILL SEC	4	1955 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	SIR WINSTON CHURCHILL SEC	5	1958 Small Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	SIR WINSTON CHURCHILL SEC	6	1999 Addition	Low	Meets Structural Life Safety Requirements	Low
39	Vancouver	SIR WM VAN HORNE ELEMENTARY	1	1911 Original Building	Low	Meets Structural Life Safety Requirements	
39	Vancouver	SIR WM VAN HORNE ELEMENTARY	2	1950 Extension	Low	Meets Structural Life Safety Requirements	
39	Vancouver	SOUTH HILL EDUCATION CENTRE	1	3-Storey Original School	High 3	Inactive	High 3
39	Vancouver	SOUTH HILL EDUCATION CENTRE	2	Gymnasium Block	High 3	Inactive	
39	Vancouver	SOUTHLANDS ELEMENTARY	1	1951 2-Storey Central Classrooms	High 2	Structural Upgrade Required	High 1
39	Vancouver	SOUTHLANDS ELEMENTARY	2	1954 2-Storey South Classrooms	High 2	Structural Upgrade Required	
39	Vancouver	SOUTHLANDS ELEMENTARY	3	1951 Gymnasium	High 1	Structural Upgrade Required	
39	Vancouver	TECUMSEH ANNEX	1	Classroom Wing	Medium	Non Structural Upgrade Required	Medium
39	Vancouver	TECUMSEH ANNEX	2	Administrative Wing	Medium	Non Structural Upgrade Required	
39	Vancouver	TECUMSEH ANNEX	3	Gymnasium Wing	Medium	Non Structural Upgrade Required	
39	Vancouver	TECUMSEH ELEMENTARY	1	1910 3-Storey Classroom Wing	Medium	Non Structural Upgrade Required	Medium
39	Vancouver	TECUMSEH ELEMENTARY	2	1948 Gymnasium Wing	Medium	Non Structural Upgrade Required	
39	Vancouver	TECUMSEH ELEMENTARY	3	Classroom Wing	Low	Meets Structural Life Safety Requirements	
39	Vancouver	TECUMSEH ELEMENTARY	4	Classroom Wing	Low	Meets Structural Life Safety Requirements	
39	Vancouver	TEMPLETON SECONDARY	1	1926 3-Storey Classrooms (Blocks 1 & 1A)	High 2	Supported 2013	
39	Vancouver	TEMPLETON SECONDARY	2	1926 Auditorium/Gymnasium/Shops	High 1	Supported 2013	High 1
39	Vancouver	TEMPLETON SECONDARY	3	1928 Cafeteria/Library	Medium	Supported 2013	
39	Vancouver	TEMPLETON SECONDARY	4	1962 3-Storey Classrooms	High 1	Supported 2013	
39	Vancouver	TEMPLETON SECONDARY	5	1951 Gymnasium	High 2	Supported 2013	
39	Vancouver	TEMPLETON SECONDARY	6	1962 Shops (6 & 6a)	High 3	Supported 2013	
39	Vancouver	THUNDERBIRD ELEMENTARY	1	1946 1-Storey Classrooms (West)	High 3	Structural Upgrade Required	High 3
39	Vancouver	THUNDERBIRD ELEMENTARY	2	1971 2-Storey Classrooms (East)	High 3	Structural Upgrade Required	
39	Vancouver	THUNDERBIRD ELEMENTARY	3	1972 Gymnasium	High 3	Structural Upgrade Required	
39	Vancouver	THUNDERBIRD ELEMENTARY	4	Multi-Purpose	Low	Meets Structural Life Safety Requirements	
39	Vancouver	TILlicum ELEMENTARY ANNEX	1	1965 1-Storey Classrooms	High 1	Structural Upgrade Required	High 1
39	Vancouver	TILlicum ELEMENTARY ANNEX	2	1965 Gymnasium	High 1	Structural Upgrade Required	
39	Vancouver	TRAFALGAR ELEMENTARY	1	South Classrooms	N/A	Completed	N/A
39	Vancouver	TRAFALGAR ELEMENTARY	2	Gymnasium	N/A	Completed	
39	Vancouver	TRAFALGAR ELEMENTARY	3	North Classrooms	N/A	Completed	
39	Vancouver	TYEE ELEMENTARY	1	Classroom	Medium	Non Structural Upgrade Required	Medium
39	Vancouver	TYEE ELEMENTARY	2	Gym	Medium	Non Structural Upgrade Required	
39	Vancouver	UNIVERSITY HILL SECONDARY	1	Workshops	N/A	Completed	N/A
39	Vancouver	UNIVERSITY HILL SECONDARY	2	Gymnasium	N/A	Completed	
39	Vancouver	UNIVERSITY HILL SECONDARY	3	Auditorium	N/A	Completed	
39	Vancouver	UNIVERSITY HILL SECONDARY	4	Administration	N/A	Completed	
39	Vancouver	UNIVERSITY HILL SECONDARY	5	North Classrooms	N/A	Completed	
39	Vancouver	UNIVERSITY HILL SECONDARY	6	South Classrooms	N/A	Completed	
39	Vancouver	VANCOUVER TECHNICAL SECONDARY	1	Main Classroom West Wing	N/A	Completed	N/A
39	Vancouver	VANCOUVER TECHNICAL SECONDARY	2	Main Classroom East Wing	N/A	Completed	
39	Vancouver	VANCOUVER TECHNICAL SECONDARY	3	Woodwork Shop	N/A	Completed	
39	Vancouver	VANCOUVER TECHNICAL SECONDARY	4	Music Room	N/A	Completed	
39	Vancouver	VANCOUVER TECHNICAL SECONDARY	5	Auto Shop and Home Economics	N/A	Completed	
39	Vancouver	VANCOUVER TECHNICAL SECONDARY	6	Gymnasium and Cafeteria	N/A	Completed	
39	Vancouver	WALTER MOBERLY ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
39	Vancouver	WALTER MOBERLY ELEMENTARY	2	1950 Addition	N/A	Completed	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk	
39	Vancouver	WALTER MOBERLY ELEMENTARY	3	1946 Classrooms	N/A	Completed	N/A	
39	Vancouver	WALTER MOBERLY ELEMENTARY	4	Post 1992 Additions	N/A	Completed	N/A	
39	Vancouver	WAVERLEY ANNEX	1	1971 1-Storey Original Building	High 3	Structural Upgrade Required	High 3	
39	Vancouver	WAVERLEY ELEMENTARY	1	1958 1-Storey North Classrooms	High 1	Supported 2013	High 1	
39	Vancouver	WAVERLEY ELEMENTARY	2	1965 1-Storey South Classrooms	High 2	Supported 2013		
39	Vancouver	WAVERLEY ELEMENTARY	3	1965 Gymnasium	High 1	Supported 2013		
39	Vancouver	WINDERMERE COMMUNITY SECONDARY	1	1960 1-Storey Workshops (West Side)	High 2	Structural Upgrade Required		
39	Vancouver	WINDERMERE COMMUNITY SECONDARY	2	1960 Auditorium	High 2	Structural Upgrade Required	High 1	
39	Vancouver	WINDERMERE COMMUNITY SECONDARY	3	1960 3-Storey South-West Classrooms	High 3	Structural Upgrade Required		
39	Vancouver	WINDERMERE COMMUNITY SECONDARY	4	1960 2-Storey Cafeteria/Admin	High 1	Structural Upgrade Required		
39	Vancouver	WINDERMERE COMMUNITY SECONDARY	5	1960 3-Storey North & West Wing Classrooms	High 2	Structural Upgrade Required		
39	Vancouver	WINDERMERE COMMUNITY SECONDARY	6	1960 3-Storey East Wing Classrooms	High 3	Structural Upgrade Required		
39	Vancouver	WINDERMERE COMMUNITY SECONDARY	7	1970 3-Storey NorthEast Wing Classrooms	High 2	Non Structural Upgrade Required		
39	Vancouver	WINDERMERE COMMUNITY SECONDARY	8	1960 Gymnasium	High 2	Structural Upgrade Required		
39	Vancouver	WINDERMERE COMMUNITY SECONDARY	9	1970 Shops	High 2	Structural Upgrade Required		
40	New Westminster	CONNAUGHT HEIGHTS ELEMENTARY	1	single-storey classroom	Medium	Non Structural Upgrade Required		Medium
40	New Westminster	CONNAUGHT HEIGHTS ELEMENTARY	2	gymnasium	Medium	Non Structural Upgrade Required		
40	New Westminster	CONNAUGHT HEIGHTS ELEMENTARY	3	multipurpose	Medium	Non Structural Upgrade Required		
40	New Westminster	F W HOWAY ELEMENTARY	1	1973 2-Storey Classrooms	High 1	Supported 2013	High 1	
40	New Westminster	F W HOWAY ELEMENTARY	2	1973 Gymnasium	High 1	Supported 2013	High 2	
40	New Westminster	HUME PARK	1	1962 2-Storey Classroom	High 2	Inactive		
40	New Westminster	LORD KELVIN ELEMENTARY	1	1963 single-storey classroom	Low	Meets Structural Life Safety Requirements	Medium	
40	New Westminster	LORD KELVIN ELEMENTARY	2	1963 gymnasium	Medium	Non Structural Upgrade Required		
40	New Westminster	LORD KELVIN ELEMENTARY	3	2000 1-storey Classroom. Add'n	Low	Meets Structural Life Safety Requirements		
40	New Westminster	LORD TWEEDSMUIR ELEMENTARY	1	1937 2-Storey Classrooms	Low	Meets Structural Life Safety Requirements	High 2	
40	New Westminster	LORD TWEEDSMUIR ELEMENTARY	2	1937 2-Storey Gymnasium	High 2	Structural Upgrade Required		
40	New Westminster	LORD TWEEDSMUIR ELEMENTARY	3	1-Storey Classrooms	Low	Meets Structural Life Safety Requirements		
40	New Westminster	NEW WESTMINSTER SECONDARY	1	Two-Storey Classroom	High 1	Supported/Capital Project		
40	New Westminster	NEW WESTMINSTER SECONDARY	2	Small Gymnasium & Cafeteria	High 1	Supported/Capital Project	High 1	
40	New Westminster	NEW WESTMINSTER SECONDARY	3	1952 Single-Storey Cafeteria	High 1	Supported/Capital Project		
40	New Westminster	NEW WESTMINSTER SECONDARY	4	1955 Single-Storey Administration	High 1	Supported/Capital Project		
40	New Westminster	NEW WESTMINSTER SECONDARY	5	1972 Single-Storey Automotive Shops	High 3	Supported/Capital Project		
40	New Westminster	NEW WESTMINSTER SECONDARY	6	1969 Single-Storey Band Rooms	High 2	Supported/Capital Project		
40	New Westminster	NEW WESTMINSTER SECONDARY	7	North & South Large Gyms and Theatre	High 1	Supported/Capital Project		
40	New Westminster	NEW WESTMINSTER SECONDARY	8	1965 Library & Administration	High 1	Supported/Capital Project		
40	New Westminster	NEW WESTMINSTER SECONDARY	9	1965 Single-Storey Shops	High 1	Supported/Capital Project		
40	New Westminster	QAYQAYT ELEMENTARY (was John Robs)	1	1928 3-storey classroom	N/A	Completed	N/A	
40	New Westminster	QAYQAYT ELEMENTARY (was John Robs)	2	1928 Gymnasium	N/A	Completed		
40	New Westminster	QAYQAYT ELEMENTARY (was John Robs)	3	1971 single-storey classroom	N/A	Completed		
40	New Westminster	QUEEN ELIZABETH ELEMENTARY	1	1987 Single-storey Classroom	Low	Meets Structural Life Safety Requirements	Low	
40	New Westminster	QUEEN ELIZABETH ELEMENTARY	2	1987 Gymnasium	Low	Meets Structural Life Safety Requirements		
40	New Westminster	RICHARD MCBRIDE ELEMENTARY	1	1929 2-Storey Classroom	High 1	Supported 2013	High 1	
40	New Westminster	RICHARD MCBRIDE ELEMENTARY	2	1929 Gymnasium	High 2	Supported 2013		
41	Burnaby	ALPHA SECONDARY	1	1975 Gymnasium	High 2	Proceeding to Construction	High 1	
41	Burnaby	ALPHA SECONDARY	2	1950 1-Storey Classrooms	Medium	Proceeding to Construction		
41	Burnaby	ALPHA SECONDARY	3	1956 Small Gymnasium	High 2	Proceeding to Construction		
41	Burnaby	ALPHA SECONDARY	4	1956 2-Storey Classrooms	High 1	Proceeding to Construction		
41	Burnaby	ALPHA SECONDARY	5	1968 3-Storey Classrooms	High 1	Proceeding to Construction		

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
41	Burnaby	ALPHA SECONDARY	6	1968 Shops	High 1	Proceeding to Construction	
41	Burnaby	ARMSTRONG ELEMENTARY	1	1955 Gymnasium	High 1	Structural Upgrade Required	High 1
41	Burnaby	ARMSTRONG ELEMENTARY	2	1955 1-Storey Classrooms	High 3	Structural Upgrade Required	
41	Burnaby	AUBREY ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	AUBREY ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	AUBREY ELEMENTARY	3	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	BRANTFORD ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
41	Burnaby	BRANTFORD ELEMENTARY	2	Classrooms	N/A	Completed	
41	Burnaby	BRENTWOOD PARK ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	BRENTWOOD PARK ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	BRENTWOOD PARK ELEMENTARY	3	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	BUCKINGHAM ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	BUCKINGHAM ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	BURNABY CENTRAL SECONDARY	1	Large Gymnasium	N/A	Completed	N/A
41	Burnaby	BURNABY CENTRAL SECONDARY	2	3 Storey Classroom	N/A	Completed	
41	Burnaby	BURNABY CENTRAL SECONDARY	3	4 Storey Classroom	N/A	Completed	
41	Burnaby	BURNABY CENTRAL SECONDARY	4	Shops	N/A	Completed	
41	Burnaby	BURNABY CENTRAL SECONDARY	5	Small Gymnasium	N/A	Completed	
41	Burnaby	BURNABY NORTH SECONDARY	1	1960 Main Gym, Small Gym, Drama & Offices	High 1	Supported 2013	High 1
41	Burnaby	BURNABY NORTH SECONDARY	2	1960 3-Storey Classrooms	High 1	Supported 2013	
41	Burnaby	BURNABY NORTH SECONDARY	3	1960 Shops	High 1	Supported 2013	
41	Burnaby	BURNABY NORTH SECONDARY	4	1955 South Gymnasium	High 1	Supported 2013	
41	Burnaby	BURNABY NORTH SECONDARY	5	1955 2-Storey Classrooms	High 1	Supported 2013	
41	Burnaby	BURNABY NORTH SECONDARY	6	1955 1-Storey Classrooms/Admin	High 1	Supported 2013	
41	Burnaby	BURNABY SOUTH SECONDARY	1	Whole School	Low	Meets Structural Life Safety Requirements	Low
41	Burnaby	CAMERON ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	CAMERON ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	CANADA WAY EDUCATION CENTRE	1	Whole School	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	CAPITOL HILL ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
41	Burnaby	CAPITOL HILL ELEMENTARY	2	Two Storey Classroom	N/A	Completed	
41	Burnaby	CAPITOL HILL ELEMENTARY	3	Two Storey Classroom	N/A	Completed	
41	Burnaby	CAPITOL HILL ELEMENTARY	4	Two Storey Classroom	N/A	Completed	
41	Burnaby	CARIBOO HILL SECONDARY	1	Gymnasium	N/A	Completed	N/A
41	Burnaby	CARIBOO HILL SECONDARY	2	2 Storey Classroom	N/A	Completed	
41	Burnaby	CARIBOO HILL SECONDARY	3	3-Storey Classroom	N/A	Completed	
41	Burnaby	CARIBOO HILL SECONDARY	4	1 Storey Classroom	N/A	Completed	
41	Burnaby	CARIBOO HILL SECONDARY	5	Shops	N/A	Completed	
41	Burnaby	CARIBOO HILL SECONDARY	6	Auditorium	N/A	Completed	
41	Burnaby	CARIBOO HILL SECONDARY	7	2 Storey Classroom	N/A	Completed	
41	Burnaby	CASCADE HEIGHTS ELEMENTARY	1	1952 Gymnasium	Medium	Non Structural Upgrade Required	High 3
41	Burnaby	CASCADE HEIGHTS ELEMENTARY	2	1952 1-Storey Classrooms	Medium	Non Structural Upgrade Required	
41	Burnaby	CASCADE HEIGHTS ELEMENTARY	3	1969 1-Storey Classrooms	High 3	Structural Upgrade Required	
41	Burnaby	CASCADE HEIGHTS ELEMENTARY	4	1999 Classrooms	Low	Meets Structural Life Safety Requirements	
41	Burnaby	CHAFFEY-BURKE ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
41	Burnaby	CHAFFEY-BURKE ELEMENTARY	2	Classrooms	N/A	Completed	
41	Burnaby	CLINTON ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	CLINTON ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	CONFEDERATION PARK ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	CONFEDERATION PARK ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
41	Burnaby	DOUGLAS ROAD ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
41	Burnaby	DOUGLAS ROAD ELEMENTARY	2	2 storey classroom	N/A	Completed	
41	Burnaby	DOUGLAS ROAD ELEMENTARY	3	2 storey classroom	N/A	Completed	
41	Burnaby	DOUGLAS ROAD ELEMENTARY	4	Kindergarten	N/A	Completed	
41	Burnaby	EDMONDS COMMUNITY	1	Gymnasium	N/A	Completed	N/A
41	Burnaby	EDMONDS COMMUNITY	2	2-Storey Classroom	N/A	Completed	
41	Burnaby	EDMONDS COMMUNITY	3	1-Storey Classroom	N/A	Completed	
41	Burnaby	EDMONDS COMMUNITY	4	1-Storey Classroom	N/A	Completed	
41	Burnaby	EDMONDS COMMUNITY	5	2-Storey Classroom	N/A	Completed	Medium
41	Burnaby	FOREST GROVE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
41	Burnaby	FOREST GROVE ELEMENTARY	2	Classroom	Low	Meets Structural Life Safety Requirements	
41	Burnaby	FOREST GROVE ELEMENTARY	3	Classroom	Low	Meets Structural Life Safety Requirements	
41	Burnaby	GILMORE COMMUNITY ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
41	Burnaby	GILMORE COMMUNITY ELEMENTARY	2	1913 Classroom	N/A	Completed	
41	Burnaby	GILMORE COMMUNITY ELEMENTARY	3	Library wing	N/A	Completed	
41	Burnaby	GILMORE COMMUNITY ELEMENTARY	4	1928 Classroom	N/A	Completed	
41	Burnaby	GILMORE COMMUNITY ELEMENTARY	5	Primary classroom	N/A	Completed	Medium
41	Burnaby	GILPIN ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
41	Burnaby	GILPIN ELEMENTARY	2	Classroom / Admin	Medium	Non Structural Upgrade Required	
41	Burnaby	GILPIN ELEMENTARY	3	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	GLENWOOD ELEMENTARY	1	1955 Gymnasium	High 2	Structural Upgrade Required	High 2
41	Burnaby	GLENWOOD ELEMENTARY	2	1966 1-Storey Classroom Addition	High 2	Structural Upgrade Required	
41	Burnaby	GLENWOOD ELEMENTARY	3	1969 1-Storey Classrooms	High 3	Structural Upgrade Required	
41	Burnaby	INMAN ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
41	Burnaby	INMAN ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	INMAN ELEMENTARY	3	2 Storey Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	INMAN ELEMENTARY	4	Classroom 2003	Low	Meets Structural Life Safety Requirements	
41	Burnaby	KITCHENER ELEMENTARY	1	1973 Gymnasium	Low	Meets Structural Life Safety Requirements	High 3
41	Burnaby	KITCHENER ELEMENTARY	2	1923 2-Storey Classrooms	Low	Meets Structural Life Safety Requirements	
41	Burnaby	KITCHENER ELEMENTARY	3	1952 Primary Gymnasium	Medium	Non Structural Upgrade Required	
41	Burnaby	KITCHENER ELEMENTARY	4	1949 1-Storey Primary Classrooms	High 3	Structural Upgrade Required	
41	Burnaby	LAKEVIEW ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	LAKEVIEW ELEMENTARY	2	2-Storey Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	LAKEVIEW ELEMENTARY	3	1-Storey Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	LOCHDALE COMMUNITY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	LOCHDALE COMMUNITY	2	Classroom/Administration	Medium	Non Structural Upgrade Required	
41	Burnaby	LOCHDALE COMMUNITY	3	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	LYNDHURST ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	LYNDHURST ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	LYNDHURST ELEMENTARY	3	2 Storey Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	MARIAN EDUCATION CENTRE	1	Gymnasium	Medium	Inactive	High 1
41	Burnaby	MARIAN EDUCATION CENTRE	2	Classroom	High 1	Inactive	
41	Burnaby	MARLBOROUGH ELEMENTARY	1	1952 Primary Gymnasium	Medium	Non Structural Upgrade Required	High 3
41	Burnaby	MARLBOROUGH ELEMENTARY	2	1950 1-Storey Primary Classrooms	Medium	Non Structural Upgrade Required	
41	Burnaby	MARLBOROUGH ELEMENTARY	3	1965 West Gymnasium	Medium	Non Structural Upgrade Required	
41	Burnaby	MARLBOROUGH ELEMENTARY	4	1965 3-Storey Classrooms	High 3	Structural Upgrade Required	
41	Burnaby	MARLBOROUGH ELEMENTARY	5	1965 1-Storey Classrooms	Medium	Non Structural Upgrade Required	
41	Burnaby	MAYWOOD COMMUNITY ELEMENTARY	1	1962 Gymnasium	Medium	Non Structural Upgrade Required	
41	Burnaby	MAYWOOD COMMUNITY ELEMENTARY	2	1962 1-Storey Classrooms/Admin	High 3	Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
41	Burnaby	MAYWOOD COMMUNITY ELEMENTARY	3	1950 1-Storey Club Metro	Medium	Non Structural Upgrade Required	High 3
41	Burnaby	MAYWOOD COMMUNITY ELEMENTARY	4	1-Storey Modular Wing	Low	Meets Structural Life Safety Requirements	
41	Burnaby	MAYWOOD COMMUNITY ELEMENTARY	5	1968 2-Storey Classrooms	Low	Meets Structural Life Safety Requirements	
41	Burnaby	MONTECITO ELEMENTARY	1	1971 Gymnasium	Medium	Proceeding to Construction	High 1
41	Burnaby	MONTECITO ELEMENTARY	2	1971 2-Storey Classroom/Admin	High 1	Proceeding to Construction	
41	Burnaby	MORLEY ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
41	Burnaby	MORLEY ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	MORLEY ELEMENTARY	3	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	MORLEY ELEMENTARY	4	Classroom (1999)	Low	Meets Structural Life Safety Requirements	
41	Burnaby	MOSCROP JR SECONDARY	1	1955 Gymnasium	Medium	Non Structural Upgrade Required	High 3
41	Burnaby	MOSCROP JR SECONDARY	2	1955 3-Storey Classrooms	High 3	Structural Upgrade Required	
41	Burnaby	MOSCROP JR SECONDARY	3	1959 2-Storey Classrooms	High 3	Structural Upgrade Required	
41	Burnaby	MOSCROP JR SECONDARY	4	2001 Additions	Low	Meets Structural Life Safety Requirements	
41	Burnaby	NELSON ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	NELSON ELEMENTARY	2	2-Storey Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	NELSON ELEMENTARY	3	2-Storey Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	PARKCREST ELEMENTARY	1	1960 Gymnasium	Medium	Non Structural Upgrade Required	High 3
41	Burnaby	PARKCREST ELEMENTARY	2	1960 1-Storey Classrooms	Medium	Non Structural Upgrade Required	
41	Burnaby	PARKCREST ELEMENTARY	3	1964 2-Storey Classrooms	High 3	Structural Upgrade Required	
41	Burnaby	ROSSER ELEMENTARY	1	1954 Gymnasium	High 3	Structural Upgrade Required	High 3
41	Burnaby	ROSSER ELEMENTARY	2	1924 2-Storey Classrooms	Medium	Non Structural Upgrade Required	
41	Burnaby	SCHOU - RESOURCE CENTRE	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	SCHOU - RESOURCE CENTRE	2	1914 classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	SEAFORTH ELEMENTARY	1	1972 Gymnasium	Medium	Non Structural Upgrade Required	High 3
41	Burnaby	SEAFORTH ELEMENTARY	2	1957 1-Storey Classrooms/Admin	Medium	Non Structural Upgrade Required	
41	Burnaby	SEAFORTH ELEMENTARY	3	1965 1-Storey Classrooms	High 3	Structural Upgrade Required	
41	Burnaby	SEAFORTH ELEMENTARY	4	1982 1-Storey Classrooms	Low	Meets Structural Life Safety Requirements	
41	Burnaby	SEAFORTH ELEMENTARY	5	1993 Classrooms	Low	Meets Structural Life Safety Requirements	Medium
41	Burnaby	SECOND STREET COMMUNITY	1	Gymnasium	Medium	Non Structural Upgrade Required	
41	Burnaby	SECOND STREET COMMUNITY	2	2-Storey Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	SECOND STREET COMMUNITY	3	2-Storey Classroom (1999)	Low	Meets Structural Life Safety Requirements	Medium
41	Burnaby	SOUTH SLOPE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
41	Burnaby	SOUTH SLOPE ELEMENTARY	2	Single Storey Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	SOUTH SLOPE ELEMENTARY	3	Two Storey Classroom	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	SPERLING ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
41	Burnaby	SPERLING ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	High 3
41	Burnaby	STONE CREEK ELEMENTARY	1	1973 Gymnasium	Medium	Non Structural Upgrade Required	
41	Burnaby	STONE CREEK ELEMENTARY	2	1973 2-Storey Classrooms	High 3	Structural Upgrade Required	
41	Burnaby	STONE CREEK ELEMENTARY	3	Classrooms	Low	Meets Structural Life Safety Requirements	High 1
41	Burnaby	STRIDE AVENUE ELEMENTARY	1	1969 Gymnasium	Medium	Supported 2013	
41	Burnaby	STRIDE AVENUE ELEMENTARY	2	1924 2-Storey Classrooms	Medium	Supported 2013	
41	Burnaby	STRIDE AVENUE ELEMENTARY	3	1949 1-Storey Classrooms	Medium	Supported 2013	
41	Burnaby	STRIDE AVENUE ELEMENTARY	4	1969 2-Storey Classrooms	High 1	Supported 2013	Medium
41	Burnaby	SUNCREST ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
41	Burnaby	SUNCREST ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	TWELFTH AVENUE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
41	Burnaby	TWELFTH AVENUE ELEMENTARY	2	Library	Medium	Non Structural Upgrade Required	
41	Burnaby	TWELFTH AVENUE ELEMENTARY	3	1958, 1962 Classrooms	Medium	Non Structural Upgrade Required	
41	Burnaby	TWELFTH AVENUE ELEMENTARY	4	1964, 1967, 1969 Classrooms	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
41	Burnaby	WESTRIDGE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	WESTRIDGE ELEMENTARY	2	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	WESTRIDGE ELEMENTARY	3	Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	WINDSOR ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
41	Burnaby	WINDSOR ELEMENTARY	2	2 Storey Classroom	Medium	Non Structural Upgrade Required	
41	Burnaby	WINDSOR ELEMENTARY	3	1 Storey Classroom	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	ALBION ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
42	Maple Ridge/Pitt Meadow:	ALBION ELEMENTARY	2	Classroom - East	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	ALBION ELEMENTARY	3	Classroom - North/West	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	ALBION ELEMENTARY	4	Classroom - South/West	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	ALBION ELEMENTARY	5	Classroom Addition 2000	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	ALOUETTE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
42	Maple Ridge/Pitt Meadow:	ALOUETTE ELEMENTARY	2	Classrooms (1989)	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	ALOUETTE ELEMENTARY	3	Classrooms (1999)	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	ARTHUR PEAKE CENTRE	1	Activity Room	Low	Meets Structural Life Safety Requirements	Low
42	Maple Ridge/Pitt Meadow:	ARTHUR PEAKE CENTRE	2	Classrooms/Adminstration	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	ARTHUR PEAKE CENTRE	3	Classrooms (North)	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	DAVIE JONES ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
42	Maple Ridge/Pitt Meadow:	DAVIE JONES ELEMENTARY	2	1976 Classrooms	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	DAVIE JONES ELEMENTARY	3	1989 Classrooms	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	ERIC LANGTON ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
42	Maple Ridge/Pitt Meadow:	ERIC LANGTON ELEMENTARY	2	Classrooms - Centre	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	ERIC LANGTON ELEMENTARY	3	Classrooms - North	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	ERIC LANGTON ELEMENTARY	4	Library	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	ERIC LANGTON ELEMENTARY	5	Classrooms - East	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	FAIRVIEW ELEMENTARY	1	1989 1-Storey Classrooms (West)	Low	Meets Structural Life Safety Requirements	High 3
42	Maple Ridge/Pitt Meadow:	FAIRVIEW ELEMENTARY	2	1960 Gymnasium and Classrooms	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	FAIRVIEW ELEMENTARY	3	1980 1-Storey Classrooms (East)	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	FAIRVIEW ELEMENTARY	4	1960 1-Storey Classrooms & Admin. (N/E)	High 3	Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	GARIBALDI SECONDARY	1	Gymnasium	N/A	Completed	N/A
42	Maple Ridge/Pitt Meadow:	GARIBALDI SECONDARY	2	Administration Wing	N/A	Completed	
42	Maple Ridge/Pitt Meadow:	GARIBALDI SECONDARY	3	Classrooms - 2-Storey	N/A	Completed	
42	Maple Ridge/Pitt Meadow:	GARIBALDI SECONDARY	4	Classrooms and Administration	N/A	Completed	
42	Maple Ridge/Pitt Meadow:	GARIBALDI SECONDARY	5	Shops	N/A	Completed	
42	Maple Ridge/Pitt Meadow:	GARIBALDI SECONDARY	6	Classrooms - 1 Storey	N/A	Completed	
42	Maple Ridge/Pitt Meadow:	GARIBALDI SECONDARY	7	Cafeteria & Science Wing	N/A	Completed	
42	Maple Ridge/Pitt Meadow:	GARIBALDI SECONDARY	8	Auditorium - Upgraded in 1993	N/A	Completed	
42	Maple Ridge/Pitt Meadow:	GLENWOOD ELEMENTARY	1	Classrooms-South wing	Low	Meets Structural Life Safety Requirements	Low
42	Maple Ridge/Pitt Meadow:	GLENWOOD ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	GLENWOOD ELEMENTARY	3	Classrooms-North wing	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	GOLDEN EARS ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
42	Maple Ridge/Pitt Meadow:	GOLDEN EARS ELEMENTARY	2	Classrooms-West	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	GOLDEN EARS ELEMENTARY	3	Classrooms-East	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	GOLDEN EARS ELEMENTARY	4	Classrooms-South/West	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	GOLDEN EARS ELEMENTARY	5	Administration/Classrooms-1996	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	GOLDEN EARS ELEMENTARY	6	Classrooms-South/East-1999	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	HARRY HOOGE ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
42	Maple Ridge/Pitt Meadow:	HARRY HOOGE ELEMENTARY	2	Classrooms/Admin/Other	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	HARRY HOOGE ELEMENTARY	3	Classroom addition (1992)	Low	Meets Structural Life Safety Requirements	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
42	Maple Ridge/Pitt Meadow:	HIGHLAND PARK ELEMENTARY	1	Gymnasium and Services	Medium	Non Structural Upgrade Required	Medium
42	Maple Ridge/Pitt Meadow:	HIGHLAND PARK ELEMENTARY	2	Classrooms and Administration	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	HIGHLAND PARK ELEMENTARY	3	Classrooms	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	LAITY VIEW ELEMENTARY	1	Classrooms (1978 & 1981)	Low	Meets Structural Life Safety Requirements	Medium
42	Maple Ridge/Pitt Meadow:	LAITY VIEW ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	LAITY VIEW ELEMENTARY	3	Classrooms & Library (1991)	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	LAITY VIEW ELEMENTARY	4	Classrooms (2001)	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	MAPLE RIDGE ELEMENTARY	1	Washrooms/Change rooms	Medium	Non Structural Upgrade Required	Medium
42	Maple Ridge/Pitt Meadow:	MAPLE RIDGE ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	MAPLE RIDGE ELEMENTARY	3	Gymnasium	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	MAPLE RIDGE ELEMENTARY	4	Classrooms 1993	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	MAPLE RIDGE SECONDARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
42	Maple Ridge/Pitt Meadow:	MAPLE RIDGE SECONDARY	2	West Wing (Science)	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	MAPLE RIDGE SECONDARY	3	SE Classroom Block	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	MAPLE RIDGE SECONDARY	4	Arts and Shops Block	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	MOUNT CRESCENT ELEMENTARY	1	Classroom (North)	Low	Inactive	Medium
42	Maple Ridge/Pitt Meadow:	MOUNT CRESCENT ELEMENTARY	2	Gymnasium	Medium	Inactive	
42	Maple Ridge/Pitt Meadow:	MOUNT CRESCENT ELEMENTARY	3	Classroom (Central)	Medium	Inactive	
42	Maple Ridge/Pitt Meadow:	MOUNT CRESCENT ELEMENTARY	4	Classroom (West)	Medium	Inactive	
42	Maple Ridge/Pitt Meadow:	MOUNT CRESCENT ELEMENTARY	5	Classrooms	Medium	Inactive	
42	Maple Ridge/Pitt Meadow:	MOUNT CRESCENT ELEMENTARY	6	Classroom (1999 addition)	Low	Inactive	
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS ELEMENTARY	2	Classroom (North)	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS ELEMENTARY	3	Classroom (South)	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS ELEMENTARY	4	Classroom (West)	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS ELEMENTARY	5	Classroom (South-West)	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS SECONDARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS SECONDARY	2	Exercise Room	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS SECONDARY	3	Classrooms	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS SECONDARY	4	Library and Classrooms	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS SECONDARY	5	Shops	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS SECONDARY	6	Administration	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS SECONDARY	7	Multi-Purpose	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	PITT MEADOWS SECONDARY	8	Classrooms - Upgraded 1999	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	RIVERSIDE ELEMENTARY	1	Gymnasium	Medium	Inactive	Medium
42	Maple Ridge/Pitt Meadow:	RIVERSIDE ELEMENTARY	2	Classrooms (South)	Low	Inactive	
42	Maple Ridge/Pitt Meadow:	RIVERSIDE ELEMENTARY	3	Classrooms (North)	Low	Inactive	
42	Maple Ridge/Pitt Meadow:	WEBSTERS CORNER ELEMENTARY	1	Gymnasium (upgraded 1993)	Low	Meets Structural Life Safety Requirements	Medium
42	Maple Ridge/Pitt Meadow:	WEBSTERS CORNER ELEMENTARY	2	Classroom (East) upgraded 1993	Low	Meets Structural Life Safety Requirements	
42	Maple Ridge/Pitt Meadow:	WEBSTERS CORNER ELEMENTARY	3	Classroom (South)	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	WEBSTERS CORNER ELEMENTARY	4	Multi Purpose/Classroom	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	WESTVIEW SECONDARY	1	1992 1-Storey Classrooms/Multipurpose	High 3	Structural Upgrade Required	High 3
42	Maple Ridge/Pitt Meadow:	WESTVIEW SECONDARY	2	1992 Gymnasium	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	WESTVIEW SECONDARY	3	1992 1-Storey Classrooms/Library	Medium	Non Structural Upgrade Required	
42	Maple Ridge/Pitt Meadow:	WESTVIEW SECONDARY	4	1995 Classrooms/Shops	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	ANMORE ELEMENTARY	1	Classrooms	N/A	Completed	N/A
43	Coquitlam	ANMORE ELEMENTARY	2	Old Gymnasium	N/A	Completed	
43	Coquitlam	ANMORE ELEMENTARY	3	New Gymnasium	N/A	Completed	
43	Coquitlam	BAKER DRIVE ELEMENTARY	1	1969 2-storey classroom	N/A	Completed	N/A

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
43	Coquitlam	BAKER DRIVE ELEMENTARY	2	1969 gymnasium	N/A	Completed	N/A
43	Coquitlam	BANTING MIDDLE	1	1962 Central Gymnasium & Stage Block	High 1	Proceeding to Construction	High 1
43	Coquitlam	BANTING MIDDLE	2	1962 1-Storey Classroom & Admin. Block	High 1	Proceeding to Construction	
43	Coquitlam	BANTING MIDDLE	3	1962 2-Storey Northeast Classroom Block	High 1	Proceeding to Construction	
43	Coquitlam	BANTING MIDDLE	4	1968 2-Storey Southeast Classroom/Library	High 1	Proceeding to Construction	
43	Coquitlam	BANTING MIDDLE	5	1969 1-Storey West Music/Exercise	High 1	Proceeding to Construction	
43	Coquitlam	BIRCHLAND ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
43	Coquitlam	BIRCHLAND ELEMENTARY	2	Classroom/Admin	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	CAPE HORN ELEMENTARY	1	North Classroom	Medium	Non Structural Upgrade Required	Medium
43	Coquitlam	CAPE HORN ELEMENTARY	2	Activity Room	Medium	Non Structural Upgrade Required	
43	Coquitlam	CAPE HORN ELEMENTARY	3	South Classroom	Medium	Non Structural Upgrade Required	
43	Coquitlam	CEDAR DRIVE ELEMENTARY	1	1955 Gymnasium	Medium	Non Structural Upgrade Required	High 3
43	Coquitlam	CEDAR DRIVE ELEMENTARY	2	1969 1-Storey Classrooms (South)	High 3	Structural Upgrade Required	
43	Coquitlam	CEDAR DRIVE ELEMENTARY	3	Classrooms/Admin (1994 upgrade)	Low	Meets Structural Life Safety Requirements	N/A
43	Coquitlam	CENTENNIAL SECONDARY	1	1965 2-storey classroom	N/A	Under Construction	
43	Coquitlam	CENTENNIAL SECONDARY	2	1968 2-storey classroom	N/A	Under Construction	
43	Coquitlam	CENTENNIAL SECONDARY	3	1965 shops	N/A	Under Construction	
43	Coquitlam	CENTENNIAL SECONDARY	4	1965 gym / theatre	N/A	Under Construction	
43	Coquitlam	CENTENNIAL SECONDARY	5	1970 2-storey classroom	N/A	Under Construction	
43	Coquitlam	CENTENNIAL SECONDARY	6	2001 gym	N/A	Under Construction	Medium
43	Coquitlam	CENTRAL ELEMENTARY	1	1954-1973 Classrooms & gymnasium	Medium	Non Structural Upgrade Required	
43	Coquitlam	CENTRAL ELEMENTARY	2	1993 & 2001 Additions	Low	Meets Structural Life Safety Requirements	High 3
43	Coquitlam	COLLEGE PARK ELEMENTARY	1	1971 Gymnasium	Medium	Inactive	
43	Coquitlam	COLLEGE PARK ELEMENTARY	2	1971 Classroom	High 3	Inactive	
43	Coquitlam	COLLEGE PARK ELEMENTARY	3	1976 Classroom	Low	Inactive	Medium
43	Coquitlam	COMO LAKE MIDDLE	1	Main Building	Medium	Non Structural Upgrade Required	
43	Coquitlam	COMO LAKE MIDDLE	2	Gymnasium	Medium	Non Structural Upgrade Required	
43	Coquitlam	COMO LAKE MIDDLE	3	Classroom	Medium	Non Structural Upgrade Required	Medium
43	Coquitlam	COQUITLAM ALTERNATE BASIC EDUCA	1	Original Classroom Building	Medium	Non Structural Upgrade Required	
43	Coquitlam	COQUITLAM ALTERNATE BASIC EDUCA	2	1965 & 1969 Addition	Medium	Non Structural Upgrade Required	
43	Coquitlam	COQUITLAM ALTERNATE BASIC EDUCA	3	1979 Addition	Medium	Non Structural Upgrade Required	High 3
43	Coquitlam	CORONATION PARK ELEMENTARY	1	Gymnasium	High 3	Inactive	
43	Coquitlam	CORONATION PARK ELEMENTARY	2	Classrooms/Admin	High 3	Inactive	
43	Coquitlam	CORONATION PARK ELEMENTARY	3	Montessori	High 3	Inactive	High 3
43	Coquitlam	DR. CHARLES BEST SECONDARY	1	1969 3-Storey Classrooms	High 3	Structural Upgrade Required	
43	Coquitlam	DR. CHARLES BEST SECONDARY	2	1969 1-Storey Classrooms	High 3	Structural Upgrade Required	
43	Coquitlam	DR. CHARLES BEST SECONDARY	3	1969 Cafeteria & Gymnasium	High 3	Structural Upgrade Required	
43	Coquitlam	DR. CHARLES BEST SECONDARY	4	1999 2-Storey Classrooms	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	DR. CHARLES BEST SECONDARY	5	1999 Gymnasium	Low	Meets Structural Life Safety Requirements	N/A
43	Coquitlam	EAGLE RIDGE ELEMENTARY	1	Original Classroom	N/A	Completed	
43	Coquitlam	EAGLE RIDGE ELEMENTARY	2	Gymnasium	N/A	Completed	
43	Coquitlam	EAGLE RIDGE ELEMENTARY	3	1984 Two Storey Addition	N/A	Completed	
43	Coquitlam	EAGLE RIDGE ELEMENTARY	4	2004 repair to fire damage	N/A	Completed	High 3
43	Coquitlam	GLENAYRE ELEMENTARY	1	1959 1-Storey East Classrooms	Medium	Non Structural Upgrade Required	
43	Coquitlam	GLENAYRE ELEMENTARY	2	1958 2-Storey West Classrooms	High 3	Structural Upgrade Required	
43	Coquitlam	GLENAYRE ELEMENTARY	3	1958 Gymnasium	Medium	Non Structural Upgrade Required	Medium
43	Coquitlam	HARBOUR VIEW ELEMENTARY	1	1963 1-storey classroom	Medium	Non Structural Upgrade Required	
43	Coquitlam	HARBOUR VIEW ELEMENTARY	2	1970 1-storey classrooms	Medium	Non Structural Upgrade Required	
43	Coquitlam	HARBOUR VIEW ELEMENTARY	3	1963 gymnasium	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
43	Coquitlam	HAZEL TREMBATH ELEMENTARY	1	Classroom	Low	Meets Structural Life Safety Requirements	Low
43	Coquitlam	HAZEL TREMBATH ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	HILLCREST MIDDLE	1	1966 1-Storey Classrooms	High 3	Structural Upgrade Required	High 3
43	Coquitlam	HILLCREST MIDDLE	2	Multipurpose Room	Medium	Non Structural Upgrade Required	
43	Coquitlam	HILLCREST MIDDLE	3	Shops	Medium	Non Structural Upgrade Required	
43	Coquitlam	HILLCREST MIDDLE	4	Classrooms & Gym -'98 Addition	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	IOCO SCHOOL	1	Activity Room	Medium	Inactive	Medium
43	Coquitlam	IOCO SCHOOL	2	Classrooms	Medium	Inactive	
43	Coquitlam	IRVINE ELEMENTARY	1	1969 2-Storey North Classrooms & Admin	High 1	Supported 2013	High 1
43	Coquitlam	IRVINE ELEMENTARY	2	1970 2-Storey South Classrooms	High 1	Supported 2013	
43	Coquitlam	IRVINE ELEMENTARY	3	1971 Gymnasium	High 1	Supported 2013	
43	Coquitlam	JAMES PARK ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
43	Coquitlam	JAMES PARK ELEMENTARY	2	Classrooms (West)	N/A	Completed	
43	Coquitlam	JAMES PARK ELEMENTARY	3	Classrooms (East)	N/A	Completed	
43	Coquitlam	JAMES PARK ELEMENTARY	4	Classrooms (South-East)	N/A	Completed	
43	Coquitlam	KILMER ELEMENTARY	1	West Classroom	Low	Meets Structural Life Safety Requirements	Low
43	Coquitlam	KILMER ELEMENTARY	2	East Administration and Gym	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	LEIGH ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
43	Coquitlam	LEIGH ELEMENTARY	2	Classrooms (North)	Medium	Non Structural Upgrade Required	
43	Coquitlam	LEIGH ELEMENTARY	3	Classrooms (West)	Medium	Non Structural Upgrade Required	
43	Coquitlam	LEIGH ELEMENTARY	4	Classrooms and Administration	Medium	Non Structural Upgrade Required	
43	Coquitlam	LINCOLN ELEMENTARY	1	Classrooms	High 1	Inactive	High 1
43	Coquitlam	LINCOLN ELEMENTARY	2	Gymnasium	High 1	Inactive	
43	Coquitlam	LORD BADEN-POWELL ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
43	Coquitlam	LORD BADEN-POWELL ELEMENTARY	2	Classrooms - East	N/A	Completed	
43	Coquitlam	LORD BADEN-POWELL ELEMENTARY	3	Classrooms - West	N/A	Completed	
43	Coquitlam	MAILLARD MIDDLE	1	Original Building	N/A	Completed	N/A
43	Coquitlam	MAILLARD MIDDLE	2	Gymnasium	N/A	Completed	
43	Coquitlam	MAILLARD MIDDLE	3	1999 Addition	N/A	Completed	
43	Coquitlam	MAPLE CREEK MIDDLE	1	1975 Gymnasium	High 1	Structural Upgrade Required	High 1
43	Coquitlam	MAPLE CREEK MIDDLE	2	1975 2-Storey Classrooms	High 1	Structural Upgrade Required	
43	Coquitlam	MAPLE CREEK MIDDLE	3	Classrooms - 1999 Addition	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	MARY HILL ELEMENTARY	1	1961 1-Storey South Classrooms	High 3	Structural Upgrade Required	High 3
43	Coquitlam	MARY HILL ELEMENTARY	2	1960 1-Storey North Classrooms	High 3	Structural Upgrade Required	
43	Coquitlam	MARY HILL ELEMENTARY	3	1960 Gymnasium	Medium	Non Structural Upgrade Required	
43	Coquitlam	MEADOWBROOK ELEMENTARY	1	1975 1-storey classroom	N/A	Completed	N/A
43	Coquitlam	MEADOWBROOK ELEMENTARY	2	1967 gymnasium	N/A	Completed	
43	Coquitlam	MILLER PARK COMMUNITY	1	East - Classroom	N/A	Completed	N/A
43	Coquitlam	MILLER PARK COMMUNITY	2	North - Gym	N/A	Completed	
43	Coquitlam	MILLER PARK COMMUNITY	3	West - Classroom	N/A	Completed	
43	Coquitlam	MILLSIDE ELEMENTARY	1	Main Building	Medium	Inactive	Medium
43	Coquitlam	MILLSIDE ELEMENTARY	2	Annex	Low	Inactive	
43	Coquitlam	MINNEKHADA MIDDLE	1	1968 2-Storey Main Building	High 1	Supported 2013	High 1
43	Coquitlam	MINNEKHADA MIDDLE	2	1969 Gymnasium	High 1	Supported 2013	
43	Coquitlam	MINNEKHADA MIDDLE	3	1968 Technical/Art	High 1	Supported 2013	
43	Coquitlam	MONTGOMERY MIDDLE	1	1961 2-Storey Main Building	High 1	Supported 2013	High 1
43	Coquitlam	MONTGOMERY MIDDLE	2	1968 Music/Industrial Arts	High 1	Supported 2013	
43	Coquitlam	MONTGOMERY MIDDLE	3	1968 2-Storey Classroom Additions	High 1	Supported 2013	
43	Coquitlam	MOODY ELEMENTARY	1	1950 1-Storey Classrooms	High 2	Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
43	Coquitlam	MOODY ELEMENTARY	2	1957 2-Storey Classrooms	High 3	Structural Upgrade Required	High 2
43	Coquitlam	MOODY ELEMENTARY	3	1976 gymnasium	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	MOODY MIDDLE	1	1969 2-Storey Classrooms	NA	Under Construction	
43	Coquitlam	MOODY MIDDLE	2	1969 Industrial Arts	NA	Under Construction	
43	Coquitlam	MOODY MIDDLE	3	1969 Gymnasium & Cafeteria	NA	Under Construction	NA
43	Coquitlam	MOODY MIDDLE	4	1961 1-Storey Learning Resource Center	NA	Under Construction	
43	Coquitlam	MOODY MIDDLE	5	1993 Gym Addition	NA	Under Construction	
43	Coquitlam	MOUNTAIN MEADOWS ELEMENTARY	1	Original structure 1987	Medium	Non Structural Upgrade Required	
43	Coquitlam	MOUNTAIN MEADOWS ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	Medium
43	Coquitlam	MOUNTAIN MEADOWS ELEMENTARY	3	Addition 1989	Medium	Non Structural Upgrade Required	
43	Coquitlam	MOUNTAIN VIEW ELEMENTARY	1	Single storey classrooms	Medium	Non Structural Upgrade Required	
43	Coquitlam	MOUNTAIN VIEW ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	Medium
43	Coquitlam	MOUNTAIN VIEW ELEMENTARY	3	Two storey classrooms	Medium	Non Structural Upgrade Required	
43	Coquitlam	MUNDY ROAD ELEMENTARY	1	Classroom Additions	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	MUNDY ROAD ELEMENTARY	2	Original Building	Low	Meets Structural Life Safety Requirements	Low
43	Coquitlam	MUNDY ROAD ELEMENTARY	3	Multi-Purpose Room	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	NESTOR ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	NESTOR ELEMENTARY	2	Classrooms/library	Low	Meets Structural Life Safety Requirements	Medium
43	Coquitlam	NESTOR ELEMENTARY	3	Classrooms (South)	Medium	Non Structural Upgrade Required	
43	Coquitlam	NESTOR ELEMENTARY	4	Admin./Kindergarten (post 1992)	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	PANORAMA HEIGHTS ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	PANORAMA HEIGHTS ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	Low
43	Coquitlam	PANORAMA HEIGHTS ELEMENTARY	3	Central Hallway	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	PARKLAND ELEMENTARY	1	North-West Block	N/A	Completed	N/A
43	Coquitlam	PARKLAND ELEMENTARY	2	South-East Block	N/A	Completed	
43	Coquitlam	PINETREE WAY ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	PINETREE WAY ELEMENTARY	2	Classrooms - West	Low	Meets Structural Life Safety Requirements	Low
43	Coquitlam	PINETREE WAY ELEMENTARY	3	Rotunda at Entrance	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	PINETREE WAY ELEMENTARY	4	Classrooms - East	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	PITT RIVER MIDDLE	1	Main Building	N/A	Completed	
43	Coquitlam	PITT RIVER MIDDLE	2	North Gym	N/A	Completed	
43	Coquitlam	PITT RIVER MIDDLE	3	East Classroom	N/A	Completed	N/A
43	Coquitlam	PITT RIVER MIDDLE	4	Music Room	N/A	Completed	
43	Coquitlam	PITT RIVER MIDDLE	5	Shop Wing	N/A	Completed	
43	Coquitlam	PLEASANTSIDE ELEMENTARY	1	Gymnasium	N/A	Completed	
43	Coquitlam	PLEASANTSIDE ELEMENTARY	2	1967 and 1976 Classrooms	N/A	Completed	N/A
43	Coquitlam	PLEASANTSIDE ELEMENTARY	3	1980 Classrooms	N/A	Completed	
43	Coquitlam	PORT MOODY SECONDARY	1	1972 3-Storey North Classrooms	High 3	Structural Upgrade Required	
43	Coquitlam	PORT MOODY SECONDARY	2	1972 2-Storey South Classrooms	High 3	Structural Upgrade Required	High 3
43	Coquitlam	PORT MOODY SECONDARY	3	1972 Gymnasium/Music/Media Rooms	Low	Meets Structural Life Safety Requirements	
43	Coquitlam	PORTER STREET ELEMENTARY	1	Classroom Block	N/A	Completed	
43	Coquitlam	PORTER STREET ELEMENTARY	2	Gym Block	N/A	Completed	N/A
43	Coquitlam	R C MACDONALD ELEMENTARY	1	Classroom Block	N/A	Completed	
43	Coquitlam	R C MACDONALD ELEMENTARY	2	Gym Block	N/A	Completed	N/A
43	Coquitlam	RANCH PARK ELEMENTARY	1	1962 1-storey classroom	N/A	Completed	
43	Coquitlam	RANCH PARK ELEMENTARY	2	1962 gymnasium	N/A	Completed	N/A
43	Coquitlam	ROCHESTER ELEMENTARY	1	Classroom	N/A	Completed	
43	Coquitlam	ROCHESTER ELEMENTARY	2	Gymnasium	N/A	Completed	N/A
43	Coquitlam	ROCHESTER ELEMENTARY	3	Dressing Rooms	N/A	Completed	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
43	Coquitlam	ROY STIBBS ELEMENTARY	1	Single Storey Admin	N/A	Completed	N/A
43	Coquitlam	ROY STIBBS ELEMENTARY	2	Gymnasium	N/A	Completed	
43	Coquitlam	ROY STIBBS ELEMENTARY	3	1994 Two-Storey Classroom	N/A	Completed	
43	Coquitlam	SEAVIEW COMMUNITY SCHOOL	1	1964 & 1966 classrooms	N/A	Completed	N/A
43	Coquitlam	SEAVIEW COMMUNITY SCHOOL	2	1966 Activity Room	N/A	Completed	
43	Coquitlam	SEAVIEW COMMUNITY SCHOOL	3	1968 classrooms	N/A	Completed	
43	Coquitlam	VANIER ELEMENTARY	1	Classroom	High 3	Inactive	High 3
43	Coquitlam	VANIER ELEMENTARY	2	Gym	High 3	Inactive	
43	Coquitlam	WALTON ELEMENTARY	1	Original Structure	Medium	Non Structural Upgrade Required	Medium
43	Coquitlam	WALTON ELEMENTARY	2	School Addition	Medium	Non Structural Upgrade Required	
43	Coquitlam	WESTWOOD ELEMENTARY	1	Original 1969 structure	N/A	Completed	N/A
43	Coquitlam	WESTWOOD ELEMENTARY	2	1992 Gymnasium Addition	N/A	Completed	
43	Coquitlam	WESTWOOD ELEMENTARY	3	1992 Classroom Block Addition	N/A	Completed	
44	North Vancouver	ARGYLE SECONDARY	1	1960 2-Storey Classrooms	High 1	Supported 2012	High 1
44	North Vancouver	ARGYLE SECONDARY	2	1960 Gymnasium	High 1	Supported 2012	
44	North Vancouver	ARGYLE SECONDARY	3	1969 3-Storey Classrooms	High 1	Supported 2012	
44	North Vancouver	ARGYLE SECONDARY	4	1969 Gymnasium	High 1	Supported 2012	
44	North Vancouver	ARGYLE SECONDARY	5	1969 2-Storey Classrooms	High 2	Supported 2012	
44	North Vancouver	ARGYLE SECONDARY	6	1959 1-Storey Shop Wing	High 1	Supported 2012	
44	North Vancouver	ARGYLE SECONDARY	7	2000 Library & Cafeteria Add'n	Low	Supported 2012	
44	North Vancouver	BALMORAL JR SECONDARY	1	1959 3-Storey Classrooms	High 3	Structural Upgrade Required	High 3
44	North Vancouver	BALMORAL JR SECONDARY	2	1959 Gymnasium	Medium	Non Structural Upgrade Required	
44	North Vancouver	BALMORAL JR SECONDARY	3	1959 2-Storey Administration	High 3	Structural Upgrade Required	
44	North Vancouver	BLUERIDGE ELEMENTARY	1	SW Classrooms	Medium	Inactive	Medium
44	North Vancouver	BLUERIDGE ELEMENTARY	2	NW Classrooms	Low	Inactive	
44	North Vancouver	BLUERIDGE ELEMENTARY	3	SE Gymnasium	Low	Inactive	
44	North Vancouver	BLUERIDGE ELEMENTARY	4	NE Classrooms	Medium	Inactive	
44	North Vancouver	BOUNDARY COMMUNITY ELEMENTARY	1	West Classrooms	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	BOUNDARY COMMUNITY ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	
44	North Vancouver	BOUNDARY COMMUNITY ELEMENTARY	3	Library & Multi-Purpose	Medium	Non Structural Upgrade Required	
44	North Vancouver	BOUNDARY COMMUNITY ELEMENTARY	4	East Classrooms	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	BRAEMAR ELEMENTARY	1	East Classrooms	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	BRAEMAR ELEMENTARY	2	West and Central Classrooms	Medium	Non Structural Upgrade Required	
44	North Vancouver	BRAEMAR ELEMENTARY	3	Gymnasium	Medium	Non Structural Upgrade Required	
44	North Vancouver	BRAEMAR ELEMENTARY	4	Library and Multi-Purpose	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	BROOKSBANK ELEMENTARY	1	North Classroom Wing	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	BROOKSBANK ELEMENTARY	2	South Classroom Wing	Medium	Non Structural Upgrade Required	
44	North Vancouver	BROOKSBANK ELEMENTARY	3	Central Classrooms and Gymnasium	Medium	Non Structural Upgrade Required	
44	North Vancouver	CANYON HEIGHTS ELEMENTARY	1	gymnasium	N/A	Completed	N/A
44	North Vancouver	CANYON HEIGHTS ELEMENTARY	2	1-storey classroom/admin.	N/A	Completed	
44	North Vancouver	CANYON HEIGHTS ELEMENTARY	3	2-storey classroom block	N/A	Completed	
44	North Vancouver	CAPILANO ELEMENTARY	1	original 2-storey classroom	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	CAPILANO ELEMENTARY	2	1958 gymnasium	Medium	Non Structural Upgrade Required	
44	North Vancouver	CAPILANO ELEMENTARY	3	1958/1963 2-storey classroom	Medium	Non Structural Upgrade Required	
44	North Vancouver	CAPILANO ELEMENTARY	4	Two-Storey Classroom	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	CARISBROOKE ELEMENTARY	1	1959 two-storey classroom	N/A	Completed	N/A
44	North Vancouver	CARISBROOKE ELEMENTARY	2	1959 classroom	N/A	Completed	
44	North Vancouver	CARISBROOKE ELEMENTARY	3	1962 two-storey classroom add'n	N/A	Completed	
44	North Vancouver	CARISBROOKE ELEMENTARY	4	1969 library	N/A	Completed	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
44	North Vancouver	CARISBROOKE ELEMENTARY	5	2001 Gymnasium & Administration	N/A	Completed	
44	North Vancouver	CARSON GRAHAM SECONDARY	1	1964 Administration/ Classroom Wing	N/A	Completed	
44	North Vancouver	CARSON GRAHAM SECONDARY	2	1964 Gymnasium	N/A	Completed	
44	North Vancouver	CARSON GRAHAM SECONDARY	3	1964 Vocational	N/A	Completed	
44	North Vancouver	CARSON GRAHAM SECONDARY	4	1964 Electronics Wing	N/A	Completed	
44	North Vancouver	CARSON GRAHAM SECONDARY	5	1964 Shops Wing	N/A	Completed	N/A
44	North Vancouver	CARSON GRAHAM SECONDARY	6	1966/1973 Classroom Addition	N/A	Completed	
44	North Vancouver	CARSON GRAHAM SECONDARY	7	1966 Vocational Wing Addition	N/A	Completed	
44	North Vancouver	CARSON GRAHAM SECONDARY	8	2001 Gymnasium/Administration Add'n	N/A	Completed	
44	North Vancouver	CLEVELAND ELEMENTARY	1	1962 two-storey classroom	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	CLEVELAND ELEMENTARY	2	1962 gymnasium	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	CLEVELAND ELEMENTARY	3	1967 single-storey classroom	Medium	Non Structural Upgrade Required	
44	North Vancouver	CLEVELAND ELEMENTARY	4	1988 single-storey multi-purpose	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	CONTINUING ED SD 44	1	1955 Two-Storey Classroom	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	CONTINUING ED SD 44	2	1955 Gymnasium	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	CONTINUING ED SD 44	3	1955 Single-Storey Administration	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	CONTINUING ED SD 44	4	1955 Single-Storey Maintenance Stores	Medium	Non Structural Upgrade Required	
44	North Vancouver	CONTINUING ED SD 44	5	1955 Single-Storey Cafeteria	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	COVE CLIFF ELEMENTARY	1	Classrooms	Low	Meets Structural Life Safety Requirements	Low
44	North Vancouver	COVE CLIFF ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	CURRICULUM SERVICE CENTER	1	1962 Single-Storey Curriculum Ctr	Medium	Non Structural Upgrade Required	
44	North Vancouver	CURRICULUM SERVICE CENTER	2	1965 Gymnasium	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	CURRICULUM SERVICE CENTER	3	1977 Single-Storey Curriculum Ctr	Medium	Non Structural Upgrade Required	
44	North Vancouver	DOROTHY LYNAS ELEMENTARY	1	1990 Classroom & Gymnasium	Low	Meets Structural Life Safety Requirements	Low
44	North Vancouver	EASTVIEW ELEMENTARY	1	North Classrooms	Medium	Non Structural Upgrade Required	
44	North Vancouver	EASTVIEW ELEMENTARY	2	West Gymnasium and Multi-Purpose	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	EASTVIEW ELEMENTARY	3	South Central Classrooms	Medium	Non Structural Upgrade Required	
44	North Vancouver	EASTVIEW ELEMENTARY	4	Activity Area & East Classrooms	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	FROMME ELEMENTARY	1	Classrooms	Low	Inactive	Medium
44	North Vancouver	FROMME ELEMENTARY	2	Gymnasium	Medium	Inactive	
44	North Vancouver	HANDSWORTH SECONDARY	1	1960 2-Storey North Classrooms	High 1	Supported 2013	
44	North Vancouver	HANDSWORTH SECONDARY	2	1965 2-Storey East Classrooms	High 1	Supported 2013	
44	North Vancouver	HANDSWORTH SECONDARY	3	1971 3-Storey Southeast Classrooms	High 1	Supported 2013	
44	North Vancouver	HANDSWORTH SECONDARY	4	1960 1-Storey Cafeteria	High 1	Supported 2013	High 1
44	North Vancouver	HANDSWORTH SECONDARY	5	1965 Automotive Shop	High 1	Supported 2013	
44	North Vancouver	HANDSWORTH SECONDARY	6	1960 Main Gymnasium	High 1	Supported 2013	
44	North Vancouver	HANDSWORTH SECONDARY	7	1971 West Gym & Music Room	High 1	Supported 2013	
44	North Vancouver	HANDSWORTH SECONDARY	8	1971 2-Storey Central Library & Classrooms	Low	Supported 2013	
44	North Vancouver	HIGHLANDS ELEMENTARY	1	1950 1&2 storey classrm & Admin	N/A	Completed	
44	North Vancouver	HIGHLANDS ELEMENTARY	2	1959 gymnasium	N/A	Completed	
44	North Vancouver	HIGHLANDS ELEMENTARY	3	1952 single-storey classroom	N/A	Completed	N/A
44	North Vancouver	HIGHLANDS ELEMENTARY	4	1952 gymnasium	N/A	Completed	
44	North Vancouver	HIGHLANDS ELEMENTARY	5	1953 Two-storey classroom	N/A	Completed	
44	North Vancouver	KEITH LYNN ALTERNATIVE SECONDAR'	1	1951 single-storey classroom	Medium	Inactive	
44	North Vancouver	KEITH LYNN ALTERNATIVE SECONDAR'	2	1958 gymnasium	High 3	Inactive	High 3
44	North Vancouver	KEITH LYNN ALTERNATIVE SECONDAR'	3	1915/1964 two-storey classroom	Medium	Inactive	
44	North Vancouver	KEITH LYNN ALTERNATIVE SECONDAR'	4	1972 Library addition	Medium	Inactive	
44	North Vancouver	LARSON ELEMENTARY	1	1964 two-storey classroom	Medium	Non Structural Upgrade Required	
44	North Vancouver	LARSON ELEMENTARY	2	1964 gymnasium	Medium	Non Structural Upgrade Required	Medium

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
44	North Vancouver	LARSON ELEMENTARY	3	1965 single-storey classroom	Low	Meets Structural Life Safety Requirements	Medium
44	North Vancouver	LARSON ELEMENTARY	4	Two-Storey Classroom & Gym Add'n	Low	Meets Structural Life Safety Requirements	Medium
44	North Vancouver	LONSDALE ELEMENTARY	1	1911 Classroom Block	High 3	Inactive	High 3
44	North Vancouver	LONSDALE ELEMENTARY	2	1967 Library Addition	Medium	Inactive	
44	North Vancouver	LONSDALE ELEMENTARY	3	1957 Gymnasium	Medium	Inactive	
44	North Vancouver	LONSDALE ELEMENTARY	4	Annex	Medium	Inactive	
44	North Vancouver	LYNNMOUR COMMUNITY	1	West Classrooms	Medium	Non Structural Upgrade Required	
44	North Vancouver	LYNNMOUR COMMUNITY	2	Central Classrooms	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	LYNNMOUR COMMUNITY	3	East Gymnasium	Medium	Non Structural Upgrade Required	
44	North Vancouver	LYNNMOUR COMMUNITY	4	East Classrooms	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	MONTROYAL ELEMENTARY	1	South Classrooms	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	MONTROYAL ELEMENTARY	2	Central Classrooms	Medium	Non Structural Upgrade Required	
44	North Vancouver	MONTROYAL ELEMENTARY	3	North Music and Multi-Purpose	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	MONTROYAL ELEMENTARY	4	North Gymnasium	Medium	Non Structural Upgrade Required	
44	North Vancouver	NORGATE COMMUNITY ELEMENTARY	1	1951 single-storey classroom	Medium	Non Structural Upgrade Required	
44	North Vancouver	NORGATE COMMUNITY ELEMENTARY	2	1958 Gymnasium - 2001 upgrade	Low	Meets Structural Life Safety Requirements	Medium
44	North Vancouver	NORGATE COMMUNITY ELEMENTARY	3	2001 Single-storey Classroom	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	NORGATE COMMUNITY ELEMENTARY	4	1969 library	Medium	Non Structural Upgrade Required	
44	North Vancouver	OUTDOOR SCHOOL	1	Cafeteria and Office	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	OUTDOOR SCHOOL	2	Activity Room	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	OUTDOOR SCHOOL	3	Conference	Medium	Non Structural Upgrade Required	
44	North Vancouver	OUTDOOR SCHOOL	4	Barn	Medium	Non Structural Upgrade Required	
44	North Vancouver	OUTDOOR SCHOOL	5	Lab	Medium	Non Structural Upgrade Required	
44	North Vancouver	PLYMOUTH ELEMENTARY	1	Administration/ Gymnasium Block	Medium	Inactive	High 2
44	North Vancouver	PLYMOUTH ELEMENTARY	2	1969 Classroom Block	High 2	Inactive	
44	North Vancouver	PLYMOUTH ELEMENTARY	3	1975 Classroom Block	Medium	Inactive	
44	North Vancouver	QUEEN MARY ELEMENTARY	1	South Classrooms	N/A	Completed	N/A
44	North Vancouver	QUEEN MARY ELEMENTARY	2	North Gymnasium	N/A	Completed	
44	North Vancouver	QUEENSBURY ELEMENTARY	1	1955 Wing	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	QUEENSBURY ELEMENTARY	2	1958 Addition	Medium	Non Structural Upgrade Required	
44	North Vancouver	QUEENSBURY ELEMENTARY	3	gymnasium and administration	Medium	Non Structural Upgrade Required	
44	North Vancouver	RIDGEWAY ANNEX	1	Classroom Block	High 3	Inactive	High 3
44	North Vancouver	RIDGEWAY ANNEX	2	Gymnasium Block	Medium	Inactive	
44	North Vancouver	RIDGEWAY ELEMENTARY	1	Main Block (1911)	N/A	Completed	N/A
44	North Vancouver	RIDGEWAY ELEMENTARY	2	North Addition (1920)	N/A	Completed	
44	North Vancouver	RIDGEWAY ELEMENTARY	3	South Addition (1920)	N/A	Completed	
44	North Vancouver	RIDGEWAY ELEMENTARY	4	East Block (1944)	N/A	Completed	
44	North Vancouver	RIDGEWAY ELEMENTARY	5	Gymnasium Block (1959)	N/A	Completed	
44	North Vancouver	ROSS ROAD ELEMENTARY	1	South Classrooms	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	ROSS ROAD ELEMENTARY	2	Central Classrooms and Library	Medium	Non Structural Upgrade Required	
44	North Vancouver	ROSS ROAD ELEMENTARY	3	North Classrooms	Medium	Non Structural Upgrade Required	
44	North Vancouver	ROSS ROAD ELEMENTARY	4	Gymnasium	Medium	Non Structural Upgrade Required	
44	North Vancouver	ROSS ROAD ELEMENTARY	5	East Building	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	ROSS ROAD ELEMENTARY	6	Covered Play Area	Medium	Non Structural Upgrade Required	
44	North Vancouver	SEYCOVE SECONDARY COMMUNITY	1	2-storey upper classroom	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	SEYCOVE SECONDARY COMMUNITY	2	Gymnasium block	Medium	Non Structural Upgrade Required	
44	North Vancouver	SEYCOVE SECONDARY COMMUNITY	3	Shops/ Library/ Office Wing	Medium	Non Structural Upgrade Required	
44	North Vancouver	SEYCOVE SECONDARY COMMUNITY	4	2001 Addition	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	SEYMOUR HEIGHTS ELEMENTARY	1	South Classrooms	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
44	North Vancouver	SEYMOUR HEIGHTS ELEMENTARY	2	North Classrooms	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	SEYMOUR HEIGHTS ELEMENTARY	3	East Gymnasium	Medium	Non Structural Upgrade Required	
44	North Vancouver	SEYMOUR HEIGHTS ELEMENTARY	4	West Library	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	SHERWOOD PARK ELEMENTARY	1	1963 two-storey classroom	Medium	Non Structural Upgrade Required	Medium
44	North Vancouver	SHERWOOD PARK ELEMENTARY	2	1963 gymnasium	Medium	Non Structural Upgrade Required	
44	North Vancouver	SHERWOOD PARK ELEMENTARY	3	1976 two-storey classroom add'n	Medium	Non Structural Upgrade Required	
44	North Vancouver	SHERWOOD PARK ELEMENTARY	4	1999 Two-storey Classroom	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	UPPER LYNN ELEMENTARY	1	Classrooms	Low	Meets Structural Life Safety Requirements	Medium
44	North Vancouver	UPPER LYNN ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	UPPER LYNN ELEMENTARY	3	Library	Medium	Non Structural Upgrade Required	
44	North Vancouver	UPPER LYNN ELEMENTARY	4	Administration	Low	Meets Structural Life Safety Requirements	
44	North Vancouver	WESTVIEW ELEMENTARY	1	Classrooms	N/A	Completed	N/A
44	North Vancouver	WESTVIEW ELEMENTARY	2	Gymnasium	N/A	Completed	
44	North Vancouver	WESTVIEW ELEMENTARY	3	Covered Play Area	N/A	Completed	
44	North Vancouver	WINDSOR SECONDARY	1	1959 3-Storey Classrooms	NA	Under Construction	NA
44	North Vancouver	WINDSOR SECONDARY	2	1959 2-Storey Classrooms	NA	Under Construction	
44	North Vancouver	WINDSOR SECONDARY	3	1971 2-Storey Classrooms	NA	Under Construction	
44	North Vancouver	WINDSOR SECONDARY	4	1972 2-Storey Classrooms	NA	Under Construction	
44	North Vancouver	WINDSOR SECONDARY	5	1959 Gymnasium	NA	Under Construction	
44	North Vancouver	WINDSOR SECONDARY	6	1973 Gymnasium	NA	Under Construction	
44	North Vancouver	WINDSOR SECONDARY	7	1972 2-Storey Shops	NA	Under Construction	
44	North Vancouver	WINDSOR SECONDARY	8	1967 3-Storey Classrooms	NA	Under Construction	
45	West Vancouver	BOWEN ISLAND COMMUNITY	1	Original Block	Low	Meets Structural Life Safety Requirements	Low
45	West Vancouver	BOWEN ISLAND COMMUNITY	2	1998 Addition	Low	Meets Structural Life Safety Requirements	
45	West Vancouver	CAULFEILD ELEMENTARY	1	Original Block	Low	Meets Structural Life Safety Requirements	Medium
45	West Vancouver	CAULFEILD ELEMENTARY	2	1959 Gymnasium	Medium	Non Structural Upgrade Required	
45	West Vancouver	CAULFEILD ELEMENTARY	3	1998 Addition	Low	Meets Structural Life Safety Requirements	
45	West Vancouver	CEDARDALE CENTRE	1	Original Block	Low	Meets Structural Life Safety Requirements	Medium
45	West Vancouver	CEDARDALE CENTRE	2	1965 Activity Room Block	Medium	Non Structural Upgrade Required	
45	West Vancouver	CHARTWELL ELEMENTARY	1	Original Block	Low	Meets Structural Life Safety Requirements	Medium
45	West Vancouver	CHARTWELL ELEMENTARY	2	1976 Activity Room Block	Medium	Non Structural Upgrade Required	
45	West Vancouver	CYPRESS PARK PRIMARY	1	Original Block	Low	Meets Structural Life Safety Requirements	Low
45	West Vancouver	EAGLE HARBOUR PRIMARY	1	Original Block	Low	Meets Structural Life Safety Requirements	Medium
45	West Vancouver	EAGLE HARBOUR PRIMARY	2	1977 Activity Room Block	Medium	Non Structural Upgrade Required	
45	West Vancouver	GLENEAGLES ELEMENTARY	1	1950,1960,1967 Additions	Low	Meets Structural Life Safety Requirements	Low
45	West Vancouver	HOLLYBURN ELEMENTARY	1	1936 Block	Low	Meets Structural Life Safety Requirements	Low
45	West Vancouver	HOLLYBURN ELEMENTARY	2	1955,1959,1963,1967 Additions	Low	Meets Structural Life Safety Requirements	
45	West Vancouver	INGLEWOOD ANNEX	1	1957 Building	Medium	Non Structural Upgrade Required	Medium
45	West Vancouver	IRWIN PARK ELEMENTARY	1	1955 Bldg;1964, 1966 Additions	Medium	Non Structural Upgrade Required	Medium
45	West Vancouver	LIONS BAY COMMUNITY	1	1976 Bldg	Low	Meets Structural Life Safety Requirements	Low
45	West Vancouver	LIONS BAY COMMUNITY	2	1976 Activity Room	Low	Meets Structural Life Safety Requirements	
45	West Vancouver	PAULINE JOHNSON ELEMENTARY	1	1922 Bldg, 1943,1949 Additions	Low	Meets Structural Life Safety Requirements	Low
45	West Vancouver	RIDGEVIEW ELEMENTARY	1	1950 Bldg, 1960 Addition	Low	Meets Structural Life Safety Requirements	Medium
45	West Vancouver	RIDGEVIEW ELEMENTARY	2	1964 Detached North Wing	Medium	Non Structural Upgrade Required	
45	West Vancouver	SENTINEL SECONDARY	1	1962 2-Storey North Wing w. 1969 Addition	High 3	Structural Upgrade Required	High 3
45	West Vancouver	SENTINEL SECONDARY	2	1962 3-Storey South Wing w.1967 Addition	High 3	Structural Upgrade Required	
45	West Vancouver	SENTINEL SECONDARY	3	1962 Gym and 1969 Addition	High 3	Structural Upgrade Required	
45	West Vancouver	SENTINEL SECONDARY	4	1962 Cafeteria Wing	High 3	Structural Upgrade Required	
45	West Vancouver	WEST BAY ELEMENTARY	1	1952 Building, 1955,1965 Additio	Low	Meets Structural Life Safety Requirements	Medium

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
45 West Vancouver	WEST BAY ELEMENTARY	WEST BAY ELEMENTARY	2	1955 Activity Room	Medium	Non Structural Upgrade Required	Medium
45 West Vancouver	WEST VANCOUVER SECONDARY	WEST VANCOUVER SECONDARY	1	1957 Building	N/A	Completed	N/A
45 West Vancouver	WEST VANCOUVER SECONDARY	WEST VANCOUVER SECONDARY	2	East Classroom Wing	N/A	Completed	
45 West Vancouver	WEST VANCOUVER SECONDARY	WEST VANCOUVER SECONDARY	3	Middle Classroom Wing	N/A	Completed	
45 West Vancouver	WEST VANCOUVER SECONDARY	WEST VANCOUVER SECONDARY	4	West Classroom Wing	N/A	Completed	
45 West Vancouver	WEST VANCOUVER SECONDARY	WEST VANCOUVER SECONDARY	5	1999 Gymnasium	N/A	Completed	
45 West Vancouver	WEST VANCOUVER SECONDARY	WEST VANCOUVER SECONDARY	6	Music/Drama Wing	N/A	Completed	
45 West Vancouver	WEST VANCOUVER SECONDARY	WEST VANCOUVER SECONDARY	7	Industrial Education Building	N/A	Completed	
45 West Vancouver	WEST VANCOUVER SECONDARY	WEST VANCOUVER SECONDARY	8	Kay Meek Centre for the Performing Arts	N/A	Completed	
45 West Vancouver	WESTCOT ELEMENTARY	WESTCOT ELEMENTARY	1	1957, 1959, 1964 Building	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	CEDAR GROVE ELEMENTARY	CEDAR GROVE ELEMENTARY	1	Classroom/Admin.	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	CEDAR GROVE ELEMENTARY	CEDAR GROVE ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
46 Sunshine Coast	CEDAR GROVE ELEMENTARY	CEDAR GROVE ELEMENTARY	3	Classroom	Low	Meets Structural Life Safety Requirements	Medium
46 Sunshine Coast	CHATELECH SECONDARY	CHATELECH SECONDARY	1	Classroom	Medium	Non Structural Upgrade Required	
46 Sunshine Coast	CHATELECH SECONDARY	CHATELECH SECONDARY	2	Shops	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	CHATELECH SECONDARY	CHATELECH SECONDARY	3	Classroom (1996)	Low	Meets Structural Life Safety Requirements	
46 Sunshine Coast	CHATELECH SECONDARY	CHATELECH SECONDARY	4	Classroom/Admin/Theatre/Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
46 Sunshine Coast	DAVIS BAY ELEMENTARY	DAVIS BAY ELEMENTARY	1	Classroom/Admin.	Low	Meets Structural Life Safety Requirements	
46 Sunshine Coast	DAVIS BAY ELEMENTARY	DAVIS BAY ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	DAVIS BAY ELEMENTARY	DAVIS BAY ELEMENTARY	3	Classroom Annex	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	ELPHINSTONE SECONDARY	ELPHINSTONE SECONDARY	1	Gymnasium/Classroom	Medium	Non Structural Upgrade Required	
46 Sunshine Coast	ELPHINSTONE SECONDARY	ELPHINSTONE SECONDARY	2	Shop/Classroom	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	ELPHINSTONE SECONDARY	ELPHINSTONE SECONDARY	3	Metal Shop	Medium	Non Structural Upgrade Required	
46 Sunshine Coast	ELPHINSTONE SECONDARY	ELPHINSTONE SECONDARY	4	Classroom (East)	Medium	Non Structural Upgrade Required	N/A
46 Sunshine Coast	GIBSONS ELEMENTARY	GIBSONS ELEMENTARY	1	Classrooms/Admin.	N/A	Completed	
46 Sunshine Coast	GIBSONS ELEMENTARY	GIBSONS ELEMENTARY	2	Classrooms/Admin.	N/A	Completed	N/A
46 Sunshine Coast	GIBSONS ELEMENTARY	GIBSONS ELEMENTARY	3	Gymnasium	N/A	Completed	
46 Sunshine Coast	HALFMOON BAY ELEMENTARY	HALFMOON BAY ELEMENTARY	1	Classrooms/Administration	Low	Meets Structural Life Safety Requirements	Medium
46 Sunshine Coast	HALFMOON BAY ELEMENTARY	HALFMOON BAY ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
46 Sunshine Coast	HALFMOON BAY ELEMENTARY	HALFMOON BAY ELEMENTARY	3	Classroom Pod	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	HALFMOON BAY ELEMENTARY	HALFMOON BAY ELEMENTARY	4	Portables	Low	Meets Structural Life Safety Requirements	
46 Sunshine Coast	HERITAGE LEARNING CENTRE	HERITAGE LEARNING CENTRE	1	Classrooms	Low	Meets Structural Life Safety Requirements	Low
46 Sunshine Coast	LANGDALE ELEMENTARY	LANGDALE ELEMENTARY	1	Classrooms/Admin.	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	LANGDALE ELEMENTARY	LANGDALE ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	N/A
46 Sunshine Coast	MADEIRA PARK ELEMENTARY	MADEIRA PARK ELEMENTARY	1	Classrooms/Admin.	N/A	Completed	
46 Sunshine Coast	MADEIRA PARK ELEMENTARY	MADEIRA PARK ELEMENTARY	2	Classrooms	N/A	Completed	N/A
46 Sunshine Coast	MADEIRA PARK ELEMENTARY	MADEIRA PARK ELEMENTARY	3	Gymnasium	N/A	Completed	
46 Sunshine Coast	PENDER HARBOUR ELEM-SEC	PENDER HARBOUR ELEM-SEC	1	Classrooms/Shops/Administration	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	PENDER HARBOUR ELEM-SEC	PENDER HARBOUR ELEM-SEC	2	Gymnasium/Mezzanine	Low	Meets Structural Life Safety Requirements	
46 Sunshine Coast	ROBERTS CREEK ELEMENTARY	ROBERTS CREEK ELEMENTARY	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	ROBERTS CREEK ELEMENTARY	ROBERTS CREEK ELEMENTARY	2	Classrooms/Admin.	Low	Meets Structural Life Safety Requirements	
46 Sunshine Coast	ROBERTS CREEK ELEMENTARY	ROBERTS CREEK ELEMENTARY	3	Classrooms	Low	Meets Structural Life Safety Requirements	Medium
46 Sunshine Coast	ROBERTS CREEK ELEMENTARY	ROBERTS CREEK ELEMENTARY	4	Multipurpose Room	Low	Meets Structural Life Safety Requirements	
46 Sunshine Coast	ROBERTS CREEK ELEMENTARY	ROBERTS CREEK ELEMENTARY	5	Gymnasium/Community Rooms	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	SECHELT ELEMENTARY (leased to CSF)	SECHELT ELEMENTARY (leased to CSF)	1	Classrooms/Annex	Medium	Non Structural Upgrade Required	
46 Sunshine Coast	SECHELT ELEMENTARY	SECHELT ELEMENTARY	2	Library	Medium	Non Structural Upgrade Required	Medium
46 Sunshine Coast	SECHELT ELEMENTARY	SECHELT ELEMENTARY	3	Gymnasium	Medium	Non Structural Upgrade Required	
46 Sunshine Coast	SECHELT ELEMENTARY	SECHELT ELEMENTARY	4	Classrooms/Admin.	Medium	Non Structural Upgrade Required	
46 Sunshine Coast	SECHELT ELEMENTARY	SECHELT ELEMENTARY	5	Classrooms/Admin.	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
46	Sunshine Coast	SECHELT ELEMENTARY	6	Classrooms	Medium	Non Structural Upgrade Required	
46	Sunshine Coast	WEST SECHELT ELEMENTARY	1	Classrooms/Admin.	Medium	Non Structural Upgrade Required	
46	Sunshine Coast	WEST SECHELT ELEMENTARY	2	Classrooms/Community Rooms	Low	Meets Structural Life Safety Requirements	Medium
46	Sunshine Coast	WEST SECHELT ELEMENTARY	3	Gymnasium	Low	Meets Structural Life Safety Requirements	
47	Powell River	EDGEHILL ELEMENTARY	1	Classroom/Administration	Medium	Non Structural Upgrade Required	
47	Powell River	EDGEHILL ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	Medium
47	Powell River	HENDERSON ELEMENTARY	1	1958 1-Storey Classroom/Admin.	N/A	Completed	N/A
47	Powell River	HENDERSON ELEMENTARY	2	1958 Gymnasium	N/A	Completed	
47	Powell River	JAMES THOMSON ELEMENTARY	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
47	Powell River	JAMES THOMSON ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	
47	Powell River	JAMES THOMSON ELEMENTARY	3	Classrooms/Administration	Medium	Non Structural Upgrade Required	
47	Powell River	JAMES THOMSON ELEMENTARY	4	Music Room	Medium	Non Structural Upgrade Required	
47	Powell River	KELLY CREEK COMMUNITY	1	Classrooms/Administration	Medium	Non Structural Upgrade Required	
47	Powell River	KELLY CREEK COMMUNITY	2	Classrooms	Medium	Non Structural Upgrade Required	Medium
47	Powell River	KELLY CREEK COMMUNITY	3	Gymnasium	Medium	Non Structural Upgrade Required	
47	Powell River	MAX CAMERON SECONDARY	1	Classroom/Administration	Medium	Inactive	
47	Powell River	MAX CAMERON SECONDARY	2	Gymnasium	Medium	Inactive	
47	Powell River	MAX CAMERON SECONDARY	3	Classroom	Medium	Inactive	Medium
47	Powell River	MAX CAMERON SECONDARY	4	Band Room	Medium	Inactive	
47	Powell River	MAX CAMERON SECONDARY	5	Classroom/Shops	Medium	Inactive	
47	Powell River	OCEANVIEW MIDDLE	1	Classrooms/Adminstration	Medium	Non Structural Upgrade Required	
47	Powell River	OCEANVIEW MIDDLE	2	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
47	Powell River	OCEANVIEW MIDDLE	3	Music Room	Low	Meets Structural Life Safety Requirements	
47	Powell River	TEXADA ELEMENTARY, MIDDLE & SECC	1	Classrooms/Administration/Shops	Medium	Non Structural Upgrade Required	
47	Powell River	TEXADA ELEMENTARY, MIDDLE & SECC	2	Change Rooms	Medium	Non Structural Upgrade Required	Medium
47	Powell River	TEXADA ELEMENTARY, MIDDLE & SECC	3	Gymnasium	Medium	Non Structural Upgrade Required	
47	Powell River	TEXADA ELEMENTARY, MIDDLE & SECC	4	Elementary Classrooms	Medium	Non Structural Upgrade Required	
47	Powell River	WESTVIEW ELEMENTARY (was GRIEF P	1	Classrooms/Administration	N/A	Completed	
47	Powell River	WESTVIEW ELEMENTARY (was GRIEF P	2	Change Rooms/Storage	N/A	Completed	N/A
47	Powell River	WESTVIEW ELEMENTARY (was GRIEF P	3	Gymnasium	N/A	Completed	
48	Sea to Sky	BLACKWATER CREEK ELEMENTARY	1	Classroom	Medium	Non Structural Upgrade Required	Medium
48	Sea to Sky	DON ROSS SECONDARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
48	Sea to Sky	DON ROSS SECONDARY	2	Classroom - Centre	Medium	Non Structural Upgrade Required	Medium
48	Sea to Sky	DON ROSS SECONDARY	3	Shops - South	Medium	Non Structural Upgrade Required	
48	Sea to Sky	DON ROSS SECONDARY	4	Classroom & Library 2001	Low	Meets Structural Life Safety Requirements	
48	Sea to Sky	GARIBALDI HIGHLANDS ELEMENTARY	1	Original structure	Medium	Non Structural Upgrade Required	
48	Sea to Sky	GARIBALDI HIGHLANDS ELEMENTARY	2	1995 Addition	Low	Meets Structural Life Safety Requirements	Medium
48	Sea to Sky	GARIBALDI HIGHLANDS ELEMENTARY	3	1999 Addition	Low	Meets Structural Life Safety Requirements	
48	Sea to Sky	GARIBALDI HIGHLANDS ELEMENTARY	4	Gymnasium	Medium	Non Structural Upgrade Required	
48	Sea to Sky	HOWE SOUND SECONDARY	1	Multi purpose / Library / Drama	Low	Meets Structural Life Safety Requirements	
48	Sea to Sky	HOWE SOUND SECONDARY	2	2 storey classroom	Low	Meets Structural Life Safety Requirements	
48	Sea to Sky	HOWE SOUND SECONDARY	3	Gym addition	Low	Meets Structural Life Safety Requirements	
48	Sea to Sky	HOWE SOUND SECONDARY	4	Original gym structure	Medium	Non Structural Upgrade Required	High 1
48	Sea to Sky	HOWE SOUND SECONDARY	5	1965 Shop Wing	High 1	Structural Upgrade Required	
48	Sea to Sky	HOWE SOUND SECONDARY	6	Music room	Low	Meets Structural Life Safety Requirements	
48	Sea to Sky	HOWE SOUND SECONDARY	7	1969 2-Storey Science Block	High 1	Structural Upgrade Required	
48	Sea to Sky	MAMQUAM ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
48	Sea to Sky	MAMQUAM ELEMENTARY	2	Classroom (South)	Medium	Non Structural Upgrade Required	Medium
48	Sea to Sky	MAMQUAM ELEMENTARY	3	Classroom (North)	Medium	Non Structural Upgrade Required	
48	Sea to Sky	MYRTLE PHILIP COMMUNITY	1	Classroom	N/A	Completed	N/A

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
48	Sea to Sky	MYRTLE PHILIP COMMUNITY	2	Gymnasium	N/A	Completed	N/A
48	Sea to Sky	SQUAMISH ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
48	Sea to Sky	SQUAMISH ELEMENTARY	2	Classrooms, Admin.	Low	Meets Structural Life Safety Requirements	
48	Sea to Sky	SQUAMISH ELEMENTARY	3	Classrooms, Library, Cov. play	Low	Meets Structural Life Safety Requirements	
48	Sea to Sky	SQUAMISH ELEMENTARY	4	Classrooms (2001)	Low	Meets Structural Life Safety Requirements	
48	Sea to Sky	STAWAMUS ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
48	Sea to Sky	STAWAMUS ELEMENTARY	2	Classrooms (South East)	Medium	Non Structural Upgrade Required	
48	Sea to Sky	STAWAMUS ELEMENTARY	3	Classrooms (North)	Medium	Non Structural Upgrade Required	
48	Sea to Sky	VALLEYCLIFFE ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
48	Sea to Sky	VALLEYCLIFFE ELEMENTARY	2	Classrooms/Admin.	Low	Meets Structural Life Safety Requirements	
49	Central Coast	BELLA COOLA ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
49	Central Coast	BELLA COOLA ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	
49	Central Coast	BELLA COOLA ELEMENTARY	3	Portables	Low	Meets Structural Life Safety Requirements	
49	Central Coast	NUSATSUM ELEMENTARY	1	Whole School	Low	Meets Structural Life Safety Requirements	Low
49	Central Coast	SHEARWATER ELEMENTARY	1	Classrooms	Low	Meets Structural Life Safety Requirements	Low
49	Central Coast	SIR ALEXANDER MACKENZIE SEC	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
49	Central Coast	SIR ALEXANDER MACKENZIE SEC	2	Classrooms	Low	Meets Structural Life Safety Requirements	
50	Haida Gwaii	AGNES L MATHERS ELEM-JR SEC	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
50	Haida Gwaii	AGNES L MATHERS ELEM-JR SEC	2	Classrooms	Medium	Non Structural Upgrade Required	
50	Haida Gwaii	GEORGE M DAWSON SECONDARY	1	Gymnasium/Shops	Low	Meets Structural Life Safety Requirements	Medium
50	Haida Gwaii	GEORGE M DAWSON SECONDARY	2	Library Block	Medium	Non Structural Upgrade Required	
50	Haida Gwaii	GEORGE M DAWSON SECONDARY	3	Classrooms - East	Medium	Non Structural Upgrade Required	
50	Haida Gwaii	GEORGE M DAWSON SECONDARY	4	Classrooms - West	Medium	Non Structural Upgrade Required	N/A
50	Haida Gwaii	PORT CLEMENTS ELEMENTARY	1	Gymnasium	N/A	Completed	
50	Haida Gwaii	PORT CLEMENTS ELEMENTARY	2	Classroom	N/A	Completed	
50	Haida Gwaii	TAHAYGHEN ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
50	Haida Gwaii	TAHAYGHEN ELEMENTARY	2	Entrance/Change Rooms	Low	Meets Structural Life Safety Requirements	
50	Haida Gwaii	TAHAYGHEN ELEMENTARY	3	Classroom Block	Medium	Non Structural Upgrade Required	
52	Prince Rupert	CONRAD STREET ELEMENTARY	1	Main Building	Low	Meets Structural Life Safety Requirements	Medium
52	Prince Rupert	CONRAD STREET ELEMENTARY	2	Office/Library Wing	Low	Meets Structural Life Safety Requirements	
52	Prince Rupert	CONRAD STREET ELEMENTARY	3	Activity Wing	Low	Meets Structural Life Safety Requirements	
52	Prince Rupert	CONRAD STREET ELEMENTARY	4	Southeast Wing	Medium	Non Structural Upgrade Required	Medium
52	Prince Rupert	KANATA ELEMENTARY	1	Gym	Medium	Inactive	
52	Prince Rupert	KANATA ELEMENTARY	2	East Classrooms	Medium	Inactive	
52	Prince Rupert	KANATA ELEMENTARY	3	North Wing	Medium	Inactive	
52	Prince Rupert	KANATA ELEMENTARY	4	West Classrooms	Medium	Inactive	Low
52	Prince Rupert	PINERIDGE ELEMENTARY	1	Gym	Low	Meets Structural Life Safety Requirements	
52	Prince Rupert	PINERIDGE ELEMENTARY	2	Class room	Low	Meets Structural Life Safety Requirements	Medium
52	Prince Rupert	PORT EDWARD ELEMENTARY	1	Gym Play Area	Medium	Non Structural Upgrade Required	
52	Prince Rupert	PORT EDWARD ELEMENTARY	2	Offices	Low	Meets Structural Life Safety Requirements	
52	Prince Rupert	PORT EDWARD ELEMENTARY	3	Classrooms	Medium	Non Structural Upgrade Required	
52	Prince Rupert	PORT EDWARD ELEMENTARY	4	Dressing Room Addition	Low	Meets Structural Life Safety Requirements	High 1
52	Prince Rupert	PRINCE RUPERT MIDDLE (Was Seconda	1	1976 1-Storey Music Block	Medium	Non Structural Upgrade Required	
52	Prince Rupert	PRINCE RUPERT MIDDLE (Was Seconda	2	1958 Gym & Stage	High 1	Structural Upgrade Required	
52	Prince Rupert	PRINCE RUPERT MIDDLE (Was Seconda	3	1958 Adjacent Gym Rooms	High 1	Structural Upgrade Required	
52	Prince Rupert	PRINCE RUPERT MIDDLE (Was Seconda	4	1958 1-Storey Drafting & Art Block	High 1	Structural Upgrade Required	
52	Prince Rupert	PRINCE RUPERT MIDDLE (Was Seconda	5	1958 2-Storey Original & SW Classrooms	High 1	Structural Upgrade Required	
52	Prince Rupert	PRINCE RUPERT MIDDLE (Was Seconda	6	1981 2-Storey Food/Textiles Addition	High 2	Structural Upgrade Required	
52	Prince Rupert	PRINCE RUPERT MIDDLE (Was Seconda	7	1981 Auto Wing	High 3	Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
52	Prince Rupert	PRINCE RUPERT MIDDLE (Was Seconda	8	1981 Covered Walkway	High 3	Structural Upgrade Required	Low
52	Prince Rupert	PRINCE RUPERT MIDDLE (Was Seconda	9	1965 Southeast Industrial Wing	High 2	Structural Upgrade Required	
52	Prince Rupert	ROOSEVELT PARK ELEMENTARY	1	Class Rooms	Low	Meets Structural Life Safety Requirements	
52	Prince Rupert	ROOSEVELT PARK ELEMENTARY	2	Activity Rooms	Low	Meets Structural Life Safety Requirements	
52	Prince Rupert	ROOSEVELT PARK ELEMENTARY	3	Dressing Room	Low	Meets Structural Life Safety Requirements	
52	Prince Rupert	ROOSEVELT PARK ELEMENTARY	4	Offices	Low	Meets Structural Life Safety Requirements	Medium
52	Prince Rupert	SEAL COVE ELEMENTARY	1	Original School Classrooms	Medium	Inactive	
52	Prince Rupert	SEAL COVE ELEMENTARY	2	Library	Low	Inactive	
52	Prince Rupert	SEAL COVE ELEMENTARY	3	Two Room Addition	Low	Inactive	
52	Prince Rupert	SEAL COVE ELEMENTARY	4	Western Classrooms	Medium	Inactive	
52	Prince Rupert	SEAL COVE ELEMENTARY	5	Gym and Changerooms	Medium	Inactive	Medium
52	Prince Rupert	WESTVIEW ELEMENTARY	1	Gym	Low	Meets Structural Life Safety Requirements	
52	Prince Rupert	WESTVIEW ELEMENTARY	2	Change Rooms	Low	Meets Structural Life Safety Requirements	
52	Prince Rupert	WESTVIEW ELEMENTARY	3	Classrooms	Medium	Non Structural Upgrade Required	High 1
61	Greater Victoria	ARBUTUS MIDDLE	1	1969 2-Storey Main Classrooms	High 1	Structural Upgrade Required	
61	Greater Victoria	ARBUTUS MIDDLE	2	1969 Gymnasium	High 1	Structural Upgrade Required	
61	Greater Victoria	ARBUTUS MIDDLE	3	1975 Classroom Addition	Medium	Non Structural Upgrade Required	
61	Greater Victoria	BRAEFoot ELEMENTARY	1	1965 1-Storey Central Classrooms	Medium	Non Structural Upgrade Required	
61	Greater Victoria	BRAEFoot ELEMENTARY	2	1970 2-Storey East Wing	High 2	Structural Upgrade Required	
61	Greater Victoria	BRAEFoot ELEMENTARY	3	Activity Wing	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	BURNSIDE COMMUNITY	1	Original Building	Medium	Inactive	
61	Greater Victoria	BURNSIDE COMMUNITY	2	Gymnasium	Low	Inactive	
61	Greater Victoria	CAMPUS VIEW ELEMENTARY	1	Administration Block	Medium	Non Structural Upgrade Required	
61	Greater Victoria	CAMPUS VIEW ELEMENTARY	2	North Classroom Wing	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	CAMPUS VIEW ELEMENTARY	3	Gymnasium	High 1	Structural Upgrade Required	
61	Greater Victoria	CAMPUS VIEW ELEMENTARY	4	Centre Classroom Block	Medium	Non Structural Upgrade Required	
61	Greater Victoria	CAMPUS VIEW ELEMENTARY	5	West Classroom Block	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	CEDAR HILL MIDDLE	1	1931 2-Storey Original Building	High 1	Supported 2013	
61	Greater Victoria	CEDAR HILL MIDDLE	2	1953 2-Storey North Classrooms	High 1	Supported 2013	
61	Greater Victoria	CEDAR HILL MIDDLE	3	1953 Gymnasium	High 2	Supported 2013	
61	Greater Victoria	CEDAR HILL MIDDLE	4	1959 Centre Shops	Medium	Supported 2013	
61	Greater Victoria	CEDAR HILL MIDDLE	5	1966 North/South Shops	Medium	Supported 2013	
61	Greater Victoria	CEDAR HILL MIDDLE	6	1969 Band/Music Block	Medium	Supported 2013	
61	Greater Victoria	CEDAR HILL MIDDLE	7	1972 2-Storey South Classrooms	Medium	Supported 2013	
61	Greater Victoria	CENTRAL MIDDLE	1	South Wing	N/A	Completed	
61	Greater Victoria	CENTRAL MIDDLE	2	Gymnasium	N/A	Completed	
61	Greater Victoria	CENTRAL MIDDLE	3	Main Entrance	N/A	Completed	
61	Greater Victoria	CENTRAL MIDDLE	4	East Wing	N/A	Completed	
61	Greater Victoria	CENTRAL MIDDLE	5	Power Mechanics Shop	N/A	Completed	
61	Greater Victoria	CENTRAL MIDDLE	6	South East Wing	N/A	Completed	
61	Greater Victoria	CENTRAL MIDDLE	7	Band Room	N/A	Completed	
61	Greater Victoria	CLOVERDALE ELEMENTARY	1	1963 1-Storey North East Wing	N/A	Under Construction	
61	Greater Victoria	CLOVERDALE ELEMENTARY	2	1982 2-Storey North Wing	N/A	Under Construction	
61	Greater Victoria	CLOVERDALE ELEMENTARY	3	1964 2-Storey Central Classrooms	N/A	Under Construction	
61	Greater Victoria	CLOVERDALE ELEMENTARY	4	1982 Gymnasium	N/A	Under Construction	
61	Greater Victoria	CRAIGFLOWER ELEMENTARY	1	1963 2-Storey Main Office/Classrooms	High 2	Structural Upgrade Required	
61	Greater Victoria	CRAIGFLOWER ELEMENTARY	2	1963 1-Storey Library	High 1	Structural Upgrade Required	
61	Greater Victoria	CRAIGFLOWER ELEMENTARY	3	1963 Gymnasium	High 1	Structural Upgrade Required	
61	Greater Victoria	CRAIGFLOWER ELEMENTARY	4	1963 Storage	High 1	Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
61	Greater Victoria	CRAIGFLOWER ELEMENTARY	5	1963 Special Education Block	High 1	Structural Upgrade Required	
61	Greater Victoria	DEAN HEIGHTS ALTERNATE (#99015)	1	Administration Block	Medium	Non Structural Upgrade Required	Medium
61	Greater Victoria	DONCASTER ELEMENTARY	1	West Classrooms	N/A	Completed	N/A
61	Greater Victoria	DONCASTER ELEMENTARY	2	Gymnasium	N/A	Completed	
61	Greater Victoria	DONCASTER ELEMENTARY	3	North Classrooms	N/A	Completed	
61	Greater Victoria	DONCASTER ELEMENTARY	4	South Classrooms	N/A	Completed	
61	Greater Victoria	ESQUIMALT SECONDARY	1	1959 Main Classrooms	Medium	Non Structural Upgrade Required	
61	Greater Victoria	ESQUIMALT SECONDARY	2	1959 Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
61	Greater Victoria	ESQUIMALT SECONDARY	3	1984 Kitchen/Lunchroom/Shop	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	ESQUIMALT SECONDARY	4	1995 Auditorium/Music	Medium	Non Structural Upgrade Required	
61	Greater Victoria	FRANK HOBBS ELEMENTARY	1	Centre Block	Medium	Non Structural Upgrade Required	Medium
61	Greater Victoria	FRANK HOBBS ELEMENTARY	2	South Classroom Wing	Medium	Non Structural Upgrade Required	
61	Greater Victoria	FRANK HOBBS ELEMENTARY	3	East Classroom Block	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	FRANK HOBBS ELEMENTARY	4	Gymnasium	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	GEORGE JAY ELEMENTARY	1	1909 3-Storey Original Building	N/A	Completed	N/A
61	Greater Victoria	GEORGE JAY ELEMENTARY	2	1956 2-Storey West Classrooms	N/A	Completed	
61	Greater Victoria	GLANFORD MIDDLE	1	North Classrooms	Medium	Non Structural Upgrade Required	Medium
61	Greater Victoria	GLANFORD MIDDLE	2	South Classrooms	Medium	Non Structural Upgrade Required	
61	Greater Victoria	GLANFORD MIDDLE	3	Gymnasium	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	GLANFORD MIDDLE	4	West Classrooms	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	GORDON HEAD MIDDLE	1	Classrooms	N/A	Completed	N/A
61	Greater Victoria	GORDON HEAD MIDDLE	2	Gymnasium	N/A	Completed	
61	Greater Victoria	GORDON HEAD MIDDLE	3	81 Addition	N/A	Completed	
61	Greater Victoria	HILLCREST ELEMENTARY	1	South Classroom Block	Low	Meets Structural Life Safety Requirements	Low
61	Greater Victoria	HILLCREST ELEMENTARY	2	Centre Block	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	HILLCREST ELEMENTARY	3	Gymnasium	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	JAMES BAY COMMUNITY	1	Classrooms North	N/A	Completed	N/A
61	Greater Victoria	JAMES BAY COMMUNITY	2	Classrooms South	N/A	Completed	
61	Greater Victoria	JAMES BAY COMMUNITY	3	Gymnasium	N/A	Completed	
61	Greater Victoria	LAKE HILL ELEMENTARY	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
61	Greater Victoria	LAKE HILL ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	
61	Greater Victoria	LAMBRICK PARK SECONDARY	1	1976 1-Storey Main Classrooms	Medium	Non Structural Upgrade Required	High 1
61	Greater Victoria	LAMBRICK PARK SECONDARY	2	1976 Gymnasium	High 1	Structural Upgrade Required	
61	Greater Victoria	LAMBRICK PARK SECONDARY	3	1976 Shops	High 2	Structural Upgrade Required	
61	Greater Victoria	LAMBRICK PARK SECONDARY	4	1976 1-Storey Library	High 2	Structural Upgrade Required	
61	Greater Victoria	LAMBRICK PARK SECONDARY	5	1991 1-Storey South Classrooms	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	LAMPSON ELEMENTARY	1	Original Building	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	LANSLOWNE MIDDLE	1	1953 2-Storey East Wing	N/A	Completed	N/A
61	Greater Victoria	LANSLOWNE MIDDLE	2	1953 Gymnasium	N/A	Completed	
61	Greater Victoria	LANSLOWNE MIDDLE	3	Drama	N/A	Completed	
61	Greater Victoria	LANSLOWNE MIDDLE	4	1953 Shops	N/A	Completed	
61	Greater Victoria	MACAULAY ELEMENTARY	1	1954 2-Storey South Wing Classrooms	Medium	Non Structural Upgrade Required	High 3
61	Greater Victoria	MACAULAY ELEMENTARY	2	1954 Gymnasium	Medium	Non Structural Upgrade Required	
61	Greater Victoria	MACAULAY ELEMENTARY	3	1962 2-Storey West Wing	High 3	Structural Upgrade Required	
61	Greater Victoria	MACAULAY ELEMENTARY	4	1967 2-Storey East Wing	High 3	Structural Upgrade Required	
61	Greater Victoria	MAINTENANCE & DISTRIBUTION	2	Building 1 - Central	Medium	Non Structural Upgrade Required	Medium
61	Greater Victoria	MAINTENANCE & DISTRIBUTION	3	Building 2	Medium	Non Structural Upgrade Required	
61	Greater Victoria	MARGARET JENKINS ELEMENTARY	1	Main Building	N/A	Completed	N/A
61	Greater Victoria	MARGARET JENKINS ELEMENTARY	2	Annex	N/A	Completed	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
61	Greater Victoria	MARGARET JENKINS ELEMENTARY	3	South Classrooms	N/A	Completed	
61	Greater Victoria	MARIGOLD ELEMENTARY	1	Offices	Low	Meets Structural Life Safety Requirements	Medium
61	Greater Victoria	MARIGOLD ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
61	Greater Victoria	MARIGOLD ELEMENTARY	3	Library/New Classrooms	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	MARIGOLD ELEMENTARY	4	Gymnasium	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	MCKENZIE ELEMENTARY	1	North Wing	N/A	Completed	
61	Greater Victoria	MCKENZIE ELEMENTARY	2	New Gymnasium	Medium	Non Structural Upgrade Required	N/A
61	Greater Victoria	MCKENZIE ELEMENTARY	3	Central Classrooms	Medium	Non Structural Upgrade Required	
61	Greater Victoria	MCKENZIE ELEMENTARY	4	Old Gymnasium	Medium	Non Structural Upgrade Required	
61	Greater Victoria	MCKENZIE ELEMENTARY	5	East Wing	Medium	Non Structural Upgrade Required	
61	Greater Victoria	MONTEREY MIDDLE	1	Original Building	N/A	Completed	N/A
61	Greater Victoria	MONTEREY MIDDLE	2	North Classrooms	N/A	Completed	
61	Greater Victoria	MONTEREY MIDDLE	3	West Classrooms	N/A	Completed	
61	Greater Victoria	MOUNT DOUGLAS SECONDARY	1	Main Classrooms	N/A	Completed	N/A
61	Greater Victoria	MOUNT DOUGLAS SECONDARY	2	Old Gymnasium	N/A	Completed	
61	Greater Victoria	MOUNT DOUGLAS SECONDARY	3	New Gymnasium	N/A	Completed	
61	Greater Victoria	MOUNT DOUGLAS SECONDARY	4	Cafeteria/Music	N/A	Completed	
61	Greater Victoria	MOUNT DOUGLAS SECONDARY	5	North Classroom/Shop	N/A	Completed	
61	Greater Victoria	NORTHRIDGE ELEMENTARY	1	North Classrooms	Medium	Non Structural Upgrade Required	Medium
61	Greater Victoria	NORTHRIDGE ELEMENTARY	2	South Classrooms	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	NORTHRIDGE ELEMENTARY	3	Gymnasium	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	NORTHRIDGE ELEMENTARY	4	Library/Offices	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	OAKLANDS ELEMENTARY	1	Original Building	Low	Meets Structural Life Safety Requirements	Low
61	Greater Victoria	QUADRA ELEMENTARY	1	1914 3-Storey Original Building	N/A	Completed	N/A
61	Greater Victoria	QUADRA ELEMENTARY	2	1914 1-Storey Annex	N/A	Completed	
61	Greater Victoria	QUADRA ELEMENTARY	3	1962 2-Storey South/Central Classrooms	N/A	Completed	
61	Greater Victoria	QUADRA ELEMENTARY	4	1968 2-Storey South Classrooms	N/A	Completed	High 2
61	Greater Victoria	REYNOLDS SECONDARY	1	1966 2-Storey Main Office/Classrooms	High 2	Structural Upgrade Required	
61	Greater Victoria	REYNOLDS SECONDARY	2	1966 North-West Shops	High 2	Structural Upgrade Required	
61	Greater Victoria	REYNOLDS SECONDARY	3	1968 2-Storey East Classrooms	High 2	Structural Upgrade Required	
61	Greater Victoria	REYNOLDS SECONDARY	4	1968 Power Machine Shop	High 2	Structural Upgrade Required	
61	Greater Victoria	REYNOLDS SECONDARY	5	1970 Covered Workshed	High 2	Structural Upgrade Required	
61	Greater Victoria	REYNOLDS SECONDARY	6	1966 Music Annex	Medium	Non Structural Upgrade Required	
61	Greater Victoria	REYNOLDS SECONDARY	7	Gymnasium	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	REYNOLDS SECONDARY	8	SW Classrooms	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	ROCKHEIGHTS MIDDLE	1	Classrooms	Low	Meets Structural Life Safety Requirements	Low
61	Greater Victoria	S J WILLIS EDUCATIONAL CENTRE	1	Main Administration	High 1	Inactive	High 1
61	Greater Victoria	S J WILLIS EDUCATIONAL CENTRE	2	Auditorium	High 1	Inactive	
61	Greater Victoria	S J WILLIS EDUCATIONAL CENTRE	3	Gymnasium	Medium	Inactive	
61	Greater Victoria	S J WILLIS EDUCATIONAL CENTRE	4	Shops and Cont. Education Classrooms	High 3	Inactive	
61	Greater Victoria	S J WILLIS EDUCATIONAL CENTRE	5	South Classrooms	Medium	Inactive	
61	Greater Victoria	S J WILLIS EDUCATIONAL CENTRE	6	Addition 1958	High 1	Inactive	
61	Greater Victoria	S J WILLIS EDUCATIONAL CENTRE	7	Cont. Education	High 3	Inactive	
61	Greater Victoria	S J WILLIS EDUCATIONAL CENTRE	8	Compound	Medium	Inactive	
61	Greater Victoria	SHORELINE COMMUNITY MIDDLE	1	1968 2-Storey North Classrooms	High 1	Supported 2013	High 1
61	Greater Victoria	SHORELINE COMMUNITY MIDDLE	2	1968 1-Storey South Classrooms	High 1	Supported 2013	
61	Greater Victoria	SHORELINE COMMUNITY MIDDLE	3	1968 2-Storey Activity Wing	High 1	Supported 2013	
61	Greater Victoria	SHORELINE COMMUNITY MIDDLE	4	1983 Band Room	Low	Supported 2013	
61	Greater Victoria	SHORELINE COMMUNITY MIDDLE	5	1968 Shops	High 1	Supported 2013	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
61	Greater Victoria	SHORELINE COMMUNITY MIDDLE	6	Walkway	Low	Supported 2013	
61	Greater Victoria	SOUTH PARK ELEMENTARY	1	1895 3-Storey Main Building	Medium	Non Structural Upgrade Required	Medium
61	Greater Victoria	SOUTH PARK ELEMENTARY	2	1914 3-Storey Annex	Medium	Non Structural Upgrade Required	
61	Greater Victoria	SPECTRUM COMMUNITY	1	Main Classrooms	Low	Meets Structural Life Safety Requirements	Low
61	Greater Victoria	SPECTRUM COMMUNITY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	SPECTRUM COMMUNITY	3	Shops	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	SPECTRUM COMMUNITY	4	Drama/Dance/Music	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	SUNDANCE ELEMENTARY	1	Administration and Offices	Medium	Non Structural Upgrade Required	Medium
61	Greater Victoria	SUNDANCE ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
61	Greater Victoria	SUNDANCE ELEMENTARY	3	Gymnasium	Medium	Non Structural Upgrade Required	
61	Greater Victoria	TILlicum ELEMENTARY	1	1917 2-Storey Original Main Building	N/A	Completed	N/A
61	Greater Victoria	TILlicum ELEMENTARY	2	1945 2-Storey North Wing (Library and Staff Room)	N/A	Completed	
61	Greater Victoria	TILlicum ELEMENTARY	3	1962 2-Storey South Classrooms	N/A	Completed	
61	Greater Victoria	TILlicum ELEMENTARY	4	Gymnasium	N/A	Completed	
61	Greater Victoria	Tolmie Administration Centre	1	Original Building	Medium	Non Structural Upgrade Required	Medium
61	Greater Victoria	Tolmie Administration Centre	2	Boardroom	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	Tolmie Administration Centre	4	Annex - East	Medium	Non Structural Upgrade Required	
61	Greater Victoria	TORQUAY ELEMENTARY	1	Main Bldg and Classrooms	Medium	Non Structural Upgrade Required	Medium
61	Greater Victoria	TORQUAY ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	
61	Greater Victoria	TORQUAY ELEMENTARY	3	Additional Classrooms 1980	Medium	Non Structural Upgrade Required	
61	Greater Victoria	VICTOR SCHOOL	1	Classrooms	Low	Meets Structural Life Safety Requirements	Low
61	Greater Victoria	VICTOR SCHOOL	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	VICTORIA HIGH	1	1911 4-Storey Original Building	High 1	Supported 2004	High 1
61	Greater Victoria	VICTORIA HIGH	2	1911 2-Storey Auditorium	High 2	Supported 2004	
61	Greater Victoria	VICTORIA HIGH	3	1955 Gymnasium	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	VICTORIA HIGH	4	East Shops	N/A	Completed	
61	Greater Victoria	VICTORIA HIGH	5	Centre Shops	N/A	Completed	
61	Greater Victoria	VICTORIA HIGH	6	West Shops	N/A	Completed	
61	Greater Victoria	VICTORIA HIGH	7	North Shops	N/A	Completed	
61	Greater Victoria	VICTORIA WEST ELEMENTARY	1	Activity Wing South	N/A	Completed	N/A
61	Greater Victoria	VICTORIA WEST ELEMENTARY	2	Classrooms West	N/A	Completed	
61	Greater Victoria	VICTORIA WEST ELEMENTARY	3	Classrooms North	N/A	Completed	
61	Greater Victoria	VICTORIA WEST ELEMENTARY	4	Classrooms East	N/A	Completed	
61	Greater Victoria	VICTORIA WEST ELEMENTARY	5	Activity Wing North	N/A	Completed	
61	Greater Victoria	VIEW ROYAL ELEMENTARY	1	East Classroom Wing	Medium	Non Structural Upgrade Required	Medium
61	Greater Victoria	VIEW ROYAL ELEMENTARY	2	Centre Classroom Wing	Medium	Non Structural Upgrade Required	
61	Greater Victoria	VIEW ROYAL ELEMENTARY	3	West Classroom Wing	Medium	Non Structural Upgrade Required	
61	Greater Victoria	VIEW ROYAL ELEMENTARY	4	2 Storey NW Classroom Block	Medium	Non Structural Upgrade Required	
61	Greater Victoria	VIEW ROYAL ELEMENTARY	5	Gymnasium	Low	Meets Structural Life Safety Requirements	
61	Greater Victoria	VIEW ROYAL ELEMENTARY	6	Staff and Storage Block	Medium	Non Structural Upgrade Required	
61	Greater Victoria	WILLOWS ELEMENTARY	1	Original Building	N/A	Completed	N/A
61	Greater Victoria	WILLOWS ELEMENTARY	2	North Classrooms	N/A	Completed	
61	Greater Victoria	WILLOWS ELEMENTARY	3	West Classrooms	N/A	Completed	
62	Sooke	BELMONT SECONDARY	1	Shops	N/A	Completed	N/A
62	Sooke	BELMONT SECONDARY	2	South Wing	N/A	Completed	
62	Sooke	BELMONT SECONDARY	3	Centre Wing	N/A	Completed	
62	Sooke	BELMONT SECONDARY	4	North Wing (2 Storeys)	N/A	Completed	
62	Sooke	BELMONT SECONDARY	5	Northeast Wing	N/A	Completed	
62	Sooke	BELMONT SECONDARY	6	Bandroom	N/A	Completed	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
62	Sooke	DAVID CAMERON ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
62	Sooke	DAVID CAMERON ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	
62	Sooke	DUNSMUIR MIDDLE	1	1965 Gymnasium	N/A	Under Construction	N/A
62	Sooke	DUNSMUIR MIDDLE	2	1965 1-Storey Administration	N/A	Under Construction	
62	Sooke	DUNSMUIR MIDDLE	3	1965 2-Storey South Wing	N/A	Under Construction	
62	Sooke	DUNSMUIR MIDDLE	4	1965 Shop Wing	N/A	Under Construction	
62	Sooke	DUNSMUIR MIDDLE	5	1973 2-Storey East Wing	N/A	Under Construction	
62	Sooke	DUNSMUIR MIDDLE	6	1989 Bandroom	N/A	Under Construction	
62	Sooke	HAPPY VALLEY ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
62	Sooke	HAPPY VALLEY ELEMENTARY	2	North Section 2 Storey	N/A	Completed	
62	Sooke	HAPPY VALLEY ELEMENTARY	3	South Section 1 Storey	N/A	Completed	
62	Sooke	JOHN MUIR ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
62	Sooke	JOHN MUIR ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
62	Sooke	MILLSTREAM ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
62	Sooke	MILLSTREAM ELEMENTARY	2	Main Wing	Medium	Non Structural Upgrade Required	
62	Sooke	MILLSTREAM ELEMENTARY	3	East Wing	Medium	Non Structural Upgrade Required	
62	Sooke	PORT RENFREW ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
62	Sooke	PORT RENFREW ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
62	Sooke	RUTH KING ELEMENTARY	1	1952 1-Storey South Section	Low	Supported 2013	High 1
62	Sooke	RUTH KING ELEMENTARY	2a	1953 2-Storey Classrooms	High 1	Supported 2013	
62	Sooke	RUTH KING ELEMENTARY	2b	1957 Gymnasium	High 2	Supported 2013	
62	Sooke	SANGSTER ELEMENTARY	1	1964 Gymnasium	N/A	Completed	N/A
62	Sooke	SANGSTER ELEMENTARY	2	1956 1-Storey Classrooms	N/A	Completed	
62	Sooke	SANGSTER ELEMENTARY	3	1973 1-Storey West Wing Addition	N/A	Completed	
62	Sooke	SASEENOS ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
62	Sooke	SASEENOS ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
62	Sooke	SAVORY ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
62	Sooke	SAVORY ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
62	Sooke	SOOKE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
62	Sooke	SOOKE ELEMENTARY	2	West Wing	Medium	Non Structural Upgrade Required	
62	Sooke	SOOKE ELEMENTARY	3	North Wing	Medium	Non Structural Upgrade Required	
62	Sooke	SPENCER MIDDLE	1	Main	N/A	Completed	N/A
62	Sooke	WILLWAY ELEMENTARY	1	1977 1-Storey Main Building	High 3	Structural Upgrade Required	High 3
62	Sooke	WISHART ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
62	Sooke	WISHART ELEMENTARY	2	Classrooms (Extended)	Low	Meets Structural Life Safety Requirements	
62	Sooke	WISHART ELEMENTARY	3	2 Storey Wing (Original)	Low	Meets Structural Life Safety Requirements	
62	Sooke	WISHART ELEMENTARY	4	Library	Low	Meets Structural Life Safety Requirements	
63	Saanich	BEAVER LAKE ELEMENTARY	1	1961 Gymnasium/1971 Covered Play Area	Medium	Non Structural Upgrade Required	Medium
63	Saanich	BEAVER LAKE ELEMENTARY	2	1956 Main Building (1961/64/71/99 Additions)	Medium	Non Structural Upgrade Required	
63	Saanich	BEAVER LAKE ELEMENTARY	3	1999 Addition	Low	Meets Structural Life Safety Requirements	
63	Saanich	BRENTWOOD ELEMENTARY	1	1951 Original Building, 1956/61 Additions	Medium	Non Structural Upgrade Required	Medium
63	Saanich	BRENTWOOD ELEMENTARY	2	1970 Addition	Medium	Non Structural Upgrade Required	
63	Saanich	BRENTWOOD ELEMENTARY	3	1951 Original Gymnasium	Medium	Non Structural Upgrade Required	
63	Saanich	BRENTWOOD ELEMENTARY	4	1970 Gymnasium Addition	Low	Meets Structural Life Safety Requirements	
63	Saanich	BRENTWOOD ELEMENTARY	5	Covered Area	Low	Meets Structural Life Safety Requirements	
63	Saanich	BRENTWOOD ELEMENTARY	6	1998 Addition	Low	Meets Structural Life Safety Requirements	
63	Saanich	CHILDREN'S DEVELOPMENT CENTRE	1	1966 Main Building	High 3	Structural Upgrade Required	High 3
63	Saanich	CLAREMONT SECONDARY	1	1966 Addition (1994 Upgrade)	N/A	Completed	
63	Saanich	CLAREMONT SECONDARY	2	1961 N. Wing /1964 Addition (1994 Rebuild)	N/A	Completed	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
63	Saanich	CLAREMONT SECONDARY	3	1961 Gymnasium / 1966 Addition	N/A	Completed	N/A
63	Saanich	CLAREMONT SECONDARY	4	1961 S. Wing /1966 Addition /1975 Addition	N/A	Completed	
63	Saanich	CLAREMONT SECONDARY	5	1966 Addition /1975 Addition	N/A	Completed	
63	Saanich	CLAREMONT SECONDARY	6	1994 Addition	N/A	Completed	N/A
63	Saanich	CORDOVA BAY ELEMENTARY	1	1956 Gymnasium / 1966 Addition (2003 Upgrade)	N/A	Under Construction	
63	Saanich	CORDOVA BAY ELEMENTARY	2	1945 Main Building (1961/65/69 Additions)	N/A	Under Construction	
63	Saanich	CORDOVA BAY ELEMENTARY	3	1966 Covered Area / 1969 Addition (Upgrade)	N/A	Under Construction	
63	Saanich	CORDOVA BAY ELEMENTARY	4	1966/69 Additions	N/A	Under Construction	
63	Saanich	CORDOVA BAY ELEMENTARY	5	1956/1965 Additions	N/A	Under Construction	
63	Saanich	DEEP COVE ELEMENTARY	1	1956 Original Building	N/A	Completed	N/A
63	Saanich	DEEP COVE ELEMENTARY	2	1965 Addition	N/A	Completed	
63	Saanich	DEEP COVE ELEMENTARY	3	1965 Addition	N/A	Completed	
63	Saanich	DEEP COVE ELEMENTARY	4	1966 Addition	N/A	Completed	
63	Saanich	DEEP COVE ELEMENTARY	5	1966 Addition	N/A	Completed	
63	Saanich	DEEP COVE ELEMENTARY	6	1966/1982 Additions	N/A	Completed	
63	Saanich	DEEP COVE ELEMENTARY	7	1969 Addition	N/A	Completed	
63	Saanich	DEEP COVE ELEMENTARY	8	1982 Addition	N/A	Completed	
63	Saanich	DEEP COVE ELEMENTARY	9	1982 Addition	N/A	Completed	
63	Saanich	DEEP COVE ELEMENTARY	10	1991 Addition	N/A	Completed	
63	Saanich	GREENGLADE ELEMENTARY	1	1975 Original Building	Low	Inactive	Medium
63	Saanich	GREENGLADE ELEMENTARY	2	1989 Addition	Medium	Inactive	
63	Saanich	KEATING ELEM ANNEX	1	1976 West Wing	Low	Meets Structural Life Safety Requirements	Low
63	Saanich	KEATING ELEM ANNEX	2	1976 East Wing	Low	Meets Structural Life Safety Requirements	
63	Saanich	KEATING ELEMENTARY	1	1963 1-Storey NorthEast Wing (2001 Upgrade)	Low	Meets Structural Life Safety Requirements	High 2
63	Saanich	KEATING ELEMENTARY	2	1969 Gymnasium Addition	Low	Meets Structural Life Safety Requirements	
63	Saanich	KEATING ELEMENTARY	3	1966 Covered Area (2001 Upgrade)	Low	Meets Structural Life Safety Requirements	
63	Saanich	KEATING ELEMENTARY	4	1969 1-Storey Addition	High 2	Structural Upgrade Required	
63	Saanich	KEATING ELEMENTARY	5	1967 1-Storey Addition	High 3	Structural Upgrade Required	
63	Saanich	KEATING ELEMENTARY	6	1966 Covered Play Area (Converted to FDK space in 2001)	High 3	Structural Upgrade Required	
63	Saanich	KEATING ELEMENTARY	7	1991 Addition	Low	Meets Structural Life Safety Requirements	High 1
63	Saanich	LOCHSIDE ELEMENTARY	1	1963 1-Storey Main Building	Low	Proceeding to Construction	
63	Saanich	LOCHSIDE ELEMENTARY	2	1963 1-Storey Main/1971 Addition	High 1	Proceeding to Construction	
63	Saanich	LOCHSIDE ELEMENTARY	3	1991 1-Storey Addition	Low	Proceeding to Construction	
63	Saanich	LOCHSIDE ELEMENTARY	4	1967 Gymnasium	High 1	Proceeding to Construction	
63	Saanich	LOCHSIDE ELEMENTARY	5	1999 1-Storey Addition	Low	Proceeding to Construction	
63	Saanich	MCTAVISH ELEMENTARY	1	1956 & 1966 Additions	Medium	Inactive	High 1
63	Saanich	MCTAVISH ELEMENTARY	2	1951 Original Building (1956/61/66 Additions)	Medium	Inactive	
63	Saanich	MCTAVISH ELEMENTARY	3	1966 Gymnasium	High 1	Inactive	
63	Saanich	MCTAVISH ELEMENTARY	4	1998 Addition	Low	Inactive	
63	Saanich	NORTH SAANICH MIDDLE	1	Original Building (Pre 1954)/1954 Addition	N/A	Completed	N/A
63	Saanich	NORTH SAANICH MIDDLE	2	1956 Addition	N/A	Completed	
63	Saanich	NORTH SAANICH MIDDLE	3	1962/64/74/99 Additions	N/A	Completed	
63	Saanich	NORTH SAANICH MIDDLE	4	1967 & 1969 Additions	N/A	Completed	
63	Saanich	NORTH SAANICH MIDDLE	5	1974 Addition	N/A	Completed	
63	Saanich	NORTH SAANICH MIDDLE	6	1999 Addition	N/A	Completed	
63	Saanich	NORTH SAANICH MIDDLE	7	2001 Addition	N/A	Completed	
63	Saanich	NORTH SAANICH MIDDLE	8	2001 Addition (covered area)	N/A	Completed	
63	Saanich	PARKLAND SECONDARY	1	1973 Gymnasium	N/A	Under Construction	N/A
63	Saanich	PARKLAND SECONDARY	2	1973 Main Building (Fire Damage Repair 2004)	N/A	Under Construction	
63	Saanich	PARKLAND SECONDARY	3	1973 Main Building	N/A	Under Construction	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
63	Saanich	PARKLAND SECONDARY	4	2000 Addition	N/A	Under Construction	N/A
63	Saanich	PARKLAND SECONDARY	5	1973 Main Building (Upgraded 2000)	N/A	Under Construction	
63	Saanich	PARKLAND SECONDARY	6	1974 Addition (Math Wing)	N/A	Under Construction	
63	Saanich	PROSPECT LAKE ELEMENTARY	1	1975 Covered Area (2003 Upgrade)	N/A	Completed	
63	Saanich	PROSPECT LAKE ELEMENTARY	2	1963 Main Building (2003 Upgrade)	N/A	Completed	N/A
63	Saanich	PROSPECT LAKE ELEMENTARY	3	1992 Addition	N/A	Completed	
63	Saanich	PROSPECT LAKE ELEMENTARY	4	1967/75 Additions	N/A	Completed	
63	Saanich	PROSPECT LAKE ELEMENTARY	5	1967 Gymnasium	N/A	Completed	
63	Saanich	SAANICHTON ELEMENTARY	1	1963-66 Main Building (2001 Upgrade)	Low	Meets Structural Life Safety Requirements	
63	Saanich	SAANICHTON ELEMENTARY	2	1966/79 Additions (2003 Upgrade)	Low	Meets Structural Life Safety Requirements	Medium
63	Saanich	SAANICHTON ELEMENTARY	3	1979 Addition	Medium	Non Structural Upgrade Required	
63	Saanich	SAANICHTON ELEMENTARY	4	1969 Addition (Small 1993 Addition)	Medium	Non Structural Upgrade Required	
63	Saanich	SANSBURY ELEMENTARY	1	1956 Original Building (1961/66 Additions)	High 3	Inactive	
63	Saanich	SANSBURY ELEMENTARY	2	1966 Gymnasium	High 1	Inactive	High 1
63	Saanich	SANSBURY ELEMENTARY	3	1966 Addition	Medium	Inactive	
63	Saanich	SANSBURY ELEMENTARY	4	1969 Addition	Medium	Inactive	
63	Saanich	SANSBURY ELEMENTARY	5	Portable	Low	Inactive	
63	Saanich	SIDNEY ELEMENTARY	1	1951 Original Building	Medium	Non Structural Upgrade Required	
63	Saanich	SIDNEY ELEMENTARY	2	1951 Original Building, 1964 Addition	Medium	Non Structural Upgrade Required	
63	Saanich	SIDNEY ELEMENTARY	3	1956 Addition	Medium	Non Structural Upgrade Required	
63	Saanich	SIDNEY ELEMENTARY	4	1966 Addition (2003 Upgrade)	Low	Meets Structural Life Safety Requirements	
63	Saanich	SIDNEY ELEMENTARY	5	1969 Addition	Medium	Non Structural Upgrade Required	Medium
63	Saanich	SIDNEY ELEMENTARY	6	1969 Addition	Medium	Non Structural Upgrade Required	
63	Saanich	SIDNEY ELEMENTARY	7	1981 Addition	Medium	Non Structural Upgrade Required	
63	Saanich	SIDNEY ELEMENTARY	8	1966 Addition (2002 Upgrade)	Low	Meets Structural Life Safety Requirements	
63	Saanich	SIDNEY ELEMENTARY	9	1969 Addition	Medium	Non Structural Upgrade Required	
63	Saanich	STELLY'S SECONDARY	1	1976 Main Building	N/A	Completed	
63	Saanich	STELLY'S SECONDARY	2	1976 Gymnasium	N/A	Completed	
63	Saanich	STELLY'S SECONDARY	3	1992 Addition	N/A	Completed	N/A
63	Saanich	STELLY'S SECONDARY	4	1996 Addition	N/A	Completed	
63	Saanich	STELLY'S SECONDARY	5	Permanent Portable	N/A	Completed	
64	Gulf Islands	FERNWOOD ELEMENTARY	1	Original 1977	Medium	Non Structural Upgrade Required	
64	Gulf Islands	FERNWOOD ELEMENTARY	2	Gymnasium /1989 Addition	Medium	Non Structural Upgrade Required	Medium
64	Gulf Islands	FERNWOOD ELEMENTARY	3	Multipurpose	Medium	Non Structural Upgrade Required	
64	Gulf Islands	FULFORD ELEMENTARY	1	Gymnasium/Administration	Low	Meets Structural Life Safety Requirements	
64	Gulf Islands	FULFORD ELEMENTARY	2	Classrooms 1983	Medium	Non Structural Upgrade Required	Medium
64	Gulf Islands	FULFORD ELEMENTARY	3	Classrooms 1993	Low	Meets Structural Life Safety Requirements	
64	Gulf Islands	GALIANO COMMUNITY	1	Classrooms	Medium	Non Structural Upgrade Required	
64	Gulf Islands	GALIANO COMMUNITY	2	1982 Expansion Inc. Gymnasium	Medium	Non Structural Upgrade Required	Medium
64	Gulf Islands	GALIANO COMMUNITY	3	1986 Expansion	Medium	Non Structural Upgrade Required	
64	Gulf Islands	MAYNE ELEM-JR SEC	1	Old School	Medium	Non Structural Upgrade Required	
64	Gulf Islands	MAYNE ELEM-JR SEC	2	1974 Addition	Medium	Non Structural Upgrade Required	
64	Gulf Islands	MAYNE ELEM-JR SEC	3	1975-1976 Addition/Gym	Medium	Non Structural Upgrade Required	Medium
64	Gulf Islands	MAYNE ELEM-JR SEC	4	Shop (1982)	Medium	Non Structural Upgrade Required	
64	Gulf Islands	MAYNE ELEM-JR SEC	5	Kindergarten (Portable)	Low	Meets Structural Life Safety Requirements	
64	Gulf Islands	PENDER ISLANDS ELEM-SEC	1	Gymnasium/Classrooms	Medium	Non Structural Upgrade Required	
64	Gulf Islands	PENDER ISLANDS ELEM-SEC	2	Classroom Additions	Medium	Non Structural Upgrade Required	Medium
64	Gulf Islands	PENDER ISLANDS ELEM-SEC	3	2002 Expansion	Low	Meets Structural Life Safety Requirements	
64	Gulf Islands	SALT SPRING ELEMENTARY	1	Original	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
64	Gulf Islands	SALT SPRING ELEMENTARY	2	1972 Addition/Gym	Medium	Non Structural Upgrade Required	Medium
64	Gulf Islands	SALT SPRING ELEMENTARY	3	1976 Addition	Medium	Non Structural Upgrade Required	
64	Gulf Islands	SALT SPRING ISLAND MIDDLE	1	Gymnasium	N/A	Completed	N/A
64	Gulf Islands	SALT SPRING ISLAND MIDDLE	2	Classrooms	N/A	Completed	
64	Gulf Islands	SALT SPRING ISLAND MIDDLE	3	Modular/Music	N/A	Completed	
64	Gulf Islands	SALT SPRING ISLAND MIDDLE	4	Vocational	N/A	Completed	
64	Gulf Islands	SALT SPRING ISLAND MIDDLE	4	Vocational	N/A	Completed	
64	Gulf Islands	SATURNA ISLAND ELEMENTARY	1	Original	Medium	Non Structural Upgrade Required	Medium
64	Gulf Islands	SATURNA ISLAND ELEMENTARY	2	Addition	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	5 ACRES ALTERNATE	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	BAYVIEW ELEMENTARY	1	Classroom	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	BAYVIEW ELEMENTARY	2	Multipurpose Room	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	BAYVIEW ELEMENTARY	3	Gymnasium	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	BRECHIN ELEMENTARY	1	1992 Gymnasium	Low	Meets Structural Life Safety Requirements	
68	Nanaimo/Ladysmith	BRECHIN ELEMENTARY	2	1964 2-Storey Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	BRECHIN ELEMENTARY	3	1992 1-Storey Classrooms	Low	Meets Structural Life Safety Requirements	
68	Nanaimo/Ladysmith	CHASE RIVER ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	CHASE RIVER ELEMENTARY	2	Single Storey Classrooms	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	CILAIRE ELEMENTARY	1	1966 2-Storey Classrooms	High 2	Structural Upgrade Required	High 2
68	Nanaimo/Ladysmith	CILAIRE ELEMENTARY	2	1971 Gymnasium	High 2	Structural Upgrade Required	
68	Nanaimo/Ladysmith	CILAIRE ELEMENTARY	3	1971 2-Storey Concrete Change Rooms	High 2	Structural Upgrade Required	
68	Nanaimo/Ladysmith	DAVIS ROAD ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	DAVIS ROAD ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	DAVIS ROAD ELEMENTARY	3	Classrooms	Low	Meets Structural Life Safety Requirements	
68	Nanaimo/Ladysmith	DEPARTURE BAY ELEMENTARY	1	Multipurpose Room	Low	Meets Structural Life Safety Requirements	
68	Nanaimo/Ladysmith	DEPARTURE BAY ELEMENTARY	2	Two Storey Classroom	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	DEPARTURE BAY ELEMENTARY	3	Classrooms	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	DUFFERIN CRESCENT ELEMENTARY	1	Gymnasium	Medium	Inactive	Medium
68	Nanaimo/Ladysmith	DUFFERIN CRESCENT ELEMENTARY	2	2 Classrooms	Medium	Inactive	
68	Nanaimo/Ladysmith	FAIRVIEW ELEMENTARY	1	Gym/Activity Room	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	FAIRVIEW ELEMENTARY	2	East Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	FAIRVIEW ELEMENTARY	3	West Classrooms	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	FOREST PARK ELEMENTARY	1	Classrooms 1	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	FOREST PARK ELEMENTARY	2	Classrooms 2	Low	Meets Structural Life Safety Requirements	
68	Nanaimo/Ladysmith	FOREST PARK ELEMENTARY	3	Administration, Library	Low	Meets Structural Life Safety Requirements	
68	Nanaimo/Ladysmith	FOREST PARK ELEMENTARY	4	Gymnasium	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	FOREST PARK ELEMENTARY	5	Services	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	FOREST PARK ELEMENTARY	6	Classrooms	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	GABRIOLA ELEMENTARY	1	1976 Gymnasium	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	GABRIOLA ELEMENTARY	2	East Classrooms	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	GABRIOLA ELEMENTARY	3	Central Classrooms	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	GEORGIA AVENUE ELEMENTARY	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	GEORGIA AVENUE ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
68	Nanaimo/Ladysmith	GEORGIA AVENUE ELEMENTARY	3	Classrooms and Administration	Medium	Non Structural Upgrade Required	
68	Nanaimo/Ladysmith	HAMMOND BAY ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
68	Nanaimo/Ladysmith	HAMMOND BAY ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	
68	Nanaimo/Ladysmith	HAREWOOD ELEMENTARY	1	Gymnasium	Medium	Inactive	Medium
68	Nanaimo/Ladysmith	HAREWOOD ELEMENTARY	2	Classrooms	Medium	Inactive	
68	Nanaimo/Ladysmith	JOHN BARSBY COMMUNITY	1	Auditorium, Kitchen, Multi-purpose	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	JOHN BARSBY COMMUNITY	2	1999 Addition 2 Storey	Low	Meets Structural Life Safety Requirements	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
68	Nanaimo/Ladysmith	JOHN BARSBY COMMUNITY	3	Classrooms Two Storey	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	JOHN BARSBY COMMUNITY	4	Single Storey	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	LADYSMITH INTERMEDIATE	1	Gymnasium 1955	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	LADYSMITH INTERMEDIATE	2	Classrooms 1955/1995	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	LADYSMITH INTERMEDIATE	3	Library, Multi-Purpose 1995	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	LADYSMITH PRIMARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	LADYSMITH PRIMARY	2	Original Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	LADYSMITH PRIMARY	3	Addition	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	LADYSMITH SECONDARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	LADYSMITH SECONDARY	2	Auditorium/Lunch Room	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	LADYSMITH SECONDARY	3	Two Storey Timber Frame	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	LADYSMITH SECONDARY	4	Single Storey Masonry	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	MCGIRR ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
68	Nanaimo/Ladysmith	MCGIRR ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	Low
68	Nanaimo/Ladysmith	MCGIRR ELEMENTARY	3	Classrooms 1999	Low	Meets Structural Life Safety Requirements	Low
68	Nanaimo/Ladysmith	MOUNT BENSON ELEMENTARY	1	Gymnasium, Multi-Purpose Room, Change Rooms	Low	Inactive	Medium
68	Nanaimo/Ladysmith	MOUNT BENSON ELEMENTARY	2	Single Storey T-Frame	Medium	Inactive	Medium
68	Nanaimo/Ladysmith	MOUNTAIN VIEW ELEMENTARY	1	Classrooms 1998	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	MOUNTAIN VIEW ELEMENTARY	2	Gymnasium 1998	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	MOUNTAIN VIEW ELEMENTARY	3	Kindergarten 1982	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	MOUNTAIN VIEW ELEMENTARY	4	Multipurpose 1977	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	MOUNTAIN VIEW ELEMENTARY	5	Classrooms 1967,1969	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	N.D.S.S.ANNEX	1	Music Room - typical of six in district	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	NANAIMO DISTRICT SECONDARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	NANAIMO DISTRICT SECONDARY	2	Library	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	NANAIMO DISTRICT SECONDARY	3	Classrooms Two Storey	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	NANAIMO DISTRICT SECONDARY	4	Shops	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	NANAIMO DISTRICT SECONDARY	5	Cafeteria	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	NORTH CEDAR INTERMEDIATE	1	1969 Gymnasium	High 3	Structural Upgrade Required	High 3
68	Nanaimo/Ladysmith	NORTH CEDAR INTERMEDIATE	2	1969 2-Storey Classrooms	Medium	Non Structural Upgrade Required	High 3
68	Nanaimo/Ladysmith	NORTH CEDAR INTERMEDIATE	3	1969 Shops	Low	Meets Structural Life Safety Requirements	High 3
68	Nanaimo/Ladysmith	NORTH CEDAR INTERMEDIATE	4	1979 Band/Music Block	Low	Meets Structural Life Safety Requirements	High 3
68	Nanaimo/Ladysmith	NORTH OYSTER ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	NORTH OYSTER ELEMENTARY	2	Classrooms Single Storey	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	NORTH OYSTER ELEMENTARY	3	Classrooms 1993 Addition	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	NORTHFIELD ALTERNATE	1	Classrooms	Medium	Inactive	Medium
68	Nanaimo/Ladysmith	PARK AVENUE ELEMENTARY	1	Gymnasium Change Rooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	PARK AVENUE ELEMENTARY	2	Single Storey Timber Frame	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	PARK AVENUE ELEMENTARY	3	1999 Addition Classrooms	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	PAULINE HAARER ELEMENTARY	1	Classrooms	N/A	Completed	N/A
68	Nanaimo/Ladysmith	PAULINE HAARER ELEMENTARY	2	Classrooms 1950	N/A	Completed	N/A
68	Nanaimo/Ladysmith	PAULINE HAARER ELEMENTARY	3	Gymnasium	N/A	Completed	N/A
68	Nanaimo/Ladysmith	PAULINE HAARER ELEMENTARY	4	Kindergarten	N/A	Completed	N/A
68	Nanaimo/Ladysmith	PAULINE HAARER ELEMENTARY	5	Library	N/A	Completed	N/A
68	Nanaimo/Ladysmith	PLEASANT VALLEY ELEMENTARY	1	1976 Gymnasium	Low	Meets Structural Life Safety Requirements	High 2
68	Nanaimo/Ladysmith	PLEASANT VALLEY ELEMENTARY	2	1973 2-Storey Classrooms	High 2	Structural Upgrade Required	High 2
68	Nanaimo/Ladysmith	PLEASANT VALLEY ELEMENTARY	3	1983 1-Storey Library & Classrooms	Low	Meets Structural Life Safety Requirements	High 2
68	Nanaimo/Ladysmith	PLEASANT VALLEY ELEMENTARY	4	1999 1-Storey Classrooms	Low	Meets Structural Life Safety Requirements	High 2
68	Nanaimo/Ladysmith	PRINCESS ROYAL ELEMENTARY	1	Gymnasium	Low	Inactive	Medium

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
68	Nanaimo/Ladysmith	PRINCESS ROYAL ELEMENTARY	2	Single Storey Timber Frame	Medium	Inactive	Medium
68	Nanaimo/Ladysmith	QUARTERWAY ELEMENTARY	1	West Wing	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	QUARTERWAY ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	QUARTERWAY ELEMENTARY	3	East Wing	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	ROCK CITY ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	ROCK CITY ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	ROCK CITY ELEMENTARY	3	Primary Annex	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	ROCK CITY ELEMENTARY	4	Classrooms	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	RUTHERFORD COMMUNITY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	RUTHERFORD COMMUNITY	2	Two Storey	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	RUTHERFORD COMMUNITY	3	Single Storey Timber Frame	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	RUTHERFORD COMMUNITY	4	Kindergarten and Multi-Purpose Room	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	SEAVIEW ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	SEAVIEW ELEMENTARY	2	Administration	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	SEAVIEW ELEMENTARY	3	Classrooms	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	SOUTH WELLINGTON ELEMENTARY	1	Classrooms	High 2	Inactive	High 2
68	Nanaimo/Ladysmith	UPLANDS PARK ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
68	Nanaimo/Ladysmith	UPLANDS PARK ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	VAST CENTRE	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	WATERLOO ELEMENTARY	1	Gymnasium	Low	Inactive	Low
68	Nanaimo/Ladysmith	WATERLOO ELEMENTARY	2	Classrooms	Low	Inactive	Low
68	Nanaimo/Ladysmith	WELLINGTON SECONDARY	1	1967 2-Storey Science Wing (Block A)	N/A	Completed	N/A
68	Nanaimo/Ladysmith	WELLINGTON SECONDARY	2	1977 2-Storey Admin (Block E)	N/A	Completed	N/A
68	Nanaimo/Ladysmith	WELLINGTON SECONDARY	3	1969 1-Storey Central Core (Block F)	N/A	Completed	N/A
68	Nanaimo/Ladysmith	WELLINGTON SECONDARY	4	1967 Shops (Block B)	N/A	Completed	N/A
68	Nanaimo/Ladysmith	WELLINGTON SECONDARY	5	2000 ??? (Block C)	N/A	Completed	N/A
68	Nanaimo/Ladysmith	WELLINGTON SECONDARY	6	1971 ??? (Block D)	N/A	Completed	N/A
68	Nanaimo/Ladysmith	WOODBANK PRIMARY	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	WOODBANK PRIMARY	2	Library/Classroom	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	WOODBANK PRIMARY	3	Gymnasium	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	WOODLANDS SECONDARY	1	1959 3-Storey Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	WOODLANDS SECONDARY	2	1953 2-Storey Classrooms	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	WOODLANDS SECONDARY	3	1953 Gymnasium	Medium	Non Structural Upgrade Required	Medium
68	Nanaimo/Ladysmith	WOODLANDS SECONDARY	4	1953 Shops & Cafeteria	Medium	Non Structural Upgrade Required	Medium
69	Qualicum	BALLENAS SECONDARY	1	1991 1-Storey Classrooms	Low	Meets Structural Life Safety Requirements	Medium
69	Qualicum	BALLENAS SECONDARY	2	1976 1-Storey Classrooms/Gym	Medium	Non Structural Upgrade Required	Medium
69	Qualicum	BALLENAS SECONDARY	3	2000 1-Storey Classrooms/Gym	Low	Meets Structural Life Safety Requirements	Medium
69	Qualicum	BOWSER ELEMENTARY	1	Building A	Medium	Non Structural Upgrade Required	Medium
69	Qualicum	BOWSER ELEMENTARY	2	Gymnasium, MP Room, Library	Low	Meets Structural Life Safety Requirements	Medium
69	Qualicum	BOWSER ELEMENTARY	3	Classrooms	Low	Meets Structural Life Safety Requirements	Medium
69	Qualicum	FALSE BAY SCHOOL	1	Classroom	Medium	Non Structural Upgrade Required	Medium
69	Qualicum	FRENCH CREEK ELEMENTARY	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
69	Qualicum	FRENCH CREEK ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	Medium
69	Qualicum	KWALIKUM SECONDARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
69	Qualicum	KWALIKUM SECONDARY	2	1981 2-Storey Classrooms	Medium	Non Structural Upgrade Required	Medium
69	Qualicum	KWALIKUM SECONDARY	3	1981 1-Storey Classrooms	Low	Meets Structural Life Safety Requirements	Medium
69	Qualicum	KWALIKUM SECONDARY	4	1988 1-Storey Classrooms	Low	Meets Structural Life Safety Requirements	Medium
69	Qualicum	KWALIKUM SECONDARY	5	2001 2-Storey Classrooms	Low	Meets Structural Life Safety Requirements	Medium
69	Qualicum	PARKSVILLE ELEMENTARY	1	Gymnasium	N/A	Completed	Medium

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
69	Qualicum	PARKSVILLE ELEMENTARY	2	Classrooms & Multi-Purpose Room	N/A	Completed	N/A
69	Qualicum	PARKSVILLE ELEMENTARY	3	1994 Addition	N/A	Completed	
69	Qualicum	QUALICUM BEACH ELEMENTARY	1	Activity Room	Medium	Non Structural Upgrade Required	
69	Qualicum	QUALICUM BEACH ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	Medium
69	Qualicum	QUALICUM BEACH ELEMENTARY	3	Classrooms/Administration	Medium	Non Structural Upgrade Required	
69	Qualicum	QUALICUM BEACH ELEMENTARY	4	Classrooms 2000	Low	Meets Structural Life Safety Requirements	
69	Qualicum	WINCHELSEA ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
69	Qualicum	WINCHELSEA ELEMENTARY	2	Classrooms & MP Room	Low	Meets Structural Life Safety Requirements	
70	Alberni	A W NEILL MIDDLE	1	1956 Gymnasium	Medium	Partially Complete?	Medium
70	Alberni	A W NEILL MIDDLE	2	1956 2-Storey Classrooms	Medium	Partially Complete?	
70	Alberni	A W NEILL MIDDLE	3	1956 1-Storey Block	Medium	Partially Complete?	
70	Alberni	A W NEILL MIDDLE	4	1956 1-Storey Music/Mechanical Block	Medium	Partially Complete?	
70	Alberni	ALBERNI DISTRICT SECONDARY	1	Gymnasium	N/A	Completed	N/A
70	Alberni	ALBERNI DISTRICT SECONDARY	2	Library	N/A	Completed	
70	Alberni	ALBERNI DISTRICT SECONDARY	3	Music Room	N/A	Completed	
70	Alberni	ALBERNI DISTRICT SECONDARY	4	Community Services Building	N/A	Completed	
70	Alberni	ALBERNI DISTRICT SECONDARY	5	Industrial Education	N/A	Completed	
70	Alberni	ALBERNI DISTRICT SECONDARY	6	Industrial Education	N/A	Completed	
70	Alberni	ALBERNI DISTRICT SECONDARY	7	Auditorium	N/A	Completed	
70	Alberni	ALBERNI DISTRICT SECONDARY	8	Main School	N/A	Completed	
70	Alberni	ALBERNI DISTRICT SECONDARY	9	Main School	N/A	Completed	
70	Alberni	ALBERNI ELEMENTARY	1	Activity Room	Medium	Non Structural Upgrade Required	
70	Alberni	ALBERNI ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
70	Alberni	ALBERNI ELEMENTARY	3	Field House	Medium	Non Structural Upgrade Required	
70	Alberni	EIGHTH AVENUE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
70	Alberni	EIGHTH AVENUE ELEMENTARY	2	Annex	Medium	Non Structural Upgrade Required	
70	Alberni	EIGHTH AVENUE ELEMENTARY	3	1997 Classrooms	Low	Meets Structural Life Safety Requirements	
70	Alberni	ERIC J DUNN MIDDLE	1	Gymnasium/Auditorium	Medium	Non Structural Upgrade Required	Medium
70	Alberni	ERIC J DUNN MIDDLE	2	Building D South Side Classrooms	Medium	Non Structural Upgrade Required	
70	Alberni	ERIC J DUNN MIDDLE	3	Building A, F	Medium	Non Structural Upgrade Required	
70	Alberni	ERIC J DUNN MIDDLE	4	Building B, E	Medium	Non Structural Upgrade Required	
70	Alberni	GILL ELEMENTARY	1	Activity Room	Medium	Non Structural Upgrade Required	Medium
70	Alberni	GILL ELEMENTARY	2	2 Storey Timber Frame	Medium	Non Structural Upgrade Required	
70	Alberni	JOHN HOWITT ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
70	Alberni	JOHN HOWITT ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
70	Alberni	MAQUINNA ELEMENTARY	1	Building 1 Gymnasium	N/A	Completed	N/A
70	Alberni	MAQUINNA ELEMENTARY	2	Building 1 Classrooms	N/A	Completed	
70	Alberni	MAQUINNA ELEMENTARY	3	Building 2 - Classroom	N/A	Completed	
70	Alberni	MAQUINNA ELEMENTARY	4	Building 3 - Classroom	N/A	Completed	
70	Alberni	UCLUELET ELEMENTARY	1	1964 Gymnasium	Medium	Non Structural Upgrade Required	High 1
70	Alberni	UCLUELET ELEMENTARY	2	1963 2-Storey Classrooms	High 1	Structural Upgrade Required	
70	Alberni	UCLUELET SECONDARY	1	1947 1-Storey North Classroom Wing	Medium	Non Structural Upgrade Required	High 1
70	Alberni	UCLUELET SECONDARY	2	1947 1-Storey Activity Room & Offices	Medium	Non Structural Upgrade Required	
70	Alberni	UCLUELET SECONDARY	3	1963 1-Storey West Wing	High 1	Structural Upgrade Required	
70	Alberni	UCLUELET SECONDARY	4	1973 Shops & Gymnasium Building	High 1	Structural Upgrade Required	
70	Alberni	UCLUELET SECONDARY	5	1987 1-Storey Bandroom/Cafeteria Building	Low	Meets Structural Life Safety Requirements	
70	Alberni	WICKANINNISH COMMUNITY	1	1971 2-Storey Main Building	High 3	Structural Upgrade Required	High 3
70	Alberni	WOOD ELEMENTARY	1	1965 Gymnasium	Medium	Non Structural Upgrade Required	Medium
70	Alberni	WOOD ELEMENTARY	2	1969 Library	Low	Meets Structural Life Safety Requirements	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
70	Alberni	WOOD ELEMENTARY	3	1958 1-Storey Classrooms	Medium	Non Structural Upgrade Required	
71	Comox Valley	AIRPORT ELEMENTARY	1	Gymnasium/Stage	Low	Meets Structural Life Safety Requirements	Medium
71	Comox Valley	AIRPORT ELEMENTARY	2	Classrooms - South Wing	Medium	Non Structural Upgrade Required	
71	Comox Valley	AIRPORT ELEMENTARY	3	Classrooms - North Wing	Medium	Non Structural Upgrade Required	
71	Comox Valley	ARDEN ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
71	Comox Valley	ARDEN ELEMENTARY	2	Original and 1989 Classrooms	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	ARDEN ELEMENTARY	3	1994 Classrooms	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	BROOKLYN ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
71	Comox Valley	BROOKLYN ELEMENTARY	2	Classrooms 1963	Medium	Non Structural Upgrade Required	
71	Comox Valley	BROOKLYN ELEMENTARY	3	Classrooms 1981	Medium	Non Structural Upgrade Required	
71	Comox Valley	BROOKLYN ELEMENTARY	4	Change Rooms	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	COMOX ELEMENTARY	1	Gymnasium	Low	Inactive	Medium
71	Comox Valley	COMOX ELEMENTARY	2	1965 Classrooms	Medium	Inactive	
71	Comox Valley	COMOX ELEMENTARY	3	1966 Classrooms	Medium	Inactive	
71	Comox Valley	COURTENAY ELEMENTARY	1	1960 Gymnasium	Medium	Non Structural Upgrade Required	High 3
71	Comox Valley	COURTENAY ELEMENTARY	2	1960 2-Storey Classrooms	High 3	Structural Upgrade Required	
71	Comox Valley	COURTENAY ELEMENTARY	3	1970 1-Storey Classroom Addition	Medium	Non Structural Upgrade Required	
71	Comox Valley	CUMBERLAND ELEMENTARY	1	Entire 1972 Building	Low	Meets Structural Life Safety Requirements	Medium
71	Comox Valley	CUMBERLAND ELEMENTARY	2	Music Room	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	CUMBERLAND ELEMENTARY	3	Annex	Medium	Non Structural Upgrade Required	
71	Comox Valley	CUMBERLAND ELEM-JR SEC	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	CUMBERLAND ELEM-JR SEC	2	1964 Classrooms, 1970/1976/1992 Additions	Low	Meets Structural Life Safety Requirements	Low
71	Comox Valley	CUMBERLAND ELEM-JR SEC	3	1993 Classroom Addition and Renovation	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	DENMAN ISLAND ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
71	Comox Valley	DENMAN ISLAND ELEMENTARY	2	Classroom	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	ECOLE PUNTLEDGE PARK ELEMENTAR	1	Classroom / Admin (North)	Medium	Non Structural Upgrade Required	Medium
71	Comox Valley	ECOLE PUNTLEDGE PARK ELEMENTAR	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	ECOLE PUNTLEDGE PARK ELEMENTAR	3	Classrooms / Library	Medium	Non Structural Upgrade Required	
71	Comox Valley	ECOLE PUNTLEDGE PARK ELEMENTAR	4	Classrooms	Medium	Non Structural Upgrade Required	
71	Comox Valley	ECOLE PUNTLEDGE PARK ELEMENTAR	5	Classrooms (2000)	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	ECOLE ROBB ROAD	1	Gymnasium	N/A	Completed	N/A
71	Comox Valley	ECOLE ROBB ROAD	2	Annex	N/A	Completed	
71	Comox Valley	ECOLE ROBB ROAD	3	1959 2-Storey	N/A	Completed	
71	Comox Valley	ECOLE ROBB ROAD	4	1971 Masonry Addition	N/A	Completed	
71	Comox Valley	ECOLE ROBB ROAD	5	Circa 1955 - Single Storey	N/A	Completed	
71	Comox Valley	ECOLE ROBB ROAD	6	Band Room	N/A	Completed	
71	Comox Valley	GEORGES P VANIER SECONDARY	1	1966 1-Storey Shops & 1989 Arts Wing	High 1	Proceeding to Construction	High 1
71	Comox Valley	GEORGES P VANIER SECONDARY	2	1966 1-Storey Original School	High 1	Proceeding to Construction	
71	Comox Valley	GEORGES P VANIER SECONDARY	3	1966 2-Storey Science Block	High 1	Proceeding to Construction	
71	Comox Valley	GEORGES P VANIER SECONDARY	4	1968 1-Storey Library/Classrooms	High 2	Proceeding to Construction	
71	Comox Valley	GEORGES P VANIER SECONDARY	5	1989 1-Storey Storage	Low	Proceeding to Construction	
71	Comox Valley	GLACIER VIEW ELEMENTARY	1	Classrooms	Medium	Inactive	Medium
71	Comox Valley	GLACIER VIEW ELEMENTARY	2	Classrooms/Administration	Medium	Inactive	
71	Comox Valley	GLACIER VIEW ELEMENTARY	3	Gymnasium	Medium	Inactive	
71	Comox Valley	GLACIER VIEW ELEMENTARY	4	Classrooms	Low	Inactive	
71	Comox Valley	GLACIER VIEW ELEMENTARY	5	Gym Change Rooms	Medium	Inactive	
71	Comox Valley	GLACIER VIEW ELEMENTARY	6	Annex Classrooms	Low	Inactive	
71	Comox Valley	GLACIER VIEW ELEMENTARY	7	East Wing 1999	Low	Inactive	
71	Comox Valley	GLACIER VIEW ELEMENTARY	8	Band Room - Portable on permanent fdn-1999	Low	Inactive	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
71	Comox Valley	HIGHLAND SECONDARY	1	Gymnasium 1978	N/A	Completed	N/A
71	Comox Valley	HIGHLAND SECONDARY	2	Academic Block 1978	N/A	Completed	
71	Comox Valley	HIGHLAND SECONDARY	3	Shops 1978	N/A	Completed	
71	Comox Valley	HIGHLAND SECONDARY	4	Academic Block 1998	N/A	Completed	
71	Comox Valley	HIGHLAND SECONDARY	5	Band Addition 1998	N/A	Completed	
71	Comox Valley	HORNBY ISLAND ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
71	Comox Valley	HORNBY ISLAND ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	LAKE TRAIL MIDDLE	1	1955 Old Gym	Medium	Non Structural Upgrade Required	High 2
71	Comox Valley	LAKE TRAIL MIDDLE	2	1955 1-Storey Admin./Multi-Purpose	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	LAKE TRAIL MIDDLE	3	1955 2-Storey Classrooms	Medium	Non Structural Upgrade Required	
71	Comox Valley	LAKE TRAIL MIDDLE	4	1964 1-Storey Science/Shops/Arts	High 2	Structural Upgrade Required	
71	Comox Valley	LAKE TRAIL MIDDLE	5	1999 New Gym/Library	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	MIRACLE BEACH ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
71	Comox Valley	MIRACLE BEACH ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
71	Comox Valley	MIRACLE BEACH ELEMENTARY	3	Classrooms (Post 1992)	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	ROYSTON ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
71	Comox Valley	ROYSTON ELEMENTARY	2	Classroom - 1967	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	ROYSTON ELEMENTARY	3	Classrooms - 1952/63	Medium	Non Structural Upgrade Required	
71	Comox Valley	ROYSTON ELEMENTARY	4	Classrooms - 1990	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	TSOLUM ELEMENTARY	1	1953 Block - Gymnasium	Low	Inactive	Medium
71	Comox Valley	TSOLUM ELEMENTARY	2	1955 Block	Medium	Inactive	
71	Comox Valley	TSOLUM ELEMENTARY	3	Annex	Medium	Inactive	
71	Comox Valley	UNION BAY ELEMENTARY	1	Original Classrooms	Low	Meets Structural Life Safety Requirements	Low
71	Comox Valley	UNION BAY ELEMENTARY	2	1953 Addition, Classrooms	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	VALLEY VIEW ELEMENTARY	1	1993 Building	Low	Meets Structural Life Safety Requirements	Low
71	Comox Valley	VALLEY VIEW ELEMENTARY	2	2000 Building	Low	Meets Structural Life Safety Requirements	
71	Comox Valley	VILLAGE PARK ELEMENTARY	1	Classroom / Admin	Low	Inactive	Medium
71	Comox Valley	VILLAGE PARK ELEMENTARY	2	Gymnasium / Covered play area	Medium	Inactive	
71	Comox Valley	VILLAGE PARK ELEMENTARY	3	Classrooms / Change rooms	Medium	Inactive	
72	Campbell River	CARIHI SECONDARY	1	Building A - Circa 1965	N/A	Completed	N/A
72	Campbell River	CARIHI SECONDARY	2	Building A - 1971 Addition	N/A	Completed	
72	Campbell River	CARIHI SECONDARY	3	Building B - 1966	N/A	Completed	
72	Campbell River	CARIHI SECONDARY	4	Building C - 1966 Shops	N/A	Completed	
72	Campbell River	CARIHI SECONDARY	5	Building D - Gymnasium (1967)	N/A	Completed	
72	Campbell River	CARIHI SECONDARY	6	Building D - Cafeteria (1967)	N/A	Completed	
72	Campbell River	CARIHI SECONDARY	7	Building C - 1973 Shops Addition	N/A	Completed	
72	Campbell River	CARIHI SECONDARY	8	1999 Addition	N/A	Completed	
72	Campbell River	CEDAR ANNEX	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
72	Campbell River	CEDAR ANNEX	2	Classrooms	Medium	Non Structural Upgrade Required	
72	Campbell River	CEDAR ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
72	Campbell River	CEDAR ELEMENTARY	2	Classrooms and Activity Room	Medium	Non Structural Upgrade Required	
72	Campbell River	CORTES ISLAND ELEM-JR SEC	1	1977 Gymnasium	High 3	Structural Upgrade Required	High 2
72	Campbell River	CORTES ISLAND ELEM-JR SEC	2	1977 Gym Auxiliary Services	High 3	Structural Upgrade Required	
72	Campbell River	CORTES ISLAND ELEM-JR SEC	3	1977 1-Storey Administration	High 2	Structural Upgrade Required	
72	Campbell River	CORTES ISLAND ELEM-JR SEC	4	1977 1-Storey Classrooms	High 2	Structural Upgrade Required	
72	Campbell River	DISCOVERY PASSAGE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
72	Campbell River	DISCOVERY PASSAGE ELEMENTARY	2	South Classrooms	Medium	Non Structural Upgrade Required	
72	Campbell River	DISCOVERY PASSAGE ELEMENTARY	3	North Classrooms	Medium	Non Structural Upgrade Required	
72	Campbell River	ECOLE DES DEUX MONDES ELEMENTA	1	1966 Classrooms	N/A	Completed	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
72	Campbell River	ECOLE DES DEUX MONDES ELEMENTA	2	1972 Addition	N/A	Completed	N/A
72	Campbell River	ECOLE DES DEUX MONDES ELEMENTA	3	1975 Addition	N/A	Completed	
72	Campbell River	ECOLE DES DEUX MONDES ELEMENTA	4	Gymnasium (1966)	N/A	Completed	
72	Campbell River	ECOLE PHOENIX MIDDLE	1	1977 1-Storey Science Wing	N/A	Completed	N/A
72	Campbell River	ECOLE PHOENIX MIDDLE	2	1977 Gymnasium	N/A	Completed	
72	Campbell River	ECOLE PHOENIX MIDDLE	3	1977 Change Rooms	N/A	Completed	
72	Campbell River	ECOLE PHOENIX MIDDLE	4	1977 Shops	N/A	Completed	
72	Campbell River	ECOLE PHOENIX MIDDLE	5	1977 2-Storey Commerce & Admin.	N/A	Completed	
72	Campbell River	ECOLE PHOENIX MIDDLE	6	1977 2-Storey Classrooms	N/A	Completed	
72	Campbell River	ECOLE PHOENIX MIDDLE	7	1977 1-Storey Library	N/A	Completed	
72	Campbell River	ECOLE PHOENIX MIDDLE	8	1999 General Instruction	N/A	Completed	
72	Campbell River	ECOLE WILLOW POINT ELEMENTARY	1	Gymnasium	N/A	Completed	N/A
72	Campbell River	ECOLE WILLOW POINT ELEMENTARY	2	Classrooms	N/A	Completed	
72	Campbell River	OYSTER RIVER ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
72	Campbell River	OYSTER RIVER ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
72	Campbell River	OYSTER RIVER ELEMENTARY	3	Classroom Addition	Low	Meets Structural Life Safety Requirements	Medium
72	Campbell River	PENFIELD ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
72	Campbell River	PENFIELD ELEMENTARY	2	Classrooms / Admin	Medium	Non Structural Upgrade Required	N/A
72	Campbell River	PINECREST ELEMENTARY	1	1966 1-Storey Structure	N/A	Completed	
72	Campbell River	PINECREST ELEMENTARY	2	1969 1-Storey Addition	N/A	Completed	N/A
72	Campbell River	PINECREST ELEMENTARY	3	1972 1-Storey Classroom Addition	N/A	Completed	
72	Campbell River	PINECREST ELEMENTARY	4	1976 1-Storey Addition	N/A	Completed	
72	Campbell River	PINECREST ELEMENTARY	5	1975 Change Room Addition	N/A	Completed	
72	Campbell River	PINECREST ELEMENTARY	6	1978 1-Storey Classroom Addition	N/A	Completed	Medium
72	Campbell River	QUADRA ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
72	Campbell River	QUADRA ELEMENTARY	2	East Classrooms & Library	Low	Meets Structural Life Safety Requirements	
72	Campbell River	QUADRA ELEMENTARY	3	South Classrooms	Medium	Non Structural Upgrade Required	
72	Campbell River	QUADRA ELEMENTARY	4	SW Classrooms/Multi/Admin	Low	Meets Structural Life Safety Requirements	Medium
72	Campbell River	ROBRON MIDDLE	1	Classrooms	Medium	Inactive	
72	Campbell River	ROBRON MIDDLE	2	Shops	Low	Inactive	
72	Campbell River	ROBRON MIDDLE	3	Change Rooms	Low	Inactive	
72	Campbell River	ROBRON MIDDLE	4	Gymnasium	Low	Inactive	Medium
72	Campbell River	ROBRON MIDDLE	5	1982 Classrooms	Low	Inactive	
72	Campbell River	ROBRON MIDDLE	6	1982 Shops	Medium	Inactive	
72	Campbell River	ROCKLAND ELEMENTARY	1	Gymnasium	Medium	Inactive	
72	Campbell River	ROCKLAND ELEMENTARY	2	Classrooms	Medium	Inactive	Medium
72	Campbell River	SANDOWNE ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
72	Campbell River	SANDOWNE ELEMENTARY	2	Classroom / Admin	Low	Meets Structural Life Safety Requirements	Low
72	Campbell River	SANDOWNE ELEMENTARY	3	1992 Classrooms	Low	Meets Structural Life Safety Requirements	
72	Campbell River	SOUTHGATE MIDDLE	1	1971 Original Block	N/A	Completed	N/A
72	Campbell River	SOUTHGATE MIDDLE	2	1975 Shop Wing	N/A	Completed	
72	Campbell River	SOUTHGATE MIDDLE	3	1975 Classroom Block	N/A	Completed	
72	Campbell River	SOUTHGATE MIDDLE	4	1976 Block	N/A	Completed	
72	Campbell River	SOUTHGATE MIDDLE	5	Gymnasium - 1971	N/A	Completed	
72	Campbell River	SOUTHGATE MIDDLE	6	1976 Activity/Music	N/A	Completed	
72	Campbell River	SOUTHGATE MIDDLE	7	1999 Addition	N/A	Completed	
72	Campbell River	SURGE NARROWS ELEMENTARY	1	Classrooms & Administration	Low	Meets Structural Life Safety Requirements	Medium
72	Campbell River	SURGE NARROWS ELEMENTARY	2	Community Hall, Gymnasium	Medium	Non Structural Upgrade Required	
75	Mission	ALBERT MCMAHON ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
75 Mission		ALBERT MCMAHON ELEMENTARY	2	Classrooms (East)	Medium	Non Structural Upgrade Required	Medium
75 Mission		ALBERT MCMAHON ELEMENTARY	3	Classrooms (West)	Low	Meets Structural Life Safety Requirements	
75 Mission		CEDAR VALLEY	1	Multi-Purpose	Medium	Non Structural Upgrade Required	
75 Mission		CEDAR VALLEY	2	Classroom/Administration	Low	Meets Structural Life Safety Requirements	Medium
75 Mission		CEDAR VALLEY	3	Classroom (West)	Low	Meets Structural Life Safety Requirements	
75 Mission		CEDAR VALLEY	4	Classroom (South)	Medium	Non Structural Upgrade Required	
75 Mission		CHERRY HILL ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
75 Mission		CHERRY HILL ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	Medium
75 Mission		CHERRY HILL ELEMENTARY	3	Classrooms (1999)	Low	Meets Structural Life Safety Requirements	
75 Mission		DEWDNEY ELEMENTARY	1	1940 Classrooms	Medium	Non Structural Upgrade Required	
75 Mission		DEWDNEY ELEMENTARY	2	1959 Classrooms	Medium	Non Structural Upgrade Required	Medium
75 Mission		DEWDNEY ELEMENTARY	3	1992 Gym Addition	Low	Meets Structural Life Safety Requirements	
75 Mission		DURIEU ELEMENTARY	1	Classroom (East & West Wing)	Medium	Non Structural Upgrade Required	
75 Mission		DURIEU ELEMENTARY	2	Administration	Low	Meets Structural Life Safety Requirements	Low
75 Mission		DURIEU ELEMENTARY	3	Gymnasium	Low	Meets Structural Life Safety Requirements	
75 Mission		EDWIN S RICHARDS ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
75 Mission		EDWIN S RICHARDS ELEMENTARY	2	Classroom - Centre	Low	Meets Structural Life Safety Requirements	Low
75 Mission		EDWIN S RICHARDS ELEMENTARY	3	Classroom - North	Low	Meets Structural Life Safety Requirements	
75 Mission		EDWIN S RICHARDS ELEMENTARY	4	Classroom - South/East	Low	Meets Structural Life Safety Requirements	
75 Mission		EDWIN S RICHARDS ELEMENTARY	5	Classroom (2000) - North/East	Low	Meets Structural Life Safety Requirements	
75 Mission		FERNDALE ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
75 Mission		FERNDALE ELEMENTARY	2	Classroom, Administration	Low	Meets Structural Life Safety Requirements	Low
75 Mission		FERNDALE ELEMENTARY	3	Classrooms, Library (1995)	Low	Meets Structural Life Safety Requirements	
75 Mission		FRASERVIEW ELEMENTARY	1	Gymnasium	Medium	Inactive	
75 Mission		FRASERVIEW ELEMENTARY	2	Classrooms (Central)	Medium	Inactive	Medium
75 Mission		FRASERVIEW ELEMENTARY	3	Classrooms/Change rooms (East)	Low	Inactive	
75 Mission		FRASERVIEW ELEMENTARY	4	Classrooms/Multipurpose (2000)	Low	Inactive	
75 Mission		HATZIC ELEMENTARY	1	Classrooms (South)	Medium	Non Structural Upgrade Required	
75 Mission		HATZIC ELEMENTARY	2	Library	Medium	Non Structural Upgrade Required	Medium
75 Mission		HATZIC ELEMENTARY	3	Classroom (Central)	Medium	Non Structural Upgrade Required	
75 Mission		HATZIC ELEMENTARY	4	Gymnasium	Medium	Non Structural Upgrade Required	
75 Mission		HATZIC ELEMENTARY	5	Classroom (North)	Medium	Non Structural Upgrade Required	
75 Mission		HATZIC SECONDARY	1	Classroom/Administration	Medium	Non Structural Upgrade Required	
75 Mission		HATZIC SECONDARY	2	Gymnasium	Medium	Non Structural Upgrade Required	Medium
75 Mission		HATZIC SECONDARY	3	Classroom	Medium	Non Structural Upgrade Required	
75 Mission		HATZIC SECONDARY	4	Gymnasium	Medium	Non Structural Upgrade Required	
75 Mission		HATZIC SECONDARY	5	Classroom (West)	Medium	Non Structural Upgrade Required	
75 Mission		HILLSIDE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
75 Mission		HILLSIDE ELEMENTARY	2	Administration/Library	Medium	Non Structural Upgrade Required	Medium
75 Mission		HILLSIDE ELEMENTARY	3	Classrooms	Low	Meets Structural Life Safety Requirements	
75 Mission		HILLSIDE ELEMENTARY	4	Classrooms (1997)	Low	Meets Structural Life Safety Requirements	
75 Mission		MISSION CENTRAL ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
75 Mission		MISSION CENTRAL ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	Low
75 Mission		MISSION CENTRAL ELEMENTARY	3	Classrooms/Music (1999)	Low	Meets Structural Life Safety Requirements	
75 Mission		MISSION SECONDARY	1	1991 Gymnasium (West)	Low	Meets Structural Life Safety Requirements	
75 Mission		MISSION SECONDARY	2	1993 Gymnasium (East)	Low	Meets Structural Life Safety Requirements	
75 Mission		MISSION SECONDARY	3	1991 2-Storey Classrooms (West)	Medium	Non Structural Upgrade Required	
75 Mission		MISSION SECONDARY	4	1993 2-Storey Classrooms (South)	Low	Meets Structural Life Safety Requirements	High 3
75 Mission		MISSION SECONDARY	5	1993 1-Storey Cafeteria/Library	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
75	Mission	MISSION SECONDARY	6	1993 1-Storey Classrooms (Central)	Low	Meets Structural Life Safety Requirements	
75	Mission	MISSION SECONDARY	7	1970 Shops	High 3	Structural Upgrade Required	
75	Mission	MISSION SECONDARY	8	1974 1-Storey Bandroom/Admin.	Medium	Non Structural Upgrade Required	
75	Mission	SILVERDALE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
75	Mission	SILVERDALE ELEMENTARY	2	Classroom (West Wing)	Low	Meets Structural Life Safety Requirements	
75	Mission	SILVERDALE ELEMENTARY	3	Classroom	Medium	Non Structural Upgrade Required	
75	Mission	SILVERDALE ELEMENTARY	4	Classroom/Admin. (1992 addition)	Low	Meets Structural Life Safety Requirements	
75	Mission	WEST HEIGHTS ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
75	Mission	WEST HEIGHTS ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	
78	Fraser-Cascade	AGASSIZ ELEM-SEC	1	North Wing	Medium	Non Structural Upgrade Required	Medium
78	Fraser-Cascade	AGASSIZ ELEM-SEC	2	Gymnasium (Const 2000)	Low	Meets Structural Life Safety Requirements	
78	Fraser-Cascade	AGASSIZ ELEM-SEC	3	South Wing	Medium	Non Structural Upgrade Required	
78	Fraser-Cascade	AGASSIZ ELEM-SEC	4	Administration	Medium	Non Structural Upgrade Required	
78	Fraser-Cascade	AGASSIZ ELEM-SEC	5	Technical School (Const 1993)	Low	Meets Structural Life Safety Requirements	Medium
78	Fraser-Cascade	BOSTON BAR ELEM-SEC	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
78	Fraser-Cascade	BOSTON BAR ELEM-SEC	2	Classroom/admin north wing	Medium	Non Structural Upgrade Required	
78	Fraser-Cascade	BOSTON BAR ELEM-SEC	3	West Classroom wing	Medium	Non Structural Upgrade Required	
78	Fraser-Cascade	BOSTON BAR ELEM-SEC	4	south shops wing	Medium	Non Structural Upgrade Required	N/A
78	Fraser-Cascade	C E BARRY INTERMEDIATE	1	1972 Gymnasium	N/A	Completed	
78	Fraser-Cascade	C E BARRY INTERMEDIATE	2	1972 1-Storey Classroom/Washroom Wing, Adjacent	N/A	Completed	
78	Fraser-Cascade	C E BARRY INTERMEDIATE	3	1972 1-Storey Classroom Wing	N/A	Completed	Medium
78	Fraser-Cascade	COQUIHALLA ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	
78	Fraser-Cascade	COQUIHALLA ELEMENTARY	2	Classrooms West	Medium	Non Structural Upgrade Required	
78	Fraser-Cascade	COQUIHALLA ELEMENTARY	3	Classrooms East	Medium	Non Structural Upgrade Required	
78	Fraser-Cascade	COQUIHALLA ELEMENTARY	4	Classrooms North	Low	Meets Structural Life Safety Requirements	
78	Fraser-Cascade	COQUIHALLA ELEMENTARY	5	Middle Wing	Low	Meets Structural Life Safety Requirements	Medium
78	Fraser-Cascade	DISTRICT ALTERNATE SEC PROG	1	Entire Building	Medium	Non Structural Upgrade Required	
78	Fraser-Cascade	HARRISON HOT SPRINGS ELEMENTAR'	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
78	Fraser-Cascade	HARRISON HOT SPRINGS ELEMENTAR'	2	Class Rooms	Medium	Non Structural Upgrade Required	
78	Fraser-Cascade	HOPE SECONDARY	1	Classroom Wing	N/A	Completed	N/A
78	Fraser-Cascade	HOPE SECONDARY	2	Gymnasium	N/A	Completed	
78	Fraser-Cascade	HOPE SECONDARY	3	centre Block	N/A	Completed	
78	Fraser-Cascade	HOPE SECONDARY	4	Industrial Shops	N/A	Completed	
78	Fraser-Cascade	KENT ELEMENTARY	1	East & Library Upgrade 1994	Low	Meets Structural Life Safety Requirements	Medium
78	Fraser-Cascade	KENT ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	
78	Fraser-Cascade	KENT ELEMENTARY	3	West Wing	Medium	Non Structural Upgrade Required	
78	Fraser-Cascade	KENT ELEMENTARY	4	East Wing	Medium	Non Structural Upgrade Required	
78	Fraser-Cascade	MCCAFFREY ALTERNATE	1	McCaffrey Elem school	Medium	Non Structural Upgrade Required	Medium
78	Fraser-Cascade	YALE ELEMENTARY	1	North Block - Gymnasium	Low	Meets Structural Life Safety Requirements	Low
78	Fraser-Cascade	YALE ELEMENTARY	2	Center Block - Administration	Low	Meets Structural Life Safety Requirements	
78	Fraser-Cascade	YALE ELEMENTARY	3	south block - classroom	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	AB GREENWELL ELEMENTARY	1	Gymnasium	High 3	Inactive	High 3
79	Cowichan Valley	AB GREENWELL ELEMENTARY	2	Single Storey Classrooms	Low	Inactive	
79	Cowichan Valley	ALEX AITKEN	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
79	Cowichan Valley	ALEX AITKEN	2	1992 & 2000 Classrooms	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	ALEX AITKEN	3	Pre-1992 Classrooms	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	ALEXANDER ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
79	Cowichan Valley	ALEXANDER ELEMENTARY	2	Main Block	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	ALEXANDER ELEMENTARY	3	West Block	Medium	Non Structural Upgrade Required	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
79	Cowichan Valley	ALEXANDER ELEMENTARY	4	Open Area	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	BENCH ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
79	Cowichan Valley	BENCH ELEMENTARY	2	Masonry Addition	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	BENCH ELEMENTARY	3	1999 Addition	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	BENCH ELEMENTARY	4	Single Storey Timber Frame	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	CHEMAINUS SECONDARY	1	Timber Frame - Auditorium	Medium	Non Structural Upgrade Required	Medium
79	Cowichan Valley	CHEMAINUS SECONDARY	2	Structural Steel Post & Beam - gymnasium	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	CHEMAINUS SECONDARY	3	Two Storey Timber Frame - classrooms	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	CHEMAINUS SECONDARY	4	Single Storey Timber Frame	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	COBBLE HILL 1	1	Two-storey woodframe 1938	Medium	Inactive	Medium
79	Cowichan Valley	COWICHAN SECONDARY	1	1949 Gymnasium	High 2	Structural Upgrade Required	High 2
79	Cowichan Valley	COWICHAN SECONDARY	2	1949 2-Storey Classrooms	High 2	Structural Upgrade Required	
79	Cowichan Valley	COWICHAN SECONDARY	3	1949 1-Storey Classrooms	High 2	Structural Upgrade Required	
79	Cowichan Valley	COWICHAN SECONDARY	4	1965 Shop Building	High 1	Structural Upgrade Required	
79	Cowichan Valley	COWICHAN SECONDARY	5	1965 2-Storey Commercial Building	High 1	Structural Upgrade Required	
79	Cowichan Valley	COWICHAN SECONDARY	6	1976 1-Storey Band Building	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	COWICHAN STATION ELEMENTARY	1	Gymnasium	Medium	Inactive	High 3
79	Cowichan Valley	COWICHAN STATION ELEMENTARY	2	Classrooms	High 3	Inactive	
79	Cowichan Valley	COWICHAN STATION ELEMENTARY	3	Annex	Low	Inactive	
79	Cowichan Valley	CROFTON ELEMENTARY	1	Activity Room	N/A	Completed	N/A
79	Cowichan Valley	CROFTON ELEMENTARY	2	Single Storey Classroom	N/A	Completed	
79	Cowichan Valley	CROFTON ELEMENTARY	3	Single Storey Timber Frame (2)	N/A	Completed	
79	Cowichan Valley	DISCOVERY ELEMENTARY	1	Classrooms	Low	Meets Structural Life Safety Requirements	Low
79	Cowichan Valley	DISCOVERY ELEMENTARY	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	DISTRICT RESOURCE CENTRE	1	Classrooms	Medium	Non Structural Upgrade Required	Medium
79	Cowichan Valley	DRINKWATER ELEMENTARY	1	Activity Room	N/A	Completed	N/A
79	Cowichan Valley	DRINKWATER ELEMENTARY	2	Single Storey Classrooms 1	N/A	Completed	
79	Cowichan Valley	DRINKWATER ELEMENTARY	3	Music Building and Classrooms	N/A	Completed	
79	Cowichan Valley	DRINKWATER ELEMENTARY	4	Gymnasium	N/A	Completed	
79	Cowichan Valley	DUNCAN ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
79	Cowichan Valley	DUNCAN ELEMENTARY	2	MckLrdy Building	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	DUNCAN ELEMENTARY	3	1912 2-Storey Original School (Upgraded 1999)	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	DUNCAN ELEMENTARY	4	Original Gymnasium	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	ELSIE MILES ELEMENTARY	1	Single Storey Timber Frame	Medium	Non Structural Upgrade Required	Medium
79	Cowichan Valley	GEORGE BONNER MIDDLE	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
79	Cowichan Valley	GEORGE BONNER MIDDLE	2	Single Storey Timber Frame	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	KHOWHEMUN ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
79	Cowichan Valley	KHOWHEMUN ELEMENTARY	2	Original Construction	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	KHOWHEMUN ELEMENTARY	3	1993, 1999 Addition	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	KOKSILAH ELEMENTARY	1	1958 1-Storey Classroom Block	Medium	Non Structural Upgrade Required	High 3
79	Cowichan Valley	KOKSILAH ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	KOKSILAH ELEMENTARY	3	1978 2-Storey Masonry	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	KOKSILAH ELEMENTARY	4	1968 1-Storey Kindergarten	High 3	Structural Upgrade Required	
79	Cowichan Valley	LAKE COWICHAN SECONDARY	1	Gymnasium	N/A	Completed	N/A
79	Cowichan Valley	LAKE COWICHAN SECONDARY	2	Phase I Renovation - Administration	N/A	Completed	
79	Cowichan Valley	LAKE COWICHAN SECONDARY	3	Phase II Renovation - Classrooms	N/A	Completed	
79	Cowichan Valley	LAKE COWICHAN SECONDARY	4	Industrial Arts Wing	N/A	Completed	
79	Cowichan Valley	LAKE COWICHAN SECONDARY	5	Music Building	N/A	Completed	
79	Cowichan Valley	LAKE COWICHAN SECONDARY	6	Woodwork Shop	N/A	Completed	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
79	Cowichan Valley	LAKE COWICHAN SECONDARY	7	Continuing Education	N/A	Completed	
79	Cowichan Valley	MILL BAY ELEMENTARY	1	Block 1 Gymnasium	Medium	Non Structural Upgrade Required	Medium
79	Cowichan Valley	MILL BAY ELEMENTARY	2	Block 2 Classrooms	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	MILL BAY ELEMENTARY	3	Block 3 Two Storey Annex	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	MILL BAY ELEMENTARY	4	Block 4 Pre-1958	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	MOUNT PREVOST MIDDLE	1	Two Storey Timber Frame	Medium	Non Structural Upgrade Required	Medium
79	Cowichan Valley	MOUNT PREVOST MIDDLE	2	Single Storey Timber Frame	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	MOUNT PREVOST MIDDLE	3	1994 renovation addition and seismic upgrade	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	PALSSON ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
79	Cowichan Valley	PALSSON ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	QUAMICHAN MIDDLE	1	2001 Addition & Seismic Upgrade	Low	Meets Structural Life Safety Requirements	Medium
79	Cowichan Valley	QUAMICHAN MIDDLE	2	Two Storey Timber Frame	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	QUAMICHAN MIDDLE	3	Single Storey Timber Frame	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	SOMENOS ELEMENTARY	1	Activity Room	Medium	Non Structural Upgrade Required	Medium
79	Cowichan Valley	SOMENOS ELEMENTARY	2	Single Storey T-Frame	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	TANSOR ELEMENTARY	1	Classrooms / Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
79	Cowichan Valley	TANSOR ELEMENTARY	2	Classrooms / Kindergarten	Low	Meets Structural Life Safety Requirements	
79	Cowichan Valley	TANSOR ELEMENTARY	3	Classrooms / Multi-Purpose	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	TANSOR ELEMENTARY	4	Classroom / Administration	Medium	Non Structural Upgrade Required	
79	Cowichan Valley	THETIS ISLAND ELEMENTARY	1	Two Room School	Low	Meets Structural Life Safety Requirements	Low
79	Cowichan Valley	YOUNT ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
79	Cowichan Valley	YOUNT ELEMENTARY	2	Classrooms	Medium	Non Structural Upgrade Required	
82	Coast Mountains	BEAR VALLEY SCHOOL	1	1 Storey Classroom	Medium	Non Structural Upgrade Required	Medium
82	Coast Mountains	BEAR VALLEY SCHOOL	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	CALEDONIA SR SECONDARY	1	1967 2-storey classroom	Medium	Non Structural Upgrade Required	Medium
82	Coast Mountains	CALEDONIA SR SECONDARY	2	1967 Shops	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	CALEDONIA SR SECONDARY	3	1975 automotive shop	Medium	Non Structural Upgrade Required	
82	Coast Mountains	CALEDONIA SR SECONDARY	4	1967 gymnasium	Medium	Non Structural Upgrade Required	
82	Coast Mountains	CASSIE HALL ELEMENTARY	1	1957 1-storey classroom	Medium	Non Structural Upgrade Required	Medium
82	Coast Mountains	CASSIE HALL ELEMENTARY	2	1957 Gymnasium	Medium	Non Structural Upgrade Required	
82	Coast Mountains	CASSIE HALL ELEMENTARY	3	2001 classroom	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	CLARENCE MICHIEL ELEMENTARY	1	1968 1-storey classroom	Medium	Non Structural Upgrade Required	Medium
82	Coast Mountains	CLARENCE MICHIEL ELEMENTARY	2	1-storey classrooms	Medium	Non Structural Upgrade Required	
82	Coast Mountains	E T KENNEY ELEMENTARY	1	1966 1-storey classroom	Medium	Inactive	Medium
82	Coast Mountains	E T KENNEY ELEMENTARY	2	1974 Gymnasium	Medium	Inactive	
82	Coast Mountains	HAZELTON SECONDARY	1	Block 'E'	Low	Meets Structural Life Safety Requirements	Low
82	Coast Mountains	HAZELTON SECONDARY	2	Block 'D'	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	HAZELTON SECONDARY	3	Block 'C'	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	HAZELTON SECONDARY	4	Block 'B'	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	HAZELTON SECONDARY	5	Block 'A'	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	JOHN FIELD ELEMENTARY	1	Original Classroom Block	Low	Meets Structural Life Safety Requirements	Low
82	Coast Mountains	JOHN FIELD ELEMENTARY	2	Classroom Block Addition	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	JOHN FIELD ELEMENTARY	3	Gym Block	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	JOHN FIELD ELEMENTARY	4	1964 Classroom Block	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	KILDALA ELEMENTARY	1	1956 2-storey classroom	Medium	Non Structural Upgrade Required	Medium
82	Coast Mountains	KILDALA ELEMENTARY	2	1956 gymnasium	Medium	Non Structural Upgrade Required	
82	Coast Mountains	KILDALA ELEMENTARY	3	1965 2-storey classroom	Medium	Non Structural Upgrade Required	
82	Coast Mountains	KILDALA ELEMENTARY	4	1965 1-storey addition	Medium	Non Structural Upgrade Required	
82	Coast Mountains	KITI K'SHAN ELEMENTARY	1	1965 2-storey classroom	Medium	Inactive	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
82	Coast Mountains	KITI K'SHAN ELEMENTARY	2	1971 2-storey classroom	Medium	Inactive	Medium
82	Coast Mountains	KITI K'SHAN ELEMENTARY	3	1973 Gymnasium	Medium	Inactive	
82	Coast Mountains	KITI K'SHAN ELEMENTARY	4	1991 1-storey classroom	Low	Inactive	
82	Coast Mountains	KITI K'SHAN ELEMENTARY	5	2001 1-storey classroom	Low	Inactive	
82	Coast Mountains	KITWANGA ELEM-JR SEC	1	Kitwanga Primary	Low	Meets Structural Life Safety Requirements	Low
82	Coast Mountains	KITWANGA ELEM-JR SEC	2	Secondary	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	KITWANGA ELEM-JR SEC	3	Gymnasium & Community Hall	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	MOUNT ELIZABETH SECONDARY	1	1955 2-storey classroom	Medium	Non Structural Upgrade Required	Medium
82	Coast Mountains	MOUNT ELIZABETH SECONDARY	2	1966 2-storey classroom	Medium	Non Structural Upgrade Required	
82	Coast Mountains	MOUNT ELIZABETH SECONDARY	3	1956 gymnasium	Medium	Non Structural Upgrade Required	
82	Coast Mountains	MOUNT ELIZABETH SECONDARY	4	1973 Gymnasium	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	MOUNT ELIZABETH SECONDARY	5	1979 Theatre	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	MOUNT ELIZABETH SECONDARY	6	1956 1-storey classroom	Medium	Non Structural Upgrade Required	
82	Coast Mountains	NECHAKO ELEMENTARY	1	1954 1-storey classroom	Medium	Non Structural Upgrade Required	Medium
82	Coast Mountains	NECHAKO ELEMENTARY	2	1954 2-storey classroom	Medium	Non Structural Upgrade Required	
82	Coast Mountains	NECHAKO ELEMENTARY	3	1954 gymnasium	Medium	Non Structural Upgrade Required	Low
82	Coast Mountains	NEW HAZELTON ELEMENTARY	1	Gymnasium Block	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	NEW HAZELTON ELEMENTARY	2	Classroom / Admin Block	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	PARKSIDE SECONDARY	1	1969 1-storey classroom	Medium	Inactive	Medium
82	Coast Mountains	PARKSIDE SECONDARY	2	1969 gymnasium	Medium	Inactive	
82	Coast Mountains	R.E.M. LEE THEATRE (CALEDONIA SR. 5	1	1973 Auditorium	Low	Meets Structural Life Safety Requirements	Low
82	Coast Mountains	ROY WILCOX ELEMENTARY	1	1957 2-storey classroom	Medium	Non Structural Upgrade Required	Medium
82	Coast Mountains	ROY WILCOX ELEMENTARY	2	1957 Gymnasium	Low	Meets Structural Life Safety Requirements	
82	Coast Mountains	THORNHILL ELEMENTARY	1	1-storey classroom	Medium	Non Structural Upgrade Required	Medium
82	Coast Mountains	THORNHILL JR SECONDARY	1	1972 1-storey classroom	Medium	Inactive	Medium
82	Coast Mountains	THORNHILL JR SECONDARY	2	1972 Gymnasium	Medium	Inactive	
82	Coast Mountains	THORNHILL PRIMARY	1	1967 1-storey classroom	Medium	Non Structural Upgrade Required	Medium
82	Coast Mountains	THORNHILL PRIMARY	2	1974 1-storey classroom	Medium	Non Structural Upgrade Required	
82	Coast Mountains	THORNHILL PRIMARY	3	1974 Gymnasium	Medium	Non Structural Upgrade Required	
82	Coast Mountains	UPLANDS ELEMENTARY	1	1957 1-storey classroom	Medium	Non Structural Upgrade Required	Medium
82	Coast Mountains	UPLANDS ELEMENTARY	2	1970 1-storey classroom	Medium	Non Structural Upgrade Required	
82	Coast Mountains	UPLANDS ELEMENTARY	3	1959 Gymnasium	Medium	Non Structural Upgrade Required	
82	Coast Mountains	UPLANDS ELEMENTARY	4	1991 1-storey classroom	Low	Meets Structural Life Safety Requirements	
84	Vancouver Island West	CAPTAIN MEARES ELEM-SEC	1	Sec. Classrooms/Shops/Administration	Medium	Non Structural Upgrade Required	Medium
84	Vancouver Island West	CAPTAIN MEARES ELEM-SEC	2	Elem. Classrooms/Kindergarten	Low	Meets Structural Life Safety Requirements	
84	Vancouver Island West	CAPTAIN MEARES ELEM-SEC	3	Gymnasium/Library/Music	Medium	Non Structural Upgrade Required	
84	Vancouver Island West	GOLD RIVER SECONDARY	1	Classrooms/Shops	N/A	Completed	N/A
84	Vancouver Island West	GOLD RIVER SECONDARY	2	Gymnasium	N/A	Completed	
84	Vancouver Island West	KYUQUOT ELEM-SEC	1	Classrooms/Admin.	Low	Meets Structural Life Safety Requirements	Medium
84	Vancouver Island West	KYUQUOT ELEM-SEC	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
84	Vancouver Island West	KYUQUOT ELEM-SEC	3	Portables	Medium	Non Structural Upgrade Required	
84	Vancouver Island West	RAY WATKINS ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
84	Vancouver Island West	RAY WATKINS ELEMENTARY	2	Classroom/Administration	Low	Meets Structural Life Safety Requirements	
84	Vancouver Island West	ZEBALLOS ELEM-SEC	1	Classrooms/Admin	N/A	Completed	N/A
84	Vancouver Island West	ZEBALLOS ELEM-SEC	2	Gymnasium/Art Room	N/A	Completed	
84	Vancouver Island West	ZEBALLOS ELEM-SEC	3	Portables	N/A	Completed	
85	Vancouver Island North	A J ELLIOTT ELEMENTARY	1	Central Classrooms	Low	Meets Structural Life Safety Requirements	Low
85	Vancouver Island North	A J ELLIOTT ELEMENTARY	2	North Addition	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	A J ELLIOTT ELEMENTARY	3	Gymnasium	Low	Meets Structural Life Safety Requirements	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
85	Vancouver Island North	ALERT BAY ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	ALERT BAY ELEMENTARY	2	North Classrooms	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	ALERT BAY ELEMENTARY	3	South Classrooms	Medium	Non Structural Upgrade Required	Medium
85	Vancouver Island North	ALERT BAY ELEMENTARY	4	Primary Classrooms	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	ALERT BAY ELEMENTARY	5	Primary Gymnasium	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	CHESLAKEES ELEMENTARY	1	GYMNASIUM	Medium	Non Structural Upgrade Required	Medium
85	Vancouver Island North	CHESLAKEES ELEMENTARY	2	CLASSROOM	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	COAL HARBOUR ELEMENTARY	1	Classrooms	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	COAL HARBOUR ELEMENTARY	2	Gymnasium	Medium	Non Structural Upgrade Required	Medium
85	Vancouver Island North	COAL HARBOUR ELEMENTARY	3	Link	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	EAGLE VIEW ELEMENTARY	1	MAIN BUILDING - EAST CLASSROOM	N/A	Completed	
85	Vancouver Island North	EAGLE VIEW ELEMENTARY	2	GYMNASIUM/ACTIVITY ROOM	N/A	Completed	N/A
85	Vancouver Island North	EAGLE VIEW ELEMENTARY	3	WEST CLASSROOMS	N/A	Completed	
85	Vancouver Island North	ECHO BAY ELEMENTARY	1	School and Teacherage	Medium	Inactive	Medium
85	Vancouver Island North	FORT RUPERT ELEMENTARY	1	East Classrooms	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	FORT RUPERT ELEMENTARY	2	West Classrooms	Medium	Non Structural Upgrade Required	Medium
85	Vancouver Island North	FORT RUPERT ELEMENTARY	3	Gymnasium	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	NORTH ISLAND SECONDARY	1	MUSIC/DRAMA	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	NORTH ISLAND SECONDARY	2	GYMNASIUM CHANGE ROOMS	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	NORTH ISLAND SECONDARY	3	GYMNASIUM	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	NORTH ISLAND SECONDARY	4	SHOPS	Low	Meets Structural Life Safety Requirements	Medium
85	Vancouver Island North	NORTH ISLAND SECONDARY	5	SOUTH CLASSROOMS	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	NORTH ISLAND SECONDARY	6	WEST CLASSROOMS	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	NORTH ISLAND SECONDARY	7	EAST CLASSROOMS	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	PORT HARDY SECONDARY	1	SHOPS/CLASSROOMS	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	PORT HARDY SECONDARY	2	GYMNASIUM	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	PORT HARDY SECONDARY	3	SE. CLASSROOM ADD.	Low	Meets Structural Life Safety Requirements	Low
85	Vancouver Island North	PORT HARDY SECONDARY	4	SW. MPR + DRAMA	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	PORT HARDY SECONDARY	5	ART ROOM ADD.	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	PORT HARDY SECONDARY	6	NW CLASSROOM ADD.	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	QUATSINO ELEMENTARY	1	Main Building	Low	Meets Structural Life Safety Requirements	Low
85	Vancouver Island North	ROBERT SCOTT ELEMENTARY	1	GYMNASIUM	Medium	Inactive	Medium
85	Vancouver Island North	ROBERT SCOTT ELEMENTARY	2	CLASSROOMS	Medium	Inactive	
85	Vancouver Island North	SEA VIEW ELEM-JR SEC	1	Intermediate Classrooms	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	SEA VIEW ELEM-JR SEC	2	Covered Walkways	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	SEA VIEW ELEM-JR SEC	3	Gymnasium	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	SEA VIEW ELEM-JR SEC	4	Covered Play Area	Medium	Non Structural Upgrade Required	Medium
85	Vancouver Island North	SEA VIEW ELEM-JR SEC	5	Primary Building	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	SEA VIEW ELEM-JR SEC	6	Jr. Secondary Classrooms	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	SEA VIEW ELEM-JR SEC	7	Shop	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	SUNSET ELEMENTARY	1	GYMNASIUM	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	SUNSET ELEMENTARY	2	CENTRAL CLASSROOM BLOCK	Medium	Non Structural Upgrade Required	Medium
85	Vancouver Island North	SUNSET ELEMENTARY	3	NORTH CLASSROOM BLOCK	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	WOSS LAKE ELEMENTARY	1	Gymnasium	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	WOSS LAKE ELEMENTARY	2	West Classrooms	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	WOSS LAKE ELEMENTARY	3	East Classrooms	Medium	Non Structural Upgrade Required	Medium
85	Vancouver Island North	WOSS LAKE ELEMENTARY	4	Link	Low	Meets Structural Life Safety Requirements	
85	Vancouver Island North	WOSS LAKE ELEMENTARY	5	Covered Play Area	Medium	Non Structural Upgrade Required	
85	Vancouver Island North	WOSS LAKE ELEMENTARY	6	West Classroom Addition	Low	Meets Structural Life Safety Requirements	

SEISMIC STRUCTURAL RISK RATINGS BY BLOCK (April 2016)

SD	SD Name	Facility Name	Block #	Block Name	Current Risk	Status	School Risk
87	Stikine	ATLIN SCHOOL	1	1981 Single-Storey Classroom	Medium	Non Structural Upgrade Required	Medium
87	Stikine	ATLIN SCHOOL	2	1981 Gymnasium	Low	Meets Structural Life Safety Requirements	
87	Stikine	DEASE LAKE	1	Classroom/ Admin Block	Low	Meets Structural Life Safety Requirements	Low
87	Stikine	DEASE LAKE	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
87	Stikine	DEASE LAKE	3	1991 Addition	Low	Meets Structural Life Safety Requirements	
87	Stikine	TAHLTAN	1	Classroom/ Admin Block	Low	Meets Structural Life Safety Requirements	Low
87	Stikine	TAHLTAN	2	Gymnasium	Low	Meets Structural Life Safety Requirements	
92	Nisga'a	LAKALZAP ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
92	Nisga'a	LAKALZAP ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	Low
92	Nisga'a	NATHAN BARTON ELEMENTARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
92	Nisga'a	NATHAN BARTON ELEMENTARY	2	Classrooms	Low	Meets Structural Life Safety Requirements	
92	Nisga'a	NISGA'A ELEM/SECONDARY	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Medium
92	Nisga'a	NISGA'A ELEM/SECONDARY	2	Primary Classroom	Low	Meets Structural Life Safety Requirements	
92	Nisga'a	NISGA'A ELEM/SECONDARY	3	Classroom	Medium	Non Structural Upgrade Required	
93	Conseil Scolaire Francop	ECOLE ANNE HEBERT	1	1964 1-Storey Classrooms (Original)	High 3	Structural Upgrade Required	High 3
93	Conseil Scolaire Francop	ECOLE ANNE HEBERT	2	1989 1-Storey Extension	Low	Meets Structural Life Safety Requirements	
93	Conseil Scolaire Francop	ECOLE DE BOIS-JOLI	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
93	Conseil Scolaire Francop	ECOLE DE BOIS-JOLI	2	Classrooms	Medium	Non Structural Upgrade Required	
93	Conseil Scolaire Francop	ECOLE COTE DU SOLIEL	1	1948 Gymnasium	High 3	Proceeding to Construction	High 1
93	Conseil Scolaire Francop	ECOLE COTE DU SOLIEL	2	1948 1-Storey Classrooms	High 2	Proceeding to Construction	
93	Conseil Scolaire Francop	ECOLE COTE DU SOLIEL	3	2-Storey Classrooms	Medium	Proceeding to Construction	
93	Conseil Scolaire Francop	ECOLE COTE DU SOLIEL	4	Activity Room/Band	Low	Proceeding to Construction	
93	Conseil Scolaire Francop	ECOLE COTE DU SOLIEL	5	1-Storey Masonry Classrooms	High 1	Proceeding to Construction	
93	Conseil Scolaire Francop	ECOLE COTE DU SOLIEL	6	1-Storey Former Shops	Low	Proceeding to Construction	
93	Conseil Scolaire Francop	ECOLE DES DEUX RIVES	1	Gymnasium	Low	Meets Structural Life Safety Requirements	Low
93	Conseil Scolaire Francop	ECOLE DES DEUX RIVES	2	Classroom (North)	Low	Meets Structural Life Safety Requirements	
93	Conseil Scolaire Francop	ECOLE DES DEUX RIVES	3	Classroom (South)	Low	Meets Structural Life Safety Requirements	
93	Conseil Scolaire Francop	ECOLE DES PIONNIERS	1	1958 2-Storey Classrooms	High 1	Proceeding to Construction	High 1
93	Conseil Scolaire Francop	ECOLE DES PIONNIERS	2	1958 Gymnasium	Low	Proceeding to Construction	
93	Conseil Scolaire Francop	ECOLE DES PIONNIERS	3	1967 Shops Wing	High 1	Proceeding to Construction	
93	Conseil Scolaire Francop	ECOLE DES PIONNIERS	4	1958 1-Storey East Wing	Medium	Proceeding to Construction	
93	Conseil Scolaire Francop	ECOLE OCEAN (Princess Anne Elementar	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
93	Conseil Scolaire Francop	ECOLE OCEAN (Princess Anne Elementar	2	Classrooms	Medium	Non Structural Upgrade Required	
93	Conseil Scolaire Francop	ECOLE ROSE-DES-VENTS	1	Classroom - West	N/A	Completed	N/A
93	Conseil Scolaire Francop	ECOLE ROSE-DES-VENTS	2	Classroom - North/West	N/A	Completed	
93	Conseil Scolaire Francop	ECOLE ROSE-DES-VENTS	3	Classroom - East	N/A	Completed	
93	Conseil Scolaire Francop	ECOLE ROSE-DES-VENTS	4	Gymnasium	N/A	Completed	
93	Conseil Scolaire Francop	ECOLE ROSE-DES-VENTS	5	Classroom - North/East	N/A	Completed	
93	Conseil Scolaire Francop	LA VERENDRYE ELEMENTARY	1	Classroom	Medium	Non Structural Upgrade Required	Medium
93	Conseil Scolaire Francop	LA VERENDRYE ELEMENTARY	2	Portables	Low	Meets Structural Life Safety Requirements	
93	Conseil Scolaire Francop	LES VOYAGEURS	1	Gymnasium	Medium	Non Structural Upgrade Required	Medium
93	Conseil Scolaire Francop	LES VOYAGEURS	2	Classrooms	Medium	Non Structural Upgrade Required	