

LOG OF TEST HOLE

TEST HOLE NO.
MW10-17

LOCATION: See Drawing No. 19-4752-3-103

CLIENT: TRI-EAGLE DEVELOPMENT CORP.
PROJECT: 1590 Cedar Hill X Road

TOP OF HOLE ELEV:

METHOD: Solid Stem Auger

DATE: 6-Dec-2010

DRILLING CO.: Drillwell

FILE NO.: 19-4752-3

INSPECTOR: JH



DEPTH (m)	DCPT PENETRATION (blows/300 mm)	SPT PENETRATION (blows/300 mm)	WATER CONTENT (%)	WATER LEVEL	SAMPLES	GRAIN SIZE (%)	SOIL HEADSPACE READING (ppm)	DEPTH (m)
			○ Disturbed ● Undisturbed	▼ Plastic Limit Liquid Limit	■ Disturbed □ Undisturbed ⊗ No Recovery	▲ Passing #200 sieve △ Passing #4 sieve	■ GASTECH reading ⊗ PID reading	

LOG OF TEST HOLE (NO EST.) RRS 19-4752-3 CEDAR HILL X ROAD DEVELOPMENT.GPJ THURBER BC.GDT 29/3/11- THURBER VICTORIA DECEMBER 2010.GLB

