



CLIENT: **Husky Oil Operations Ltd.**
 PROJECT: **Confirmation of Remediation**
10420 8th Strret
Dawson Creek, B.C.

MONITORING WELL LOG

MONITORING WELL NO: **BH402**
 SURFACE ELEVATION:

SLR JOB NO: 211.05717.00009

DEPTH (m)	SAMPLE TYPE	SAMPLE ID	SOIL TYPE	SOIL DESCRIPTION	FIELD TEST DATA					WELL COMPLETION	WATER LEVEL	WELL COMPLETION NOTES	DEPTH (m)
					ORGANIC VAPOUR LEVEL (ppmv)								
					1	10	100	1000	10000				
0.0				Ground Surface									
0.0				SAND Loose, brown, dry									protective monument, stick-up, jplug
0.0				CLAY Some silt, medium-plasticity, occasional rust inclusions, soft, dark-grey, moist									cement
0.5		RMH27											
0.7		RMH28		@ 0.5 m to 0.7 m - organic matter, soft, black, moist									
1.6		RMH29		@ 1.6 m - fine sand inclusions, firm, dark brown									
2.5		RMH30		@ 2.5 m to 4.3 m - mottled, light brown									
3.5		RMH31		@ 3.5 m to 13.5 m - trace gravel									(September 17, 2009)
4.4		RMH32		@ 4.4 m to 5.4 m - silty, mottled, soft									bentonite seal
6.0		RMH36		@ 6.0 m to 6.8 m - silty, mottled, soft									
6.8		RMH37		@ 6.8 m to 13.5 m - hard									
8.0		RMH37											

COPY REPORT PR - 400-SERIES BHS.GPJ SLR_CAN V5.1.GDT 2/7/11

DRILLING METHOD: Solid Stem Auger Drilling

Notes: AUGER SAMPLE

DRILLING DATE: August 19, 2009 LOGGED BY: RMH

