



LEVELTON Levelton Consultants

Corporation of the District of Central Saanich, Fire Department
1498 & 1516 Keating X Rd., Victoria, BC

BH10-05

Pg 1 of 1

Project No: V110-0886-00

Depth (ft) (m)	Description	Symbol	Depth (m)	Sample		Well and Backfill Details	Headspace Vapour Concentration			Laboratory Analysis /Comments
				Number/ ID	Type		▲ (ppm.) ▲	10	100	
0.2	Compact, dark brown, silty, ORGANICS , trace sand and gravel, roots, dry.		0.2	05-1	●		50			
2	Stiff, mottled yellow/brown, SILT , trace sand and gravel, dry.			05-2	●		50			
4				05-3	●					
6				05-4	●					
8	- becomes very stiff at 2.1m									
10										
12										
14	- becomes stiff to firm, grey/blue at 4.0m depth.			05-5	●					
16			4.9							
18	Compact, grey, gravelly, SAND , trace silt, trace cobble, moist to wet.			05-6	●			100		
20			6.1							
22	Bottom of hole at 6.1 metres									
24										

HAZMAT V110-0886 BH.GPJ LEVELTON DATA TEMPLATE.GDT 6/7/10

Sample Symbols	Backfill Symbols	Soil Symbols	Notes	Logged By	Kelly
● Grab Sample	Filter Sand	Organic SILT (Topsoil)		Drilled/ Excavated By	RV
	Bentonite	SILT		Date Drilled or Excavated	5/20/2010
	Solid Pipe	Gravelly SAND		Elevation (grade)	
	Slotted Pipe			Water Level Recorded On	5/20/2010
	Slough/Cuttings			Drill Method	Solid Stem Auger
	Concrete			This log is for environmental purposes only. This log is the sole property of Levelton Consultants Ltd. and cannot be used or duplicated in anyway without express written permission.	