SLR

SLR JOB NO: 205.03133.02

CLIENT: Three Point Properties
PROJECT: Bamberton DSI
DL 73 & Block B of Lot 30-G
1455 Trowsse Road

BOREHOLE LOG

BOREHOLE NO: BHF-05 / MW06-02
SURFACE ELEVATION: 3.17 m

DEPTH (m)	SAMPLE TYPE	SAMPLE ID	SPT COUNT	SOIL TYPE	SOIL DESCRIPTION	FIELD TEST DATA: ORGANIC VAPOUR LEVEL (ppmv) 1 10 100 1000 10000	WELL COMPLETION	WATER LEVEL	WELL COMPLETION NOTES	ELEVATION (m)
					concrete concrete paved surface				plug, cement seal and roadbox	3
		BHF05-A			**fill** medium sand and round gravel between cobble, brown, moist				sand	
									bentonite seal	
1.0		BHF05-B							sand and blast rock	2
2.0									bentonite	1
		BHF05-C								
3.0									silica sand	0
									silica sand	
4.0		BHF05-D						▼	GW = 4.09 mbg (07/18/06)	-1
5.0		BHF05-E			**sand and gravel** sand and rounded gravel with pockets of silt, brown, wet				50 mm Ø10 slot PVC pipe	-2
		BHF05-F			**sand and silt** gravelly coarse sand and silt with shell fragments, grey, wet					
6.0		BHF05-G			**silt and gravel** silt and angular gravel with shell fragments, brown, wet					-3
					End of borehole at 6.7 m Groundwater Information: Depth to groundwater from TOP = 4.05 m (07/18/06) bedrock refusal				endplug Monitoring well completed in hollow stem auger	

DRILLING METHOD: Solid Stem Auger Drilling

Notes: AUGER SAMPLE

DRILL DATE: June 12, 2006 LOGGED BY: RH

Sheet 1 of 1

COPY REPORT 205.03133 BAMBERTON 06 MW AND TP.GPJ SLR_CAN V5.1.GDT 7/22/08