

Project No: 2689.02.01

Client: Rimrock Development Ltd.

Monitoring Well No: MW1

Monitoring Well Location: Centre of east property boundary

Reference Point:

Datum:

Monitoring Well Condition:

Elevation:

Depth/Elev.	Description	Symbol	Depth	Installation Sketch	Well Details	Notes
0	Ground Surface		0			
-1.494	FILL 0.0-1.5m: sand and silt, some concrete bricks, no odour or staining		1		0.3-1.2m: bentonite holeplug	
-2.103	FILL 1.5-2.1m: hog fuel, black, natural odour, fill, no sheen		2			
-2.987	Sandy SILT 2.1-3.0m: grey sandy SILT, some gravel, very faint odour		3			
-4.877	Sandy SILT 3.0-4.9m: sandy SILT, till, some gravel, no odour or staining, moist to wet, grey, compact, 5cm thick sand seam at 3.0m, medium grained		4			
	End of Borehole		5			
			6			

Depth to W.L.

Hole Drilled to: 4.9m

Open to: 4.6m

Depth Casing/Auger 4.9m



Date: April 7, 1997

Logged By: SP

Sheet: 1 of 1