



**LEVELTON**  
Engineering Solutions

# BOREHOLE LOG

Borehole Number: BH 3

Client: Sharon Peers

Levelton Project ID: 1804-0756-02

Project: DSI

Site Location: 31322 Caswell Avenue, Mission, BC

Depth (m)	Description	Symbol	Depth/Elev. (m)	Install Detail	COMMENTS
0	Ground Surface		0.00		
0.30	<b>LOAM</b> Red-brown, organic-like odour		0.30		
1.52	<b>SAND</b> -Coarse, some silt, light grey-brown		1.52		
2.13	-Coarse, gravelly, grey		2.13		
3.05	-Coarse, some silt, grey, moist		3.05		
3.66	some cobbles, light brown-grey		3.66		
4.27	silty, some clay, some gravel, dense, grey		4.27		
12'-13'	boulder encountered at 12'-13'				
6.10	<b>ROCK</b> boulder and granite fragments		6.10		
7.62	<b>SAND</b> gravelly, trace silt, trace clay, moist, grey		7.62		
25	End of Hole				Monitoring well completed as a standpipe.

Logged By: L. Oswald

Drilled by: Beck

Datum:

Date Drilled: 1 November 2005

Water Level Recorded on: 2 May 2006

Sheet No: 1 of 1