

Terrain stability, terrain hazard, and surficial mapping studies conducted in northeast British Columbia

- Alexander, S. (1998): Preliminary geotechnical report - Canyon Road slides; *British Columbia Ministry of Transportation*, File M44-16-31.
- Anonymous (1973): Inspection of the Attachie Landslide; unpublished company report, *Thurber*.
- Anonymous (1978): Site C Reservoir, shoreline stability assessment; unpublished company report, *Thurber*, File 15-2-62, 75 pages.
- Anonymous (1981): A report on field inspection of overburden landslides, Site C Reservoir; unpublished company report, *Thurber*, File 15-2-169-A.
- BC Hydro, (1990): Peace River - Site C Project, reservoir slopes, Task CL70; *BC Hydro*, File H2243, 17 pages.
- BC MoT (1968): Report on slide activity, slope stability factors and remedial measures at the Beaton River slide; *British Columbia Ministry of Transportation*.
- Bednarski, J. (in press): Surficial geology, Estet Lake, British Columbia (94P/11); *Geological Survey of Canada*, Open File 5506, 1:50 000 scale.
- Bednarski, J. (in press): Surficial geology, Kimea Creek, British Columbia (94P/10); *Geological Survey of Canada*, Open File 5505, 1:50 000 scale.
- Bednarski, J. (in press): Surficial geology, Thinahtea Lake, British Columbia (94P/09); *Geological Survey of Canada*, Open File 5479, 1:50 000 scale.
- Bednarski, J. (in press): Surficial geology, June Lake, British Columbia (94P/16); *Geological Survey of Canada*, Open File 5480, 1:50 000 scale.
- Bednarski, J. (in press): Surficial geology, Pesh Creek, British Columbia (94P/08); *Geological Survey of Canada*, Open File 5481, 1:50 000 scale.
- Bednarski, J.M. (1999): Preliminary report on mapping surficial geology of Trutch map area, northeastern British Columbia; *in Current Research, Geological Survey of Canada*, 1999-A/B, pages 35-43.
- Bednarski, J.M. (2000): Surficial geology Trutch, British Columbia; *Geological Survey of Canada*, Open File 3885, 1: 250,000 scale.
- Bednarski, J.M. (2001): Drift composition and surficial geology of the Trutch map area (94G), Northeastern British Columbia; *Geological Survey of Canada*, Open File 3815, 25 pages.
- Bednarski, J.M. (2005a): Surficial geology, Estsine Lake, British Columbia (94P/13); *Geological Survey of Canada*, Open File 4825, 1:50,000 scale.
- Bednarski, J.M. (2005b): Surficial geology, Gote Creek, British Columbia (94P/12); *Geological Survey of Canada*, Open File 4846, 1:50,000 scale.
- Bidwell, A.K. (1999): Engineering geology of the Fort St. John area; unpublished M.Eng. thesis, *University of Alberta*, 101 pages.
- Bobrowsky, P.T., and Rutter, N. (1990): Geological evidence for an ice-free corridor in northeastern British Columbia, Canada; *Current Research in the Pleistocene*, Issue 7, pages 133-135.

- Bobrowsky, P.T. and Smith, C.P. (1992a): Quaternary studies in the Peace River District 1990: stratigraphy, mass movements and glaciation limits (94P); *in Geological Fieldwork 1991, B.C. Ministry of Energy, Mines and Petroleum Resources*, Paper 1991-1, pages 363-374.
- Bobrowsky, P.T. and Smith, C.P. (1992b): Quaternary studies in the Peace River District 1990: stratigraphy, mass movements and glaciation limits (94P); *in Geological Fieldwork 1991, B.C. Ministry of Energy, Mines and Petroleum Resources*, Paper 1992-1, pages 363-374.
- Bobrowsky, P.T., Levson, V., Liverman, D.G.E. and Rutter, N.W. (1987): Quaternary geology of northwestern Alberta and northeastern British Columbia; *International Union for Quaternary Research*, Fieldtrip Guidebook A24, 12th International Congress, Ottawa, ON, 62 pages.
- Bobrowsky P.T., Catto, N. and Levson, V. (1991): Reconnaissance Quaternary geological investigations in Peace River District, British Columbia; *in Geological Fieldwork 1990, B.C. Ministry of Energy, Mines and Petroleum Resources*, Paper 1991-1, pages 345-358.
- Bobrowsky, P.T., Evans, S.G., Clague, J.J., VanDine, D.F. and Hutchinson, J.N. (1997): GIS landslide hazard mapping in south central British Columbia, Canada; *in Engineering Geology and the Environment*; IAEG Congress, June 23-27, 1997, Athens Greece.
- Bostock, H.S. (1948): Physiography of the Canadian Cordillera with special reference to the area north of the 55th parallel; *Geological Survey of Canada*, Memoir 247, 106 pages.
- Bruce, I. (2002): Stoddard Creek Crossing replacement - geotechnical design report; unpublished company report, *BGC Engineering*, File 0272-003-01, 28 pages.
- Calvert, H.T., Dyke, L.D., Sladen, W.E. and Raymond, E.L. (2004): Electrical resistivity imaging for investigating slope stability, Fort St. John, British Columbia (94A/02); 2004 Joint Assembly, Eos, *Transactions of the American Geophysical Union*, Volume 85, no 17, page NS43A-02.
- Carabetta, D.G. and Leighton, J.C. (1984): Elleh Creek Landslide on B.C. Railway's Fort Nelson Subdivision; 37th Canadian Geotechnical Conference, September 17, 1984, Toronto, Canada, pages 65-73.
- Catto, N.R., Liverman, D.G.E., Bobrowsky, P.T. and Rutter, N. (1996): Laurentide, Cordilleran, and Montane glaciation in the western Peace River - Grande Prairie Region, Alberta and British Columbia, Canada; *Quaternary International*, Volume 32, pages 21-32.
- Cavers, D.S. and McClarty, E.A. (1998): Use of surface pipeline segments to mitigate slide problems on the Fort Nelson natural gas mainline; 1998 International Pipeline Conference, ASME, June 7-11, 1998, Calgary, Alberta, pages 151-158.
- Cornish, L.J. and Moore, D.P. (1985): Dam foundation investigations for a project on soft shale; *BC Hydro*, pages 171-178.
- Coulter, T.S. (1973): Report on the stability of the south bank of the Peace River near Halfway River; *British Columbia Ministry of Transportation*, File L4-MG8-336.
- Coulter, T.S. (1988): Beaton River crossing, detailed geotechnical investigation; unpublished company report, *Thurber*, File 17-604-40.
- Cruden, D.M., Keegan, T.R., Thompson, S. and McKlunge, J.E. (1991): The landslide dam on the Saddle River near Rycroft, Alberta; 44th Canadian Geotechnical Conference, October 1, 1991, Calgary, Canada.

- Cruden, D.M., Keegan, T.R. and Thompson, S. (1993): The landslide dam on the Saddle River near Rycroft, Alberta; *Canadian Geotechnical Journal*, Volume 30, pages 1003-1015.
- Cruden, D.M., Lu, Z.Y., Thompson, S. and Weimer, N. (1995): Alberta's largest historic landslide; 48th Canadian Geotechnical Conference, September 25-27, 1995, Vancouver, BC, pages 893-900.
- Cruden, D.M., Lu, Z.Y. and Thomson, S. (1997): The 1939 Montagneuse River landslide, Alberta; *Canadian Geotechnical Journal*, Volume 34, pages 799-810.
- Cruden, D.M., Ruel, M. and Thompson, S. (1990): Landslides along the Peace River, Alberta; 43rd Canadian Geotechnical Conference, Volume 1, pages 61-67.
- Evans, G. (2003): Characterising landslide risk in Canada; Geohazards 2003, June 9-10, 2003, Edmonton, AB.
- Evans, S.G., Hu, X.Q. and Eneqren, E.G. (1996): The 1973 Attachie Slide, Peace River Valley, near Fort St. John, British Columbia, Canada: a landslide with a high-velocity flowslide component in Pleistocene sediments; 7th International Symposium of Landslides, Trondheim, Norway, Volume 2, pages 715-720.
- Fletcher, L., Hungr, O. and Evans, S.G. (2002): Contrasting failure behaviour of two large landslides in clay and silt; *Canadian Geotechnical Journal*, Volume 39, pages 46-62.
- Fulton, R.J. (1995): Surficial materials of Canada; *Geological Survey of Canada*, Map 1880A, 1:5,000,000 scale.
- Geertsema, M. (2005): Catastrophic geomorphic hazards in northern British Columbia; unpublished Ph.D. thesis, *Universiteit Utrecht*.
- Geertsema, M. (2006): Hydrogeomorphic hazards in northern British Columbia; *Universiteit Utrecht*, NGS 341, 185 pages.
- Geertsema, M. and Clague, J.J. (2001): Flowslides and drowned, buried forests at Halden Creek, northeastern British Columbia; Canadian Quaternary Association, Annual Meeting 2001, August 20-24, 2001 Whitehorse, YT.
- Geertsema, M. and Schwab, J.W. (2004): Challenges with terrain stability mapping in northern British Columbia - the special case of large complex landslides; Proceedings, 57th Canadian Geotechnical Conference, October 24-27, 2004, Quebec City, QC, pages 11-18.
- Geertsema, M. and Clague, J.J. (2005): 1000-year record of landslide dams at Halden Creek, northeastern British Columbia; Joint Meeting of the Geological Association of Canada, the Mineralogical Association of Canada, the Canadian Society of Petroleum Geologists and the Canadian Society of Soil Sciences, May 15-18, 2005, Halifax, NS.
- Geertsema, M. and Clague, J.J. (2006): 1000-year record of landslide dams at Halden Creek, northeastern British Columbia; Geophysical Research Abstracts, European Geosciences Union General Assembly 2006, April 02-07, 2006, Vienna, Austria, Issue 8, 916 pages.
- Geertsema, M., Clague, J.J., Schwab, J.W. and Evans, S.G. (2006a): An overview of recent large catastrophic landslides in northern British Columbia, Canada; *Engineering Geology*, Volume 83, pages 120-143.
- Geertsema, M., Hungr, O., Schwab, J.W. and Evans, S.G. (2006b): A large rockslide-debris avalanche in cohesive soil at Pink Mountain, northeastern British Columbia, Canada; *Engineering Geology*, Volume 83, pages 64-75.

- Hanna, A. and Little, T.E. (1992): An estimate of rebound potential of the Shaftesbury Shale at a damsite in British Columbia; 38th Canadian Geotechnical Conference, Edmonton, AB, pages 375-392.
- Harbricht, T.N. (1988): Stability investigation - Cache Creek Hill Slide; *British Columbia Ministry of Transportation*, File M44-16-02.
- Harbricht, T.N. (1989): Report on stability investigation for 0.9 km slide; *British Columbia Ministry of Transportation*, File M44-16-40.
- Harbricht, T.N. (1990a): Report on stability investigation, Montney Hill Slide; *British Columbia Ministry of Transportation*, File M44-16-28.
- Harbricht, T.N. (1990b): Stability investigation for Peace View Hill Slide; *British Columbia Ministry of Transportation*.
- Harbricht, T.N. (1991): Report on stability investigation for Upper Montney Hill Slide Area, North Peace District; *British Columbia Ministry of Transportation*, File M44-16-33.
- Hartman, G. (2005): unpublished MSc thesis, *Simon Fraser University*.
- Holland, S.S. (1964): Landforms of British Columbia, a physiographic outline; *British Columbia Department of Mines and Petroleum Resources*, Bulletin 48, 138 pages.
- Hungr, O. (1981): Site C Reservoir, a review of the mobility of bedrock landslides; unpublished company report, *Thurber*, File 15-2-169, 27 pages.
- Hungr, O. (1982): Feasibility of stabilizing the Attachie Slide and adjacent areas, Site C Reservoir; unpublished company report, *Thurber*, File 15-2-169.
- Hungr, O., Gerath, R.F. and Morgan, G.C. (1984): Landslides of the Scatter River area, northeastern British Columbia; Proceedings, 37th Canadian Geotechnical Conference, September 17, 1984, Toronto, ON, pages 113-119.
- Imrie, A.S. (1991): Stress-induced response from both natural and construction-related processes in the deepening of the Peace River Valley, B.C.; *Canadian Geotechnical Journal*, Volume 28, pages 719-728.
- Jones, I. (1999): North Beatton River valley wall instabilities, geotechnical assessment; unpublished company report, *Geo-Engineering*.
- Leir, M., Mitchell, A.M. and Ramsay, S. (2004): Regional landslide susceptibility mapping for pipelines in British Columbia; sponsored by the *Canadian Geotechnical Society*, 57th Canadian Geotechnical conference, October 24-27, 2004, Quebec City, QC, pages 19-27.
- Lu, Z.Y., Cruden, D.M. and Thomson, S. (1998): Landslides and preglacial channels in the western Peace River lowland, Alberta; Proceedings, sponsored by the *Canadian Geotechnical Society*, 51st Canadian Geotechnical Conference, October 4-8, 1998, Edmonton, AB, pages 267-274.
- McKane, C.S. (2004): A review of the Cache Creek Landslide located at Mile 51 along the Peace River, near Fort St. John, BC, with implications for the BC Hydro Site C dam reservoir; unpublished B.Sc. thesis, *University of British Columbia*, 110 pages.
- Maber, C.T. and Stewart, P. (1976): The Peace River Hill Landslide; Proceedings, sponsored by the *Canadian Geotechnical Society*, 29th Canadian Geotechnical Conference, Vancouver, BC, pages 33-47.

- Mathews, W.H. (1978a): Surficial geology, Charlie Lake, British Columbia (94A); *Geological Survey of Canada*, Map 1460A, 1:250,000 scale.
- Mathews, W.H. (1978b): Quaternary stratigraphy and geomorphology of Charlie Lake (94A) map area, British Columbia; *Geological Survey of Canada*, Paper 76-20, 25 pages.
- Mathews, W.H. (1980a): Surficial geology, Dawson Creek, British Columbia (93P); *Geological Survey of Canada*, Map 1467A, 1:250,000 scale.
- Mathews, W.H. (1980b): Retreat of the last ice sheets in northeastern British Columbia and adjacent Alberta; *Geological Survey of Canada*, Bulletin 331, 22 pages.
- Miller, B.G.N. (2000): Two landslides and their dams, Peace River lowlands, Alberta; unpublished MSC thesis, *University of Alberta*, 149 pages.
- Miller, B.G.N. and Cruden, D.M. (2001): Landslides, landslide dams, and the geomorphology of tributaries in the Peace River lowland, Alberta; Proceedings, 54th Canadian Geotechnical Conference, September 4-9, 2001, Calgary, AB, pages 363-370.
- Miller, B.G.N. and Cruden, D.M. (2002): The Eureka River landslide and dam, Peace River lowlands, Alberta; *Canadian Geotechnical Journal*, Volume 39, pages 863-878.
- Pritchard, M. (2004): Triad bridge-geotechnical/geological and materials engineering services; unpublished company report, *BGC Engineering*, File 0272-009-01, 7 pages.
- Pritchard, M. (2005): Site inspection, Fort St. John CN subdivision, Mile 716.2 and 720.0; unpublished company report, *BGC Engineering*, File 0034-1943, 2 pages.
- Raymond, E.L., Evans, S.G. and Couture, R. (2002): Geological log of two boreholes at 2001 Cecil Lake Road landslide, near Fort St. John, British Columbia; *Geological Survey of Canada*, Open File 4294.
- Reimchen, T.H.F. (1980): Surficial geology, Dawson Creek, British Columbia (93P); *Geological Survey of Canada*, Map 1467A, 1:250,000 scale.
- Rutter, N.W. (1977): Multiple glaciations in the area of Williston Lake, British Columbia; *Geological Survey of Canada, Energy Mines and Resources Canada*, Bulletin 273, 31 pages.
- Sargent, D. W. and Cornish, L.J. (1985): Water susceptibility of Shaftsbury shale; 38th Canadian Geotechnical Conference, pages 1-10.
- Scott, J.S. (1989): Engineering geology and land use planning in the Prairie region of Canada; in Chapter 12 of Quaternary Geology of Canada and Greenland; Fulton, R J., Editor, *Geological Survey of Canada*, Geology of Canada, no 1, pages 713-723.
- Severin, J. (2004): Landslides in the Charlie Lake map sheet, Fort St. John; unpublished M.Sc. thesis, *University of British Columbia*, 207 pages.
- Sladen, W.E. and Dyke, L.D. (2004): Rainfall, pore water pressure, and slope movement in silts and shales near Fort St. John, British Columbia; 57th Canadian Geotechnical Conference, October 24-27, 2004, Quebec City, QC, pages 38-44.
- Stott, D.F. (1982): Lower Cretaceous Fort St. John Group and Upper Cretaceous Dunvegan Formation of the foothills and plains of Alberta, British Columbia, District of Mackenzie, and Yukon Territory; *Geological Survey of Canada*, Bulletin 328, 124 pages.

Thompson, R.I. (1975): Bedrock geology of the Beaton River (94H), Fontas River (94I), and Petitot River (96P) map areas, northeastern British Columbia; *Geological Survey of Canada*, Paper 75-11, 8 pages.

Thompson, R.I. (1986): Bedrock geology, Halfway River, British Columbia; *Geological Survey of Canada*, Map 1634A, 1:250,000 scale.

Thomson, S. and Morgenstern, N.R. (1979): Landslides in argillaceous rock, prairie Provinces, Canada; in *Rockslides and Avalanches*, *Elsevier Press*, Amsterdam, pages 515-540.

Zandbergen, J. (2000): Investigation of the slope failure at the Big Bam Ski Hill near Taylor, British Columbia, unpublished B.Sc. thesis, *University of British Columbia*, 66 pages.