

INCIDENT NAME

Big Bar Landslide

INCIDENT LOCATION

North of Big Bar on the Fraser River

August 16, 2019



UPDATES

- Rock scalers continue rock manipulation operations to create passageways and pools to allow for the natural movement of fish through the rocks.
- Crews are capturing fish through beach seining and fish wheel operations at three new sites, and then slinging the fish via helicopter in oxygenated buckets. One new helicopter has been added, and an additional seining crew is on site to enhance capture opportunities.
- Rock scaling crews are finalizing a trail to the site to expedite access to their worksite.
- A new camp near the incident is now operational, allowing crews to stay closer to the worksite and lengthen the operational period.



Rock scaling crews conducting rock manipulation to create pools and passageways (along the shoreline) for natural fish movement upstream.

