

JOB CRUSHING AVERAGE



Client: EAC Project#
 Pit Name: Malahat
 Material: Coarse Wash

Date	Sieve	16.0	12.5	9.5	4.75	2.36	1.18	0.600	0.300	0.150	0.075	Pan	Fracture
15-May-18	% Ret.		14.3	21.4	50.8	7.4	0.2	0.1	0.6	0.4	1.0	3.8	97%
	% Pass.		85.7	64.4	13.6	6.1	6.0	5.9	5.3	4.8	3.8		
16-May-18	% Ret.		16.9	21.1	45.5	9.2	1.2	0.1	1.0	0.2	1.0	3.7	98%
	% Pass.		83.1	62.0	16.5	7.3	6.1	6.0	5.0	4.8	3.7		
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												