

JOB CRUSHING AVERAGE



Client: EAC Project#
 Pit Name: Malahat
 Material: Coarse

Date	Sieve	16.0	12.5	9.5	4.75	2.36	1.18	0.600	0.300	0.150	0.075	Pan	Fracture
15-May-18	% Ret.		20.9	28.1	39.4	7.3	0.9	0.1	0.9	0.7	0.9	1.0	98%
	% Pass.		79.1	51.0	11.6	4.4	3.5	3.4	2.5	1.8	1.0		
16-May-18	% Ret.		16.2	26.4	44.7	8.7	1.2	0.1	1.0	0.5	0.6	0.6	98%
	% Pass.		83.8	57.5	12.7	4.0	2.8	2.8	1.8	1.3	0.6		
24-May-18	% Ret.		23.5	31.4	40.1	3.7	0.1	0.1	0.1	0.1	0.3	0.5	98%
	% Pass.		76.5	45.1	5.0	1.2	1.1	1.0	0.9	0.9	0.5		
25-May-18	% Ret.		17.5	28.7	44.1	6.1	0.8	0.4	0.4	0.3	0.7	0.8	97%
	% Pass.		82.5	53.7	9.6	3.5	2.7	2.2	1.8	1.4	0.8		
26-May-18	% Ret.		22.6	31.7	40.2	3.7	0.1	0.1	0.1	0.1	0.5	0.8	98%
	% Pass.		77.4	45.7	5.5	1.8	1.7	1.6	1.5	1.3	0.8		
28-May-18	% Ret.		18.2	31.5	44.1	4.5	0.2	0.1	0.1	0.2	0.4	0.6	97%
	% Pass.		81.8	50.2	6.1	1.6	1.4	1.3	1.2	1.0	0.6		
29-May-18	% Ret.		16.9	32.4	46.1	3.5	0.1	0.1	0.1	0.1	0.3	0.5	97%
	% Pass.		83.1	50.7	4.7	1.1	1.0	1.0	0.9	0.8	0.5		
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												
	% Ret.												
	% Pass.												