

Photos



Figure 1 View from the top of the face looking down at the pit floor where there is room for crusher setup and stockpiling (July 2022).



Figure 2 View of pit face, looking northeast (July 2022).



Figure 3 View of pit face, looking east. The dirtier material visible in the top right corner of this photo is the overburden requiring relocation (July 2022).



Figure 4 Photo taken from atop the overburden shown in Figure 3, facing west. (July 2022).