

MONITORING WELL LOG BH6-MW6

SHEET 1 of 1

PROJECT No: TR6030.01

DATE: 25/9/06

EASTING:

SITE: Victoria CO

LOGGED BY: Alan Lynch

NORTHING:

CLIENT: TELUS

CONTRACTOR: Uniwide Drilling Co.

ELEVATION:

| WATER LEVEL | WELL DEPTH (m) | WELL | LEGEND | DEPTH (m) | DESCRIPTION | ODOUR | FID (ppmv) | SAMPLE LABEL | DEPTH (m) |
|-------------|----------------|------|--------|-----------|---|-------|------------|--------------|-----------|
| | | | | 0 | Ground Surface | | | | |
| | | | | | Asphalt | | | | |
| | | | | | Fill | | | | |
| | | | | | Sand and gravel. | | | | |
| | | | | | No HC odours or stain. | | | | |
| | | | | | Fill | | | | |
| | | | | | Mixture of sand and brick. | | | | |
| | | | | | No HC odours or stain. | | | | |
| | | | | 1 | | | | | |
| | | | | 2 | | | | | |
| | | | | 3 | | | | | |
| | | | | | Concrete | | | | |
| | | | | | Brown Clay | | | | |
| | | | | | No HC odours or stain. | | | | |
| 3/11/07 | 3.635 | | | 4 | | | | | |
| | | | | | Grey Clay | | 160 | BH6-6 | 4.1 |
| | | | | | Firm and damp clay. | | | | |
| | | | | | Some wood, trace debris likely from concrete above. | | | | |
| | | | | | EOH @4.4m-bgs | | | | |
| | | | | 5 | | | | | |
| | | | | 6 | | | | | |

NOTES : Borehole was re-drilled from Stage 2 PSI and completed as a monitoring well during the DSL.

Descriptions are based on observations and hand testing of grab samples. Mechanical Tests were not performed unless otherwise stated.

First Occurrence of Groundwater
Static Groundwater Level : 3.635 m bgs

Reviewed By:

FILE