



NEXT
Environmental Inc.

Project No.: SAM020103.01

Project: Detailed Site Investigation

Location
of Borehole: southeast of storage garage

Site Address: 12160 - 88th Avenue, Surrey, BC

Borehole Log: BH109

Logged By: dk

Client: Sammy's Carpets & Hardwood Ltd.

SUBSURFACE PROFILE				SAMPLE			
Depth	Symbol	Description	Depth/Elev.	Well Completion Details	Number	Vapour (ppmv)	Lab Analysis
0		Ground Surface	0.00				
0		ASPHALT					
1		SAND FILL					
2		Brown SAND FILL, wet.					
3		strong hydrocarbons odours observed from 0.6m to 2.7m.			109-1	300 ppm	
4							
5					109-2	300 ppm	
6							
7		SAND FILL	2.13				
8		Brown/grey SAND FILL, wet.			109-3/5	250 ppm	B,VPHs,MTBE, L/H/Ps, m
9			2.74				
10		SILT					
11		Grey/brown Sandy SILT, moist to wet.		109-4	100 ppm	B,VPHs,MTBE, L/H/Ps, m	
12							
13							
14							
15							
16							
17							
18							
19							
20			6.10				

Drilled By: Beck Drilling & Environmental Services Ltd.

Drill Method: Solid Stem Auger

Drill Date: June 7th, 2006

Depth to Water
(below top) & Date: 1.4m June 9th, 2006

Top of Pipe (top)
Well Elevation: 99.91

Surface Grade Elevation: 100.03

Groundwater
Analysis: BTEXS/VPHs/MTBE/L/H/Ps/metals

Sheet: 1 of 1