

Borehole No.: 3157-BH9
 Location: See Location Plan
 Date Drilled: April 20, 2007
 Supervision: M. Thatcher

Drilling Method: Track-mounted Drill Rig

Sampling Method: n/a

depth (m)	Description	sample no. recovery Headspace	monitoring well details	Remarks
0	Dark brown, moist, sand and silt FILL			Bentonite
	Light brown, mottled, moist, clayey SILT			Blank PVC
1				
2				PVC Screen
				Filter Sand
3	Moist, brown./grey, stiff CLAY; some silt; trace sand and gravel			▼ GWL Apr 23, 2007
4				
5				
6				
7	Grey, wet very soft CLAY			
8				
9	End of Borehole Refusal @ 9.0 m			

Project No.: 071-03157
 Project Location: 3811 Rowland Avenue
 Project: Detailed Site Investigation

Logged by: MT

