



Levelton Consultants Ltd.
301-19292 60th Ave
Surrey, BC, V3S 3M2

Borehole

08-MW2

Project No.	FV08-0477-01
Client	Ruth and Naomi's Mission
Site Location	9302 Fletcher St, Chilliwack, BC

Backfill Symbols	Filler Sand	Bentonite	Solid Pipe	Slotted Pipe	Slough/Cuttings	Concrete
Soil Symbols	Sand	Silt	Clay	Gravel	Sand & Silt	Sand & Gravel

Depth (ft) (m)	Description	Symbol	Depth/ Elevation (m)	Sample		Well and Backfill Details	Headspace Vapour Concentration			Laboratory Analysis /Comments
				Number/ ID	Type		▲ (ppm.)	▲ (ppm.)	■ (% Iel)	
	Concrete (building foundation)		0.5							
	SILT, some fine sand, trace gravel, dry to damp, no odour		1.3	08-MW2 @4'			0.5			Sample not analyzed
				08-MW2 @5'			0.5			Sample not analyzed
	SAND, silty, damp, no odour		2.4	08-MW2 @6'						Sample not analyzed
	CLAY, silty, grey, damp to moist, no odour		3.7	08-MW2 @10'			0.4			Sample not analyzed
	SAND, medium, grey, moist		4.4	08-MW2 @13'			0.4			Sample analyzed for VOC and BTEX/VPH
	-wet at approximately 3.5m			08-MW2 @16'			0.6			Sample not analyzed
	GRAVEL, silty, some rounded cobbles, wet, no odour		10.7	08-MW2 @25'			0.9			Sample analyzed for VOC and BTEX/VPH
	Bottom of hole at 10.70 meters									

Grab Sample	NOTES		Logged By	Julien
			Drilled/ Excavated By	RMSS
			Date Drilled or Excavated	5/15/2008
			Datum	
			Water Level Recorded On	11/5/2008

LEVELTON HAZMAT SURREY 808-0159-01 LOGS GFJ LEVELTON SURREY.GDT 1/29/09

This log is for environmental purposes only
This log is the sole property of Levelton Consultants Ltd. and cannot be used or duplicated in anyway without express written permission