


| | | | |
|--|------------------------|---|---|
| CLIENT: IMPERIAL OIL | | EXCAVATION CONTRACTOR: POLLOCK CONTRACTING LTD. | PROJECT No.: V5-268 |
| LOCATION: FORMER MADEIRA PARK BULK PLANT | | EXCAVATION AREA: SAMSUNG 130 EXC. | TEST PIT No.: 14 |
| TEST PIT LOG | PLOTTED: 19970214.0903 | | SAMPLE TYPE: <input type="checkbox"/> CORE <input checked="" type="checkbox"/> SPLIT SPOON <input type="checkbox"/> SHELBY <input checked="" type="checkbox"/> DISTURBED <input type="checkbox"/> NO RECOVERY |
| | CAD FILE No.: 5268TP14 | | |

| DEPTH (m) | SOIL DESCRIPTION | STRATIGRAPHY PLOT | SAMPLE TYPE | SAMPLE NUMBER | SOIL VAPOUR CONCENTRATION (%LEL) | | | | WATER LEVEL | MONITORING WELL INSTALLATION |
|-----------|---|-------------------|-------------|---------------|----------------------------------|----|----|----|-------------|------------------------------|
| | | | | | 20 | 40 | 60 | 80 | | |
| 0 | Fine to medium SAND, trace to some silt, trace gravel, light grey, moist. | | | TP14-1 | | | | | | No monitoring well installed |
| .5 | -gravelly, fractured rock, organics, dark brown, below 0.6 m | | | TP14-2 | | | | | | |
| 1 | -some gravel/fractured rock, grey brown below 1.5 m | | | TP14-3 | | | | | | |
| 1.5 | | | | | | | | | | |
| 2 | Refusal on bedrock at 1.82 m. | | | | | | | | | |
| 2.5 | | | | | | | | | | |
| 3 | | | | | | | | | | |
| 3.5 | | | | | | | | | | |
| 4 | | | | | | | | | | |
| 4.5 | | | | | | | | | | |



| |
|--------------------------------------|
| GROUND SURFACE ELEVATION (m): N/A |
| TOP OF CASING ELEVATION (m): N/A |

| |
|----------------------------|
| DATE EXCAVATED: 1996 10 15 |
| OBSERVED WATER LEVEL: |
| LOGGED BY: CMF |
| SHEET 4 OF 4 |