Any use which a person makes of this data, or any reliance on or decisions to be made based on it, are the sole responsibility of such person. Imperial Oil/SNC-Lavalin Inc./ CSAP/MOE are not responsible for any use or modification of this data. Imperial Oil/SNC-Lavalin Inc./CSAP/MOE accept no responsibility for losses or damages, if any, suffered by any person as a result of decisions made or actions taken based on this data

SNC·LAVALIN

Client
Imperial Oil

Location
1002 Industrial Way, Squamish, BC

Borehole No. : 14-18

PAGE 1 OF 1

Drilling Contractor	Badger Daylighting/Uniwide Drilling	Date Monitored	2014 05 09	Project Number:	617832
Drilling Method	Hydrovac/Hollow Stem Auger	Ground Surface Elev. (m)	99.068	Borehole Logged By:	SJB
Borehole Dia. (m)	0.20	Top of Casing Elev. (m)	99.030	Date Drilled:	2014 05 09
Pipe/Slotted Pipe Dia. (m)	0.05/0.05	Northing: n/a	Easting: n/a	Log Typed By:	SGP

Drilling Legend: Sample Interval; Vac. Extraction; Auger Flight

Water/NAPL Levels: Water Level 1; Water Level 2; NAPL; NAPL

Reading within indicated scale; Reading outside indicated scale

Solid PVC; Slotted PVC

Well Name 1: MW14-18

Depth in Metres	Soil Description	Stratigraphy Plot	Sample Interval Core Run	Sample Number	Blow Count	% Recovery	Soil Vapour (ppm) 10^1 10^2 10^3 10^4
0	GRAVEL (FILL).						
	SAND and GRAVEL (FILL), fine to coarse grained sand, fine and coarse subrounded gravel, trace silt, brown, dry.						
1	Below 1.1 m - wet.						
	Below 1.6 m - some silt			18-1			0
2				18-2			0
3				18-3			0
4	SILT, some fine grained sand, dark brown, soft, wet, organics.			18-4			0
5				18-5 18-6*			0
	Bottom of hole at 5.3 m.						
6							
7							
8							
9							
10							

CONCRETE
BENTONITE
SAND
BENTONITE

NOTES
Bolded sample denotes sample analyzed.
* denotes blind field duplicate.

Print Date: 2015.08.05 QA1: MDH Date Approved: 2015.08.05